

INS. CASE OWNER:

CC 6 / CTI1901

8182, Adm

LKK:

IDAC:

Surveyor:

Adnan

DOI:

11/10/19

Date / Time :

11/10/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. :

SLR 9478J

Claim No. :

Name of Insured :

Policy No. :

Insured Tel No. :

HP:

Make / Model :

Excess Sec II :S\$

D.O.A :

9/10/19

Place of Accident :

Is driver the owner?

(YES / NO)

Nature of Accident :

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)


OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability :

%

Final ? Yes / No

SLJ 1879E



INSRS:

WSP:

Tel :

Liability :

RMKS:

Hum
meng

INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time	STAGE	DATE / PIC
SLJ 1879E - x	Non-Reporting ltr (1st):	
SLR 9478J - x	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List: Handler Typist	
	Notification ltr (if non-pickup)	
	After call ltr to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA :	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	
PRELIMINARY ADVICE Date/Time: Sent By: Confirm by:		
FINALIZATION Date/Time:	Confirm with:	Confirm by:
Repair Cost: S\$	(days) Reduction: %	Email ☐ Call ☐
FINAL SETTLEMENT Date/Time:	Confirm with:	Email ☐ Call ☐
Final Liability: %	(Agreed / Assessed) BOLA S/N No. :	If NO or B 28, Ass. Lia :
Repair Cost: S\$		
Loss of Rental (LOR): S\$	(days)	
Loss of Use (LOU): S\$	(\$ x days)	
Loss of Income (LOI): S\$	(\$ x days)	
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LO ☐	[Tick only one]	
GIA/LTA Search: S\$		
Medical: S\$		
Disbursement: S\$	(e.g. Tow/ Independent)	1) Claim status: Normal/Reject/Private Settle
Legal Cost: S\$		2) Report Format:
Total: S\$	Global Sum S\$:	3) Survey fee:
FINAL PAYMENT Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1: S\$	Name 1:	
Payee 2: (Strike if N.A.) S\$	Name 2:	
Payee 3: (Strike if N.A.) S\$	Name 3:	

ASS. REC. BY:

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLJ1879E Yr Regn: 2016 / NovType: (M.Car) M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Kia Forte K3 C.C. 1591Colour: White A/C: Insured / Std / NI / NASp. Reading: 52937 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNAFX411MH5668574Gen. Cond: Good / Fair / Poor / BurntSteering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt orModi: Nil / (S/Rim) / STD A/Rim orTyre Size: F: 205/55R16R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Nexen

Front

Rear

R/Bal. 06 mmR/Bal. 06 mmL/Bal. 06 mmL/Bal. 06 mm

D.O.A. _____

D.O.I. 11/10/19

Survey held at

Hua meng

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP China

MV:

PV:

Nett:

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + PS SI

Photos

Others

TOTAL

Report Format: _____

Lump Sum / L.B.I: (\$ _____)