

ASS. REC. BY:

REF: CS/MSG 19018191 / Ut93

Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person):

Katherine Wong

of

MSG

Date/Time:

15.10.19 16.10.19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No.:

SFA 8080P

Insured:

SGR 1963L

at Workshop m/s

Imperium Automotive

Tel:

9748 7940

of

25 KAK Bukit Road 4 #01-49

Policy No.:

29090404TM C

Claim No.:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

12.10.2019

CA / REV / REP. / REV 24 HRS

Date/Time:

15.10.19 4.15pm

Person Contacted:

Shawn Tan

H.O.D. Endorsement:

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate	
	SFA 8080P - NA / AG 17018041 / 24	DOA - 12/10/2019
	SGR 1963L - NA / AG 19018041 / 24	DOA - 12/10/2019
21/10@ 10:01am-	Sent message pending estimate	

ASS. REQ. BY:

REF: MS19

Marcus

ASSIGNMENT

From: _____ Date: 16.10.2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SFA 8080P

at Workshop m/s: Imperium Automotive

of 25 Laki Bukit Road 4 #01-49 Singapore

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 49

IDAC Accident Rpt: _____ Consistent? : Yes or No

SIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: 22 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SFA 8080P Yr Regn: 13/1/11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or A1

Make: Jaguar XF 3.0 cc 2967

Colour: Brown A/C: Insured / Std / NI / NA

Sp. Reading: 109399 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SAJAC05D7BFR96910

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/45R18

R: _____

BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 6

Rear: 6

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 12/10/19

D.O.I. 16/10/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or +

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

17/10/19 21A 39733 21/10/19

24/10/19 1/2 9200 confirmed with shuman. (Ref: 32092.83) 21/10/19

RECEIVED 30 OCT 2019

25/10/2019

Date/Time, File Pass to?

: Preli. Report

1) 30/10/2019

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 10

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS: \$

Photos

Others

TOTAL

Add Fee:

: Site Insp (\$

: Interview (\$

: Tech. Invs (\$

: Weekend (\$

Rep. Form: _____

Lump Sum / I.B.I.: 92007

261

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Oct 2019 17:38		15 Oct 2019 16:10 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	EXCLUSIVE LIMO & CAR RENTALS, Co. Reg. No.: 52963858D		
Main Claimant:	Khng Teck Siong, ID: S15248761		
Vehicle Reg. No.:	SFA8080P	Date of Loss:	12/10/2019 15:00 - :59 [104 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	29090404TMC (Comprehensive) Coverage: 01/08/2019 - 31/07/2020
Vehicle Reg. No. (Insured):	SGR1963L	Policy No. (Claimant):	
		Excess:	
Repairer:	Imperium Automotive - Kaki Bukit (HQ) 25 Kaki Bukit Road 4, #01-49 Synergy@KB, 417800 Kaki Bukit - Tel: 97489940		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 16/10/2019]		
Driver/Custodian (Insured):	NG EE SOON (/ Male) , NRIC: S1442633G Email:		
Adj Asg. Remarks:	on WP, Lieb: NR, Agree on SJE. Assign: Marcus Chua from LKK Auto Consultants Pte Ltd. Contact: Shawn Tan @ 9748 9940.		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Sent Message

This mail is associated with :

***SFA8080P (608564)
(SGR1963L]**

TP
Khng Teck Siong
Oct 12 2019 4:00PM
[EXCLUSIVE LIMO & CAR RENTALS]
Imperium Automotive - Kaki Bukit

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 21/10/2019 10:01 AM.
To katherine_wong@sg.msig-asia.com
Subject *SFA8080P (608564) [SGR1963L]

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SFA 8080P on 16/10/2019
We are pending estimate from repairer.

Best Regards,

Denise Tay | Case Handler
LKK Auto Consultants Pte Ltd

DOCUMENTS SUMMARY

There are no documents.

Jaguar XF

Price Range

Depreciation

2011

Vehicle Type

Submit

Advanced Search

Home > Used Cars > RPM Automobile Pte Ltd > Jaguar XF 3.0A Luxury

Jaguar XF 3.0A Luxury

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Price \$50,500**Depreciation** \$15,480 /yr
View models with similar depre**Reg Date** 29-Apr-2011
(1yr 6mths 12days COE left)**Mileage** N.A.**Manufactured** 2011**Road Tax** \$2,348 /yr**Transmission** Auto**Dereg Value** \$38,184 as of today (change)**OMV** \$53,497**COE** \$57,100**ARF** \$53,497**Engine Cap** 2,967 cc**Power** 175.0 kW (234 bhp)**Curb Weight** 1,735 kg**No. of Owners** 2**Type of Vehicle** Luxury Sedan**Features**

Smooth And Effortless V6 Drive, Power And Comfort! Try It And You Will Never Look Back! View specs of the Jaguar XF (2008-2013)

Accessories

Signature Jaguar Gear Selector, Keyless Entry/Start/Stop, Touch Screen Infotainment System With Navi, Bluetooth, Reverse Camera, Paddle Shifters.

Description

Well Maintained, Tip Top Condition! 100% Accident-Free! No Repairs Needed! Flexible Loan And Trade In Available! Call Us For Appointment To Arrange For Viewing Now!

Category

PARF Car

Status

Available

Resources**Car Valuation - Free**
Find out the market value of your existing car for free. Get started**Vehicle Evaluation**
Afraid of lemons? Request to have this car evaluated professionally. Find out more

Posted on: 15-Oct-2019 | Last Updated on: 15-Oct-2019

Upfront Payment
Compare

» more Financial info



Location Map

Price Chart

Click on the point to view the vehicle

Shortlist

Compare

Add note

Report Error

More Actions

Seller Information**Company**RPM Automobile Pte Ltd
» dealer's price list
» 17 vehs sold | 16 vehs available**Address**31 West Coast Highway #01-26
Search cars nearby this location

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 876I

Vehicle Details

Vehicle No.: SFA8080P

Vehicle to be Exported: No

Intended Deregistration Date: 16 Oct 2019

Vehicle Make: JAGUAR

Vehicle Model: XF 3.0 V6 LUXURY AT ABS D/AB HID
2WD 4DR

Primary Colour: Grey

Manufacturing Year: 2010

Engine No.: 591525333FC

Chassis No.: SAJAC05D7BFR96910

Maximum Power Output: 175.0 kW (234 bhp)

Open Market Value: \$56,697.00

Original Registration Date: 13 Jan 2011

First Registration Date: 13 Jan 2011

Transfer Count: 0

Actual ARF Paid: \$56,697.00 28348

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 12 Jan 2021

PARF Rebate Amount: \$31,183.00

Intended COE Rebate Details

COE Expiry Date: 12 Jan 2021

COE Category: B - Car (1601cc & above)

COE Period(Years): 10

QP Paid: \$69,000.00

COE Rebate Amount: \$8,550.00

Total Rebate Amount: \$39,733.00

The information contained herein is correct as at 16 Oct 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	14/10/2019 14:10
Date Of Accident	12/10/2019 15:55
Exact Location Of Accident	CTE (AYE) BEFORE BRADDELL RD EXIT
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SFA8080P
Insured/Policyholder	
Name Of Registered Owner	KHNG TECK SIONG
NRIC No	S15248761
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97880818
Alternative Phone No	OFFICE-97880818
Vehicle Particulars	
Manufacturer	JAGUAR
Model	XF 3.0 V6 LUXURY AT ABS D/AB HID 2WD 4DR
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100361834-05
Cover Note Number	
Driver	
Name of Driver	KHNG JUN JIE
NRIC No	S9043678C
Date Of Birth	17/11/1990
Occupation	OUTDOOR
Date Of Driving Pass	16/11/2009
Driving Experience	9 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97587338
Fax Number	
Contact Number	OFFICE-97587338
EMail Address	NOEMAIL

Address	23 ROSEWOOD DRIVE #01-10
Postcode	737918
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : KARIN CHEW HUI XIN GENDER: : FEMALE
Passenger 2	NAME: : - GENDER: : FEMALE
Passenger 3	NAME: : - GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BISHAN NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 20 BISHAN STREET 23 , POSTCODE: 579757 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-5529999 - FAX NO: 65561905
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20191014/2086.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGR1963L
Vehicle Make/Model/Colour	

Details Of Properties

Vehicle Category	PRIVATE CAR
Name of Driver	NG EE SOON
NRIC/Passport Number	S1442633G
Contact Number	90913200
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	2
Passenger 1	NAME: :
	GENDER: :

DETAILS OF INJURED PERSON 1

Name	KHNG JUN JIE
Approximate Age	
Injuries Sustain	BODY
Injured person in which vehicle?	SFA8080P
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

DETAILS OF INJURED PERSON 2

Name	KARIN CHEW HUI XIN
Approximate Age	
Injuries Sustain	BODY
Injured person in which vehicle?	SFA8080P
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud; regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

CTE (0.45)

A: JFAR000P
B: JFAR03L

← ← ↑ ↑ ↑ ↑

Refer to police report - 7/20/90/4/2086.

I/We declare the foregoing particulars are true in every respect.

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____

Police Report


**SINGAPORE
POLICE FORCE**


T/20191014/2086

1 of 4

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

Report No. T/20191014/2086

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 14/10/2019 13:26	Vide Report No.: F/20191012/0110	Station Diary No.: 120
--	-------------------------------------	---------------------------

Informant's Particulars

Name of Informant: KHNG JUN JIE			Address: 23 ROSEWOOD DRIVE #01-10 SINGAPORE 737918	
ID Type / ID No.: NRIC NO / S9043678C			Contact No.: Home/Office: Mobile: 97587338	
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 28	Date of Birth: 17/11/1990	Type of Informant: Driver	
Race: Chinese			Language:	Institution / School Name:
Occupation: PROPERTY AGENT			Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 12/10/2019 15:55	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 CENTRAL EXPRESSWAY BRADDELL ROAD Along CTE towards AYE, before Braddell Rd Exit				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SFA8080P	Car				Slightly Damaged	3
SGR1963L	Car				Slightly Damaged	1

Details of Person Involved

Details of crash involved:	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Police Report



**SINGAPORE
POLICE FORCE**



T/20191014/2086

2 of 4

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

Report No. T/20191014/2086

CONTINUATION OF REPORT

Passenger:			
Name	Karin Chew Hui Xin	ID No.	S9420288H
Related Vehicle	SFA8080P (Car)	Contact No.	90600098
Hospital/Clinic	HEALTHLINK MEDICAL CENTRE	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	14/10/2019	Date Discharge	NIL
No. of Days granted Medical Leave	02	Degree of Injury	Slight
Driver:			
Name	KHNG JUN JIE	ID No.	S9043678C
Related Vehicle	SFA8080P (Car)	Contact No.	97587338
Hospital/Clinic	KHOO TECK PUAT HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	12/10/2019	Date Discharge	13/10/2019
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Driver:			
Name	Ng Ee Soon	ID No.	S1442633G
Related Vehicle	SGR1963L (Car)	Contact No.	90913200
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 12/10/2019 at about 1555hrs, I was driving my vehicle (SFA8080P) along CTE towards AYE on the exit lane towards PIE. The traffic was very heavy, as such, I then came to stop behind other vehicles queuing to exit. Suddenly, I felt an impact from the rear of my vehicle.

Upon making a check, I realized that another vehicle (SGR1963L) had collided into the rear of my vehicle. As I had passengers inside my vehicle that required ambulance assistance, I then called for ambulance and police. Subsequently I felt pain around my back area. I then went to see a doctor and was given 3 days of medical leave.

Police Report



SINGAPORE
POLICE FORCE



T/20191014/2086

3 of 4

Police Station Of Origin:

Bishan N.P.C

20 Bishan Street 23 SINGAPORE 579757

Tel No: 1800-5529999

Report No. T/20191014/2086

CONTINUATION OF REPORT

Police Report



SINGAPORE
POLICE FORCE



T/20191014/2086

4 of 4

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

Report No: T/20191014/2086

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

E /
Sgt 2 LIM HWEE JIE, SAMUEL

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
14/10/2019 13:26

Officer In Charge Of Case:
TP / GIT /
Sgt 3 MUHAMMAD AFIQ BIN RAHMAT
Contact No.: 65476171



SINGAPORE
POLICE FORCE

Classification Of Case:

SIGNATURE

Authentication Stamp
NP168

IMPERIUM AUTOMOTIVE

25 Kaki Bukit Road 4 #01-49 Synergy @ KB Singapore 417800

Tel: 9478 9940

Fax: 6346 7213

Vehicle No: SFA 8080P

Model: Jaguar XF 3.0 V6 Luxury

not approved
Lali
L/S # 9200/
16/10/19
Shepherd
10

QTY

List Price:

Prices \$

1	Rear boot lid	2263.21	sub/suc	2995.60	✓
2	Rear boot hinge- RH/LH @ 125.00		8u	250.00	X
1	Rear boot rubber	155.00	twi	278.00	✓
1	Rear boot lock	233.59	twi	335.00	✓
1	Rear boot lock catch		17	69.10	X
1	Rear boot inner trim		17	455.00	X
1	Rear boot emblem LOGO		17	179.50	X
1	Rear boot emblem "XF"		1u	79.50	✓
1	Rear boot outer moulding		17	415.10	X
2	Rear boot reflector- RH/LH @ 321.80		17	643.60	X
1	Rear windscreen moulding		17	239.40	X
2	Rear taillamp- RH/LH @ 491.80		CNE	983.60	✓
2	Rear taillamp panel housing- RH/LH @ 296.50		R	593.00	X
1	Rear bumper	2215.30	DLS	2823.60	✓
1	Rear bumper lower lid	366.12	DLS	698.00	✓
4	Rear bumper PPC sensor @ 356.70	245 x 4 = 980	CNE	1426.80	✓
1	Rear bumper centre guide		CNE	193.60	✓
2	Rear bumper holder- RH/LH @ 91.60		CNE	183.20	✓
1	Rear bumper reinforcement	850	DLS	865.80	✓
2	Rear bumper side retainer- RH/LH @ 131.60		17	263.20	X
2	Rear exhaust box- RH/LH @ 1468.20		R	2936.40	X
2	Rear exhaust box heat shield - RH/LH @ 278.20		R	556.40	X
2	Rear exhaust chrome pipe- RH/LH @ 405.00	205	0/500	810.00	12C
6	Rear exhaust mounting @ 40.50		17	243.00	X
1	Rear end panel	1163.00	R-510	1788.90	✓
1	Rear end panel garnish	266.50	CNE	499.60	✓
1	Rear spare tyre panel cardboard		8u	616.00	X
1	Rear floor panel	1650.00	crumpled	3521.00	✓
2	Rear fender - RH/LH @ 3861.00		R	7722.00	X
2	Rear fender air vent - RH/LH @ 185.40		17	370.80	X
2	Rear fender inner trims - RH/LH @ 1218.30	365.20 x 2 = 730.40	re/to.1	2436.60	✓
2	Rear chassis members - RH/LH @ 1348.70		R	2687.40	X
				38158.70	
Less 10%				-3815.87	
			Subtotal	34342.83	

12518.02

1	Rear number plate with casing
1	Rear bumper clip
1	Rear battery

Subtotal	650.00
----------	--------

- Panel beating, cut, weld, remove and replacing above parts
- To respray painting and etc
- To checking front wiring
- To remove, refix cushion
- To remove, refix rear exhaust
- To respray undercoating
- To remove fuel pipe and oil tank
- To remove and refit rear windscreen glass
- To remove and refit rear reverse sensor

Subtotal	6300.00
----------	---------

14396.2 /

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19018191/UTF3N2

Date: 30/10/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29090404
Claimant Vehicle No :	SFA8080P	Insured Vehicle No :	SGR1963L
Date of Loss:	12/10/2019	Nature of Claim:	TP
		Claim No:	608564

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFA8080P	Engine No:	591525333FC
Make & Model:	JAGUAR XF, 3.0 V6 LUXURY (A)	Chassis No:	SAJAC05D7BFR96910
Reg. Date:	13/01/2011 (Man. Year: 2010)	Odometer:	109399 km
Colour:	Brown		
Engine Capacity:	2967 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45R18	Rear Tyre Size:	245/45R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	34,992.83	11,316.22	23,676.61	67.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,300.00	3,080.00	3,220.00	51.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	41,292.83	14,396.22	26,896.61	65.14
Approved Total (Overridden) (S\$)		9,200.00		
Nett Amount (S\$)	41,292.83	9,200.00	32,092.83	77.72

INSPECTION

Date of Assignment:	15/10/2019	
Date Inspected:	16/10/2019	Inspected At:
		Imperium Automotive - Kaki Bukit (HQ)
		25 Kaki Bukit Road 4, #01-49
		Synergy@KB
		Singapore 417800
Estimated Period of Repair:	10.0 days	

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Oct 2019)

Parts: 143 JAGUAR XF 3.0 V6 LUXURY (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SFA8080P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Bent/Buckled	2,995.60 FL	*2,263.21 FL
2	2		*REAR BOOT HINGE-RH/LH	Serviceable	250.00 FL	*- FL
3	1		*REAR BOOT RUBBER	Twisted	278.00 FL	*155.00 FL
4	1		*REAR BOOT LOCK	Twisted	335.00 FL	*233.59 FL
5	1		*REAR BOOT LOCK CATCH	Not Necessary	69.10 FL	*- FL
6	1		*REAR BOOT INNER TRIM	Not Necessary	455.00 FL	*- FL
7	1		*REAR BOOT EMBLEM LOGO	Not Necessary	179.50 FL	*- FL
8	1		*REAR BOOT EMBLEM XF	Necessary	79.50 FL	*79.50 FL
9	1		*REAR BOOT OUTER MOULDING	Not Necessary	415.10 FL	*- FL
10	2		*REAR BOOT REFLECTOR-RH/LH	Not Necessary	643.60 FL	*- FL
11	1		*REAR WINDSCREEN MOULDING	Not Necessary	239.40 FL	*- FL
12	2		*REAR TAILLAMP-RH/LH	Cracked	983.60 FL	*983.60 FL
13	2		*REAR TAILLAMP PANEL HOUSING-RH/LH	Repair	593.00 FL	*- FL
14	1		*REAR BUMPER	Distorted	2,823.60 FL	*2,215.30 FL
15	1		*REAR BUMPER LOWER LID	Distorted	698.00 FL	*366.12 FL
16	4		*REAR BUMPER PDC SENSOR	Cracked	1,426.80 FL	*980.00 FL
17	1		*REAR BUMPER CENTRE GUIDE	Cracked	193.60 FL	*193.60 FL
18	2		*REAR BUMPER HOLDER-RH/LH	Cracked	183.20 FL	*183.20 FL
19	1		*REAR BUMPER REINFORCEMENT	Distorted	865.80 FL	*850.00 FL
20	2		*REAR BUMPER SIDE RETAINER-RH/LH	Not Necessary	263.20 FL	*- FL
21	2		*REAR EXHAUST BOX-RH/LH	Repair	2,936.40 FL	*- FL
22	2		*REAR EXHAUST BOX HEAT SHIELD-RH/LH	Repair	556.40 FL	*- FL
23	1		*REAR EXHAUST CHROME PIPE-RH/LH	O/s Dented	810.00 FL	*205.00 FL
24	6		*REAR EXHAUST MOUNTING	Not Necessary	243.00 FL	*- FL
25	1		*REAR END PANEL	Badly Dented	1,788.90 FL	*1,163.00 FL
26	1		*REAR END PANEL GARNISH	Cracked	499.60 FL	*266.50 FL
27	1		*REAR SPARE TYRE PANEL CARDBOARD	Serviceable	616.00 FL	*- FL
28	1		*REAR FLOOR PANEL	Crumpled	3,521.00 FL	*1,650.00 FL
29	2		*REAR FENDER-RH/LH	Repair	7,722.00 FL	*- FL
30	2		*REAR FENDER AIR VENT-RH/LH	Not Necessary	370.80 FL	*- FL
31	2		*REAR FENDER INNER TRIMS-RH/LH	Deformed/Torn	2,436.60 FL	*730.40 FL
32	2		*REAR CHASSIS MEMBERS-RH/LH	Repair	2,687.40 FL	*- FL
33	1		*REAR NUMBER PLATE WITH CASING	Serviceable	120.00 FS	*- FS
34	1		*REAR BUMPER CLIP	Necessary	80.00 FS	*50.00 FS
35	1		*REAR BATTERY	Serviceable	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	38,808.70	12,568.02
- List Item Discount on L Items 10.00/10.00% (\$\$)	3,815.87	1,251.80
Total Parts (\$\$)	34,992.83	11,316.22

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,CUT,WELD,REMOVE AND REPLACING ABOVE PARTS	New	3,000.00	1,500.00
2	TO RESPRAY PAINTING AND ETC	New	2,000.00	1,200.00
3	TO CHECKING FRONT WIRING	New	100.00	30.00
4	TO REMOVE,REFIX CUSHION	New	200.00	80.00
5	TO REMOVE,REFIX REAR EXHAUST	New	250.00	80.00
6	TO RESPRAY UNDERCOATING	New	150.00	80.00
7	TO REMOVE FUEL PIPE AND OIL TANK	New	250.00	60.00
8	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	250.00	0.00
9	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	100.00	50.00
Gross Labour Cost (S\$)			6,300.00	3,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >