

12/01/2018

ASS. REC. BY:

REF:

08/SPP/19018196/Ay d362

Special Instruction:

Surveyor: Adrian

ASSIGNMENT (Office)

From (Person): Hafzul Furhan

of

SPP

Date/Time:

15/10/2019 3:47pm

Estimated Cost:

Bill to:

OD/PT/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBF 9014X

Insured:

QX 298E

at Workshop m/s

TICK HZI Motor

Tel:

6842 9089

of

1 loki Bukit Ave 6 # 01-54

Policy No:

Claim No:

AEMD/105/009/209/100

Sum Insured:

Excess:

Make of Veh:

D.O.A.

28/09/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

4:32pm 15/10/19

Person Contacted:

Connie

Vehicle IN/OUT

Date/Time

Action/Instruction

Estimate /

GBF 1014X-03/1PL/5012772/Kda3

27/11/2018

AX208E-X

Do Not Finalise

ASS. REC. BY:

REF: SPF

## ASSIGNMENT

From:

Date:

16/10/2019

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

GBF 9014X

at Workshop m/s

Tick Hai Motor

of

1 Kerei Street Ave 6 # 01-54

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

1pm.

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GBF 9014X

Yr Regn:

2017, March.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan NV200c.c 1461

Colour

white.

A/C:

Insured / Std / NI / NA

Sp. Reading

89312.

T/Radio:

Insured / Std / NI / NA

Eng/No:

VSKYBAM2020139478

C/No:

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 175/70R14C.

R:

175/70R14C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Habilead.

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

16/10/19.

Survey held at

Tick Hai.Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP SPF.30/1Submit L/S \$2100/- 4 days  
(Range Cor = \$2000/- - \$2500/-)  
0 weekend

Do Not Finalise

RECEIVED 31 JAN 2020

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 30/1/20 TypistDays Of Repair: 4

Resurvey No. of Trip:

Survey Fee:

220

Transportation:

S + RS: \$

Photos

Others

TOTAL

220

Report Format:

Lump Sum / L.E.I: (\$)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

## Nivitha (LKK Auto)

---

**From:** Hafizul Farhan RAHMAT (SPF) <Hafizul\_Farhan\_RAHMAT@spf.gov.sg>  
**Sent:** Tuesday, 15 October 2019 3:47 PM  
**To:** Admin-D (LKKAuto); assignments; SUR  
**Cc:** Frankie THAY (SPF); Cui Fen ENG (SPF)  
**Subject:** Pre-repair Survey of GBF9014X (vs QX298E on 28.9.2019)

Our ref: AEMD/105/009/2019/100

Hi,

Kindly conduct pre-repair survey of **GBF9014X** at

Tick Hai Motor & Welding Services  
Blk 1 Kaki Bukit Ave 6  
#01-54 Auto@Kaki Bukit  
Singapore 417883

Contact person: Ms Connie, Tel: 6842 9089

*Best Regards,*

*Hafizul Farhan Bin Rahmat*

*AEMD / PLD*

*Singapore Police Force*

*DID: (65) 6478 4840 | FAX: (65) 6478 4848*



**WARNING:** "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

MSME19129164 / SME Motor Pte Ltd - Kaki Bukit  
 ENTRY DATE & TIME: 30/09/2019 14:10  
 SUBMITTED BY: Chia Pei Ying

## SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Tick Hai motor &amp; WS

## ACCIDENT STATEMENT

Date Of Report	30/09/2019 14:10
Date Of Accident	28/09/2019 09:50
Exact Location Of Accident	ALJUNIED RD/ GEYLANG EAST CENTRAL TRAFFIC JUNCTION
Country/State of Loss	SINGAPORE

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBF9014X
<b>Insured/Policyholder</b>	
Name Of Registered Owner	IN FLORA AND GIFTS
Co Reg No	52983547M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-94592022

## Vehicle Particulars

Manufacturer	NISSAN
Model	NV200

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

## Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z/19/VC00/103249
Cover Note Number	

## Driver

Name of Driver	TAN BOON ENG
NRIC No	S1601386B
Date Of Birth	08/05/1963
Occupation	INDOOR
Date Of Driving Pass	02/12/1980
Driving Experience	38 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94592022
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 896A TAMPINES ST 81 #02-870  
 Postcode 521896  
 Was driver an employee of the Insured's Company YES  
 If No, Relationship of the Driver with the Insured  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

### Other Information

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 2  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 2  
 Passenger 1 NAME: : UNKNOWN  
 GENDER: : FEMALE

### Details of Police Action

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 Police Station Name BEDOK NORTH NEIGHBOURHOOD POLICE CENTRE  
 Police Station Address ROAD: 30 BEDOK NORTH ROAD , POSTCODE: 469676 , COUNTRY: SINGAPORE  
 Police Station Contact TEL NO: 1800-2449999 - FAX NO: 62447258  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

### Circumstances of Accident

REFER TO POLICE REPORT: T/20190928/2192.

### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number QX298E  
 Vehicle Make/Model/Colour  
 Details Of Properties VEHICLE B  
 Vehicle Category GOVERNMENT  
 Name of Driver DERRICK LIM  
 NRIC/Passport Number  
 Contact Number 98207865  
 Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

 **In fiera & gifts** 

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

TICK HERE

## Sketch Plan #2 Pg. 1


SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
  2. This Form must be completed by the Policyholder and/or the Authorised Driver.
  3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
  4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
  5. Any false reporting may be referred to the Police for investigation.
  6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
  7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
  8. Consent under the Personal Data Protection Act (PDPA)
- I understand, acknowledge, agree and consent that :
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time      Driver's Signature (If driver is not the policyholder) / Date & Time      Witnessed by Reporting Centre Personnel

## Sketch Plan






## Sketch Plan #3 Pg. 1

Describe Circumstances of the Accident

Refer to police report

## Declaration

We declare the foregoing particulars are true in every respect.

 **In** 要領物と礼品  
 Policyholder's Signature / Date & Time      Driver's Signature (If driver is not the policyholder) / Date & Time      Witnessed by Reporting Centre Personnel

Insurance Co.	<u>Lompac</u>		
Vehicle NO.	<u>GBF9014X</u>	Date Of Accident	<u>28, 9, 19</u>
<input type="checkbox"/> Reporting Only <input type="checkbox"/> Own Damage Claim <input checked="" type="checkbox"/> Third Party Claim			

## Sketch Plan #4 Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20190928/2182

Police Station Of Origin:  
Bedok North N.P.C  
30 Bedok North Road SINGAPORE 469676  
Tel No: 1800-2449999

1 of 3

Report No. T/20190928/2192

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 28/09/2019 22:55		Vide Report No.: G/20190928/0095		Station Diary No.: 178	
<b>Informant's Particulars</b>					
Name of Informant: TAN BOON ENG			Address: APT BLK 896A TAMPINES STREET 81 #02-870 SINGAPORE 521896		
ID Type / ID No.: NRIC NO / S1601386B			Contact No.: Home/Office: Mobile: 94592022		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 56	Date of Birth: 08/05/1963	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: FLORIST			Driving Licence Information: Class: 3		Date of Expiry:

## General Information of the Accident

Type of Accident:	Non-Injury Government Vehicle	Drink Drive: No	Date/Time of Accident: 28/09/2019 09:50	Type of Location: X-Junction
Location: Along Road 1 ALJUNIED ROAD  ALONG ALJUNIED ROAD				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Dual Carriage Way		Traffic Control: Traffic Light - Working	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

## Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBF9014X	Van	NISSAN	NV200	White	Slightly Damaged	1
QX298E	POLICE CAR	TOYOTA	COROLLA ALTIS 1.6 AUTO	Multi-Colored	Slightly Damaged	1

## Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

## Sketch Plan #5 Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20190928/2192

Police Station Of Origin:  
Bedok North N.P.C  
30 Bedok North Road SINGAPORE 469676  
Tel No: 1800-2449999

2 of 3

Report No. T/20190928/2192

## CONTINUATION OF REPORT

<b>Driver</b>			
Name	TAN BOON ENG		ID No. S1601386B
Related Vehicle	GBF9014X (Van)		Contact No. 94592022
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Driver</b>			
Name	DERRICK LIM		ID No. NIL
Related Vehicle	QX298E (POLICE CAR)		Contact No. 98207865
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 28th September at around 0950hrs, I was driving my company van bearing registration plate number GBF9014X ( White Colored Nissan NV200 ) along Aljunied Road. Subsequently, while approaching the junction of Aljunied Road and Geylang East Central, I was on the lane to turn right into Geylang East Central.

Subsequently, while I was waiting to turn right, there was a police vehicle bearing registration plate number QX298E ( Toyota Altis ) who knocked onto the rear portion of my vehicle. The impact had cause my handphone ( Black Colored Samsung Note 8 ) which was mounted at the front portion of the van to fall off. My handphone screen had a slight crack due to this.

We alighted from our vehicles and exchange particulars. Traffic police also came to scene reference G/20190928/0095. No one was injured. Due to this accident, the van that I was driving had the following damages:

- 1) Rear bumper dented
- 2) Rear left side of vehicle dented

For the police car, its' front bumper was cracked. I have no video footages of the accident. That's all.

## Sketch Plan #6 Pg. 1

**SINGAPORE  
POLICE FORCE**

T/20190928/2192

Police Station Of Origin:  
Bedok North N.P.C  
30 Bedok North Road SINGAPORE 469676  
Tel No: 1800-2449999

3 of 3





Report No. T/20190928/2192

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Sgt 2 AHMAD BIN HASHIM 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 28/09/2019 22:55
Officer In Charge Of Case: TP / GIA / Staff Sgt WONG SIEU LUI Contact No.: 65476151	Classification Of Case:
Authentication Stamp NP188  SINGAPORE POLICE FORCE  SIGNATURE	

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Business
Owner ID:	547M
<b>Vehicle Details</b>	
Vehicle No.:	GBF9014X
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Jan 2020
Vehicle Make:	NISSAN
Vehicle Model:	NV200 1.5 MT ABS AIRBAG 2WD 6DR E5 W/RC
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	K9KC400D056360
Chassis No.:	VSKYBAM20Z0139478
Maximum Power Output:	-
Open Market Value:	\$20,122.00
Original Registration Date:	30 Mar 2017
First Registration Date:	30 Mar 2017
Transfer Count:	0
Actual ARF Paid:	\$1,007.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	29 Mar 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$41,659.00
COE Rebate Amount:	\$30,068.00
<b>Total Rebate Amount:</b>	<b>\$30,068.00</b>

The information contained herein is correct as at 10 Jan 2020

OK

REG NO : 48992400W

**Chassis : VSKYBAM20Z0139478**

Labour	Amount (\$)
To check rear electrical wiring system	\$ 180.00
To transfer door component from old door to new door	\$ 300.00

To remove & reinstall door glass	\$ 180.00
To remove & reinstall reverse sensors	\$ 150.00
To apply anti-rusting coating on affected panels	\$ 200.00
Labour to remove, cut, change & panel beating	\$ 1,800.00
To putty and respray affected areas	\$ 1,200.00
<b>Labour Total :</b>	<b>\$ 4,010.00</b>
<b>Total (Parts &amp; Labour)</b>	<b>\$ 8,540.74</b>

X  
50  
60  
600  
400

1140

total: 2623 06

h/s 2.1K.

04 Days.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair Range : 2K-2.5K

H.S.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGINEERING & MGT DIVISION			Ref : CS/SPF19018196/Ayd3e2	
ACCIDENT CLAIM SECTION (SPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMY SINGAPORE 298333			Date : 05-02-2020  Code : SPF	
ATTN : HAFIZUL FARHAN				
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	QX 298E	Veh. Inspected	GBF 9014X	
Policy No.		Coverage (\$)	0.00	
Claim No.	AEMD/105/009/2019/100	Excess (\$)	0.00	
Assign From	HAFIZUL FARHAN	Assign Date	15/10/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	NISSAN NV200	c.c	1461	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	VSKYBAM20Z0139478	Colour	WHITE	
Odometer	89312	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	175/70 R14C	HABILEAD	6 mm	
L/H Front Tyre	175/70 R14C	HABILEAD	6 mm	
R/H Rear Tyre	175/70 R14C	HABILEAD	6 mm	
L/H Rear Tyre	175/70 R14C	HABILEAD	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	28/09/2019	Inspection Date	16/10/2019	
Survey held at	TICK HAI MOTOR & WELDING SERVICES BLK 1 KAKI BUKIT AVE 6 #01-54 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>		






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF19018196/Ayd3e2		
ACCIDENT CLAIM SECTION (SPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMY SINGAPORE 298333		Date : 05-02-2020		
ATTN : HAFIZUL FARHAN		Code : SPF		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	QX 298E	Veh. Inspected	GBF 9014X	
Policy No.		Coverage (\$)	0.00	
Claim No.	AEMD/105/009/2019/100	Excess (\$)	0.00	
Assign From	HAFIZUL FARHAN	Assign Date	15/10/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	NISSAN NV200	c.c	1461	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	VSKYBAM20Z0139478	Colour	WHITE	
Odometer	89312	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	175/70 R14C	HABILEAD	6 mm	
L/H Front Tyre	175/70 R14C	HABILEAD	6 mm	
R/H Rear Tyre	175/70 R14C	HABILEAD	6 mm	
L/H Rear Tyre	175/70 R14C	HABILEAD	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	28/09/2019	Inspection Date	16/10/2019	
Survey held at	TICK HAI MOTOR & WELDING SERVICES BLK 1 KAKI BUKIT AVE 6 #01-54 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 9014X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	TAILLAMP (LH)	NOT NECESSARY	192.60	-
1	REAR BOOT DOOR (LH)	TO REPAIR SEE LABOUR	1,364.25	-
2	REAR BOOT DOOR HINGE (LH)	NOT NECESSARY	218.28	-
1	REAR BOOT RUBBER	NOT NECESSARY	104.33	-
1	REAR BOOT LOCK (TOP)	NOT NECESSARY	144.45	-
1	REAR BOOT LOCK (BOTTOM)	NOT NECESSARY	144.45	-
1	NISSAN LOGO	NECESSARY	72.23	72.23
1	"NV200" EMBLEM	NECESSARY	80.25	80.25
1	NUMBER PLATE TOP GARNISH	NOT NECESSARY	264.83	-
1	REAR BUMPER	DEFORMED	770.40	770.40
1	REAR BUMPER REFLECTOR (LH)	CRACKED	80.25	80.25
1	REAR BUMPER SPONGE	CRACKED	128.60	128.60
1	END PANEL (INNER)	TO REPAIR SEE LABOUR	754.35	-
1	END PANEL (OUTER)	DENTED	216.68	216.68
	LESS 10% DISCOUNT		-453.60	-134.84
			4,082.35	1,213.57
<b><u>SPECIAL NETT ITEMS</u></b>				
2	REVERSE SENSOR (SN)	DAMAGED	323.40	200.00
1	"70KM/H" STICKER (SN)	NECESSARY	15.00	15.00
1	END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	WINDSCREEN SEALANT (SN)	NOT NECESSARY	60.00	-
			448.40	265.00
<b><u>LABOUR</u></b>				
	TO CHECK REAR ELECTRICAL WIRING SYSTEM.		180.00	30.00
	TO TRANSFER DOOR COMPONENT FROM OLD DOOR TO NEW DOOR.	NOT NECESSARY	300.00	-
	TO REMOVE & REINSTALL DOOR GLASS.	NOT NECESSARY	180.00	-
	TO REMOVE & REINSTALL REVERSE SENSORS.		150.00	50.00
	TO APPLY ANTI-RUSTING COATING ON AFFECTED PANE		200.00	60.00

Report Ref No. CS/SPF19018196/Ayd3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR TO REMOVE, CUT, CHANGE & PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BOOT DOOR (LH) AND END PANEL (INNER). TO PUTTY AND RESPRAY AFFECTED AREAS.		1,800.00	600.00
			1,200.00	400.00
			4,010.00	1,140.00
GRAND TOTAL			8,540.75	2,618.57
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,100.00

Report Ref No. CS/SPF19018196/Ayd3e2

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$2,500

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.