

(08/11/13)

REF: \*

NS/INC19018210/K2V9302

Surveyor: Kelvin

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD ☒ TP ☐ NS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: SJR 71847Policy No. 5111690080 (08/08/2019 - 07/08/2020)Claims No. MT/1066735-003

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SHC 1989E Yr Regn: 20 Dec 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai c.c. 1685Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 21 2341 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KMHCB410MH4100067Gen. Cond: Good / ~~Fair~~ / Poor / BurntSteering: Insured / Jammed / Leaked / Burnt orBrake: Insured / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 205/60R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Marked

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 12/10/19 D.O.I. 15/10/19Survey held at C/DHE (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front / Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

SJR 71847: CA/22215021368/12/2019 2019-21/12/2019

SHC 1989E: CSIFC19007911/13 2019-30/11/2019

22/10/19 Chd P/P \$11402.88/ 6 Dgs. (Red 10,062.96, 475)

RECEIVED 23 OCT 2019

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 22/10 - typist

Days Of Repair: 6Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

S + RS \$ \_\_\_\_\_

Photos

160

160

## Veron Chen (LKKAUTO)

**From:** MTCL@income.com.sg  
**Sent:** Tuesday, 22 October 2019 3:27 PM  
**To:** Veron Chen (LKKAUTO)  
**Subject:** RE: REQUEST FOR CLAIM NUMBER

Dear Sir/Mdm,

We have registered the claim.

Our reference number: MT/1066735-003

Please allow the claim officer 2-3 working days to respond to your case.

We appreciate if you do not respond to this email. Thank you

Best regards

**Diana Tay**  
Senior Admin Assistant  
[www.income.com.sg](http://www.income.com.sg)



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify. Find out more at [Income.com.sg/careers](http://Income.com.sg/careers)

**in** with you

**From:** Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]  
**Sent:** Tuesday, 22 October 2019 12:32 PM  
**To:** MTCL@income.com.sg  
**Subject:** REQUEST FOR CLAIM NUMBER

Dear Sir/Madam,

Kindly provides us the claim number

S/NO	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.
1	MT/1066735-003	COMFORT TRANSPORTATION PTE LTD	SHC 1989E	SJR 71847

D.O.A	Time of Accident	Estimate	Tentative repair cost
12/10/2019	9:00	\$21,465.84	\$11,402.88

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**Disclaimer**

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

eBaoTech

General Claim

Hello, NAC\_PAYA\_UBI\_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

## Policy Query

Policy No.	<input type="text"/>	Date of Accident	<input type="text" value="12/10/2019 08:41"/>
Vehicle No.(For Motor)	<input type="text" value="SJR7184T"/>	Certificate Number	<input type="text"/>

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5111690080		ZEENATH BEGUM BINTI ISMAIL	S78045740	GPC	drive CLASSIC	SJR7184T	SJR7184T	08/08/2019	07/08/2020

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	14/10/2019 15:28
Date Of Accident	12/10/2019 09:00
Exact Location Of Accident	BKE TWDS PIE (CHANGI)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC1989E
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088937MFSH
Cover Note Number	

### Driver

Name of Driver	WANG CHEE KEAT
NRIC No	S2606494E
Date Of Birth	14/03/1965
Occupation	OUTDOOR
Date Of Driving Pass	20/10/1994
Driving Experience	24 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96183619
Fax Number	
Contact Number	
Email Address	WANGCHEEKEAT@SINGNET.COM.SG

Address	BLK 488C CHOA CHU KANG AVE 5 #11-157
Postcode	683488
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	16
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLS REFER TO ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJR7184T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	91112078
Address	
Postcode	
Insurance Company Name	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Nature Of Damage	FRT

No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number GBH6879B  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category COMMERCIAL VEHICLE  
Name of Driver CHEW CHEONG SAR  
NRIC/Passport Number  
Contact Number 96709133  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage REAR AND FRT  
No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SLH4709D  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage REAR AND FRT  
No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number SML6834D  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage REAR AND FRT  
No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 5

Vehicle Registration Number  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category NA/UNKNOWN  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address

Postcode  
Insurance Company Name  
Nature Of Damage REAR AND FRT  
No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 6

Vehicle Registration Number SMG6687M  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage REAR AND FRT  
No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 7

Vehicle Registration Number SLD1589Z  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage FRT  
No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 8

Vehicle Registration Number  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category NA/UNKNOWN  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage REAR AND FRT  
No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 9

Vehicle Registration Number  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category NA/UNKNOWN  
Name of Driver



NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage REAR AND FRT

No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 10

Vehicle Registration Number

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category NA/UNKNOWN

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage REAR AND FRT

No. Of Passenger (Including Driver)

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

*Handwritten signature*

*Handwritten signature*

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 12.10.2019@1145hrs

Reporting Centre Personnel's Signature:  
Name:  
NRIC/FIN No.: June

### SKETCH PLAN

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99

A- SHC 1989E  
B- SJR 7184T  
C-GBH 6879B  
D- SLH 4709D  
E- SML 6834D  
F- UNKNOWN  
G- SMG 6687M  
H- SLD 1589Z  
I- UNKNOWN  
J- UNKNOWN  
K- UNKNOWN  
L- UNKNOWN  
M-UNKNOWN  
O-UNKNOWN  
P-UNKNOWN  
N- UNKNOWN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

[illegible]

I/We declare the foregoing particulars are true in every respect.

MOORT TRANSPORTATION PTE LTD  
CO. REG. NO. 19930J621R

Policyholder's Signature \_\_\_\_\_  
Date & Time \_\_\_\_\_

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 12.10.2019@1145hrs

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No: June

**IMPORTANT NOTE:** Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

## ADDENDUM

### (A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MCD619136113 Vehicle Registration No: SHC1989E  
Name (as shown in NRIC) : WANG CHEE KEAT NRIC/FIN/Passport No : Sxxxx494E  
( **Vehicle Driver** Vehicle Owner ) (\*) Please delete as appropriate  
Address : BLK 488C CHOA CHU KANG AVE 5 #11-157 Singapore ( 683488 )  
Contact (Tel) : Mobile No. :  
Email Address :  
Date of Accident : 12/10/2019 Time of Accident : 09:00  
Place of Accident : BKE TWDS PIE (CHANGI)  
Insurance Company: MS First Capital Insurance Ltd

### (B) **ADDITIONAL INFORMATION** AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Addin 3P vehicle No. : L to P ( unknown )

---

---

---

---

---

---


---

---

---

---

Policyholder / Driver's Signature  
Date:

  
Reporting Centre Personnel's Signature  
Name: xiaoyan  
NRIC/FIN No.:  
Date: 14.10.2019

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305341465

STOMER  
 COMFORT TRANSPORTATION PTE LTD  
 7010045  
 STOMER NO. 383 SIN MING DRIVE  
 DRESS Singapore SINGAPORE 575717  
 65508755 (D)

REGN NO.	SHC1989E	MILEAGE
MAKE	HYUNDAI	FUEL E 1/2 F
MODEL	I-40	DATE/TIME IN 12.10.2019 09:00
YR OF MANU	20.12.2017	TARGET DATE
CHASSIS CODE	KMHLB41UMHU100067	COMPLETION DATE/TIME


ACCOUNT CARD NO.

### JOB DESCRIPTION

Accident Date: 12.10.2019  
 NATURE: 3P 12.10.2019

S/NO LABOR CODE DESCRIPTION

XTCMC - Rear, Front



CHECKED & PASSED OUT BY

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SHC1989E LKE

Vehicle No.: SHC1989E

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard

## REPAIR ESTIMATE\*

VEHICLE NO : SHC 1989E

DATE : 14.10.2019

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet / But - But			\$ 2,265.90
	Bonnet Hinge (LH/RH)	\$	41.00	\$ 82.00
	Bonnet Lock / Jamb			\$ 36.90
	Bonnet Absorber X sue	\$	58.10	\$ 116.20
	Bonnet Insulator / sue			\$ 196.50
	Bonnet Insulator Clips / sue			\$ 8.40
	Radiator Grille / sue			\$ 1,110.10
	Radiator Grille H Emblem / sue			\$ 39.50
	Front Bumper Cover / sue			\$ 1,052.20
	Front Bumper Sponge X sue			\$ 99.20
	Front Bumper Reinforcement X sue			\$ 402.10
	Front Bumper Lip X sue			\$ 54.90
	Front Bumper Bracket Top (LH/RH) X sue	\$	22.40	\$ 44.80
	Front Bumper Bracket (LH/RH) X sue	\$	24.60	\$ 49.20
	Headlamp Support Top Cover X sue			\$ 222.60
	Headlamp Support Panel Assy / sue			\$ 907.40
	Headlamp (LH/RH) / sue	\$	1,388.00	\$ 2,776.00
	Radiator / But			\$ 698.30
	Radiator Fan Blade, Cowling, Motor Assy X sue			\$ 792.95
	Radiator Bracket (RH/LH) X sue	\$	6.50	\$ 13.00
	Radiator Hose Upper / sue			\$ 36.50
	Radiator Hose Lower / sue			\$ 36.50
	Radiator Expansion Tank X sue			\$ 28.30
	Radiator Guard X sue	\$	20.00	\$ 40.00
	Horn Unit (LH/RH) / sue	\$	73.80	\$ 147.60
	Horn Wire X sue			\$ 156.50
	Front Fender (LH) / But			\$ 566.30
	Front Fender Shield (LH) X sue			\$ 174.90
	Air Cleaner Assy + sue			\$ 118.60
	Air Duct / sue			\$ 134.60
	Air Flow Sensor X sue			\$ 502.20
	Air Cleaner Bottom Assy X sue			\$ 325.00
	Aircon Condenser / But			\$ 927.50
	Aircon Suction & Liquid Hose + sue			\$ 624.00
	Aircon Discharge Hose / sue			\$ 162.60
	Battery Tray X sue			\$ 52.00
	Wiper Panel Top Garnish X sue			\$ 222.60
	Wiper Container X sue			\$ 61.90
	Wiper Container Motor X sue			\$ 75.00
	Inter Cooler X sue			\$ 1,032.50
	Inter Cooler Mounting (2 PCS) X sue			\$ 25.90
	Hose B To Inter Cooler X sue			\$ 229.70
	Hose C To Inter Cooler Inlet X sue			\$ 294.50
	Pipe To Inter Cooler X sue			\$ 167.05
	Pipe To Inter Cooler Outlet X sue			\$ 244.55
	Actuator - Swirl Control X sue			\$ 814.60

SHC 1989E

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Intake Manifold Assy <i>X</i> <i>me</i>			\$ 1,141.10	
	<b>SUB TOTAL</b>			<b>\$ 19,310.65</b>	
	<b>LESS 20%</b>			<b>\$ 3,862.13</b>	
	<b>DISCOUNTED TOTAL</b>			<b>\$ 15,448.52</b>	
	Front Fender Advertisement Logo (LH) <i>me</i>			\$ 100.00	Nett /
	New Battery <i>X</i> <i>me</i>			\$ 207.00	Nett
				<b>\$ 307.00</b>	
	<b>Labour Charge</b>				
	Panel Beating			<del>\$ 1,000.00</del> <i>800</i>	
	Spray Painting Charge			<del>\$ 1,000.00</del> <i>800</i>	
	Wiring Charge			<del>\$ 50.00</del> <i>20</i>	
	Tuff Kote			<del>\$ 100.00</del> <i>50</i>	
	Towing Charge			<del>\$ 50.00</del> <i>X</i>	
	Remove/Refix Aircon & Refill Gas			<del>\$ 150.00</del> <i>60</i>	
	Remove/Refix Dashboard			\$ 450.00	<i>X</i>
	Remove/Refix Fuse Box			\$ 180.00	<i>X</i>
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00	<i>X</i>
	<b>TOTAL LABOUR</b>			<b>\$ 3,460.00</b>	

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper X Repair			\$ 553.00
	Rear Bumper Reinforcement X sue			\$ 428.40
	Rear Bumper Reinforcement Bracket (LH/RH) X sue	S	80.30	\$ 160.60
	Rear Bumper Clip 10 pcs X sue			\$ 22.00
	Rear Bumper Bracket X sue	S	35.60	\$ 71.20
	Rear Bumper Sponge X sue			\$ 118.40
	Rear Bumper Under Cover X sue			\$ 228.00
	<b>SUB TOTAL</b>			<b>\$ 1,581.60</b>
	<b>LESS 20%</b>			<b>\$ 316.32</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 1,265.28</b>
	Rear Bumper Advertisement Logo - acc			\$ 50.00
	Rear Bumper Rubber Mat X 2m			\$ 50.00
				<b>\$ 100.00</b>
	<b>Labour Charge</b>			100
	Panel Beating			\$ <del>250.00</del>
	Spray Painting Charge			\$ <del>250.00</del> 200
	Wiring Charge			\$ <del>50.00</del> X m
	<b>TOTAL LABOUR</b>			<b>\$ 650.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 21,230.80</b>
	Kahin (C/M)			
	M 15/10/19 1515h			
	6 Days.			
	PIP			
	Before Paint photo			
			21,465.84	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.



**COMFORTDELGRO  
ENGINEERING**

Our Job Ref No 305341465  
Date 21.10.19

ComfortDelGro Engineering Pte Ltd  
59 Luyang Drive Singapore 508969  
Fax: 6546 8156



**FINALIZATION FORM**

To LKK  
Attn : Mr KALVIN ANG  
Vehicle Reg No. SHC1989E CTPL

Fax :

12.10.19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC SJR7184T
  2. The finalized amount shall be:
    - (a) Spare Parts after List discount \$9,182.88
    - (b) Labour Charges \$2,220.00
    - Total for Part-By-Part Repair Cost** \$11,402.88
    - (c.) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: 20%  
**Final Lumpsum Repair cost** \_\_\_\_\_
  3. Estimated normal period for repairs: 6 working days.
  4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
  5. Thank you for your assistance. We confirm the estimates and finalized amount
- Signature :  Signature :   
Name : LIM KWOK ENG Name : Calvin  
Tel : 62148316 Date : 22/10/19  
Fax : 65468156

**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO  
ENGINEERING

VEHICLE NO. : SHC1989E

MODEL I-40

JOB NO 305341465

TYPE OF CASE : TP-SJR7184T

SURVEY BY : LKE/Calvin Amp

DATE : 15/10/19

## SUPPLEMENTARY OF PARTS AND LABOUR COSTS

[illegible]

- 10%
- 10%
- 10%
- 10%
- 10%

COMFORTDELGRO ENGINEERING PTE LTD  
REPAIR ESTIMATE

Date: 21.10.2019  
Time: 19:14:14  
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305341465  
REGN NO : SHC1989E  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 20.12.2017  
DATE/TIME IN : 12.10.2019 09:00  
ACCIDENT DATE : 12.10.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0572-A	I40VC PANEL ASSY-HOOD+	1 L	2,265.90	20.00	1,812.72
0002	04-01-0103-0805-G	I40VC PAD-HOOD INSULATING	1 L	196.50	20.00	157.20
0003	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60
0004	04-01-0101-0110-G	HYUNDAI CLIP-BONNET INSUL	10 L	8.40	20.00	6.72
0005	04-01-0103-0651-G	I40VC HINGE ASSY-BONNET L	1 L	41.00	20.00	32.80
0006	04-01-0103-0652-G	I40VC HINGE ASSY-BONNET R	1 L	41.00	20.00	32.80
0007	04-01-0103-2175-G	I40V3 SYMBOL MARK-H	1 L	39.50	20.00	31.60
0008	04-01-0103-2164-A	I40V3 GRILLE ASSY-RADIATO	1 L	1,110.10	20.00	888.08
0009	04-01-0103-2322-A	I40V3 BUMPER W LIP & FOG	1 L	1,052.20	20.00	841.76
0010	04-01-0103-0779-G	I40VC STRIP	1 L	7.40	20.00	5.92
0011	04-01-0103-0641-G	I40VC CARRIER ASSY-FR END	1 L	907.40	20.00	725.92
0012	04-01-0103-0781-A	I40V2 LAMP ASSY-HEAD LH#	1 L	1,388.00	20.00	1,110.40
0013	04-01-0103-0782-A	I40V2 LAMP ASSY-HEAD RH#	1 L	1,388.00	20.00	1,110.40

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE

Date: 21.10.2019

Time: 19:14:14

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS : COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305341465  
 REGN NO : SHC1989E  
 MILEAGE : 0000000000  
 MAKE : HYUNDAI  
 MODEL : I-40  
 DATE OF REGN : 20.12.2017  
 DATE/TIME IN : 12.10.2019 09:0  
 ACCIDENT DATE : 12.10.2019

## JOB / PARTS DESCRIPTION

## QTY IND UNIT-PRICE DISC% AMOUNT

0014 04-01-0103-0604-G	I40VC LATCH ASSY-HOOD	1 L	36.90	20.00	29.52
0015 04-01-0103-0574-A	I40VC PANEL-FENDER LH+	1 L	566.30	20.00	453.04
0016 02-01-0103-0048-G	I40V2 DUCT-AIR	1 L	134.60	20.00	107.68
0017 01-01-0103-0039-A	I40V2 CONDENSER ASSY-COOL	1 L	927.50	20.00	742.00
0018 16-01-0103-0103-A	I40VC RADIATOR ASSY	1 L	698.30	20.00	558.64
0019 16-01-0103-0118-G	I40VC HOSE-RADIATOR UPR	1 L	36.50	20.00	29.20
0020 16-01-0103-0067-G	I40V2 HOSE-RADIATOR LWR	1 L	36.50	20.00	29.20
0021 02-01-0103-0044-G	I40VC ^-DEVICE ASSY-SWIRL	1 L	208.40	20.00	166.72
0022 20-01-9999-2025-A	PRESTONE ANTIFREEZE COOLA	1 L	8.00	20.00	6.40
0023 01-01-0103-0040-G	I40V2 HOSE-DISCHARGE	1 L	162.60	20.00	130.08
0024 17-01-9999-0007-A	(ALL) HALOGEN BULB 12V55W	4 L	48.00	20.00	38.40
0025 09-01-0103-0092-G	I40VC HORN ASSY-LOW PITCH	1 L	73.80	20.00	59.04

COMFORTDELGRO ENGINEERING PTE LTD  
REPAIR ESTIMATE

Date: 21.10.2019  
Time: 19:14:14  
Page: 3

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305341465  
REGN NO : SHC1989E  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 20.12.2017  
DATE/TIME IN : 12.10.2019 09:0  
ACCIDENT DATE : 12.10.2019

JOB / PARTS DESCRIPTION	QTY	IND	UNIT	PRICE	DISC%	AMOUNT
0026 09-01-0103-0093-G I40VC HORN ASSY-HIGH PITC	1	L		73.80	20.00	59.04

SUB-TOTAL : 9,182.88

JOB NATURE

0000 23-01	TOWING FEE	0.00
0001 20-05	RENEW ADVERTISMENT STICKER-	150.00
0002 L	PANEL BEATING	940.00
0003 23-502	SPRAYPAINT ON AFFECTED AREA	1000.00
0004 17-01	CHECK ALL LIGHTING	20.00
0005 20-00	TUFF COAT ON AFFECTED PARTS.	50.00
0006 L	REMOVE/REFIX AIRCON & REFILL GAS	60.00
SUB-TOTAL :		2,220.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305341465  
REGN NO : SHC1989E  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 20.12.2017  
DATE/TIME IN : 12.10.2019 09:0  
ACCIDENT DATE : 12.10.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 11,402.88

MVA NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO  
SURVEYOR NAME & SIGNATURE  
DATE :


**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No: 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19018210/K1vf3e2			
73 BRAS BASAH ROAD			
#05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			
		Date: 29-10-2019	
		Code: INC4	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SJR 7184T	Veh. Inspected	SHC 1989E
Policy No.	5111690080	Coverage (\$)	0.00
Claim No.	MT/1066735-003	Excess (\$)	0.00
Assign From		Assign Date	15/10/2019
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KMHLB41UMHU100067	Colour	BLUE
Odometer	212391	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	HANKOOK	7 mm
L/H Front Tyre	205/60 R16	HANKOOK	7 mm
R/H Rear Tyre	205/60 R16	HANKOOK	7 mm
L/H Rear Tyre	205/60 R16	HANKOOK	7 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.			
DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	12/10/2019	Inspection Date	15/10/2019
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.			
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 3

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1989E**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	BONNET	BENT	2,265.90	2,265.90
2	BONNET HINGE (LH/RH) @\$41.00	BENT	82.00	82.00
1	BONNET LOCK	JAMMED	36.90	36.90
2	BONNET ABSORBER @\$58.10	SERVICEABLE	116.20	-
1	BONNET INSULATOR	TORN	196.50	196.50
1	BONNET INSULATOR CLIPS	NECESSARY	8.40	8.40
1	RADIATOR GRILLE	CRACKED	1,110.10	1,110.10
1	RADIATOR GRILLE H EMBLEM	CRACKED	39.50	39.50
1	FRONT BUMPER COVER	CRACKED	1,052.20	1,052.20
1	FRONT BUMPER SPONGE	SERVICEABLE	99.20	-
1	FRONT BUMPER REINFORCEMENT	SERVICEABLE	402.10	-
1	FRONT BUMPER LIP	SERVICEABLE	54.90	-
2	FRONT BUMPER BRACKET TOP (LH/RH) @\$22.40	SERVICEABLE	44.80	-
2	FRONT BUMPER BRACKET (LH/RH) @\$24.60	SERVICEABLE	49.20	-
1	HEADLAMP SUPPORT TOP COVER	SERVICEABLE	222.60	-
1	HEADLAMP SUPPORT PANEL ASSY	CRACKED	907.40	907.40
2	HEADLAMP (LH/RH) @\$1388.00	CRACKED	2,776.00	2,776.00
1	RADIATOR	BENT	698.30	698.30
1	RADIATOR FAN BLADE, COWLING, MOTOR ASSY	SERVICEABLE	792.95	-
2	RADIATOR BRACKET (RH/LH) @\$6.50	SERVICEABLE	13.00	-
1	RADIATOR HOSE UPPER	TORN	36.50	36.50
1	RADIATOR HOSE LOWER	TORN	36.50	36.50
1	RADIATOR EXPANSION TANK	SERVICEABLE	28.30	-
2	RADIATOR GUARD @\$20.00	SERVICEABLE	40.00	-
2	HORN UNIT (LH/RH) @\$73.80	CRACKED	147.60	147.60
1	HORN WIRE	SERVICEABLE	156.50	-
1	FRONT FENDER (LH)	BUCKLED	566.30	566.30
1	FRONT FENDER SHIELD (LH)	SERVICEABLE	174.90	-
1	AIR CLEANER ASSY	SERVICEABLE	118.60	-
1	AIR DUCT	CRACKED	134.60	134.60

Report Ref No. NS/INC19018210/K1vf3e2





# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	AIR FLOW SENSOR	SERVICEABLE	502.20	-
1	AIR CLEANER BOTTOM ASSY	SERVICEABLE	325.00	-
1	AIRCON CONDENSER	BENT	927.50	927.50
1	AIRCON SUCTION & LIQUID HOSE	SERVICEABLE	624.00	-
1	AIRCON DISCHARGE HOSE	CRACKED	162.60	162.60
1	BATTERY TRAY	SERVICEABLE	52.00	-
1	WIPER PANEL TOP GARNISH	SERVICEABLE	222.60	-
1	WIPER CONTAINER	SERVICEABLE	61.90	-
1	WIPER CONTAINER MOTOR	SERVICEABLE	75.00	-
1	INTER COOLER	SERVICEABLE	1,032.50	-
2	INTER COOLER MOUNTING	SERVICEABLE	25.90	-
1	HOSE B TO INTER COOLER	SERVICEABLE	229.70	-
1	HOSE C TO INTER COOLER INLET	SERVICEABLE	294.50	-
1	PIPE TO INTER COOLER	SERVICEABLE	167.05	-
1	PIPE TO INTER COOLER OUTLET	SERVICEABLE	244.55	-
1	ACTUATOR - SWIRL CONTROL	SERVICEABLE	814.60	-
1	INTAKE MANIFOLD ASSY	SERVICEABLE	1,141.10	-
1	REAR BUMPER	TO REPAIR SEE LABOUR	553.00	-
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	428.40	-
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @\$80.30	SERVICEABLE	160.60	-
10	REAR BUMPER CLIP	NOT NECESSARY	22.00	-
2	REAR BUMPER BRACKET @\$35.60	SERVICEABLE	71.20	-
1	REAR BUMPER SPONGE	SERVICEABLE	118.40	-
1	REAR BUMPER UNDER COVER	SERVICEABLE	228.00	-
1	RUBBER STRIP (BONNET)	TORN	7.40	7.40
1	SWIRL CONTROL DEVICE ASSY	SHORTED	208.40	208.40
1	PRESTONE ANTIFREEZE COOLANT	NECESSARY	8.00	8.00
4	HALOGEN BULB 12V55W 2 PIN @\$12.00	NECESSARY	48.00	48.00
10	FRONT BUMPER CLIPS @\$2.00	NECESSARY	22.00	22.00
	LESS 20% DISCOUNT		-4,237.21	-2,295.72
			16,948.84	9,182.88

Report Ref No. NS/INC19018210/K1vf3e2



## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT FENDER ADVERTISEMENT LOGO (LH) (SN)	NECESSARY	100.00	100.00
1	NEW BATTERY (SN)	SERVICEABLE	207.00	-
1	REAR BUMPER ADVERTISEMENT LOGO (SN)	NECESSARY	50.00	50.00
1	REAR BUMPER RUBBER MAT (SN)	NOT NECESSARY	50.00	-
			407.00	150.00
	<b><u>LABOUR</u></b>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BUMPER.		1,350.00	940.00
	SPRAY PAINTING CHARGE.		1,250.00	1,000.00
	WIRING CHARGE.		100.00	20.00
	TUFF KOTE.		100.00	50.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE / REFIX AIRCON & REFILL GAS.		150.00	60.00
	REMOVE / REFIX DASHBOARD.	NOT NECESSARY	450.00	-
	REMOVE / REFIX FUSE BOX.	NOT NECESSARY	180.00	-
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.	NOT NECESSARY	480.00	-
			4,110.00	2,070.00
	<b>GRAND TOTAL</b>		<b>21,465.84</b>	<b>11,402.88</b>
<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>				<b>11,402.88</b>

Report Ref No. NS/INC19018210/K1vf3e2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.