

ASS. REC. BY:

REF: CS3/SMD 19018234/Gcf3

Special Instruction:

Survivor: GQ

ASSIGNMENT (Office)

From (Person): Hwang shiang Yi

of SMO

Date/Time: 16.10.19 9.03a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKZ 3714L

Insured: SJU 1297A

at Workshop m/s E M Solution

Tel: 64560226

of 160 soh ming brw #03-18

Policy No: D18MPV01015701

Claim No: CMD 1904868

Sum Insured:

Excess:

Make of Veh: (Client's Record)

D.O.A. 14.10.2019

CA / REV / REP. / REV 24 HRS

Date/Time: 16.10.19 9.21a.m

Person Contacted:

Bernard

H.O.P. Endorsement:

Vehicle IN/OUT

Date/Time Action/Instruction (X) Estimate

SJU 1297A: X

SKZ 3714L: X

Dismantle: 17/10/2019

After repair: 21/10/2019

meimn

ISS REC BY: PRs REP: SMD

ASSIGNMENT

From: _____ Date: 16.10.2019

Veh No: SKZ 3714L Yr Regn: 20 Jan 2016

Estimated Cost: _____

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD: TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or _____

To Inspect Vehicle No: SKZ 3714L

Make: Honda Vezel C.C: 1496

at Workshop m/s- EM Solution

Colour: Blue A/C: Insured / Std / NI / NA

of 160 Sin Ming Drive #03-1B

Sp. Reading: 85262 T/Radio: Insured / Std / NI / NA

Insured: _____

Eng/No: _____

Policy No: _____

C/No: RU11106749

Claims No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: _____ Excess: _____

Steering: In order / Jammed / Leaked / Burnt or


(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh: _____

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)



Remark: The veh had commenced its repair at the time of inspection.

Tyre Size: F: 215/60 R16
R: 11

Bal. or Market Value: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

IDAC Accident Rpt: _____ Consistent? : Yes or No

TOYO / YOKO or Pirelli PELLAS.

GIA / PR Seen: _____ Consistent? : Yes or No

Front R/Bal. 6 mm

Est. Repairs: 8 days Res.: Yes or No

Rear R/Bal. 6 mm

Lum Sum: _____ % 3 Val: Yes or No

L/Bal. 6 mm

CA / REV / REP. / 24 HRS my'

D.O.A. _____ D.O.I. 16-10-19

Date: _____ Person Contacted: _____

Survey held at w/s 11:30

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or *.

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>\$7000 - \$8000</u>

RECEIVED 24 OCT 2019

Date/Time, File Pass to? : Preli. Report

Days Of Repair: 8

1) : Final Report

Resurvey No. of Trip: 2

Date/Time, File Return to?

Survey Fee:	
Transportation:	
\$ + RS \$	
Photos	
Others	
TOTAL	

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Wheel end (% _____)

Report Format: PRs

Lump Sum / T.B. (if)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Oct 2019		16 Oct 2019 09:03 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [\[Created by insurer\]](#)

Insured:	TAN LENG YEN JACLYN, ID: S6907638F		
Main Claimant:	NG HUI BENG, ID: S7912804Z		
Vehicle Reg. No.:	SKZ3714L	Date of Loss:	14/10/2019 19:00 - :59
Claim Type:	TP / CMTD1904868	Policy/Cover Note No.:	D18MTPV01015701 (Comprehensive)
Vehicle Reg. No. (Insured):	SJU1297A	Policy No. (Claimant):	D19MTPV01000398
		Excess:	
Repairer:	E M Solution Pte Ltd (HQ) 160 Sin Ming Drive,, #03-18, Sin Ming Autocity, 575722 Sin Ming - Tel: 64560226		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]		
Claimant's Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 25/10/2019]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/10/2019 13:20
Date Of Accident	14/10/2019 19:05
Exact Location Of Accident	LORNIE HIGHWAY EXIT PIE TOWARDS TUAS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKZ3714L
Insured/Policyholder	
Name Of Registered Owner	NG HUI BENG
NRIC No	S7912804Z
Email Address	MICHEAL.THE.BENG@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97876451
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL 1.5X A
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE.
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D19MTPV01000398
Cover Note Number	20/01/2019 TO 19/01/2020

Driver

Name of Driver	NG HUI BENG
NRIC No	S7912804Z
Date Of Birth	12/05/1979
Occupation	INDOOR
Date Of Driving Pass	19/07/2003
Driving Experience	16 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97876451
Fax Number	
Contact Number	OFFICE-NOPHONE
Email Address	MICHEAL.THE.BENG@GMAIL.COM

Address	BLK 663A JURONG WEST 65 #05-285
Postcode	641663
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJU1297A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	DAVID SEAN TAN JIA YI
NRIC/Passport Number	
Contact Number	64560226
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

Sompo
Vehicle: SKZ
3714L

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

15/10/19

Driver's Signature
(if driver is not the policyholder)
Date & Time:




Reporting Centre Personnel's Signature
Name: N...
NRIC/FIN No.: 15/10/19

Sketch Plan Pg. 2

SKETCH PLAN

Date: 14/10/19 Time: 07:04 PM Location: Lornie Highway exit PIE towards Tuas
 My Vehicle A: SKZ 3714 L Vehicle B: SJU 1297 A Vehicle C/Others: /



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 14/10/19 at about 7:04 pm I was travelling on the straight road of Lornie Highway Exit PIE towards Tuas. The traffic was slow moving, I stopped my vehicle - SKZ 3714 L while the front vehicle also stopped. Out of a sudden, a vehicle - SJU 1297 A from behind collided onto the rear of my vehicle. I reported this incident for T/party claim against SJU 1297 A for damages.

() Claim OD / TP at Ah Lim Motor Claim OD / TP at other workshop () Reporting Only

Remarks: Please forward a copy of this report to **EMV SOLUTION PTE LTD**

My workshop : 160 Sin Ming Drive
 Email Address : #03-18/19 Sin Ming Autocity
 & Myself : Singapore 575722
 Email Address : Tel: 6456 0226 Fax: 6458 4500
 Email: emautosolution@singnet.com.sg

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information.

DECLARATION
 I/We declare the foregoing particulars are true in every respect. Vehicle SKZ 3714 L

Policyholder's Signature: [Signature] Date & Time: 15/10/2019
 Driver's Signature (if driver is not the policyholder): [Signature] Date & Time: 15/10/2019
 Witnessed by Reporting Personnel: [Signature] Meili 15/10/2019



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	804Z
Vehicle Details	
Vehicle No.:	SKZ3714L
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Oct 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X A
Primary Colour:	Blue
Manufacturing Year:	2015
Engine No.:	L15B4026752
Chassis No.:	RU11106749
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$19,508.00
Original Registration Date:	20 Jan 2016
First Registration Date:	20 Jan 2016
Transfer Count:	0
Actual ARF Paid:	\$9,508.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Jan 2026
PARF Rebate Amount:	\$7,131.00
Intended COE Rebate Details	
COE Expiry Date:	19 Jan 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$54,301.00
COE Rebate Amount:	\$33,981.00
Total Rebate Amount:	\$41,112.00

The information contained herein is correct as at 16 Oct 2019

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Oct 2019		16 Oct 2019 09:03 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TAN LENG YEN JACLYN , ID: S6907638F								
Main Claimant:	NG HUI BENG , ID: S7912804Z								
Vehicle Reg. No.:	SKZ3714L	Date of Loss:	14/10/2019 19:00 - :59 [44 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / CMTD1904868	Policy/Cover Note No.:	D18MTPV01015701 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJU1297A	Policy No. (Claimant):	D19MTPV01000398						
		Excess:							
Repairer:	E M Solution Pte Ltd (HQ) 160 Sin Ming Drive,, #03-18, Sin Ming Autocity, 575722 Sin Ming - Tel: 64560226								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]								
Claimant's Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 25/10/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKZ3714L (CMTD1904868)**
[SJU1297A]
TP
NG HUI BENG
Oct 14 2019 7:00PM
[TAN LENG YEN JACLYN]
E M Solution Pte Ltd

Upload Documents Upload Photos Compose New Letter		View <input type="button" value="View in Browser"/>
		1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
Assessment Reports		
No	Finalized On	Ah Lim Motor Company (Sin Ming)
1	15/10/19 14:01	Accident Statement
		3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
Photos/Images		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)
1	17/10/19 08:49	General View
2	17/10/19 08:49	General View
3	17/10/19 08:49	General View
4	17/10/19 08:49	General View
5	17/10/19 08:49	General View
6	17/10/19 08:49	General View
7	17/10/19 08:49	General View
8	17/10/19 08:49	General View
9	17/10/19 08:49	General View
10	17/10/19 08:49	General View
11	17/10/19 08:49	General View
12	17/10/19 08:49	General View
13	17/10/19 08:49	General View
14	17/10/19 08:49	General View
15	17/10/19 08:49	General View
16	17/10/19 08:49	General View
17	17/10/19 08:49	General View
18	17/10/19 08:49	General View
19	17/10/19 08:49	General View
20	17/10/19 08:49	General View
21	17/10/19 08:49	General View
22	17/10/19 08:49	General View
23	17/10/19 08:49	General View
24	17/10/19 08:49	General View
25	17/10/19 08:49	General View
26	17/10/19 08:49	General View
27	17/10/19 08:49	General View
28	17/10/19 08:49	General View
29	17/10/19 08:49	General View
30	17/10/19 08:49	General View
31	17/10/19 08:49	General View
32	17/10/19 08:49	General View
33	17/10/19 08:49	General View
34	17/10/19 08:49	General View
35	17/10/19 08:49	General View
36	17/10/19 08:49	General View
37	17/10/19 08:49	General View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (Sin Ming)	Thumbnail	Print
38	17/10/19 08:49	General View	 Load JPG	<input checked="" type="checkbox"/>
39	17/10/19 08:49	General View	 Load JPG	<input checked="" type="checkbox"/>
40	17/10/19 08:49	General View	 Load JPG	<input checked="" type="checkbox"/>
41	17/10/19 08:49	General View	 Load JPG	<input checked="" type="checkbox"/>
42	17/10/19 08:49	General View	 Load JPG	<input checked="" type="checkbox"/>
43	17/10/19 08:49	General View	 Load JPG	<input checked="" type="checkbox"/>
44	17/10/19 08:49	General View	 Load JPG	<input checked="" type="checkbox"/>
45	17/10/19 08:49	General View	 Load JPG	<input checked="" type="checkbox"/>
46	17/10/19 08:49	General View	 Load JPG	<input checked="" type="checkbox"/>
47	17/10/19 08:49	General View	 Load JPG	<input checked="" type="checkbox"/>
48	17/10/19 08:49	General View	 Load JPG	<input checked="" type="checkbox"/>
49	17/10/19 08:50	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
50	17/10/19 08:50	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
51	17/10/19 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	17/10/19 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	17/10/19 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	17/10/19 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	17/10/19 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	17/10/19 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
57	17/10/19 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
58	17/10/19 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
59	17/10/19 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
60	17/10/19 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
61	17/10/19 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
62	17/10/19 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
63	17/10/19 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
64	17/10/19 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
65	17/10/19 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
66	17/10/19 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
67	17/10/19 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
68	17/10/19 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
69	17/10/19 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
70	17/10/19 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
71	17/10/19 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
72	17/10/19 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
73	17/10/19 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
74	17/10/19 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
75	17/10/19 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
76	17/10/19 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
77	17/10/19 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
78	17/10/19 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
79	17/10/19 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
80	17/10/19 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
81	17/10/19 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
82	17/10/19 15:00	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
83	21/10/19 17:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
84	21/10/19 17:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
85	21/10/19 17:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
86	21/10/19 17:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
87	21/10/19 17:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
88	21/10/19 17:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
89	21/10/19 17:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
90	21/10/19 17:34	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (Sin Ming)	Thumbnail	Print
91	21/10/19 17:34	After Repair Photo		<input checked="" type="checkbox"/>
92	21/10/19 17:34	After Repair Photo		<input checked="" type="checkbox"/>
93	21/10/19 17:34	After Repair Photo		<input checked="" type="checkbox"/>
94	21/10/19 17:34	After Repair Photo		<input checked="" type="checkbox"/>
95	21/10/19 17:34	After Repair Photo		<input checked="" type="checkbox"/>
96	21/10/19 17:34	After Repair Photo		<input checked="" type="checkbox"/>
97	21/10/19 17:34	After Repair Photo		<input checked="" type="checkbox"/>
98	21/10/19 17:34	After Repair Photo		<input checked="" type="checkbox"/>
99	21/10/19 17:34	After Repair Photo		<input checked="" type="checkbox"/>
100	21/10/19 17:34	After Repair Photo		<input checked="" type="checkbox"/>
101	21/10/19 17:34	After Repair Photo		<input checked="" type="checkbox"/>
102	21/10/19 17:34	After Repair Photo		<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	15/10/19 16:39	PRI - ACK		<input type="checkbox"/>
2	15/10/19 17:13	PRI - No Consensus(pending for address)		<input type="checkbox"/>
3	16/10/19 09:03	PRI - LKK		<input type="checkbox"/>

Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (Sin Ming)	Thumbnail	Print
1	15/10/19 14:01	Accident Statement		<input type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (Sin Ming)	Thumbnail	Print
1	15/10/19 13:56	Accident Photo		<input checked="" type="checkbox"/>
2	15/10/19 13:56	Accident Photo		<input checked="" type="checkbox"/>
3	15/10/19 13:56	Accident Photo		<input checked="" type="checkbox"/>
4	15/10/19 13:56	Accident Photo		<input checked="" type="checkbox"/>
5	15/10/19 13:56	Accident Photo		<input checked="" type="checkbox"/>
6	15/10/19 13:56	Accident Photo		<input checked="" type="checkbox"/>
7	15/10/19 13:56	Accident Photo		<input checked="" type="checkbox"/>
8	15/10/19 13:56	Accident Photo		<input checked="" type="checkbox"/>
9	15/10/19 13:56	Accident Photo		<input checked="" type="checkbox"/>
10	15/10/19 13:56	Accident Photo		<input checked="" type="checkbox"/>
11	15/10/19 13:56	Accident Photo		<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (Sin Ming)	Thumbnail	Print
1	15/10/19 13:49	Sketch Plan		<input type="checkbox"/>
2	15/10/19 13:50	CI - DRIVER'S PARTICULAR		<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	<input type="button" value="Reset"/>	<input type="button" value="Save"/>	<input type="button" value="Print"/>
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer
 Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO19018234/GCF3S2
Date: 24/10/2019

REFERENCE

Handling Insurer: Sompo Insurance Singapore Pte. Ltd. Policy No: D18MTPV01015701
Claimant Vehicle No : SKZ3714L **Insured Vehicle No :** SJU1297A
 Date of Loss: 14/10/2019 Nature of Claim: TP Claim No: CMTD1904868

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKZ3714L**
 Make & Model: HONDA VEZEL, 1.5 (A) Engine No: L15B4026752
 Reg. Date: 20/01/2016 (Man. Year: 2015) Chassis No: RU11106749
 Colour: Blue Odometer: 85262 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: PETLAS 6 mm Rear Left Side: PETLAS 6 mm
 Front Right Side: PETLAS 6 mm Rear Right Side: PETLAS 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 16/10/2019
 Date Inspected: 16/10/2019 Inspected At: 160 Sin Ming Drive,, #03-18, Sin Ming Autocity
 Singapore 575722
 Repairer: E M Solution Pte Ltd
 Estimated Period of Repair: 8.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000.00 - \$8,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 24 Oct 2019)
Parts: M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKZ3714L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >