

<<

Service Request Details

Claim

S9M023O9

Reference

CS3/ASM19018235/Hcf3s2 

Loss Date

October 14, 2019

Report Date

Oct 15, 2019 12:00:00 AM

Request Date

October 16, 2019

Due Date

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Wait for: Approve invoice

Add Invoice

Vehicle Information

Incident Vehicle Registration #

SMP2050D

Make

TPVD TOYOTA

Model

SIENTA HYBRID 1.5X CVT

Service Address

Primary Contact/Insured

SIM KWAN TIONG DAMIEN

296 PUNGGOL CENTRAL, #11-497, 820296, Singapore

damienskt@gmail.com

Claim Handler

NG Stacey

6568804351

stacey.ng@axa.com.sg

Additional Instructions

Messages	Invoices	History	Documents	Assessment	Metrics	Notes
Document Type Document SubType + Upload Documents						
NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED		
 LKKInvoice1[1].pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	November 11, 2019		
 LKKPreRepairInspection[1].pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	November 11, 2019		
 Photo After Spray.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	November 5, 2019		
 Inspection Photographs.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	November 5, 2019		
 Photo of damaged parts.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	November 5, 2019		
 TP-Immediate Advice.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	November 5, 2019		

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 SMP2050D - TP GIA REPORT.PDF	Reports & Statement	GIA Report	NG Stacey	October 15, 2019
 FBP3629J INS GIA.PDF	Reports & Statement	GIA Report	DHIWAR Namrata	October 15, 2019
 TP PRI EMAIL FROM WORKSHOP.msg	Letters and Correspondence	Third Party	DHIWAR Namrata	October 15, 2019
 SMP2050D TP GIA.PDF	Reports & Statement	GIA Report	DHIWAR Namrata	October 15, 2019
 TP PRI EMAIL FROM WORKSHOP.pdf	Letters and Correspondence	Third Party	DHIWAR Namrata	October 15, 2019