

ASS. REC. BY:

REF: LPC

589K

ASSIGNMENT

From:

Date:

23/10/19

Estimated Cost:

OD ☒ TP / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLL 6447A

at Workshop m/s

Borneo Motor

of

Spandan Crescent

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

2pm - 2:30pm
Francis

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{1up}

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLL 6447A

Yr Regn:

2017 / MAR

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA PREVIA AERAS 2.4 c.c 2362

Colour

WHITE

A/C: Insured / Std / NI / NA

Sp. Reading

115054

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTEG D56M 307146485

Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ STD A/Rim or

Tyre Size:

F: 225/50R18

R:

42

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

11/10/19

D.O.I.

23/10/19

Survey held at

BORNEO MOTOR

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Report Format :

Lump Sum / L.B.F (\$