

ASS. REC. BY:

REF: CS/FCI 19018292/USD302

Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Jason Tan

of

FCIDate/Time: 12:44pm @ 16/10/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBJ 7525E

Insured:

SH 6229B

at Workshop m/s

Precise Auto

Tel:

67457367

of

1 Icaiki Bulait Ave 6 # 02-34

Policy No:

Claim No:

D19006593MFSH

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A.

14/10/2009

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 12:56pm @ 16/10/19

Person Contacted:

MarcusVehicle IN/OUT

Date/Time	Action/Instruction
	<u>Johny</u> ✓
	<u>SH 6229B: NS/INC 19018208/K2vf3 DOA: 14/10/2019</u>
	<u>GBJ 7525E: NS/INC 19018208/K2vf3 DOA: 14/10/2019</u>
<u>17/10/19</u>	<u>@ 17:30 pm reset pending estimate from repair via email.</u>

08/11/19 wef

ASS. REC. BY: Marcus

REF:

Fur

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TR / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Date / Time

Action / Instruction

Veh No: 63J 7528E Yr Regn: 8.19

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Modi: NH / S/Rim / STD A/Rim or

Tyre Size:

R:

BS / DUN / EXNOVA / ST / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 13 NOV 2019

Date/Time, File Pass to?

1) 13/11/19

Date/Time, File Return to?

2)

☐

: Prel. Report

☒

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$ 2,100/- U/S)

130
50
50
70
300

MOTOR SURVEY ASSIGNMENT

Date	15-10-2019	Our Ref No. D19006593MFSH
Accident Date	14-10-2019	Claim Type. Third Party
Insured Vehicle	SH6229B	Third Party Vehicle. GBJ7525E
Survey Location	NO. 1 KAKI BUKIT AVE 6 #02-34/36	
Contact Person.	ARINE	
Contact No.	67457367/ 0	Fax No. 68413390
Survey Type	WITHOUT PREJUDICE: LIABILITY UNCLEAR: WE AWAIT FOR OUR INSURED VIDEO FOOTAGE	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PRECISE AUTO SERVICE	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JASON TEA CHEE KIAT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Thursday, 17 October 2019 5:30 pm
To: 'Jason Tea'; 'CWS Motor Claims'
Cc: SUR; assignments
Subject: RE: SURVEY ASSESSMENT - D19006593MFSH/1

Dear Jason,

Please be informed that we have inspected the vehicle GBJ 7525E on 16/10/2019.

We are pending estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Wednesday, 16 October 2019 12:57 pm
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Jason Tea' <JasonTea@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19006593MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



18% off now, promo code: CAR18

[Get a quote](#)

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 5 Years Renewal Coe Toyota Altis 1.6A



2.88% P.A, \$100 Down,\$0
Admin, Mthly Fm \$468, 2 Years
Warranty Engine
GV Credit Pte Ltd StarAd


[Browse by Category](#)
[« Back \(1 2 3 4 \) Next »](#)
[Sort by Date Posted](#)
[20 results/page](#)

79 vehicles

NV200

[Advanced Search](#)
[Submit](#)

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	NV200		Any	Any	2019	Any	Any	Any	Available
	Nissan	NV200 1.6A	\$46,800	\$4,950 /yr	27-Mar-2019	1,597 cc	2,349 km	Van	Available
Fuel Type: Petrol Monthly \$598 Only! Super Affordable. Still Under Warranty And Low Mileage. In House And Full Loan Available! High Trade-In. Call Us F... ABWIN Bus Pte Ltd Posted: 16-Oct-2019 Tags: 2019 Nissan NV200, 2019 nissan nv200, Nissan NV200, nissan nv200, Nissan, NV200, nv200, Used Nissan									
	Nissan	NV200 1.6A	\$49,888	\$5,160 /yr	13-Jun-2019	1,597 cc	-	Van	Available
Fuel Type: Petrol Ready Stock! Auto Transmission. Smooth Driving Experience And Good Performance. Call Fast Net Link Partners Pte Ltd Posted: 16-Oct-2019 Tags: 2019 Nissan NV200, 2019 nissan nv200, Nissan NV200, nissan nv200, Nissan, NV200, nv200, Used Nissan									
	Nissan	NV200 1.6A	\$51,888	\$5,250 /yr	03-Sep-2019	1,597 cc	-	Van	Available
Fuel Type: Petrol Warranty 3+2 Years / 100,000km. Cheapest In Town Now! Ready Stock! Loan Up To 100% With 7 Years Installment Plan. Free Front C... SG Motor Link Pte Ltd Posted: 16-Oct-2019 Tags: 2019 Nissan NV200, 2019 nissan nv200, Nissan NV200, nissan nv200, Nissan, NV200, nv200, Used Nissan									
	Nissan	NV200 1.5M	\$60,800	\$6,320 /yr	31-May-2019	1,461 cc	-	Van	Available
Fuel Type: Diesel 5 Years Warranty! High Loan Options Available! Free Warranty And Servicing! Inclusive Of Everything! No Gimmicks! No Top Ups! No Ad... Net Link Partners Pte Ltd Posted: 16-Oct-2019 Tags: 2019 Nissan NV200, 2019 nissan nv200, Nissan NV200, nissan nv200, Nissan, NV200, nv200, Used Nissan									
	Nissan e-NV200 European electric tour The all-electric Nissan e-NV200 will be going on a 10,000km, 35-day European electric tour to promote electromobility to a younger audience. Read this article								
	Nissan	NV200 1.5M	\$59,800	\$6,080 /yr	15-Aug-2019	1,461 cc	15 km	Van	Available
Fuel Type: Diesel FREE 10X SERVICING, Comes With 5Yrs/100,000km Warranty. New Unit Offer! First Owner! With Steering Wheel Control And Cabin Part... Car (S) Pte Ltd Posted: 15-Oct-2019 Tags: 2019 Nissan NV200, 2019 nissan nv200, Nissan NV200, nissan nv200, Nissan, NV200, nv200, Used Nissan									
	Nissan	NV200 1.6A	\$50,988	\$5,150 /yr	11-Sep-2019	1,597 cc	-	Van	Available
Fuel Type: Petrol Popular Mid Size Van And Is Your Best Business Partner, Loan Up To 100%, High Trade-In Value For Your Old Vehicle. Comes With 5 Ye... ABWIN Bus Pte Ltd Posted: 15-Oct-2019 Compare									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Business
Owner ID:	800W

Vehicle Details

Vehicle No.:	GBJ7525E
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Oct 2019
Vehicle Make:	NISSAN
Vehicle Model:	NV200 1.5 MT
Primary Colour:	Silver
Manufacturing Year:	2019
Engine No.:	K9KE628D665260
Chassis No.:	VSKYBAM20Z0177775
Maximum Power Output:	-
Open Market Value:	\$20,885.00
Original Registration Date:	05 Aug 2019
First Registration Date:	05 Aug 2019
Transfer Count:	0
Actual ARF Paid:	\$1,045.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	04 Aug 2029
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$21,544.00
COE Rebate Amount:	\$21,115.00
Total Rebate Amount:	\$21,115.00

The information contained herein is correct as at 16 Oct 2019

OK

PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-33/34/36 SINGAPORE 417883
 TEL : 67457367 FAX : 68413390
 CO. REG. NO. : 35766600C GST REG. NO. : 35766600C

Not Allowed
 L/S \$2100
 14/10/19 16/10/19

08-11-2019

Date Of Accident : 14-10-19

OUR REF : GBJ 7525E/T/19

Wellcome Motor Agenices
 68 Kaki Bukit Ave 6
 #02-02 ARK @ KB
 Singapore 417896

• To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party is on a "Without Prejudice" basis
 • No illiquid communication(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
 Date of report: 14-10-19
 Signature: _____
 Date: _____

ESTIMATE BILL ON VEH. NO. : GBJ 7525E
MODEL : NISSAN NV200
CHASSIS NO : VSKYBAM20Z017775

LIST ITEM

Front Bumper Fascia

Cur 548.80

548.80

Less Discount 30%: 164.64

384.16

NETT ITEM

Front Bumper Side Retainer LH

Cur 20.90

Front Bumper Clips

30

10pcs @ 4.40

Cur 44.00

Head Lamp LH

Cur 618.10

Head Lmap Lower Garnish

Cur 329.30X

Front Fender LH

Cur 504.70

Front Fender Splash Shield

Cur 138.90

Front Fender Splash Shield Clips

24

8pcs @ 4.40

Cur 35.20

Front Wheel Hup Cap

Cur 100.00

1436.60
 1292.54

1,791.10

Less Discount 10%: 179.11

1,611.99

LABOUR CHARGE

To check wiring system

20 60.00

To check & adjust computer wheel alignment

60 150.00

To respray affected areas

480 650.00

To renew damaged parts, straighten & repair front support panel, front LH wheel housing panel & aligned all parts

400 650.00

Total: 3,506.15

GST 7%: 245.43

Amount Due: 3,751.58

2637.1
 2109.68



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19018292/Usd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 14-11-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 6229B	Veh. Inspected	GBJ 7525E	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19006593MFSH	Excess (\$)	0.00	
Assign From	JASON TEA	Assign Date	16/10/2019	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN NV200 (M)	c.c	1461	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	VSKYBAM20Z0177775	Colour	SILVER	
Odometer	1615	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	175/70 R14	GOODYEAR	6 mm	
L/H Front Tyre	175/70 R14	GOODYEAR	6 mm	
R/H Rear Tyre	175/70 R14	GOODYEAR	6 mm	
L/H Rear Tyre	175/70 R14	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/10/2019	Inspection Date	16/10/2019	
Survey held at	PRECISE AUTO SERVICE NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBJ 7525E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER FASCIA	CUT	548.80	548.80
	LESS 30% DISCOUNT		-164.64	-164.64
			384.16	384.16
NETT ITEMS				
1	FRONT BUMPER SIDE RETAINER LH (N)	BENT	20.90	20.90
10	FRONT BUMPER CLIPS @\$4.40 (N)	NECESSARY	44.00	30.00
1	HEAD LAMP LH (N)	CRACKED	618.10	618.10
1	HEAD LAMP LOWER GARNISH (N)	TO REPAIR SEE LABOUR	329.30	-
1	FRONT FENDER LH (N)	DENTED / BENT	504.70	504.70
1	FRONT FENDER SPLASH SHIELD (N)	TORN	138.90	138.90
8	FRONT FENDER SPLASH SHIELD CLIPS @\$4.40 (N)	NECESSARY	35.20	24.00
1	FRONT WHEEL HUP CAP (N)	CUT	100.00	100.00
	LESS 10% DISCOUNT		-179.11	-143.66
			1,611.99	1,292.94
LABOUR				
	TO CHECK WIRING SYSTEM.		60.00	20.00
	TO CHECK & ADJUST COMPUTER WHEEL ALIGNMENT.		150.00	60.00
	TO RESPRAY AFFECTED AREAS.		650.00	480.00
	TO RENEW DAMAGED PARTS,STRAIGHTEN & REPAIR FRONT SUPPORT PANEL,FRONT LH WHEEL HOUSING PANEL & ALIGNED ALL PARTS.INCLUSIVE OF THE REPAIR OF HEAD LAMP LOWER GARNISH.		650.00	400.00
			1,510.00	960.00
GRAND TOTAL			3,506.15	2,637.10
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,100.00

Report Ref No. CS/FC119018292/Usd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.