



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:RICHARD ANG

Ref: CC4/ASM19018321/Ugs3q2
Date: 26/08/2021
Code: ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 100D	Veh. Inspected	SKR 3120S
Policy No.	VFX/P1680520	Coverage (\$)	0.00
Claim No.	S9M023PY	Excess (\$)	0.00
Assign From		Assign Date	17/10/2019

2. Vehicle Particulars & Condition

Make & Model	NISSAN QASHQAI (A)	c.c	1197
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	SJNFEAJ11U1275532	Colour	BROWN
Odometer	54392 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R17	CONTINENTAL	6 mm
L/H Front Tyre	215/60 R17	CONTINENTAL	6 mm
R/H Rear Tyre	215/60 R17	CONTINENTAL	6 mm
L/H Rear Tyre	215/60 R17	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/10/2019	Inspection Date	17/10/2019
Survey held at	Blk 15 Kaki Bukit Road 4, #01-53, S 417808		
Repairer	ZOOM AUTOWERKS PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**