

2000000

ASS. REC. BY:

REF: CS/CTI 19018325/E y f 3/2

Special Instruction:

Surveyor: Steve ASSIGNMENT (Office)

From (Person): Juan Tchu Hui Ping of CTL Date/Time: 17.10.19 11:42 AM

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJL 6087D Insured: XD 9594M

at Workshop no: Tech Cheon Automotive Tel: 96713577

of 60 Jalan Lam Huat #05-45

Policy No: DMCVSIN19307219000 Claim No: SVM19D 204892002

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 15 10 2019  
(Client's Record)

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 17 10 19 11:51 a.m Person Contacted: Mr Wong Vehicle IN / OUT

Date/Time:	Action/Instruction (✓) Estimate
	SJL 6087D - CC L/MS 150 9500 / UV / m3y D.O.A. - 21/03/2019
	XD 9594M - X

Nalam

Birryur Steve

REF:

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OO / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SJL 60870 Yr Regn: 4/12/08  
 Type: M.Cdr / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or  
 Make: Honda Fit c.c. 1339  
 Colour: White AC: Insured / Std / NI / NA  
 Sp. Reading: 183334 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: GE 61093149  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Mod: NII / S/Rim / STD A/Rim or  
 Tyre Size: F: 175/65R15  
 R: \_\_\_\_\_  
 BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal. 5 mm R/Bal. 5 mm  
 L/Bal. 5 mm L/Bal. 5 mm  
 D.O.A. 15/10/19 D.O.I. 17/10/19  
 Survey held at Tech Choon  
 Des. of Damages: Frt / Rear / O/S / NIS / UIC / Rooftop or

CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MV - 23000
	PV - 11380
	NV - 11620
	Final report \$6600, 8 days (Mr Veng) (Red \$5957-50, 47)

RECEIVED 14 NOV 2019

Date/Time, File Pass to?  : Proll. Report

Days Of Repair: 8

1)  : Final Report

Resurvey No. of Trip: 2

Date/Time, File Return to?

2) 13/11/19 Typist

Add Fee:  : Site Insp (\$

: Interview (\$

: Tech Invs (\$

: Weekend (\$

Survey Fee: 220

Transportation: \_\_\_\_\_

\_\_\_\_\_ \$ + RS. \_\_\_\_\_ \$

Phone

Others

Report Format :

Lump Sum I.B.I: (\$ 6600)

TOTAL

220

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Oct 2019		17 Oct 2019 11:42 Assign				<b>New Assignment</b> Cancel Case

  

Main	Reference	Claim Details	Documents	Show All																				
<b>CLAIM SUBFOLDER DETAILS</b>				[Created by insurer]																				
Insured:																								
Main Claimant:	<b>CHEONG KAI LENG</b>																							
Vehicle Reg. No.:	<b>SJL6087D</b>	Date of Loss:	15/10/2019 08:00 - :59																					
Claim Type:	<b>TP / SNM19D204892C02</b>	Policy/Cover Note No.:	DMCVSN19307219000																					
Vehicle Reg. No. (Insured):	<b>XD9594M</b>	Policy No. (Claimant):																						
		Excess:	S\$0.00																					
Repairer:	<b>Tech Choon Automotive Pte Ltd (HQ) 60 Jalan Lam Huat, #05-45 Carros Centre, 737869 Kranji - Tel:</b>																							
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]</b>																							
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 29/10/2019]</b>																							
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT																							
<b>ASSOCIATED MAIL RECEIVED</b>				View All	Compose Case Mail																			
There are no mail for this case.																								
<input type="checkbox"/> <b>ALL ASSOCIATED TASKS</b>																								
<table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

## Nivitha (LKK Auto)

---

**From:** Irene Tay <irene.tay@sg.cntaiping.com>  
**Sent:** Thursday, 17 October 2019 11:28 AM  
**To:** Jacqueline Tan; assignments; Asher Sng (LKK Auto)  
**Subject:** FW: Scan Image  
**Attachments:** 1162\_001.pdf

Dear Sir/Mdm (LKK),

Please get your surveyors to liaise with TECH CHOON to conduct SURVEY.

Regards,

**Irene Tay**  
Executive  
Claims Department (Motor Division)

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #15-00 Springleaf Tower Singapore 079909  
DID: (65) 63896192 | F:(65) 62247478/62247175

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

**From:** ct-admin@visionlawllc.com [mailto:ct-admin@visionlawllc.com]  
**Sent:** Thursday, October 17, 2019 10:02 AM  
**To:** Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Irene Tay <irene.tay@sg.cntaiping.com>  
**Subject:** Scan Image

# VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths  
Agents for Trade Marks  
(Incorporated with limited liability)

ERIC NG CHING BOON  
WONG KENG LEONG RAYNEY  
ALDREY WONG SU-HSIEN  
PAUL YAP TAI SAN  
ANJALLI D/O MUNIANDY  
ANG KIM NOI DIANE  
RAVENDRA KRISHNASAMY  
TAN YINGXIAN, SELWYN  
CHONG YUNHUI, CLARISSA  
SONIA LIM WEI LEE

Unique Entity Number :200721148H  
✓ **HEAD OFFICE:** 133 New Bridge Road  
#18-01/02 Chinatown Point  
Singapore 059413  
  
Branch: 490 Toa Payoh Lorong 6  
#03-11 HDB Hub  
Singapore 310490

✓ **HEAD OFFICE**  
TEL : (65) 65342811 (Hunting)  
FAX ✓ : (65) 65356802 (General)  
: (65) 65355905 (Litigation)  
E-mail : jactan@visionlawllc.com  
  
**BRANCH**  
TEL : 65 63580703  
FAX : 65 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE- KINDLY REPLY TO HEAD OFFICE FOR THIS MATTER

**Our Ref:** AM.Jt.Ins.T150.111855.19 (sj)  
**Your Ref:** SNM19D204892

17 October 2019

**CHINA TAIPING INSURANCE (S'PORE) PTE LTD**  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909  
**Attention: Motor Claims Department**

**BY FAX: 6224 7175**  
email: claimsdept@sg.cntaiping.com  
email: irene.tay@sg.cntaiping.com

Dear Sirs,

**ACCIDENT INVOLVING SJL 6087 D & XD 9594 M ON 15 OCTOBER 2019 ALONG KRANJI LINK AND KRANJI WAY T JUNCTION AT ABOUT 0805 HOURS (NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)**

We refer to your email 17 October 2019 of even date informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of Kenneth Kong as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

Venue: Tech Choon Automotive Pte Ltd  
60 Jalan Lam Huat  
#05-45 Carros Centre  
Singapore 737869  
Contact Person: Mr Wong (9671-3577 / 9675 3859 / 6367 0710)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

ANJALLI M  
(HEAD OFFICE)

**FOR SURVEYOR**

Please initial here after completion of pre-repair inspection.  
Thank you.

1<sup>st</sup> Survey on \_\_\_\_\_  
Appointed surveyor : \_\_\_\_\_  
(Name & Signature)

2<sup>nd</sup> Survey on \_\_\_\_\_  
Appointed surveyor : \_\_\_\_\_  
(Name & Signature)

3<sup>rd</sup> Survey on \_\_\_\_\_  
Appointed Surveyor : \_\_\_\_\_  
(Name & signature)

cc: **SJL 6087 D** – by fax: 6368-8025 only

**NB.: Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude our client from claiming injury-related damages arising from this accident.**

CONFIDENTIALITY  
THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	15/10/2019 19:17
Date Of Accident	15/10/2019 08:05
Exact Location Of Accident	KRANJI LINK AND KRANJI WAY - T JUNCTION
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJL6087D
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CHEONG KAI LENG
NRIC No	S9019318Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96670619
Alternative Phone No	OTHERS-96670619

### Vehicle Particulars

Manufacturer	HONDA
Model	FIT 1.3G SKYROOF A
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10920428
Cover Note Number	N.A

### Driver

Name of Driver	KONG WEI JIE BENJAMIN
NRIC No	S9021902B
Date Of Birth	26/06/1990
Occupation	INDOOR
Date Of Driving Pass	22/08/2016
Driving Experience	3 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-96670619
Fax Number	
Contact Number	
EMail Address	BENJAMNKONGWEIJIE@GMAIL.COM

Address	NA
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - FIANCE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	CHUA CHU KANG NPC
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO POLICE REPORT NO. T/20191015/2142 LODGE AT CHUA CHU KANG NPC ON 15/10/2019 AT 0750HRS, I WAS DRIVING TO WORK WHEN I REACHED AND MADE A STOP ON THE LEFT MOST LANE OF THE T-JUNCTION OF KRANJI LINK AND KRANJI WAY. THE ROAD CONSIST OF TWO LANES WHEREBY THE LEFT MOST LANE ONLY ALLOWS TO TURN LEFT AND RIGHT MOST LANE ALLOWS TO TURN RIGHT. I INCHED OUT MY CAR AS I WAS NOT ALBE TO LOOK ONTO ONCOMING TRAFFIC. SUDDENLY, A LORRY WHICH WAS ON THE RIGHT MOST LANE NEGOTIATED A LEFT TURN. THE FRONT LEFT SIDE OF THE LORRY COLLIDED ONTO THE MIDDLE RIGHT SIDE OF MY VEHICLE. MY CAR WAS DRAGGED ALONG THE ROAD BY THE LORRY BEFORE MAKING A COMPLETE STOP

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	NA
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD9594M
Vehicle Make/Model/Colour	MITSUBISHI / FUSO FV51SJD2DEA / WHITE
Details Of Properties	N.A
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	GOH SOON KIAT
NRIC/Passport Number	S1829893G
Contact Number	98460989
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver) 1

**DETAILS OF INJURED PERSON 1**

Name KONG WEI JIE BENJAMIN

Approximate Age

Injuries Sustain

Injured person in which vehicle? SJL6087D

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

**SKETCH PLAN**  
**SJL6087D**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to regulate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

  
\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time: **15 Oct 2019**

**VERIFY BY AJAX MARS (ARC)**  
**REPORTING OFFICER**  
**HASHIM BIN KAMARI**

\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:





**SINGAPORE  
POLICE FORCE**



T/20191015/2142

1 of 3

Report No. T/20191015/2142

Police Station Of Origin:  
Choa Chu Kang N.P.C  
20 Choa Chu Kang Street 52 #01-02  
SINGAPORE 689286  
Tel No: 1800-7659999

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 15/10/2019 17:32	Vide Report No.: J/20191015/0055	Station Diary No. 89
--	-------------------------------------	-------------------------

**Informant's Particulars**

Name of Informant: KONG WEI JIE, BENJAMIN		Address: APT BLK 659 CHOA CHU KANG CRESCENT #07-69 SINGAPORE 680659	
ID Type / ID No.: NRIC NO / S9021902B		Contact No.: Home/Office: Mobile: 96670619	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 29	Date of Birth: 26/06/1990	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: POLICE COAST GUARD		Driving Licence Information: Class: 2B.3	Date of Expiry:

**General Information of the Accident**

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 15/10/2019 07:50	Type of Location: T-Junction
Location: Along Road 1 KRANJI LINK				
T Junction of Kranji Link and Kranji Way				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: No	

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJL6087D	Car				Seriously Damaged	0
XD9594M	Lorry				No Damage	0

**Details of Person Involved**

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**



T/20191015/2142

2 of 3

Report No. T/20191015/2142

Police Station Of Origin:  
Choa Chu Kang N.P.C  
20 Choa Chu Kang Street 52 #01-02  
SINGAPORE 689286  
Tel No: 1800-7659999

## CONTINUATION OF REPORT

Driver			
Name	KONG WEI JIE, BENJAMIN		ID No. S9021902B
Related Vehicle	SJL6087D (Car)		Contact No. 96670619
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL		Class of Driving Licence & Expiry Date Class: 2B.3 Date of Expiry: NIL
Date Treatment	15/10/2019	Date Discharge	15/10/2019
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Name	GOH SOON KIAT		ID No. S1829893G
Related Vehicle	NIL		Contact No. NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 15/10/2019 at 0750hrs, I was driving to work when I reached and made a stop on the left most lane of the T-junction of Kranji Link and Kranji Way. The road consist of two lanes whereby the left most lane only allows to turn left and right most lane allows to turn right. I inched out my car as I was not able to look onto oncoming traffic. Suddenly, a lorry which was on the right most lane negotiated a left turn. The front left side of the lorry collided onto the middle right side of my vehicle. My car was dragged along the road by the lorry before making a complete stop



**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Choa Chu Kang N.P.C  
20 Choa Chu Kang Street 52 #01-02  
SINGAPORE 689286  
Tel No: 1800-7659999



T/20191015/2142

3 of 3

Report No. T/20191015/2142

**CONTINUATION OF REPORT**

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: J/ Sgt 3 NUR RAQIB BIN RASMAN	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 15/10/2019.17:32
Officer In Charge Of Case: TP / AEIT / SI MOHAMAD ZULFAZDLI BIN ABDULLAH Contact No. : 65476204	Classification Of Case:

Authentication Stamp  
NP168



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0030
Operating Hours : Monday to Friday, 09:00 - 17:00
UEN: S665500206 / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MBHH19137025 Vehicle Registration No: SJL6087D
Name(as shown in NRIC) : KONG WEI JIE BENJAMIN NRIC/FIN/Passport No : S9021902B
(\*Vehicle Driver / Vehicle Owner) (\* Please delete as appropriate
Address : Singapore( )
Contact (Tel) : Mobile No. : 96670619
Email Address : benjamnkongweijie@gmail.com
Date of Accident : 15/10/2019 Time of Accident : 08:05
Place of Accident : KANJI LINK AND KRANJI WAY - T JUNCTION
Insurance Company: AVIVA LTD

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

ATTACH POLICE REPORT, TAX INVOICE & MEDICAL CERTIFICATE

Policyholder / Driver's Signature
Date:

Reporting Centre Personnel's Signature
Name: SABITRA
NRIC/FIN No.:
Date: 16/10/2019

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	318Z
Vehicle Details	
Vehicle No.:	SJL6087D
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Oct 2019
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3G SKYROOF A
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	L13A4103715
Chassis No.:	GE61093149
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$13,632.00
Original Registration Date:	04 Dec 2008
First Registration Date:	04 Dec 2008
Transfer Count:	1
Actual ARF Paid:	\$13,632.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	03 Dec 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$13,786.00
COE Rebate Amount:	\$11,380.00
<b>Total Rebate Amount:</b>	<b>\$11,380.00</b>
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 17 Oct 2019

OK

**Get More Cash for Your Car. Post an Ad Today.**

Receive a higher selling price by selling your car yourself. Advertise it for sale at just \$58, list till sold.

Post an Advertisement  
Sell it yourself. Advertise it at just  
**\$58 until it's SOLD!**

Now 5 Years Renewal Deal Starting \$219 & 99



Learn More About Us  
We're Here To Help You  
Buy, Sell, Finance Your Car  
Or Cash For Us Today!

Post an Ad Advertiser Login Ways of Selling

Filter by Category: Honda Fit | Back (1 2 3 4 5) Next > | Sort by Date Posted | 20 results/page

94 vehicles

Year: Make: Price: Depreciation: Mileage: Eng Cap: Make: Veh Type: Model:

Search Selection: Honda Fit | Price: Any | Depreciation: > 10 year(s) old | Mileage: Any | Veh Type: Any | Model: Available

**Honda Fit 1.3A G (COE 100 09/2028)**  
\$41,800 | \$4,570 /yr | 29-Sep-2008 | 1,139 cc | 125,000 km | Hatchback | Available

Red Maroon. Loan Available With Lowest Interest Rates. High Trade In Welcome. Call Now To Book An Appointment To View This Beauty. Viewing Strictly Appointment Based.

Car Search

Posted: 10-Nov-2019 | Tags: 2008 Honda Fit, 2008 Honda Fit, Honda Fit

**Honda Fit 1.3A G (COE 100 10/2023)**  
\$21,800 | \$3,480 /yr | 09-Oct-2008 | 1,339 cc | 120,000 km | Hatchback | Available

Owned This Car With 80% Loan As Shown, Sports Looking Hatchback With Ferrari Signature Black With Red Stitching Contentional Seats, Pleases Condition Inside Out, All Wear And Tears Totally Minimal, Various Finance Plan To Cater Each Individuals Needs, Very...

Posted: 13-Oct-2019 | Tags: 2008 Honda Fit, 2008 Honda Fit, Honda Fit

**Honda Fit 1.3A L (DPC) (COE 100 10/2023)**  
\$24,800 | \$3,170 /yr | 24-Oct-2008 | 1,339 cc | 94,000 km | Hatchback | Available

1 Owner. Very Low Mileage. Selling As Normal Plate. L Model. High Spec With Digital Aircon. Call For Appointment To View Now!

Posted: 11-Oct-2019 | Tags: 2008 Honda Fit, 2008 Honda Fit, Honda Fit

**Honda Fit 1.3A G (COE 100 10/2028)**  
\$40,800 | \$4,420 /yr | 30-Oct-2008 | 1,339 cc | 140,000 km | Hatchback | Available

Commitment Code: A110. Flexible And Attractive Loan Available. Trade-In Available For Your Car! No Hidden Costs. For Further Information Or If You Have Any Questions Please Do Not Hesitate To Contact Us.

Posted: 10-Oct-2019 | Tags: 2008 Honda Fit, 2008 Honda Fit, Honda Fit



Is your COE expiring? Let us help you renew it!  
Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Ensure today.

**Honda Fit 1.3A G (COE 100 11/2023)**  
\$22,800 | \$3,670 /yr | 06-Nov-2008 | 1,339 cc | 51,261 km | Hatchback | Available

No Dealers Please. 2 Owners Only.

Posted: 13-Nov-2019 | Tags: 2008 Honda Fit, 2008 Honda Fit, Honda Fit

**Honda Fit 1.3A L (COE 100 11/2023)**  
\$25,800 | \$3,390 /yr | 11-Nov-2008 | 1,339 cc | 121,300 km | Hatchback | Available

Lady Owner. High Spec L Model. New Paint. Wear And Tear All Reduced. Car In Very Good Condition. 6 Months Warranty Engine And Gearbox. Clean And Well Maintained. Full Loan Available. Trade In Welcome. Please Call For Viewing Now!

Posted: 12-Nov-2019 | Tags: 2008 Honda Fit, 2008 Honda Fit, Honda Fit

**Honda Fit 1.3A GF (COE 100 11/2033)**  
\$36,800 | \$5,380 /yr | 13-Nov-2008 | 1,339 cc | - | Hatchback | Available

1 Year In House Warranty, Full High Loan Available. Free 1 x Servicing. Warranty Not By 3rd Party Workshop. Price Stated Above Is Actual Selling Price. New Parkwork Done. Fully Refurnished. Guarantee Accident Free. Die Or Vroom Evaluation Are Welcome. Purchase...

CarMart

Posted: 17-Nov-2019 | Tags: 2008 Honda Fit, 2008 Honda Fit, Honda Fit

**Honda Fit 1.5A BS (COE 100 11/2023)**  
\$26,800 | \$7,000 /yr | 17-Nov-2008 | 1,496 cc | - | Hatchback | Available

No Repairs Needed. Well Maintained. Excellent Condition. Accident Free. Beautiful Interior And Exterior. Bank And In House Loan Available. Trade In Are Welcome. Powerful Engine And Smooth Transmission. A Real Joy To Drive! Buy With Confidence! Call Us Now To...

Posted: 01-Sep-2019 | Tags: 2008 Honda Fit, 2008 Honda Fit, Honda Fit

**Honda Fit 1.3A G (COE 100 11/2023)**  
\$21,000 | \$3,140 /yr | 17-Nov-2008 | 1,339 cc | 171,000 km | Hatchback | Available

Commitment Code: A210. Flexible And Attractive Loan Available To Choose From. Trade In Available For Your Car! No Hidden Costs. For Further Information Or If You Have Any Questions Please Do Not Hesitate To Contact Us.

Posted: 27-Aug-2019 | Tags: 2008 Honda Fit, 2008 Honda Fit, Honda Fit

**Honda Fit 1.3A G (COE 100 11/2023)**  
\$23,800 | \$3,800 /yr | 25-Nov-2008 | 1,339 cc | - | Hatchback | Available

Full Loan Available At \$700 Plus. We Can Help To Convert To 210 Usage If Needed. In House Loan Or Bank Loan Available! Fast, Easy And Flexible Loan Approval! We Are sgCarMart Premium Dealer! Buy With Confidence! Viewing And Test Drive Available Daily Including Week...

88 Motor Trading

Posted: 08-Nov-2019 | Tags: 2008 Honda Fit, 2008 Honda Fit, Honda Fit

**Free Valuation for your Car**  
Find out how much your car is worth today! Protect yourself from overbidding buyers with an accurate free valuation.  
Post ad now!

Compare

# Tech Choon Automotive Pte Ltd

60 JALAN LAM HUAT #05-45

CARROS CENTRE

Singapore (737869)

Phone Number: 63670710

Fax Number: 63688025

Customer:		Date: 10/15/2019 3:36 PM - 10/15/2019
Company:		VIN
License NO:	SJL6087D	Technician:
Odometer:		Order NO:

## VEHICLE ALIGNMENT REPORT

HONDA, FIT, 09-13, GE6 2WD 14" Wheels

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	3.63°	2.17°	4.17°	4.05°
		Right	3.92° /	2.17°	4.17°	4.23°
	Camber	Left	-0.17°	-1.00°	1.00°	-0.33°
		Right	-0.15°	-1.00°	1.00°	-0.02°
	Toe	Left	-1.34°	-0.14°	0.14°	-0.01°
Right		1.26° /	-0.14°	0.14°	-0.05°	
Total		-0.08°	-0.29°	0.29°	-0.06°	
Rear	Camber	Left	-1.23°	-2.00°	0.00°	-1.28°
		Right	-0.71°	-2.00°	0.00°	-0.63°
	Toe	Left	0.36°	0.00°	0.29°	0.37°
		Right	0.28°	0.00°	0.29°	0.29°
		Total	0.64°	0.00°	0.59°	0.66°
Max Thrust Angle			-0.04°	----		-0.04°
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left		13.03°	11.75°	11.75°	13.03°
	Right		13.02°	11.75°	11.75°	13.02°
Included Angle	Left		12.86°	----	----	12.70°
	Right		12.87°	----	----	13.00°
Toe Out On Turns	Left		----	----	----	----
	Right		----	----	----	----
Max Turn Inside	Left		----	----	----	----
	Right		----	----	----	----
Toe Curve Change	Left		----	----	----	----
	Right		----	----	----	----
Setback	Front		-12mm	----	----	-5mm
	Rear		-8mm	----	----	-8mm
Track Width Diff.			19mm			19mm
Wheel Base Diff.			-4mm			3mm
Front Ride Height	Left		----	----	----	----
	Right		----	----	----	----
Rear Ride Height	Left		----	----	----	----
	Right		----	----	----	----
Frame Angle						----

# Tech Choon Automotive Pte Ltd

60 JALAN LAM HUAT #05-45

CARROS CENTRE

Singapore (737869)

Phone Number: 63670710

Fax Number: 63688025

Customer:	Date: 10/18/2019 5:33 PM - 10/18/2019
Company:	VIN
License NO: SJL6087D	Technician:
Odometer:	Order NO:

## VEHICLE ALIGNMENT REPORT

HONDA, FIT, 09-13, GE6, GE8 2WD ex. 14" Wheels

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	3.59°	2.33°	4.33°	3.70°
		Right	3.80°	2.33°	4.33°	3.88°
	Camber	Left	-0.09°	-1.00°	1.00°	-0.19°
		Right	0.06°	-1.00°	1.00°	0.13°
	Toe	Left	-0.14°	-0.14°	0.14°	0.02°
		Right	-0.12°	-0.14°	0.14°	0.01°
Total		-0.26°	-0.28°	0.28°	0.03°	
Rear	Camber	Left	-1.28°	-2.00°	0.00°	-1.35°
		Right	-0.60°	-2.00°	0.00°	-0.52°
	Toe	Left	0.36°	0.00°	0.28°	0.37°
		Right	0.29°	0.00°	0.28°	0.30°
		Total	0.65°	0.00°	0.56°	0.67°
	Max Thrust Angle			-0.04°	----	
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left		12.68°	12.00°	12.00°	12.68°
	Right		12.29°	12.00°	12.00°	12.29°
Included Angle	Left		12.59°	----	----	12.49°
	Right		12.35°	----	----	12.42°
Toe Out On Turns	Left		----	----	----	----
	Right		----	----	----	----
Max Turn Inside	Left		----	----	----	----
	Right		----	----	----	----
Toe Curve Change	Left		----	----	----	----
	Right		----	----	----	----
Setback	Front		-5mm	----	----	-5mm
	Rear		-8mm	----	----	-8mm
Track Width Diff.			20mm			20mm
Wheel Base Diff.			3mm			3mm
Front Ride Height	Left		----	----	----	----
	Right		----	----	----	----
Rear Ride Height	Left		----	----	----	----
	Right		----	----	----	----
Frame Angle						----



# TECH CHOON AUTOMOTIVE PTE. LTD.

60 JALAN LAM HUAT #05-45, CARROS CENTRE, SINGAPORE 737869

TEL: 6367 0710 FAX: 6368 8025 Email: tcawtl@singnet.com.sg *Mr Wang*

Business Reg No : 200311178 N GST Reg No, 200311178N

*Steve (LKK) WL Price 17/10/19 2.00 pm*

*83228813*

*8 days*

Estimate : ES000256

CHEONG KAI LENG ( S9019318Z )  
659 CUOA CHU KANG CRESCENT #07-59  
( SINGAPORE ) 680659

DRIVER: KONG WEI JIE. BENJAMI ( S9021902B )

Attention : Motor Claim Department

Contact : Hp 96670619/96670619

*L/S*

*Ry AL Spj*

Date : 15/10/2019

Vehicle Num: SJL8087D

Make/Model: HONDA FIT GE6

Chassis/Eng# @ GE6-1093149 @

Accident Date : 15/10/2019

Claim No. :

Reference : AM(Lins.T150.111855.19 (9) )

Policy No. : 10920428 ( AVLVA LTD )

SN	Quantity	Particular	Unit Price	Amount S\$
----	----------	------------	------------	------------

SN	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1 PC	FENDER FRONT RH / <i>DD</i>		419.50 /
2.	1 PC	FENDER DUST COVER / <i>CRV</i>		67.40 /
3.	8 PC	FENDER DUST COVER CLIP / <i>MC</i>	<del>5.00</del> <i>99 /</i>	52.00
4.	1 PC	QUARTER GLASS RH / <i>DR</i>		198.70 /
5.	1 PC	QUARTER GLASS FASTENER / <i>MC</i>		55.10 /
6.	1 PC	SIDE MIRROR RH / <i>DR</i>		461.30 /
7.	1 PC	SIDE MIRROR COVER RH / <i>DR</i>		54.30 /
8.	1 PC	DOOR HINGE TOP FRONT RH / <i>DT</i>		35.40 /
9.	1 PC	DOOR HINGE LOWER FRONT RH / <i>DT</i>		35.40 /
10.	1 PC	DOOR CHECK RH FRONT / <i>X MM</i>		39.60 X
11.	1 PC	DOOR PANEL FRONT RH / <i>DD</i>		803.30 /
12.	1 PC	DOOR RUBBER SEAL FRONT RH / <i>X MM</i>		103.90 X
13.	1 PC	DOOR PILLAR CENTRE / <i>X R</i>		621.00 X
14.	1 PC	FENDER REAR RH / <i>DD</i>		696.10 /
15.	1 PC	DOOR GLASS FRONT RH / <i>DR</i>		363.30 /
16.	1 PC	DOOR REGULATOR GEAR FRONT RH / <i>? / DT</i>		405.30 <i>300 /</i>
17.	1 PC	DOOR GLASS CHANNEL FRONT RH / <i>? / CRV</i>		69.10 /
18.	1 PC	DOOR GLASS STAY / <i>? / DT</i>		17.10 /
19.	1 PC	DOOR INNER LOCK FRONT RH / <i>DT</i>		252.00 /
20.	1 PC	DOOR OPER HANDER OUTER FRONT RH / <i>X R</i>		84.80 X
21.	1 PC	DOOR MOULDING FRONT RH / <i>DD</i>		59.00 /
22.	1 PC	DOOR PANEL REAR RH / <i>X DD</i>		767.50 /
23.	1 PC	FRONT STAY COVER / <i>X CRV</i>		26.10 /
24.	1 PC	DOOR RUBBER REAR RH / <i>X MM</i>		103.90 X

CONTINUE / ...

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



# TECH CHOON AUTOMOTIVE PTE. LTD.

60 JALAN LAM HUAT #05-45, CARROS CENTRE, SINGAPORE 737869  
 TEL: 6367 0710 FAX: 6368 8025 Email: tcawtl@singnet.com.sg  
 Business Reg No : 200311178 N GST Reg No. 200311178N

CHEONG KAI LENG ( S9019318Z )  
 659 CUQA CHU KANG CRESCENT #07-69  
 ( SINGAPORE ) 680659  
 DRIVER: KONG WEI JIE. BENJAMI ( S9021902B )  
 Attention Motor Claim Department  
 Contact: Hp 96670619/96670619

Estimate : ES000256

Date: 15/10/2019  
 Vehicle Num: SJL6087D  
 Make/Model: HONDA FIT GE6  
 Chassis/Eng#: @ GE6-1093149 @  
 Accident Date: 15/10/2019  
 Claim No.:  
 Reference: AM, Lins. T150.111855.19 (sj)  
 Policy No.: 10920428 ( AVLVA LTD )

S/N	Quantity	Particular	Unit Price	Amount S\$
25.	1 PC	DOOR TOP MOUNDING REAR RH <i>OT ? (incl OT) - OR</i>		17.30 /
26.	1 PC	DOOR HINGE TOP REAR RH <i>OT</i>		35.40 /
27.	1 PC	DOOR HINGE LOWER REAR RH <i>OT</i>		35.40 /
28.	1 PC	DOOR CHECK REAR RH <i>X MM</i>		39.60 X
29.	1 PC	DOOR INNER LOCK RH <i>OT</i>		239.60 /
30.	1 PC	DOOR OPER HANDER OUTER REAR RH <i>X R CRU</i>		84.00 X
31.	1 PC	DOOR GLASS CHANNEL REAR RH <i>OT</i>		69.10 /
32.	1 PC	DOOR GLASS OUTER MOUNDING REAR RH <i>OT</i>		58.00 /
33.	1 PC	WINDSCREEN SEALANT <i>MC</i>		65.00 /
34.	1 PC	DOOR RUBBER FRONT RH ( BODY ) <i>X MM</i>		103.90 X
35.	1 PC	DOOR RUBBER REAR RH ( BODY ) <i>X MM</i>		103.90 X

*5176.40*  
*- 20%*  
*4141.12*

*1200* 1,600.00 *1400*  
 380.00 *100*  
 1,680.00 *1380*  
 95.00 *70*  
 85.00 *60*  
 120.00 *50*  
 3,960.00  
*3060*

List Total S\$

LABOUR :

( LABOUR CHARGES )

TO REPLACE FRONT RH FENDER, FRONT & REAR DOOR  
 TO REPLACE & REPAIR DOOR PILLAR CENTRE, FENDER  
 WELLING & ADJUSTMENT

TO REMOVE & REFIX DOOR MECHANISM CHANGE F/R/R DOOR

GLASS, DOOR REGULATOR GEAR & CHECK WIRING.

REMARKS: TO SPRAY PAINTING FOR AFFECTED PORTION.  
 ( PEARL WHITE PAINT )

TO INSTALL FRONT RH QUARTER GLASS.

TO ADJUST FOUR WHEEL COMPUTER ALIGNMENT.

TO SPRAY UNDERCOAT

Labour Total S\$

SingDollars Ten Thousand Five Hundred Ninety-Three & Cents Thirty Only

E & O.E

*= 6600*

Total S\$

10,593.30

for TECH CHOON AUTOMOTIVE PTE LTD

This is only an estimate based on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun.

*12492.50*



# TECH CHOON AUTOMOTIVE PTE. LTD.

60 JALAN LAM HUAT #05-45, CARROS CENTRE, SINGAPORE 737869  
TEL: 6367 0710 FAX: 6368 8025 Email: tcawtl@singnet.com.sg  
Business Reg No : 200311178 N GST Reg No. 200311178N

CHEONG KAI LENG ( S9019318Z )  
559 CUQA CHU KANG CRESCENT #07-69  
( SINGAPORE ) 650659  
DRIVER: KONG WEI JIE BENJAMI ( S9021902B )  
Attention: Motor Claim Department  
Contact: Hp 96670619/96670619

## Supplementary Estimate : ES000257

Date: 15/10/2019  
Vehicle Num: SJI 6087D  
Make/Model: HONDA FIT GE6  
Chassis/Eng#: @ GE6-1093149 @  
Accident Date: 15/10/2019  
Claim No.:  
Reference:  
Policy No.: 10920428 ( AVLVA LTD )

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS:				
1.	1 PC	ABSORBER FRONT WHEEL RH / <i>OT</i>	918.50	506.00 ✓
2.	1 PC	ABSORBER MOUNTING FRONT X <i>XIAI</i>		42.70 X
3.	1 PC	LOWER ARM BUSH FRONT X <i>NAI</i>	- 70%	158.60 X
4.	1 PC	KNUCKLE ARM FRONT WHEEL RH / <i>OT</i>		289.20 ✓
5.	1 PC	KNUCKLE WHEEL BEARING FRONT RH - <i>MC</i>	734.80	123.30 ✓
6.	1 PC	WHEEL HUB RH ( ORIGINAL ) X <i>NAI</i>		189.40 X
List Total S\$:				1,309.20
NETT ITEMS:				
1.	1 PC	TYRE 175/65R1684H ( BRIDGESTONE ) ( <i>Front RH</i> ) - <i>TAI</i> 70%	197.50	175.00
Nett Total S\$:				175.00
LABOUR:				
( ADDITIONAL LABOUR CHARGE ) TO REPLACE FRONT WHEEL RH SUSPENSION.			25/10/19 11.05 Am	200 ✓ 480.00
Labour Total S\$:				480.00

SingDollars : One Thousand Nine Hundred Sixty-Four & Cents Twenty Only

E & O E

Total S\$

1,964.20

for TECH CHOON AUTOMOTIVE PTE LTD

This is only an estimate based on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has began.

1957.30

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Oct 2019		17 Oct 2019 11:42 <a href="#">Edit Adj Rpt</a>	<b>S\$6,600.00</b> <a href="#">Edit Estimates</a>	<b>S\$6,600.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	- Co. Reg. No.: -								
Main Claimant:	<b>CHEONG KAI LENG</b>								
Vehicle Reg. No.:	<b>SJL6087D</b>	Date of Loss:	15/10/2019 08:00 - :59 [130 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM19D204892C02</b>	Policy/Cover Note No.:	DMCVSN19307219000						
Vehicle Reg. No. (Insured):	<b>XD9594M</b>	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	<b>Tech Choon Automotive Pte Ltd (HQ)</b> 60 Jalan Lam Huat, #05-45 Carros Centre, 737869 Kranji - Tel:								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Irene Tay Hui Ping</b> - 638986192]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>CHEN TSUE YEE</b> ] ... [Final Rpt due 29/10/2019]								
Adj Asp. Remarks:	PLEASE SURVEY AND REVERT								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SJL6087D (SNM19D204892C02)  
[XD9594M]  
TP  
CHEONG KAI LENG  
Oct 15 2019 8:00AM  
[-]  
Tech Choon Automotive Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View	View in Browser	
<b>Photos/Images</b>							3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print		
1	12/11/19 17:58	General View				Load JPG	<input checked="" type="checkbox"/>	
2	12/11/19 17:58	General View				Load JPG	<input checked="" type="checkbox"/>	
3	12/11/19 17:58	General View				Load JPG	<input checked="" type="checkbox"/>	
4	12/11/19 17:58	General View				Load JPG	<input checked="" type="checkbox"/>	
5	12/11/19 17:58	General View				Load JPG	<input checked="" type="checkbox"/>	
6	12/11/19 17:58	General View				Load JPG	<input checked="" type="checkbox"/>	
7	12/11/19 17:58	General View				Load JPG	<input checked="" type="checkbox"/>	
8	12/11/19 17:58	General View				Load JPG	<input checked="" type="checkbox"/>	
9	12/11/19 17:58	General View				Load JPG	<input checked="" type="checkbox"/>	
10	12/11/19 17:58	General View				Load JPG	<input checked="" type="checkbox"/>	
11	12/11/19 17:58	General View				Load JPG	<input checked="" type="checkbox"/>	
12	12/11/19 17:58	General View				Load JPG	<input checked="" type="checkbox"/>	
13	12/11/19 17:58	General View				Load JPG	<input checked="" type="checkbox"/>	
14	12/11/19 17:58	General View				Load JPG	<input checked="" type="checkbox"/>	
15	12/11/19 17:58	General View				Load JPG	<input checked="" type="checkbox"/>	
16	12/11/19 17:58	General View				Load JPG	<input checked="" type="checkbox"/>	
17	12/11/19 17:58	General View				Load JPG	<input checked="" type="checkbox"/>	
18	12/11/19 17:58	General View				Load JPG	<input checked="" type="checkbox"/>	
19	12/11/19 17:58	General View				Load JPG	<input checked="" type="checkbox"/>	
20	12/11/19 17:58	General View				Load JPG	<input checked="" type="checkbox"/>	
21	12/11/19 17:58	General View				Load JPG	<input checked="" type="checkbox"/>	
22	12/11/19 17:58	General View				Load JPG	<input checked="" type="checkbox"/>	
23	12/11/19 17:58	General View				Load JPG	<input checked="" type="checkbox"/>	
24	12/11/19 17:59	General View				Load JPG	<input checked="" type="checkbox"/>	
25	12/11/19 17:59	General View				Load JPG	<input checked="" type="checkbox"/>	
26	12/11/19 17:59	General View				Load JPG	<input checked="" type="checkbox"/>	
27	12/11/19 17:59	General View				Load JPG	<input checked="" type="checkbox"/>	
28	12/11/19 17:59	General View				Load JPG	<input checked="" type="checkbox"/>	
29	12/11/19 17:59	General View				Load JPG	<input checked="" type="checkbox"/>	
30	12/11/19 17:59	General View				Load JPG	<input checked="" type="checkbox"/>	
31	12/11/19 17:59	General View				Load JPG	<input checked="" type="checkbox"/>	
32	12/11/19 17:59	General View				Load JPG	<input checked="" type="checkbox"/>	
33	12/11/19 17:59	General View				Load JPG	<input checked="" type="checkbox"/>	
34	12/11/19 17:59	General View				Load JPG	<input checked="" type="checkbox"/>	
35	12/11/19 17:59	General View				Load JPG	<input checked="" type="checkbox"/>	
36	12/11/19 17:59	General View				Load JPG	<input checked="" type="checkbox"/>	
37	12/11/19 17:59	General View				Load JPG	<input checked="" type="checkbox"/>	
38	12/11/19 17:59	General View				Load JPG	<input checked="" type="checkbox"/>	
39	12/11/19 17:59	General View				Load JPG	<input checked="" type="checkbox"/>	
40	12/11/19 17:59	General View				Load JPG	<input checked="" type="checkbox"/>	
41	12/11/19 17:59	General View				Load JPG	<input checked="" type="checkbox"/>	
42	12/11/19 17:59	General View				Load JPG	<input checked="" type="checkbox"/>	
43	12/11/19 17:59	General View				Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	12/11/19 17:59	General View		<input checked="" type="checkbox"/>
45	12/11/19 17:59	General View		<input checked="" type="checkbox"/>
46	12/11/19 17:59	General View		<input checked="" type="checkbox"/>
47	12/11/19 17:59	General View		<input checked="" type="checkbox"/>
48	12/11/19 17:59	General View		<input checked="" type="checkbox"/>
49	12/11/19 17:59	General View		<input checked="" type="checkbox"/>
50	12/11/19 17:59	General View		<input checked="" type="checkbox"/>
51	12/11/19 17:59	General View		<input checked="" type="checkbox"/>
52	12/11/19 17:59	General View		<input checked="" type="checkbox"/>
53	12/11/19 17:59	General View		<input checked="" type="checkbox"/>
54	12/11/19 17:59	General View		<input checked="" type="checkbox"/>
55	12/11/19 17:59	General View		<input checked="" type="checkbox"/>
56	12/11/19 17:59	Odometer Reading		<input checked="" type="checkbox"/>
57	12/11/19 17:59	Chassis Number		<input checked="" type="checkbox"/>
58	12/11/19 17:59	General View		<input checked="" type="checkbox"/>
59	12/11/19 17:59	General View		<input checked="" type="checkbox"/>
60	12/11/19 17:59	General View		<input checked="" type="checkbox"/>
61	12/11/19 17:59	General View		<input checked="" type="checkbox"/>
62	12/11/19 17:59	General View		<input checked="" type="checkbox"/>
63	12/11/19 17:59	General View		<input checked="" type="checkbox"/>
64	12/11/19 17:59	General View		<input checked="" type="checkbox"/>
65	12/11/19 17:59	General View		<input checked="" type="checkbox"/>
66	12/11/19 17:59	General View		<input checked="" type="checkbox"/>
67	12/11/19 17:59	General View		<input checked="" type="checkbox"/>
68	12/11/19 17:59	General View		<input checked="" type="checkbox"/>
69	12/11/19 17:59	General View		<input checked="" type="checkbox"/>
70	12/11/19 17:59	General View		<input checked="" type="checkbox"/>
71	12/11/19 17:59	General View		<input checked="" type="checkbox"/>
72	12/11/19 17:59	General View		<input checked="" type="checkbox"/>
73	12/11/19 17:59	General View		<input checked="" type="checkbox"/>
74	12/11/19 17:59	General View		<input checked="" type="checkbox"/>
75	12/11/19 17:59	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
76	12/11/19 17:59	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
77	12/11/19 17:59	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
78	12/11/19 17:59	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
79	12/11/19 17:59	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
80	12/11/19 17:59	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
81	12/11/19 17:59	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
82	12/11/19 17:59	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
83	12/11/19 17:59	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
84	12/11/19 17:59	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
85	12/11/19 17:59	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
86	12/11/19 17:59	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
87	12/11/19 17:59	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
88	12/11/19 17:59	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
89	12/11/19 17:59	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
90	12/11/19 17:59	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
91	12/11/19 17:59	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
92	12/11/19 17:59	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
93	12/11/19 17:59	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
94	12/11/19 17:59	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
95	12/11/19 17:59	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
96	12/11/19 17:59	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
97	12/11/19 17:59	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
98	12/11/19 17:59	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
99	12/11/19 17:59	Photographs of Damaged Parts		<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
100	12/11/19 17:59	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
101	12/11/19 17:59	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
102	12/11/19 17:59	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
103	12/11/19 17:59	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
104	12/11/19 17:59	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
105	12/11/19 17:59	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
106	12/11/19 17:59	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
107	12/11/19 18:00	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
108	12/11/19 18:00	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
109	12/11/19 18:00	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
110	12/11/19 18:00	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
111	12/11/19 18:00	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
112	12/11/19 18:00	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
113	12/11/19 18:00	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
114	12/11/19 18:00	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
115	12/11/19 18:00	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
116	12/11/19 18:00	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
117	12/11/19 18:00	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
118	12/11/19 18:00	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
119	12/11/19 18:00	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
120	12/11/19 18:00	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
121	12/11/19 18:00	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
122	12/11/19 18:00	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
123	12/11/19 18:00	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
124	12/11/19 18:00	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
125	12/11/19 18:00	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
126	12/11/19 18:00	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
127	12/11/19 18:00	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
128	12/11/19 18:00	After Repair Photo		<input checked="" type="checkbox"/>
129	12/11/19 18:00	After Repair Photo		<input checked="" type="checkbox"/>
130	12/11/19 18:00	After Repair Photo		<input checked="" type="checkbox"/>
131	12/11/19 18:00	After Repair Photo		<input checked="" type="checkbox"/>
132	12/11/19 18:00	After Repair Photo		<input checked="" type="checkbox"/>
133	12/11/19 18:00	After Repair Photo		<input checked="" type="checkbox"/>
134	12/11/19 18:00	After Repair Photo		<input checked="" type="checkbox"/>
135	12/11/19 18:00	After Repair Photo		<input checked="" type="checkbox"/>
136	12/11/19 18:00	After Repair Photo		<input checked="" type="checkbox"/>
137	12/11/19 18:00	After Repair Photo		<input checked="" type="checkbox"/>
138	12/11/19 18:00	After Repair Photo		<input checked="" type="checkbox"/>
139	12/11/19 18:00	After Repair Photo		<input checked="" type="checkbox"/>
140	12/11/19 18:00	After Repair Photo		<input checked="" type="checkbox"/>
141	12/11/19 18:00	After Repair Photo		<input checked="" type="checkbox"/>
142	12/11/19 18:00	After Repair Photo		<input checked="" type="checkbox"/>
143	12/11/19 18:00	After Repair Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/11/19 10:14	Supplementary		<input type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:**  Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CT119018325/EYF3E2

**Date:** 27/11/2019

#### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN19307219000
Claimant Vehicle No :	SJL6087D	Insured Vehicle No :	XD9594M
Date of Loss:	15/10/2019	Nature of Claim: TP	Claim No: SNM19D204892C02

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJL6087D	Engine No:	L13A4103715
Make & Model:	HONDA FIT, 1.3 (A)	Chassis No:	GE61093149
Reg. Date:	04/12/2008 (Man. Year: 2008)	Odometer:	183334 km
Colour:	White		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	175/65 R15	Rear Tyre Size:	175/65 R15
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,117.50	4,998.42	3,119.08	38.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,440.00	3,260.00	1,180.00	26.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,557.50</b>	<b>8,258.42</b>	<b>4,299.08</b>	<b>34.24</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,600.00</b>		
(S\$)	12,557.50	6,600.00	5,957.50	47.44
<b>+ GST 7.00/7.00% (S\$)</b>	879.03	462.00	417.03	47.44
<b>Nett Amount (S\$)</b>	<b>13,436.53</b>	<b>7,062.00</b>	<b>6,374.53</b>	<b>47.44</b>

#### INSPECTION

Date of Assignment:	17/10/2019	
Date Inspected:	17/10/2019 Inspected At:	Tech Choon Automotive Pte Ltd (HQ) 60 Jalan Lam Huat, #05-45 Carros Centre Singapore 737869
Estimated Period of Repair:	8.0 days	

**Adjuster:** CHEN TSUE YEE

**Manager:** YVONNE WONG YIN CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 27 Nov 2019)
<b>Parts:</b> 144	HONDA FIT 1.3 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SJL6087D)	
<b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FENDER FRONT RH	Dented	419.50 F	*419.50 FL
2	8		*FENDER DUST COVER CLIP	Necessary	52.00 F	*20.00 FL
3	1		*QUARTER GLASS RH	Broken	198.70 F	*198.70 FL
4	1		*QUARTER GLASS FASTENER	Necessary	55.10 F	*55.10 FL
5	1		*SIDE MIRROR RH	Broken	451.30 F	*451.30 FL
6	1		*SIDE MIRROR COVER RH	Broken	54.30 F	*54.30 FL
7	1		*DOOR HINGE TOP FRONT RH	Bent	35.40 F	*35.40 FL
8	1		*DOOR HINGE LOWER FRONT RH	Bent	35.40 F	*35.40 FL
9	1		*DOOR CHECK RH FRONT	Not Necessary	39.60 F	*- FL
10	1		*DOOR PANEL FRONT RH	Dented	803.30 F	*803.30 FL
11	1		*DOOR RUBBER SEAL FRONT RH	Not Necessary	103.90 F	*- FL
12	1		*DOOR PILLAR CENTRE	Repair	621.00 F	*- FL
13	1		*FENDER REAR RH	Dented	696.10 F	*696.10 FL
14	1		*DOOR GLASS FRONT RH	Broken	363.30 F	*363.30 FL
15	1		*DOOR REGULATOR GEAR FRONT RH	Bent	405.30 F	*300.00 FL
16	1		*DOOR GLASS CHANNEL FRONT RH	Crushed	69.10 F	*69.10 FL
17	1		*DOOR GLASS STAY	Bent	17.10 F	*17.10 FL
18	1		*DOOR INNER LOCK FRONT RH	Bent	252.00 F	*252.00 FL
19	1		*DOOR MOULDING FRONT RH	Dented	58.00 F	*58.00 FL
20	1		*DOOR PANEL REAR RH	Dented	767.50 F	*767.50 FL
21	1		*FRONT STAY COVER	Cut	28.10 F	*28.10 FL
22	1		*DOOR RUBBER REAR RH	Not Necessary	103.90 F	*- FL
23	1		*DOOR HINGE TOP REAR RH	Bent	35.40 F	*35.40 FL
24	1		*DOOR HINGE LOWER REAR RH	Bent	35.40 F	*35.40 FL
25	1		*DOOR CHECK REAR RH	Not Necessary	39.60 F	*- FL
26	1		*DOOR INNER LOCK RH	Bent	239.60 F	*239.60 FL
27	1		*DOOR GLASS CHANNEL REAR RH	Crushed	69.10 F	*69.10 FL
28	1		*DOOR GLASS OUTER MOULDING REAR RH	Dented	58.00 F	*58.00 FL
29	1		*WINDSCREEN SEALANT	Necessary	65.00 F	*30.00 FL
30	1		*DOOR RUBBER FRONT RH (BODY)	Not Necessary	103.90 F	*- FL
31	1		*DOOR RUBBER REAR RH (BODY)	Not Necessary	103.90 F	*- FL
32	1		*ABSORBER FRONT WHEEL RH	Bent	506.00 F	*506.00 FL
33	1		*ABSORBER MOUNTING FRONT	Not Necessary	42.70 F	*- FL
34	1		*LOWER ARM BUSH FRONT	Not Necessary	158.60 F	*- FL
35	1		*KNUCKLE ARM FRONT WHEEL RH	Bent	289.20 F	*289.20 FL
36	1		*KNUCKLE WHEEL BEARING FRONT RH	Necessary	123.30 F	*123.30 FL
37	1		*WHEEL HUB RH (ORIGINAL)	Not Necessary	189.40 F	*- FL
38	1		*TYRE 175/65R1684H (BRIDGESTONE) (70%)	Torn	175.00 FS	*122.50 FS
39	1		*FENDER DUST COVER	Crushed	67.40 F	*67.40 FL
40	1		*DOOR OPER HANDER OUTER FRONT RH	Repair	84.80 F	*- FL
41	1		*DOOR OPER HANDER OUTER REAR RH	Repair	84.00 F	*- FL
42	1		*DOOR TOP MOUNDING REAR RH	Broken	17.30 F	*17.30 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 8,117.50 6,217.40

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			- List Item Discount on L Items	0.00/20.00% (S\$)	0.00	1,218.98
			Total Parts (S\$)		8,117.50	4,998.42

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGES. TO REPLACE FRONT RH FENDER, FRONT & REAR DOOR. TO REPLACE & REPAIR DOOR PILLAR CENTRE , FENDER, WELLING & ADJUSTMENT	New	1,600.00	1,400.00
2	TO REMOVE & REFIX DOOR MECHANISM, CHANGE F/RR DOOR GLASS, DOOR REGULATOR GEAR & CHECK WIRING	New	380.00	100.00
3	TO SPRAY PAINTING FOR AFFECTED PORTION (PEARL WHITE PAINT)	New	1,680.00	1,380.00
4	TO INSTALL FRONT RH QUARTER GLASS	New	95.00	70.00
5	TO ADJUST FOUR WHEEL COMPUTER ALIGNMENT	New	85.00	60.00
6	TO SPRAY UNDERCOAT	New	120.00	50.00
7	TO REPLACE FRONT WHEEL RH SUSPENSION	New	480.00	200.00
<b>Gross Labour Cost (S\$)</b>			<b>4,440.00</b>	<b>3,260.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >