Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

CC4/III19018330/EPS3Q2 Our File No:

Date: 13/05/2020

Odometer:

REFERENCE

India International Insurance Handling Insurer:

Pte Ltd

Policy No: D18MPC0000890_01

Claimant Vehicle No:

GBF565G

14/10/2019

Insured Vehicle No:

SLA2860Z

Date of Loss:

Nature of Claim: TP Claim No:

MPC2019D0001258

DESCRIPTION & IDENTIFICATION OF VEHICLE

GBF565G Reg No:

FIAT DOBLO CARGO MAXI, 1.6 D MTJ AMT Make & Model:

Engine No: 198A30007584915

GLAZE (M)

Reg. Date: 07/06/2016 (Man. Year: 2016)

ZFA26300006C31627 Chassis No:

41589 km

Colour: Red **Engine Capacity:** 1598 cc

Market Value/New Car

N/A

Price:

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R16C Rear Tyre Size: 195/60 R16C Front Left Side: Goodyear 5 mm Rear Left Side: Goodyear 5 mm Front Right Side: Rear Right Side: Goodyear 5 mm Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	930.30	809.10	121.20	13.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	750.00	430.00	320.00	42.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,680.30	1,239.10	441.20	26.26
Approved Total (Overridden) (S\$)		1,000.00		
(S\$)	1,680.30	1,000.00	680.30	40.49
+ GST 7.00/7.00% (S\$)	117.62	70.00	47.62	40.49
Nett Amount (S\$)	1,797.92	1,070.00	727.92	40.49
Global Sum S	Settlement (S\$)	0.00		

INSPECTION

Date of Assignment: 16/10/2019

Date Inspected: 17/10/2019 Inspected At: Car City Auto Centre Pte Ltd (HQ)

Blk 9006 #01-198, Tampines Street 93

Singapore 528840

Estimated Period of Repair: 2.0 days Adjuster Report Page 2 of 4

Adjuster: CHEN TSUE YEE Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference				
Part Source:	: MRM-SG	Version: 1.0 (Last Synchronised: 13 May 2020)		
Parts:	213	FIAT DOBLO CARGO MAXI 1.6 D MTJ AMT GLAZE (M) (Catalogue:Merimen Singapore 1.0)		
Labour:	Repairer's	(Price-denominated Standard List)		
Print Code:	: (Unsubmitted, no print-code for GBF565G)			
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page			
Further Info:	: Items/values i	not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER UPPER	Cut	795.00 FL	*795.00 FL
2	1		*TOWING COVER	Repair	68.00 FL	*- FL
3	10		*BUMPER CLIPS	Necessary	39.00 FL	*39.00 FL
4	1		*FRONT BUMPER RETAINER	Broken	65.00 FL	*65.00 FL
5	1		*FRONT BUMPER PLATE & HOLDER	Serviceable	60.00 FS	*-FS
F=Fra	nchise	part. S=SpcN	ett. L=ListItemDisc.			
				Sub Total (S\$)	1,027.00	899.00
	- List Item Discount on L Items 10.00/10.00% (S\$) _			96.70	89.90	
				Total Parts (S\$)	930.30	809.10
			Report was unsubmitted during t	his print-out.		

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	LABOUR	New	300.00	200.00
2	SPRAY PAINTING	New	400.00	200.00
3	TO CHECK WIRING	New	50.00	30.00
		Gross Labour Cost (S\$)	750.00	430.00
	R	eport was unsubmitted during this print-out.		

< END OF ESTIMATES >