



CAR CITY AUTO CENTRE PTE LTD
Car City Always

Steve CLKK)
83228813

WHL 17/10/19, 11.11am
2 day
L/S
Ry AL sm

1 OF 2

Blk 9006 Tampines st93 #01-198 S'pore 528840

TEL: 6781 0300 FAX: 6782 0300 GST: 200719980C

E-mail : ccacpl@singnet.com.sg

DATE : 16-Oct-19

TO: INDIA INTERNATIONAL INSURANCE
ATTN: MOTOR CLAIMS DEPT

JOB TYPE : 3RD PARTY CLAIM

VEH NO : GBF565G

ESTIMATE REPORT

OWNER'S PARTICULAR

NAME: Eternal Joy Trading
ADDRESS:

MODEL : FIAT / DOBLO CARGO

MAI

CHASSIS NO : ZFA26300006C31627

ENGINE NO:

CONTACT NO H/P:

ACCIDENT DATE : 14/10/2019

TEL:

OWNERS INSURER : China Taiping Insurance (S) Pte Ltd

POLICY NO: DMCVSN13034291906

QUOTATION SUMMARY

CLAIM DETAIL: PARTS

REQUESTOR CONTACT :

HO /67810300

S/NO	DESCRIPTION	QTY	LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER UPPER ✓ CMF	1	\$795.00	\$795.00
2	TOWING COVER X R	1	\$68.00	\$68.00
3	BUMPER CLIPS ✓ MK	10	\$3.90	\$39.00
4	FRONT BUMPER RETAINER ✓ PR	1	\$65.00	\$65.00

PARTS PRICE : \$967.00

LESS 10% \$96.70

SUB TOTAL PRICE : \$870.30

S/NO	DESCRIPTION	QTY	UNIT S/Nett PRICE	TOTAL S/Nett PRICE
1	FRONT NUMBER PLATE & HOLDER X	1	\$60.00	\$60.00
2				

S/N PARTS PRICE : \$60.00

TOTAL PARTS PRICE : \$930.30

CLAIM DETAIL : LABOURS & SPRAY PAINTING

No	JOBS DESCRIPTION	PRICE	REVISED PRICE	APPR.
1	LABOUR	\$300.00	200	
2	SPRAY PAINTING	\$400.00	200	
3	TO CHECK WIRING	\$50.00	30	

Total Labour + Spray Paints \$750.00

VEHICLE NO : GBF565G

ESTIMATE REPORT

TOTAL LABOUR COST : \$750.00

TOTAL PARTS COST : \$930.30

TOTAL REPAIR COST : \$1,680.30

APPROVAL DETAILS

EXCESS :

NO. OF DAY :

RE-SURVEY :

PART BY PART OR LUMP-SUM :

DATE OF SURVEY :

SURVEY BY :

CONTACT NO :

FAX NO. :

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF
SUPPLEMENT REPAIR IS REQUIRED

- LKK Auto Consultants hence notify
the Repairer of the following:**
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: