

INS. CASE OWNER:

CC 3 / III 1901 8751, E 9/10/19

LKK:
IDAC:

Surveyor:

Steve

DOI:

24/10/19

Date / Time:

17/10/19

Registered in Merimen:

17/10/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHD 3235D

Name of Insured:

CTPL

Insured Tel No.:

HP:

Excess Sec II : \$

D.O.A.:

9/10/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: TAN TEUK HWEE

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

MLOMOO 45

MYNDOR

BET BAYOK WEST

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLA 2603R

INSRS:
WSP:
Tel:
Liability:
RMKS:

Vag

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time	STAGE	DATE / PIC
5/12/2012 - 1	Non-Reporting ltr (1st):	
5/12/2012 - 2	Non-Reporting ltr (2nd):	
5/12/2012 - 3	Non-Reporting ltr (Final):	
5/12/2012 - 4	Notification ltr (if non-pickup):	
5/12/2012 - 5	Call CI:	
5/12/2012 - 6	After call ltr to OI:	
5/12/2012 - 7	Documentation Check List: Handler Typist	
5/12/2012 - 8	Notification ltr (if non-pickup)	☒
5/12/2012 - 9	After call ltr to OI:	☒
5/12/2012 - 10	Authorisation To Act:	☒
5/12/2012 - 11	Release Voucher:	☒
5/12/2012 - 12	Final Repair Bill:	☒
5/12/2012 - 13	Car Rental Invoice:	☒
5/12/2012 - 14	Towing Invoice:	☒
5/12/2012 - 15	LTA / GIA:	☒
5/12/2012 - 16	Medical Bill:	☒
5/12/2012 - 17	PIR:	☒
5/12/2012 - 18	Mandate/Reject Instruction:	☒
5/12/2012 - 19	LOD:	☒
5/12/2012 - 20	Payment Breakdown Form:	☒
5/12/2012 - 21	Post-Repair Photos:	☒
5/12/2012 - 22	Others:	☒
5/12/2012 - 23		
5/12/2012 - 24		
5/12/2012 - 25		
5/12/2012 - 26		
5/12/2012 - 27		
5/12/2012 - 28		
5/12/2012 - 29		
5/12/2012 - 30		
5/12/2012 - 31		
5/12/2012 - 32		
5/12/2012 - 33		
5/12/2012 - 34		
5/12/2012 - 35		
5/12/2012 - 36		
5/12/2012 - 37		
5/12/2012 - 38		
5/12/2012 - 39		
5/12/2012 - 40		
5/12/2012 - 41		
5/12/2012 - 42		
5/12/2012 - 43		
5/12/2012 - 44		
5/12/2012 - 45		
5/12/2012 - 46		
5/12/2012 - 47		
5/12/2012 - 48		
5/12/2012 - 49		
5/12/2012 - 50		
5/12/2012 - 51		
5/12/2012 - 52		
5/12/2012 - 53		
5/12/2012 - 54		
5/12/2012 - 55		
5/12/2012 - 56		
5/12/2012 - 57		
5/12/2012 - 58		
5/12/2012 - 59		
5/12/2012 - 60		
5/12/2012 - 61		
5/12/2012 - 62		
5/12/2012 - 63		
5/12/2012 - 64		
5/12/2012 - 65		
5/12/2012 - 66		
5/12/2012 - 67		
5/12/2012 - 68		
5/12/2012 - 69		
5/12/2012 - 70		
5/12/2012 - 71		
5/12/2012 - 72		
5/12/2012 - 73		
5/12/2012 - 74		
5/12/2012 - 75		
5/12/2012 - 76		
5/12/2012 - 77		
5/12/2012 - 78		
5/12/2012 - 79		
5/12/2012 - 80		
5/12/2012 - 81		
5/12/2012 - 82		
5/12/2012 - 83		
5/12/2012 - 84		
5/12/2012 - 85		
5/12/2012 - 86		
5/12/2012 - 87		
5/12/2012 - 88		
5/12/2012 - 89		
5/12/2012 - 90		
5/12/2012 - 91		
5/12/2012 - 92		
5/12/2012 - 93		
5/12/2012 - 94		
5/12/2012 - 95		
5/12/2012 - 96		
5/12/2012 - 97		
5/12/2012 - 98		
5/12/2012 - 99		
5/12/2012 - 100		

COPY SENT
25/3/2020

ASS. REC. BY:

Steve

REF:

TU

9

ASSIGNMENT

From:

Date:

24.10.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLQ 2603 R

at Workshop m/s

Vag Singapore

of

4B Toh Guan Road East #104-123

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

10-00am - 12-00pm Owner Way

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

myr

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLQ 2603 R

Yr Regn:

29/7/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A3

c.c. 1798

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading:

112721

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

TRUZZZ 8P1A1007771

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 225/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Pirelli

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

9/10/19

D.O.I.

24/10/19

Survey held at:

VAG

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV- 29000

24/10/19 Info. note SK up (JRM)

PV- 23719

NV- 5281

45 \$3600. (Red = \$1021.35 / 221.7)

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS \$

Photos

Other

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Per Form:

Lump Sum / LD: 12

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) duly marked
- Parts price subject to insurance company
- Third party insurance company's approval
- No illegal repair should be carried out
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance company



Acknowledged by Repairer
Signature: _____
Date: _____

Vehicle Repair Estimate

(LKK) Mr. MRL 24/10/19, 11:00 am
4 dy
L/S
Ry AL SM

Date: 11-Oct-2019
Vehicle Num: SLQ2603R
Make/Model: Audi A3 1.8T cabriolet
Chassis No: TRUZZZ8P1A1007771

S/N	PARTS	QTY	PRICE	TOTAL
1	Rear bumper / CRH	1	\$ 714.00	\$ 714.00
2	Cover Upper / MC	1	\$ 35.00	\$ 35.00
3	Impact beam / DO	1	\$ 335.00	\$ 335.00
4	Lower spoiler / CRH	1	\$ 235.00	\$ 235.00
5	Striker plate / X NMI	1	\$ 80.00	\$ 80.00
6	Decklid weatherstrip / X NMI	1	\$ 160.00	\$ 160.00
7	Reinforcement rear apron End Plate. / DO	1	\$ 215.00	\$ 215.00
8	Parking aid sensor / SM	1	\$ 95.00	\$ 95.00
9	Cap for sensor (required) / MC	1		
10	Seal ring for sensor (required) / MC	4	\$ 2.00	\$ 8.00
11	Rear Tailgate / ON			
12	A3 body / MC			
13	1.8T body / MC			
14	Audi logo body / MC			
15				
16				
17				
18				
19				
TOTAL PARTS				\$ 1,877.00
TOTAL AMOUNT				\$ 1,877.00
MISCELLANEOUS ITEM				
	Sundries		\$ 30 60.00	\$ 60.00
LABOUR				
1	For the removal, transfer and installation of various associated components of rear bumper, parking aid, wireset, seals.		\$ 500 650.00	\$ 650.00
2	Body work on structure, surface preparation and spray paint bumper, trunk lid, reinforcement apron		\$ 600 1,400.00	\$ 1,400.00
3	To perform complete diagnosis of the vehicle		\$ 30 90.00	\$ 90.00
TOTAL				\$ 4,077.00
GST 7%				\$ 285.39
GRAND TOTAL				\$ 4,362.39

Steve Chen (LKK Auto)

From: Jeslyn - VAG Singapore <jeslyn@vag.sg>
Sent: Thursday, November 28, 2019 11:15 AM
To: Steve Chen (LKK Auto)
Subject: Re: Submission of Finalised repair estimate for SLQ2603R
Attachments: 28112019105439-0001.pdf

Dear Steve,

We accept your offer of Lumpsum COR \$3600 (before GST), with 04 working days or repair.

Please find attached supporting documents.

- LOD
- Tax Invoice
- LOA
- LTA Search Fee
- Car Rental invoice & agreement
- DV

Thank you.

Best Regards,

Jeslyn Chua

AVANTAGE VAG
AUTOMOTIVE SPECIALISTS

6515 9515 Sales & Service | **6795 5005** 24hr Towing | www.avantage.sg

WEST Service, Tuning & Accident Reporting Centre
48 Toh Guan Road East, #05-123 Enterprise Hub, Singapore 608586

NORTH Service & Accident Reporting Centre
160 Sin Ming Drive, #04-17 Sin Ming AutoCity, Singapore 575722

EAST Service & Accident Reporting Centre
8 Kaki Bukit Ave 4, #06-48 Premier@Kaki Bukit, Singapore 415875

CARCRAFTERS Spray Paint, Grooming & Accident Repair Centre
48 Toh Guan Road East, #05-155 Enterprise Hub, Singapore 608586

On Tue, Nov 26, 2019 at 7:05 PM Steve Chen (LKK Auto) <SteveChen@lkkauto.com> wrote:

Dear Jeslyn,

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during repair
- Parts price subject to insurance approval
- Third party liability on "Without Prejudice" basis
- No illegal or unapproved work is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Vehicle Repair Estimate

Store (LKK) ML MAIL 24/10/19, 11:00 am
4 dy
L/S
RJ AL SM

Date : 11-Oct-2019

Vehicle Num : SLQ2603R

Make/Model : Audi A3 1.8T cabriolet

Chassis No : TRUZZZ8P1A1007771

S/N	PARTS	QTY	PRICE	TOTAL
1	Rear bumper / CR4	1	\$ 714.00	\$ 714.00
2	Cover Upper / APC	1	\$ 35.00	\$ 35.00
3	Impact beam	1	\$ 335.00	\$ 335.00
4	Lower spoiler / CR4	1	\$ 235.00	\$ 235.00
5	Striker plate	1	\$ 80.00	\$ 80.00
6	Decklid weatherstrip	1	\$ 160.00	\$ 160.00
7	Reinforcement rear apron End Plate	1	\$ 215.00	\$ 215.00
8	Parking aid sensor / SM	1	\$ 95.00	\$ 95.00
9	Cap for sensor (required) / APC	1		
10	Seal ring for sensor (required) / APC	4	\$ 2.00	\$ 8.00
11	Trunk Tailgate / DN			
12	A3 bridge / APC			
13	1.8T bridge / APC			
14	Audi logo bridge / APC			
15				
16				
17				
18				
19				
	TOTAL PARTS			\$ 1,877.00
	TOTAL AMOUNT			\$ 1,877.00
	MISCELLANEOUS ITEM			
	Sundries		\$ 30 60.00	\$ 60.00
	LABOUR			
1	For the removal, transfer and installation of various associated components of rear bumper, parking aid, wireset, seals.	\$ 500	650.00	\$ 650.00
2	Body work on structure, surface preparation and spray paint bumper, trunk lid, reinforcement apron	\$ 600	1,400.00	\$ 1,400.00
3	To perform complete diagnosis of the vehicle	\$ 30	90.00	\$ 90.00
	TOTAL			\$ 4,077.00
	GST 7%			\$ 285.39
	GRAND TOTAL			\$ 4,362.39

\$4621.35

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	088G
Vehicle Details	
Vehicle No.:	SLQ2603R
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Oct 2019
Vehicle Make:	AUDI
Vehicle Model:	A3 1.8T CABRIOLET FSI AT ABS D/AB TC HID
Primary Colour:	Black
Manufacturing Year:	2010
Engine No.:	CDA091940
Chassis No.:	TRUZZZ8P1A1007771
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$42,175.00
Original Registration Date:	29 Jul 2010
First Registration Date:	29 Jul 2010
Transfer Count:	2
Actual ARF Paid:	\$42,175.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Jul 2020
PARF Rebate Amount:	\$21,087.00
Intended COE Rebate Details	
COE Expiry Date:	28 Jul 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$34,600.00
COE Rebate Amount:	\$2,632.00
Total Rebate Amount:	\$23,719.00

The information contained herein is correct as at 24 Oct 2019

OK
 11K - year
 9 month = 8249
 + 21087
 29,336

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 088G

Vehicle Details

Vehicle No.: SLQ2603R
Vehicle to be Exported: No
Intended Deregistration Date: 23 Oct 2019
Vehicle Make: AUDI
Vehicle Model: A3 1.8T CABRIOLET FSI AT ABS D/AB TC HID
Primary Colour: Black
Manufacturing Year: 2010
Engine No.: CDA091940
Chassis No.: TRUZZZ8P1A1007771
Maximum Power Output: 118.0 kW (158 bhp)
Open Market Value: \$42,175.00
Original Registration Date: 29 Jul 2010
First Registration Date: 29 Jul 2010
Transfer Count: 2
Actual ARF Paid: \$42,175.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 28 Jul 2020
PARF Rebate Amount: \$21,087.00

Intended COE Rebate Details

COE Expiry Date: 28 Jul 2020
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
QP Paid: \$34,600.00
COE Rebate Amount: \$2,641.00
Total Rebate Amount: \$23,728.00

The information contained herein is correct as at 22 Oct 2019

OK



SATISFACTION / DISCHARGE VOUCHER

Claim No :

T/P/OD Invoice No :

☐ COMPREHENSIVE

☒ THIRD PARTY

☐ OD CLAIM

☐ WINDSCREEN

Messrs : Sharon Shalom Murray.

I/We hereby declare that the repairs to my/our Motor Vehicle Model : Audi A3 1.8T
Vehicle registration No. SLQ2603R have been completed by VAG Singapore Pte Ltd
to my/our entire satisfaction. I/We agree that the payment of their account for such repairs shall
be in full direct settlement and discharge of all claims under Policy No.
VAL/GA257796 in view of the damage caused to my/our said motor vehicle's accident
on 09/10/2019.

Driver's Signature

Name : Sharon Shalom Murray.

NRIC : S7423574C.

Policyholder's Signature

Name : James Sean Murray.

NRIC : S7869088G.

Witness Signature (VAG Singapore Pte Ltd)

Name : Ang Jie Ren.

Date : 09/11/2019.

Time Discharged : 11 57Hrs.

Note :

Upon conclusion with the Third Party Claim, the Discharge Voucher has to be signed by you. In the event you refuse to sign the DV, you are liable for the repair cost and other disbursement incurred.

VAG Singapore Pte Ltd

Co Registration 201111738H

48 Toh Guan Road East #05-123 Enterprise Hub (S) 608586 T: 6515 9515

www.avantage.sg



SATISFACTION / DISCHARGE VOUCHER

Claim No :

T/P/OD Invoice No :

☐ COMPREHENSIVE ☒ THIRD PARTY ☐ OD CLAIM ☐ WINDSCREEN

Messrs : Sharon Shalom Murray.

I/We hereby declare that the repairs to my/our Motor Vehicle Model : Audi A3 1.8T
Vehicle registration No. SLQ2603R have been completed by VAG Singapore Pte Ltd
to my/our entire satisfaction. I/We agree that the payment of their account for such repairs shall
be in full direct settlement and discharge of all claims under Policy No.
VA1/GA257796 in view of the damage caused to my/our said motor vehicle's accident
on 09/10/2014.

Driver's Signature

Name : Sharon Shalom Murray.

NRIC : S7423574C.

Policyholder's Signature

Name : James Sean Murray.

NRIC : S7869088G.

Witness Signature (VAG Singapore Pte Ltd)

Name : Ang Ju Ren.

Date : 09/11/2014.

Time Discharged : 11 57Hrs.

Note :

Upon conclusion with the Third Party Claim, the Discharge Voucher has to be signed by you. In the event you refuse to sign the DV, you are liable for the repair cost and other disbursement incurred.

VAG Singapore Pte Ltd

Co Registration 201111738H

48 Toh Guan Road East #05-123 Enterprise Hub (S) 608586 T: 6515 9515

www.avantage.sg

Print Received Message

This mail is associated with :

*SLQ2603R (MCT19100206)
[SHD3235D]
TP
JAMES SEAN MURRAY
Oct 9 2019 12:00AM
[COMFORT TRANSPORTATION PTE LTD]
VAG Singapore Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 24/02/2020 16:35 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$4259.45) - SLQ2603R - Claim Handler: Priya

Approved:4259.45.

Print Received Message

This mail is associated with :

***SLQ2603R (MCT19100206)**

[SHD3235D]

TP

JAMES SEAN MURRAY

Oct 9 2019 12:00AM

[COMFORT TRANSPORTATION PTE LTD]

VAG Singapore Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 03/03/2020 10:31 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$4339.45) - SLQ2603R - Claim Handler: Priya

Approved:4339.45.

...CLAIM SUBFOLDER...(Pending for Survey Report)
Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Oct 2019 Edit Reg		24 Oct 2019 00:00 Edit Adj Rpt	S\$3,600.00 Edit Estimates	S\$3,600.00 View Rpt		Pending for Survey Report Cancel Case

MainReferenceClaim DetailsDocumentsShow All

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Main Claimant:	JAMES SEAN MURRAY, ID: 57869088G		
Vehicle Reg. No.:	SLQ2603R	Date of Loss:	09/10/2019 00:00 - :59 [110 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT19100206	Policy/Cover Note No.:	MCOM0015
Vehicle Reg. No. (Insured):	SHD3235D	Policy No. (Claimant):	VA1/GA257796
		Excess:	
Repairer:	VAG Singapore Pte Ltd (HQ) 48 Toh Guan Road East, #05-155 Enterprise Hub, 608586 Jurong West - Tel: 6515-9515		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 29/10/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- III_SG (03/03/2020): Alert - Adj Mandate Approved (S\$4339.45) - SLQ2603R - Claim Handler: Priya
- III_SG (24/02/2020): Alert - Adj Mandate Approved (S\$4259.45) - SLQ2603R - Claim Handler: Priya
- III_SG (04/02/2020): Alert - Adj Mandate Maintained - SLQ2603R - Claim Handler: Priya
- III_SG (20/11/2019): Alert - Adj Mandate Approved (S\$0.00) - SLQ2603R - Claim Handler: Priya

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLQ2603R (MCT19100206)
[SHD3235D]
TP
JAMES SEAN MURRAY
Oct 9 2019 12:00AM
[COMFORT TRANSPORTATION PTE LTD]
VAG Singapore Pte Ltd

Upload DocumentsUpload PhotosCompose New LetterViewView in Browser

Video			1 per page	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	24/02/20 15:19	Video - Accident-iv	Load MP4	
Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/11/19 16:51	General View	Load JPG	
2	28/11/19 16:51	General View	Load JPG	
3	28/11/19 16:51	General View	Load JPG	
4	28/11/19 16:51	General View	Load JPG	
5	28/11/19 16:51	General View	Load JPG	
6	28/11/19 16:51	Chassis Number	Load JPG	
7	28/11/19 16:51	General View	Load JPG	
8	28/11/19 16:51	General View	Load JPG	
9	28/11/19 16:51	General View	Load JPG	
10	28/11/19 16:51	General View	Load JPG	
11	28/11/19 16:51	General View	Load JPG	
12	28/11/19 16:51	General View	Load JPG	
13	28/11/19 16:51	General View	Load JPG	
14	28/11/19 16:51	General View	Load JPG	
15	28/11/19 16:51	General View	Load JPG	
16	28/11/19 16:51	General View	Load JPG	
17	28/11/19 16:51	General View	Load JPG	
18	28/11/19 16:51	General View	Load JPG	
19	28/11/19 16:51	General View	Load JPG	
20	28/11/19 16:51	General View	Load JPG	
21	28/11/19 16:51	General View	Load JPG	
22	28/11/19 16:51	General View	Load JPG	
23	28/11/19 16:51	General View	Load JPG	
24	28/11/19 16:51	Odometer Reading	Load JPG	
25	28/11/19 16:51	General View	Load JPG	
26	28/11/19 16:51	General View	Load JPG	
27	28/11/19 16:51	General View	Load JPG	
28	28/11/19 16:51	General View	Load JPG	
29	28/11/19 16:51	General View	Load JPG	
30	28/11/19 16:51	General View	Load JPG	
31	28/11/19 16:51	General View	Load JPG	
32	28/11/19 16:51	General View	Load JPG	
33	28/11/19 16:51	General View	Load JPG	
34	28/11/19 16:51	General View	Load JPG	
35	28/11/19 16:51	General View	Load JPG	
36	28/11/19 16:51	General View	Load JPG	
37	28/11/19 16:51	General View	Load JPG	
38	28/11/19 16:51	Photographs of Damaged Parts	Load JPG	
39	28/11/19 16:51	Photographs of Damaged Parts	Load JPG	
40	28/11/19 16:51	Photographs of Damaged Parts	Load JPG	

Video				1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
					☒
41	28/11/19 16:51	Photographs of Damaged Parts		Load JPG	☒
42	28/11/19 16:51	Photographs of Damaged Parts		Load JPG	☒
43	28/11/19 16:51	Photographs of Damaged Parts		Load JPG	☒
44	28/11/19 16:51	Photographs of Damaged Parts		Load JPG	☒
45	28/11/19 16:51	Photographs of Damaged Parts		Load JPG	☒
46	28/11/19 16:51	Photographs of Damaged Parts		Load JPG	☒
47	28/11/19 16:51	Photographs of Damaged Parts		Load JPG	☒
48	28/11/19 16:51	Photographs of Damaged Parts		Load JPG	☒
49	28/11/19 16:51	Photographs of Damaged Parts		Load JPG	☒
50	28/11/19 16:53	Photo After Spray		Load JPG	☒
51	28/11/19 16:53	Photo After Spray		Load JPG	☒
52	28/11/19 16:53	Photo After Spray		Load JPG	☒
53	28/11/19 16:53	Photo After Spray		Load JPG	☒
54	28/11/19 16:53	Photo After Spray		Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	17/10/19 14:46	TP GIA REPORT		Load PDF	
2	25/10/19 17:17	TP ESTIMATE- MARKED		Load PDF	
3	23/01/20 12:51	LOD AND OTHER DOCUMENTS		Load PDF	
4	03/02/20 16:11	WORKSHOP INVOICE		Load PDF	
5	03/02/20 16:11	RENTAL RECEIPT		Load PDF	
6	03/02/20 16:11	LTA SEARCH		Load PDF	
7	03/02/20 16:11	LOD		Load PDF	
8	24/02/20 12:12	PARF COE REBATE		Load PDF	
9	30/03/20 09:58	DISCHARGE VOUCHER		Load PDF	
10	30/03/20 09:58	AUTHORISATION TO ACT FORM		Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	18/10/19 08:23	Singapore Accident Statement		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III19018351/EGS3Q2

Date: 30/03/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015

Claimant

Vehicle No : SLQ2603R

Insured Vehicle No : SHD3235D

Date of Loss: 09/10/2019

Nature of Claim: TP

Claim No: MCT19100206

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLQ2603R

Make & Model: AUDI A3, 1.8 TFSI (A)

Engine No: CDA091940

Reg. Date: 29/07/2010 (Man. Year: 2010)

Chassis No: TRUZZZ8P1A1007771

Colour: Black

Odometer: 112721 km

Engine Capacity: 1798 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Pirelli 5 mm

Rear Left Side: Pirelli 5 mm

Front Right Side: Pirelli 5 mm

Rear Right Side: Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,845.00	3,397.75	447.25	11.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,140.00	1,130.00	1,010.00	47.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,985.00	4,527.75	1,457.25	24.35
Approved Total (Overridden) (S\$)		3,600.00		
(S\$)	5,985.00	3,600.00	2,385.00	39.85
+ GST 7.00/7.00% (S\$)	418.95	252.00	166.95	39.85
Nett Amount (S\$)	6,403.95	3,852.00	2,551.95	39.85
+ Car Rental (4.0 x S\$120.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,339.45		

INSPECTION

Date of Assignment: 24/10/2019

Date Inspected: 24/10/2019 Inspected At:

VAG SINGAPORE PTE LTD
48 TOH GUAN ROAD EAST #04-123
ENTERPRISE HUB
SINGAPORE 608586

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 03 Feb 2020)	
Parts:	N/A	AUDI A3 1.8 TFSI (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ2603R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Crushed	714.00 F	*714.00 FL
2	1		*COVER UPPER	Necessary	35.00 F	*35.00 FL
3	1		*IMPACT BEAM	Dented	335.00 F	*335.00 FL
4	1		*LOWER SPOILER	Crushed	235.00 F	*235.00 FL
5	1		*STRIKER PLATE	Not Necessary	80.00 F	*- FL
6	1		*DECKLID WEATHERSTRIP	Not Necessary	160.00 F	*- FL
7	1		*REINFORCEMENT APRON (LOWER)	Dented	215.00 F	*215.00 FL
8	1		*PARKING AID SENSOR	Shorted	95.00 F	*95.00 FL
9	1		*CAP FOR SENSOR (REQUIRED)	Necessary	5.00 F	*5.00 FL
10	4		*SEAL RING FOR SENSOR (REQUIRED)	Necessary	8.00 F	*8.00 FL
11	1		*TRUNK LID	Dented	1,200.00 F	*1,200.00 FL
12	1		*A3 BADGE	Necessary	36.00 F	*36.00 FL
13	1		*1.8T BADGE	Necessary	34.00 F	*34.00 FL
14	1		*AUDI LOGO BADGE	Necessary	60.00 F	*60.00 FL
15	1		*REAR APRON (UPPER)	Dented	235.00 F	*235.00 FL
16	1		*INNER REAR TRIM	Broken	312.00 F	*312.00 FL
17	2		*BUMPER LOWER BRACKET	Broken	26.00 F	*26.00 FL
18	1		*SUNDRIES	Necessary	60.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,845.00	3,575.00
- List Item Discount on L Items 0.00/5.00% (\$\$)	0.00	177.25
Total Parts (\$\$)	3,845.00	3,397.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	FOR THE REMOVAL ,TRANSFER AND INSTALLATION OF VARIOUS ASSOCIATED COMPONENTS OF REAR BUMPER ,PARKING AID ,WIRESET ,SEALS	New	650.00	500.00
2	BODY WORK ON STRUCTURE ,SURFACE PREPARATION AND SPRAY PAINT BUMPER ,TRUNK LID ,REINFORCEMENT APRON	New	1,400.00	600.00
3	TO PERFORM COMPLETE DIAGNOSIS OF THE VEHICLE	New	90.00	30.00
Gross Labour Cost (\$\$)			2,140.00	1,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >