



## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 13/12/2019

### Survey Details:

Date of loss	03.10.2019
Date of appointment	17.10.2019
Date of survey	25.11.2019
Location of survey	XIN HUA WORKSHOP PTE LTD

### Vehicle Details:

Claim Type:	Third party
Vehicle number	SLA397H
Make and Model	Chevrolet Sonic (1398cc)
Date of registration	19.02.2016
Excess	NIL
Market Value/ Book Value	\$ 55,000.00 (est)
Parf/COE Rebate	\$ 40,023.00 (est)
Nett Value/ ERV	\$ 14,977.00 (est)

### Repair details:

Initial Estimate	\$ 9,803.60
------------------	-------------

### Proposed/Revised repair cost:

Parts	\$ 2,630.20
Check items (estimate)	NIL
Labour	\$ 800.00
Supplementary	NIL
<b>Total</b>	<b>\$ 3,430.20</b>
<b>Lump Sum(if applicable)</b>	

Number of days for repair	<u>3</u>
---------------------------	----------



**Remarks:**

--

**Mandate:**

Liability(TP)	TBA	
Proposed repair cost	TBA	
Loss of use	TBA	
Loss of rental	TBA	
Loss of income	TBA	
LTA/GIA search fees	TBA	
Others	TBA	
<b>Proposed Total</b>	<b>TBA</b>	