

1542000

INS. CASE OWNER:

Joel. CC 4/EQ1901 8377, Ag 1/22

LKK:  
IDAC:

Surveyor:

DOI:

ASSIGNMENT

Date / Time :

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. :

x B 9881U

Claim No. :

Name of Insured :

VISHNU TOMMAY PILLAI

Policy No. :

DMLOH219-010007

Insured Tel No. :

HP:

Make / Model :

ISUZU

Excess Sec II : \$\$

D.O.A. :

12/10/19

Place of Accident :

PSA BEAM LANE 2

Is driver the owner? ( YES / NO )

( YES / NO )

Nature of Accident :

If NO, Driver Name / Age :

SHARMA GAN RAJANI

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. :

(V/L: YES / NO)

Insured Liability :

\* Final ? Yes / No

5607971P



INSRS:

WSP:

Tel:

Liability:

RMKS:

WHT



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time	STAGE	DATE / PIC
5607971P	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call Of:	
	After call ltr to OI:	
	Documentation Check List: Handler Typist	
	Notification ltr (if non-pickup)	
	After call ltr to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA :	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by: Adrain

Repair Cost: 115 \$8900.00 (16 days) Reduction: \$35,342.00 % 01

FINAL SETTLEMENT Date/Time: Confirm with: Email: Cal:

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No. : NIL

Repair Cost: \$ \$

Loss of Rental (LOR): \$ \$ ( days)

Loss of Use (LOU): \$ \$ (\$ x days)

Loss of Income (LOI): \$ \$ (\$ x days)

LOR only [ ] LOU only [ ] LOR + LOU [ ] LOR + LO [ ] (Tick only one)

GIA/LTA Search \$ \$

Medical: \$ \$

Disbursement: \$ \$ (e.g. Tow/ Independent)

Legal Cost \$ \$

Total: \$ \$ Global Sum \$ \$

FINAL PAYMENT Date/Time: Confirm with: Email: Cal:

Payee 1: \$ \$ Name 1:

Payee 2: (Strike if N.A.) \$ \$ Name 2:

Payee 3: (Strike if N.A.) \$ \$ Name 3:

\$1019.00 880 OSP 12/2/20

ASS. REC. BY

REP:

### ASSIGNMENT

20/07/10.

From \_\_\_\_\_ Date \_\_\_\_\_  
 Estimated Cost \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop n/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: **SKC7711P.** Yr Regn: **2010 / July.**  
 Type:  M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: **Honda CRV** C.C. **1997**  
 Colour: **SILVER.** A/C: **Insured / Std / NI / NA**  
 Sp Reading: **104019.** T/Radio: **Insured / Std / NI / NA**  
 Eng/No: \_\_\_\_\_  
 C/No: **JHLRE2850AC202111**  
 Gen. Cond:  Good / Fair / Poor / Burnt  
 Steering:  In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake:  In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi: **Nil** /  S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: **225/65R17.**  
 R: **225/65R17**

(Policy Condition)  
 Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: **Yes** or No  
 GIA / PR. Seen: \_\_\_\_\_ Consistent?: **Yes** or No  
 Est. Repairs: **16** days Res.: **Yes** or No  
 Lum Sum: **20.** % 3 Val.: **Yes** or No

BS /  SUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_  
 Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. **06** mm R/Bal. **06** mm  
 L/Bal. **06** mm L/Bal. **06** mm  
 D.O.A. \_\_\_\_\_ D.O.I. **17/10/19.**

CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: **IN / OUT**

Survey held at **NHT.**  
 Des. of Damages:  Frt / Rear  O/S /  N/S / UIC / Rooftop or \_\_\_\_\_  
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<b>TP EQ.</b>
	<b>L/S \$8500 / - (NV) (Red = \$35,338.20 / 81%)</b>
	<b>MV : 21K</b>
	<b>PV : 18.5K</b>
	<b>Nett, 8.5K</b>

Date/Time, File Pass to?  : Preli. Report  
 : Final Report

Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  Site Insp (\$)  
 Interview (\$)  
 Tech. Inv (\$)  
 Weekend (\$)

Survey Fee:	<b>170 + 495</b>
Transportation:	<b>50 + 50</b>
S + RS	
Floods:	<b>174.00</b>
Other:	<b>80.00</b>
TOTAL	<b>1019.00</b>

Report Format: \_\_\_\_\_  
 Long Sign / L.B.J: \_\_\_\_\_

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report	16/10/2019 12:34
Date Of Accident	13/10/2019 22:30
Exact Location Of Accident	PSA BRANI GATE 2 CARGO LOADING / UNLOADING
Country/State of Loss	SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKC7711P
<b>Insured/Policyholder</b>	
Name Of Registered Owner	AZMAN BIN MOHD HUSSIN
NRIC No	S7003117E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91900784
Alternative Phone No	OFFICE-91900784

#### Vehicle Particulars

Manufacturer	HONDA
Model	HONDA CRV
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

#### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5103254847
Cover Note Number	

#### Driver

Name of Driver	AZMAN BIN MOHD HUSSIN
NRIC No	S7003117E
Date Of Birth	09/02/1970
Occupation	OUTDOOR
Date Of Driving Pass	27/01/1994
Driving Experience	25 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91900784
Fax Number	
Contact Number	
E Mail Address	NOEMAIL

Address	APT BLK 550 JURONG WEST STREET 42 #12-237
Postcode	640550
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XB9881U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SFH1268A
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reassess policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NIC/PIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My vehicle parked stationary at PSA brani Gate 2 cargo Loading / unloading and the I went to work inside vessel.

Suddenly, my friend came into vessel and told me that veh "B" towed of chassis and roll from ramp and collided onto my vehicle.

I went out and go to the scene to take a look of my vehicle and to understand the situation.

Due to the impact, my vehicle do collided onto veh "C".

DECLARATION

(We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
 Date & Time:

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/PIN No.:





# 新福德車廠私人有限公司

## NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

Blk 1 Kaki Bukit Ave 6  
# 01-43  
Singapore 417883

15/10/2019

TP EQ  
Cecilia

Accident date: 13/10/2019

Estimated repair cost for vehicle no: SKC7711P HONDA CRV 2.0 A '10

CHASSIS: JHLRE2850AC200111

S/n	Qty	Items	U/price	Amount
1	1	Front Bonnet <i>Distorted.</i>		\$721.70 ✓
2	2	Front Bonnet Hinge <i>Bent</i>	\$76.30	\$152.60 ✓
3	1	Front Bonnet Lock <i>send</i>		\$203.60 ✓
4	1	Front Bonnet Inner Rubber <i>new</i>		\$168.40 ✓
5	2	Front Headlamp <i>cracked</i>	\$911.40	\$1,822.80 ✓
6	2	Front Headlamp Lower Bracket <i>RH Bent</i>	\$64.20	<del>\$128.40</del> 64.20 ✓
7	1	Front Grille Top <i>cracked</i>		\$283.10 ✓
8	1	Front Grille Top Chrome <i>new</i>		\$145.90 ✓
9	1	Front Grille Lower <i>new</i>		\$251.00 ✓
10	8	Front Grille Clip <i>new</i>	\$6.50	<del>\$52.00</del> 20 ✓
11	1	Front Grille Emblem Logo <i>new</i>		\$29.40 ✓
12	1	Front Bumper <i>Distorted</i>		\$460.50 ✓
13	1	Front Bumper Lower <i>cracked</i>		\$428.50 ✓
14	10	Front Bumper Clip <i>new</i>	\$6.50	<del>\$65.00</del> 30 ✓
15	2	Front Bumper Side Retainer <i>new</i>	\$33.20	\$66.40 ✓
16	1	Front R/H Bumper Fog Lamp <i>cracked</i>		\$264.20 ✓
17	1	Front Bumper Center Garnish <i>green</i>		\$282.10 ✓
18	1	Front Bumper Number Plate Garnish		\$109.60 ✓
19	1	Front Bumper Reinforcement <i>Bent</i>		\$233.70 ✓
20	1	Front Bumper Top Beam <i>new</i>		\$138.60 ✓
21	2	Front Bumper Side Protector <i>new</i>	\$86.60	\$173.20 ✓
22	2	Front Bumper Sensor <i>new</i>		\$350.00 ✓
23	1	Front Support Panel <i>Bent</i>		\$624.60 ✓
24	1	Front Support Panel Top Cover <i>Distorted</i>		\$233.60 ✓
25	1	Front R/H Chassis <i>Repair</i>		\$629.80 ✓
26	1	Front Wiper Tank <i>Distorted</i>		\$82.50 ✓
27	1	Front Air-con Condenser <i>Bent</i>		\$406.50 ✓
28	1	Front Air-con Condenser Discharge Pipe <i>Bent</i>		\$183.60 ✓



29	1	Front Air-con Condenser Section Pipe	Bent		\$196.90	✓
30	1	Front Radiator	Bent		\$1,583.50	✓
31	1	Front Radiator Fan Motor	NEW		\$301.80	+
32	1	Front Alternator	NEW		\$1,668.70	+
33	1	Front Air-con Compressor	NEW		\$1,296.80	+
34	1	Front R/H Fender	Distorted		\$615.90	✓
35	1	Front R/H Fender Protector	Deland		\$215.90	✓
36	8	Front R/H Fender Protector Clip	NEW	\$6.50	\$520.00	20
37	1	Front R/H Fender Cowling	torn		\$108.60	✓
38	8	Front R/H Fender Cowling Clip	NEW	\$6.50	\$520.00	30
39	1	Front R/H Fender Inner Panel	Distorted		\$481.80	✓
40	1	Front R/H Lower Arm	Bent		\$505.40	✓
41	1	Front R/H Knuckle Arm	Bent		\$320.80	✓
42	1	Front R/H Knuckle Arm Bearing	NEW		\$231.20	✓
43	1	Front R/H Shock Absorber	Bent		\$374.60	✓
44	1	Front R/H Drive Shaft	NEW		\$986.00	+
45	1	Front Steering Rack			\$1,879.20	+
46	1	Front R/H Side Mirror Assy	NEW		\$548.20	+
47	1	Front R/H Door	Distorted		\$1,037.50	✓
48	2	Front R/H Door Hinge	NEW	\$87.50	\$175.00	+
49	1	Front R/H Door Chrome Moulding	NEW		\$108.20	+
50	1	Front R/H Door Lower Protector	Deland		\$182.80	✓
51	6	Front R/H Door Lower Protector Clip	NEW	\$6.50	\$39.00	✓
52	1	Front R/H Door Lock	Deland		\$301.90	✓
53	1	Front R/H Door Weatherstrip	cut		\$155.00	✓
54	1	Front R/H Door Inner Trim Board	curled		\$451.80	✓
55	1	Front R/H Door Window Motor & Regulator Assy	NEW		\$441.40	+
56	1	Front R/H Door Frame Sticker	NEW		\$28.60	✓
57	1	Front L/H Door	Dented		\$1,037.50	✓
58	2	Front L/H Door Hinge	NEW	\$87.50	\$175.00	+
59	1	Front L/H Door Chrome Moulding	NEW		\$108.20	+
60	1	Front L/H Door Lower Protector	Deland		\$182.80	✓
61	6	Front L/H Door Lower Protector Clip	NEW	\$6.50	\$39.00	20
62	1	Front L/H Door Lock	NEW		\$301.90	+
63	1	Front L/H Door Weatherstrip	NEW		\$155.00	+
64	1	Front L/H Door Inner Trim Board	NEW		\$451.80	+
65	1	Front L/H Door Window Motor & Regular Assy	NEW		\$441.40	+
66	1	Front L/H Door Frame Sticker	NEW		\$28.60	+
67	1	L/H Step Panel Garnish	Deland		\$591.20	✓
68	10	L/H Step Panel Garnish Clip	NEW	\$6.50	\$65.00	30
69	1	R/H Step Panel Garnish	Deland		\$591.20	+
70	10	R/H Step Panel Garnish Clip	NEW	\$6.50	\$65.00	+
71	1	Rear L/H Door	Ripe		\$1,037.50	+

72	2	Rear L/H Door Hinge	Net	\$87.50	\$175.00	+
73	1	Rear L/H Door Chrome Moulding	Net		\$108.20	+
74	1	Rear L/H Door Lower Protector	Net		\$182.80	+
75	6	Rear L/H Door Lower Protector Clip	Net	\$6.50	\$39.00	+
76	1	Rear L/H Door Lock	Net		\$301.90	+
77	1	Rear L/H Door Weatherstrip	Net		\$155.00	+
78	1	Rear L/H Door Inner Trim Board	Net		\$451.80	+
79	1	Rear L/H Door Window Motor & Regulator Assy	Net		\$441.40	+
80	2	Rear L/H Door Frame Sticker	Net	<del>\$28.60</del> 14.30	\$28.60	+
81	1	Rear L/H Rim	Net		\$850.00	+
82	1	Rear L/H Tyre	Net		\$380.00	+
88	1	Rear R/H Fender	distorted		\$1,203.60	✓
89	1	Rear R/H Fender Inner Panel	Net		\$1,086.40	+
90	1	Rear R/H Fender Protector	cut		\$97.40	✓
91	8	Rear R/H Fender Protector Clip	Net	\$6.50	\$52.00	20
92	1	Rear R/H Fender Glass Assy	Net		\$368.40	+
93	1	Rear R/H Taillamp	cut		\$453.60	✓
94	1	Rear Bumper	delivered		\$596.40	✓
95	10	Rear Bumper Clip	Net	\$6.50	\$65.00	30
96	1	Rear Bumper Reverse Sensor (Special Nett)	Net		\$350.00	+
97	1	Rear R/H Bumper Side Retainer	Net		\$30.80	✓
98	1	Rear R/H Bumper Side Cover	distorted		\$153.10	✓
99	1	Rear R/H Bumper Mud Flap	delivered		\$44.90	✓

Subtotal :- \$35,918.20

17684

14147.20

**Labour charges**

To remove & refit cushion & trim board	<del>\$380.00</del> 60
To remove & refit air-con condenser, radiator, fan motor, air-con compressor, alternator, pipes & top up gas	<del>\$680.00</del> 250
To remove & refit front sensor	<del>\$100.00</del> 50
To remove & refit reverse sensor	<del>\$100.00</del> 50
To remove & refit front R/H door, lock, rubber, glass, trim board & <del>gear box assy</del>	<del>\$280.00</del> 80
To remove & refit front L/H door, lock, rubber, glass, trim board & <del>gear box assy</del>	<del>\$280.00</del> 80
To remove & refit rear R/H fender glass	<del>\$120.00</del> 60
Gum	<del>\$50.00</del> 30
To remove & refit front R/H undercarriage	<del>\$480.00</del> 270
To check wheel alignment	<del>\$150.00</del> 80
To check wiring	<del>\$150.00</del> 60
Towing fee	<del>\$150.00</del> 120
Tuff kote	4640 <del>\$200.00</del> 100
Panel beating	<del>\$2,400.00</del> 1800
Spray painting	<del>\$2,400.00</del> 1600

Subtotal :- \$7,920.00

Total:- \$43,838.20

total: 18747.20.  
 1/5: 75K (Nett Value)  
 16 Days  
 B.S.K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: