

ASS. REC. BY:

REF:

CS31MSG19018400/MC-00

Special Instruction:

Surveyor: Tan Siah

**ASSIGNMENT (Office)**

Winn

From (Person):

Christina Wong

of

MS19

Date/Time:

17.10.19 17.21pm

Estimated Cost:

Bill to:

**OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS**

To Inspect Vehicle No:

SMN 4681E

Insured:

GBC 3867G

at Workshop m/s

28 Auto Werkz

Tel:

93628159

of

BK 100r Bukit merah Lane 3 #01-83

Policy No:

28864950MFC

Claim No:

608692

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

15.10.2019

CA / REV / REP. / REV 24 HRS

*mp*

H.O.D. Endorsement:

Date/Time:

18.10.19 9.46am

Person Contacted:

Roger

Vehicle

IN/OUT

Date/Time

Action/Instruction ( X ) Estimate

GBC 3867G - NBA/INC19018204/Y D.O.A: 15/10/2019

SMN 4681E - NBA/INC19018204/Y D.O.A: 15/10/2019

Dismantle: 18/10/2019

ASS. REC. BY: Tanpha

REF: MS19

PRS

ASSIGNMENT

CoE 2019 Dec

From: \_\_\_\_\_ Date: 12.10.2019

Veh No: SMN 4681E Yr Regn: 20091 Dle

Estimated Cost: \_\_\_\_\_

Type:  M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: SMN 4681E

Make: Honda Civic 1.8 c.c. 1799

at Workshop m/s 28 Auto workz

Colour: Blue A/C: Insured / Std / NI / NA

of BK 102 Bukit Merah Lane 3 #01-83

Sp. Reading: 134339 T/Radio: Insured / Std / NI / NA

Insured: \_\_\_\_\_

Eng/No: \_\_\_\_\_

Policy No. \_\_\_\_\_

C/No: JAMF17/6309 S203260

Claims No. \_\_\_\_\_

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh: \_\_\_\_\_

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size: F: 205/55R16

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

R: 1 -

BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value: \$18K

Front R/Bal. 6 mm Rear R/Bal. 6 mm

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

L/Bal. 6 mm L/Bal. 6 mm

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

D.O.A. \_\_\_\_\_ D.O.I. 18/10/19 (149)

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Survey held at 28 Auto

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

CA / REV / REP. / 24 HRS up

The U/C / Chassis frame / Body Structure affected due to collision.

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Date / Time	Action / Instruction
	<u>\$3000 - \$4000, 5 days</u>
	<u>RECEIVED 14 NOV 2019</u>

Date/Time, File Pass to?  Preli. Report

Days Of Repair: 5

1) \_\_\_\_\_  Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to? \_\_\_\_\_

Add Fee:  Site Insp (\$ \_\_\_\_\_)

Survey Fee:	<u>120</u>
Transportation:	_____ \$ + RS. _____ \$
Photos:	_____
Others:	<u>11</u>
TOTAL:	<u>131</u>

2) \_\_\_\_\_

Interview (\$ \_\_\_\_\_)

Rep. Format: PRE

Tech. Invs (\$ \_\_\_\_\_)

Lump Sum / L.B.D. / % \_\_\_\_\_

Weekend (\$ \_\_\_\_\_)

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Oct 2019		17 Oct 2019 17:21 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		[Created by insurer]							
Insured:	KK WOMEN'S AND CHILDREN'S HOSPITAL PTE LTD, Co. Reg. No.: 198904227G, Tel: +6593677490, Email: ERIC.TAN.CH@KKH.COM.SG								
Main Claimant:	SRS AUTO HOLDINGS PTE. LTD., Co. Reg. No.: 201709236H								
Vehicle Reg. No.:	SMN4681E	Date of Loss:	15/10/2019 07:00 - :59 [117 Months and 29 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 608692	Policy/Cover Note No.:	28864950MKC (Comprehensive) Coverage: 01/12/2018 - 30/11/2019						
Vehicle Reg. No. (Insured):	GBC3867G	Policy No. (Claimant):	Excess: S\$500.00						
Repairer:	28 Auto Werkz Pte Ltd (HQ) Blk 1002 Bukit Merah Lane 3, #01-83, 159719 Bukit Merah - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 18/10/2019]								
Driver/Custodian (Insured):	MOHAMED SULEMAN MOHD ASHRAF (58 / Male), NRIC: S1485609I, Tel: +6596731037 Email:								
Adj Asg. Remarks:	on WP. Liab: unclear. Disagree on SJE. Contact: Mr Roger @ 9362 8159.								
<b>ASSOCIATED MAIL RECEIVED</b>		View All   Compose Case Mail							
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>		View All   Search Tasks   Create New Task   Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	236H
<b>Vehicle Details</b>	
Vehicle No.:	SMN4681E
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Oct 2019
Vehicle Make:	HONDA
Vehicle Model:	HONDA CIVIC 1.8L 5AT
Primary Colour:	Brown
Manufacturing Year:	2009
Engine No.:	R18A14016779
Chassis No.:	JHMFD16309S203260
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$26,099.00
Original Registration Date:	16 Dec 2009
First Registration Date:	16 Dec 2009
Transfer Count:	1
Actual ARF Paid:	\$26,099.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Dec 2019
PARF Rebate Amount:	\$13,049.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	15 Dec 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$19,003.00
COE Rebate Amount:	\$282.00
<b>Total Rebate Amount:</b>	<b>\$13,331.00</b>

The information contained herein is correct as at 21 Oct 2019

OK

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report	15/10/2019 16:55
Date Of Accident	15/10/2019 07:25
Exact Location Of Accident	ALONG KG JAVA RD OUTSIDE TANGLIN POLICE STATION
Country/State of Loss	SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMN4681E
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SRS AUTO HOLDINGS PTE. LTD.
Co Reg No	201709236H
Email Address	NICHOLAS76@YAHOO.COM
Mobile Phone No	(LOCAL) +65-93807188
Alternative Phone No	OFFICE-93807188

#### Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC
Exact Purpose for which vehicle was being used at time of accident	WORKING PURPOSES
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

#### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5108747945
Cover Note Number	

#### Driver

Name of Driver	NEO CHIN GUAN NICHOLAS (LIANG ZHENYUAN)
NRIC No	S7600477C
Date Of Birth	03/01/1976
Occupation	OUTDOOR
Date Of Driving Pass	12/01/1998
Driving Experience	21 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93807188
Fax Number	
Contact Number	OTHERS-93807188
EEmail Address	NICHOLAS76@YAHOO.COM

Address	BLK 152 SERANGOON NORTH AVENUE 1 #3-352
Postcode	550152
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	SERANGOON NEIGHBOURHOOD POLICE CENTRE
Police Station Address	<b>ROAD:</b> 50 SERANGOON AVE 2 #01-02 , <b>POSTCODE:</b> 556129 , <b>COUNTRY:</b> SINGAPORE
Police Station Contact	<b>TEL NO:</b> 1800-4880999 - <b>FAX NO:</b> 64883561
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO POLICE REPORT T/20191015/2031

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC3867G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name	NEO CHIN GUAN NICHOLAS (LIANG ZHENYUAN)
Approximate Age	
Injuries Sustain	SLIGHT INJURY
Injured person in which vehicle?	SMN4681E
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers; you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

*[Handwritten Signature]*  
15/10/19


Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*[Handwritten Signature]*  
15/10/19

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

*police report to police 1/10/19*

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Policyholder Signature  
Date & Time:

*[Signature]* 15/10/19  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*[Signature]* 15/10/2019  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

POLICE REPORT



**SINGAPORE  
POLICE FORCE**



T/20191015/2031

Police Station Of Origin:  
Serangoon N.P.C  
50 Serangoon Avenue 2 #01-02 SINGAPORE  
556129  
Tel No: 1800-4880999

1 of 3

Report No. T/20191015/2031

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 15/10/2019 11:01	Video Report No.: E/20191015/0038	Station Diary No.: 38
--	--------------------------------------	--------------------------

Informant's Particulars			
Name of Informant: NEO CHIN GUAN NICHOLAS		Address: APT BLK 152 SERANGOON NORTH AVENUE 1 #03-352 SINGAPORE 550152	
ID Type / ID No.: NRIC NO / S7600477C		Contact No.: Home/Office: Mobile: 93807188	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 43	Date of Birth: 03/01/1976	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: GRAB DRIVER		Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 15/10/2019 07:25	Type of Location:
Location: Along Road 1 KAMPONG JAVA ROAD towards Thomson Road				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBC3867G	Van	CITROEN		White		0
SMN4681E	Car	HONDA	CIVIC	Brown	Slightly Damaged	0

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SMN4681E	NTUC Income Insurance Co-Operative Limited	5108747945-000053	16/08/2019	15/08/2020

POLICE REPORT



**SINGAPORE  
POLICE FORCE**



T/20191015/2031

2 of 3

Report No. T/20191015/2031

Police Station Of Origin:  
Serangoon N.P.C  
50 Serangoon Avenue 2 #01-02 SINGAPORE  
556129  
Tel No: 1800-4880999

CONTINUATION OF REPORT

<b>Details of Person Involved</b>			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Driver</b>			
Name	NEO CHIN GUAN NICHOLAS	ID No.	S7600477C
Related Vehicle	SMN4681E (Car)	Contact No.	93807188
Hospital/Clinic	LIFELINK SN CLINIC & SURGERY	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	15/10/2019	Date Discharge	15/10/2019
No. of Days granted Medical Leave	03	Degree of Injury	Slight

**Brief Details.**

On 15 10 2019 I was driving a brown Honda Civic SMN4681E. At about 0725hrs after dropping off a passenger at Kandang Kerbau Hospital, I was driving out of the hospital premise to join the main road. I was at the extreme left lane. While waiting to join the main stream on my right was a white KKH van. I then drove out and join the main road still maintaining at the left most lane. However the van driver horned at me. I then gestured at him ask what was wrong. Suddenly he drove right into my lane and hit the front right corner of my vehicle causing an impact to my vehicle. We then got off our vehicles and the other driver started to scold me. He then asked me why I scolded him first. He then hurled some vulgarities at me and I told him to mind his words and that I will call the police. Just then he saw that my car was damaged, he immediately kept quiet. I asked for his particulars but he then just walked away and drove off. I do not have any onboard camera in my car. However this incident happened just outside Tanglin Police Station, I am sure there are CCTV around there. Due to the accident, my car's front right bumper was dislodged from its original position. I called for the police and the traffic police attended to me. I was then advised to lodge an accident report with ref to E/20191015/0038 in charge case IO Ivan, tel: 65476170.

Due to the accident, I sustained a sprained neck and muscle sprain on my back. I then went to seek medical attention at Lifelink SN Clinic & Surgery and I was given 3 days of mc.

POLICE REPORT



SINGAPORE  
POLICE FORCE



T/20191015/2031

Police Station Of Origin:  
Serangoon N.P.C  
50 Serangoon Avenue 2 #01-02 SINGAPORE  
556129  
Tel No: 1800-4880999

3 of 3



Report No. T/20191015/2031

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / Sgt 2 EDWIN CHAU YEW FEI 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 15/10/2019 11:01
Officer in Charge Of Case: TP / GIT / Staff Sgt SUFIYAN BIN KHAIRI Contact No.: 65476390	Classification Of Case: SN 154
Authentication Stamp NP168	



Signature:

Singapore Police Force

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Oct 2019		17 Oct 2019 17:21 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	KK WOMEN'S AND CHILDREN'S HOSPITAL PTE LTD, Co. Reg. No.: 198904227G, Tel: +6593677490, Email: ERIC.TAN.CH@KKH.COM.SG								
Main Claimant:	SRS AUTO HOLDINGS PTE. LTD., Co. Reg. No.: 201709236H								
Vehicle Reg. No.:	SMN4681E	Date of Loss:	15/10/2019 07:00 - :59 [117 Months and 29 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 608692	Policy/Cover Note No.:	28864950MKC (Comprehensive) Coverage: 01/12/2018 - 30/11/2019						
Vehicle Reg. No. (Insured):	GBC3867G	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	28 Auto Werkz Pte Ltd (HQ) Blk 1002 Bukit Merah Lane 3, #01-83, 159719 Bukit Merah - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Imm.Advice due 18/10/2019]								
Driver/Custodian (Insured):	MOHAMED SULEMAN MOHD ASHRAF (58 / Male) , NRIC: S1485609I, Tel: +6596731037 Email:								
Adj Asg. Remarks:	on WP. Liab: unclear. Disagree on SJE. Contact: Mr Roger @ 9362 8159.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SMN4681E (608692)  
[GBC3867G]

TP

SRS AUTO HOLDINGS PTE. LTD.

Oct 15 2019 7:00AM

[KK WOMEN'S AND CHILDREN'S HOSPITAL PTE LTD]

28 Auto Werkz Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View	View in Browser	
<b>Assessment Reports</b>							1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)				Thumbnail	Print	
1	17/10/19 13:39	<b>Accident Statement</b> From:SC - Reg. No: GBC3867G, Claimant: KK WOMEN'S AND CHILDREN'S HOSPITAL PTE LTD					Load HTM	
<b>Photos/Images</b>							3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print	
1	24/10/19 12:58	General View					Load JPG	<input checked="" type="checkbox"/>
2	24/10/19 12:58	General View					Load JPG	<input checked="" type="checkbox"/>
3	24/10/19 12:58	General View					Load JPG	<input checked="" type="checkbox"/>
4	24/10/19 12:58	General View					Load JPG	<input checked="" type="checkbox"/>
5	24/10/19 12:58	General View					Load JPG	<input checked="" type="checkbox"/>
6	24/10/19 12:58	General View					Load JPG	<input checked="" type="checkbox"/>
7	24/10/19 12:58	General View					Load JPG	<input checked="" type="checkbox"/>
8	24/10/19 12:58	General View					Load JPG	<input checked="" type="checkbox"/>
9	24/10/19 12:58	General View					Load JPG	<input checked="" type="checkbox"/>
10	24/10/19 12:58	General View					Load JPG	<input checked="" type="checkbox"/>
11	24/10/19 12:58	General View					Load JPG	<input checked="" type="checkbox"/>
12	24/10/19 12:58	General View					Load JPG	<input checked="" type="checkbox"/>
13	24/10/19 12:58	General View					Load JPG	<input checked="" type="checkbox"/>
14	24/10/19 12:58	General View					Load JPG	<input checked="" type="checkbox"/>
15	24/10/19 12:58	General View					Load JPG	<input checked="" type="checkbox"/>
16	24/10/19 12:58	General View					Load JPG	<input checked="" type="checkbox"/>
17	24/10/19 12:58	Photographs of Damaged Parts					Load JPG	<input checked="" type="checkbox"/>
18	24/10/19 12:58	Photographs of Damaged Parts					Load JPG	<input checked="" type="checkbox"/>
19	24/10/19 12:58	Photographs of Damaged Parts					Load JPG	<input checked="" type="checkbox"/>
20	24/10/19 12:58	Photographs of Damaged Parts					Load JPG	<input checked="" type="checkbox"/>
21	24/10/19 12:58	Photographs of Damaged Parts					Load JPG	<input checked="" type="checkbox"/>
22	24/10/19 12:58	Photographs of Damaged Parts					Load JPG	<input checked="" type="checkbox"/>
23	24/10/19 12:58	Photographs of Damaged Parts					Load JPG	<input checked="" type="checkbox"/>
24	24/10/19 12:58	Photographs of Damaged Parts					Load JPG	<input checked="" type="checkbox"/>
25	24/10/19 12:58	Photographs of Damaged Parts					Load JPG	<input checked="" type="checkbox"/>
26	24/10/19 12:58	Photographs of Damaged Parts					Load JPG	<input checked="" type="checkbox"/>
27	24/10/19 12:58	Photographs of Damaged Parts					Load JPG	<input checked="" type="checkbox"/>
28	24/10/19 12:58	Photographs of Damaged Parts					Load JPG	<input checked="" type="checkbox"/>
29	24/10/19 12:58	Photographs of Damaged Parts					Load JPG	<input checked="" type="checkbox"/>
30	24/10/19 12:58	Photographs of Damaged Parts					Load JPG	<input checked="" type="checkbox"/>
31	24/10/19 12:58	Photographs of Damaged Parts					Load JPG	<input checked="" type="checkbox"/>
32	24/10/19 12:58	Photographs of Damaged Parts					Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>							1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)				Thumbnail	Print	
1	17/10/19 13:39	<b>TPD SMN4681E GIA REPORT</b> From:SC - Reg. No: GBC3867G, Claimant: KK WOMEN'S AND CHILDREN'S HOSPITAL PTE LTD					Load PDF	
2	17/10/19 13:40	<b>TPD SMN4681E - PRI</b>					Load PDF	
3	17/10/19 14:02	<b>Workshop Details</b>					Load PDF	
4	17/10/19 14:02	<b>Disagree on SJE</b>					Load PDF	

### Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<a href="#">Reset</a>	<a href="#">Save</a>	<a href="#">Print</a>
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/MSG19018400/T1CF3E2

**Date:** 14/11/2019

#### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28864950MKC

**Claimant**  
**Vehicle No :** SMN4681E

**Insured Vehicle No :** GBC3867G

Date of Loss: 15/10/2019

Nature of Claim: TP

Claim No: 608692

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMN4681E**

Make & Model: HONDA CIVIC, 1.8 L 5AT (A)

Engine No: R18A14016779

Reg. Date: 16/12/2009 (Man. Year: 2009)

Chassis No: JHMFD16309S203260

Colour: Bronze

Odometer: 134339 km

Engine Capacity: 1799 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

#### INSPECTION

Date of Assignment: 17/10/2019

Date Inspected: 18/10/2019 Inspected At:

28 Auto Werkz Pte Ltd (HQ)  
Blk 1002 Bukit Merah Lane 3, #01-83  
Singapore 159719

Estimated Period of Repair: 5.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 -\$4,000.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 14 Nov 2019)
<b>Parts:</b> 143	HONDA CIVIC 1.8 L 5AT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMN4681E)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >