

Winan

21032002

ASS. REC. BY:

REP:

CS/SMD19018+24/12/13 172

Special Instruction:

Surveyor: Marius

ASSIGNMENT (Office)

From (Person): Agnes Chan Shu Hui of SMD

Date/Time: 18.10.19 14.18p.m

Photo O.K

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKA 8937J

Insured: SLN 4807K

at Workshop n/s Zoom Auto works

Tel: 94567920

of 150 Berlok Reservoir Road

Policy No: Digmi Pro1007256

Claim No: (MT1) 1904912

Sum Insured: _____

Excess: _____

Make of Veh:
(or Bent's Record)

D.O.A. 17.10.2019

CA / REV / REP. / REV 24 HRS

"ny"

H.O.D Endorsement: _____

Date/Time: 18.10.19 238p.m Person Contacted: Elin

Vehicle IN / OUT

Date/Time: _____ Action/Instruction (✓) Estimate Inspection - Blk 15 Kapi Bukit Road 4 #01-53

SLN 4807K: X

SKA 8937J: X

23/10 Sent Preli to Insurance Co (Pending Estimate) Meimam

10001113 wef
ASS. REC. BY: Marcus

REF:

SMO/

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OT / TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: SKA 8937J
at Workshop m/a Zoom
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

Veh No: SKA 8937J Yr Regn: 13/4/11
Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or A /
Make: KIA cerato forte c.c 1591
Colour: 3mr A/C: Insured / Std / NI / NA
Sp. Reading: 257563 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: KNAFW411MA5268656
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt - affected
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / STD A/Rim or
Tyre Size: F: 215/45 2R17
R: _____

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: € 20500
IDAC Accident Rpt: _____ Consistent?: Yes or No
GIA / PR Seen: _____ Consistent?: Yes or No
Est. Repairs: 6 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: 47A 13538
Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or radgr
Front: _____ Rear: _____
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 17/10/19 D.O.A. 18/10/19
Survey held at: _____
Des. of Damages: Frt / Rear / O/S / N/S / WC / Rooftop or
The Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
02/12/2011 1/5 Sml. Dep 96. nett 6962
31/10/19 2/5 € 6000 confid with Elin (Red \$7944.43, 56%)
5/11/19 Sant Preli by Meimer
RECEIVED 06 NOV 2019

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair: 6
Resurvey No. of Trip: 2

Survey Fee	350
Transportation:	11
Other:	
TOTAL	361

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Report Format :
 Lump Sum / B.I. (\$ 6000 =)

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: CHAN SHU HUI AGNES

Date: 05 Nov 2019

Preliminary Advice

Insured Vehicle No	: SLN4802K	Accident Date	: 17/10/2019
TP Vehicle No	: SKA8937J	Assignment Date	: 18/10/2019
Make	:	Est. Duration of Repair	: 6.00
Date of Inspection	: 18/10/2019		
Inspection At	: ZOOM AUTOWERKS PTE LTD (HQ) 130 BEDOK RESERVOIR ROAD, EUNOS SPRING, #08-1339 SINGAPORE 470130		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s.front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,944.43
Revised Amount	:S\$	6,016.75 (Lump sum)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,016.75
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :The above survey was conducted on a without "prejudice" basis

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Oct 2019		18 Oct 2019 14:18 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:	CHOO RUO HAN, ID: S1578555A								
Main Claimant:	GOH LIAN SOON GILBERT, ID: S7733372Z								
Vehicle Reg. No.:	SKA8937J	Date of Loss:	17/10/2019 23:00 - :59						
Claim Type:	TP / CMTD1904912	Policy/Cover Note No.:	D19MTPV01007256 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLN4802K	Policy No. (Claimant):							
		Excess:							
Repairer:	Zoom Autowerks Pte Ltd (HQ) 130 Bedok Reservoir Road, Eunos Spring, #08-1339, 470130 Bedok - Tel: 94507920								
Handling Insurer:	Sampo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/10/2019]								
Adj Asg. Remarks:	Please conduct survey on a without prejudice basis								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Sent Message

This mail is associated with :

***SKA8937J (CMTD1904912)
[SLN4802K]**

TP
GOH LIAN SOON GILBERT
Oct 17 2019 11:00PM
[CHOO RUO HAN]
Zoom Autowerks Pte Ltd

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 23/10/2019 15:37 PM.
To agnes.chan@sompo.com.sg
CC sur@lkkauto.com
Subject SKA8937J (CMTD1904912) SLN4802K

Dear Agnes Chan

Please be informed that we have inspected the vehicle SKA8937J on 18/10/2019.

We are still pending estimate from repairer.

Thank you

Regards
Yvonne Wong
LKK Auto Consultants Pte Ltd

DOCUMENTS SUMMARY

There are no documents.

CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)

kia cerato

Price Range ▾

Depreciation ▾

2011 ▾

Vehicle Type ▾


[Home](#) » [Used Cars](#) » [Direct Owners](#) » [Kia Cerato Forte 1.6A SX](#)

Kia Cerato Forte 1.6A SX

[Overview](#)
[Financial](#)
[Insurance](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)

Price	\$20,000		
Depreciation	\$9,920 /yr View models with similar depre	Reg Date	15-Feb-2011 (1yr 3mths 24days COE left)
Mileage	102,800 km (11.8k /yr)	Manufactured	2010
Road Tax	\$738 /yr	Transmission	Auto
Dereg Value	\$12,487 as of today (change)	OMV	\$13,791
COE	\$37,124	ARF	\$13,791
Engine Cap	1,591 cc	Power	91.1 kW (122 bhp)
Curb Weight	1,261 kg	No. of Owners	1
Type of Vehicle	Mid-Sized Sedan		

Features

Responsive 1.6L DOHC Engine, Auto Transmission Gearbox, ABS, SRS Airbags, Auto Climatic Aircon Controls, Steering Control, Reverse Sensors. [View specs of the Kia Cerato Forte \(2009-2013\)](#)

Accessories

17" Sports Rims, Leather Seats, Factory Fitted Audio System, Paddle Shift, Keyless Switch Start, Side Mirrors With Indicators, Reverse Sensors, Solar Film

Description

New Paintwork, New 6 Months Road Tax Till Feb 2020, 4 x New Types, Full Bodykits, High Specification SX Model! Push Start Button, Keyless Sporty Outlook, Popular White Colour, Optional For Short Entry, Term Drive Or COE Renewal Later, Smooth Engine And Responsive Gearbox Transmission, Trade In/Loan Available, Door Step Viewing Provided, A Unit That Will Not Disappoint You, Call Now!

Category


PARF Car, Direct Owner Sale

Status


Availabl

[Compare](#)


100% FREE
PAPERWORK
SUPPORT FOR
BOTH BUYER
& SELLER

[Price Chart](#)


Click on the point to view the vehic



kia cerato

Price Range

Depreciation

2011

Vehicle Type



Home » Used Cars » ABWIN (1994) Pte Ltd » Kia Cerato Forte 1.6A SX

Kia Cerato Forte 1.6A SX

[Overview](#)

[Financial](#)

[Insurance](#)

[Accessories](#)

[Similar](#)

[Research](#)

[Photos](#)

[Map](#)

ABWIN

YOUR FIRST CHOICE AUTOMOTIVE SERVICE PROVIDER

PREMIUM DEALER

Price \$22,800

Depreciation \$10,580 /yr
[View models with similar depre](#)

Reg Date 12-May-2011
(1yr 6mths 20days COE left)

Mileage N.A.

Manufactured 2010

Road Tax \$738 /yr

Transmission Auto

Dereg Value \$13,935 as of today [\(change\)](#)

OMV \$12,663

COE \$44,790

ARF \$12,663

Engine Cap 1,591 cc

Power 92.7 kW (124 bhp)

Curb Weight 1,251 kg

No. of Owners 1

Type of Vehicle Mid-Sized Sedan

Features

1.6L DOHC Engine (122Bhp), 4 Speed Auto Transmission With Paddle Shifters, SRS Airbags, ABS And Etc. [View specs of the Kia Cerato Forte \(2009-2013\)](#)

Accessories

New Paintwork, Original Sports Rims, New Leather Seat, Parking Sensors And Etc. Push Start Button.

Description

High Loan Available! Low Interest Rate, Like New Condition. View To Believe! Please Call Now!

Category

PARF Car, Premium Ad Car


Status

Av. [Compare](#)



Location Map

Price Chart



Click on the point to view the veh

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	372Z
Vehicle Details	
Vehicle No.:	SKA8937J
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Oct 2019
Vehicle Make:	KIA
Vehicle Model:	CERATO FORTE 1.6SX AT ABS D/AB 2WD 4DR
Primary Colour:	Blue
Manufacturing Year:	2010
Engine No.:	G4FCAH217001
Chassis No.:	KNAFW411MA5268656
Maximum Power Output:	92.7 kW (124 bhp)
Open Market Value:	\$13,013.00
Original Registration Date:	13 Apr 2011
First Registration Date:	13 Apr 2011
Transfer Count:	2
Actual ARF Paid:	\$13,013.00 <i>6576</i>
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Apr 2021
PARF Rebate Amount:	\$7,157.00
Intended COE Rebate Details	
COE Expiry Date:	12 Apr 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$41,479.00
COE Rebate Amount:	\$6,381.00
Total Rebate Amount:	\$13,538.00

The information contained herein is correct as at 21 Oct 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/10/2019 16:42
Date Of Accident	17/10/2019 23:10
Exact Location Of Accident	JUNC PETAIN RD & STURDEE RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKA8937J
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	GOH LIAN SOON GILBERT (WU LIANSHUN GILBERT)
NRIC No	S7733372Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-88007701
Alternative Phone No	OFFICE-88007701

Vehicle Particulars

Manufacturer	KIA
Model	CERATO FORTE 1.6SX AT ABS D/AB 2WD 4DR
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5101296052-01
Cover Note Number	

Driver

Name of Driver	GOH LIAN SOON GILBERT (WU LIANSHUN GILBERT)
NRIC No	S7733372Z
Date Of Birth	11/11/1977
Occupation	INDOOR
Date Of Driving Pass	02/10/2017
Driving Experience	2 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88007701
Fax Number	
Contact Number	OFFICE-88007701
EEmail Address	NOEMAIL

Address	BLK 433B SENGKANG WEST WAY #12-537
Postcode	792433
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLN4802K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1 Please report **correctly** the details of the accident to speed up the claims process.
- 2 This form must be **completed by the Policyholder and/or the Authorised Driver**.
- 3 Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repeal policy liability**.
- 4 The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 **Any false reporting may be referred to the Police for investigation.**
- 6 The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7 By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8 **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers", the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) All insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time



Driver's Signature
(If driver is not the policyholder)
Date & Time




Reporting Centre Personnel's Signature
Name:
NRIC/TIN No.:

Accident Sketch Plan

SKETCH PLAN

Vehicle A: SKA 8937J

Vehicle B: SLN4802K




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on the stated date & time, I, vehicle A;
SKA 8937J, was travelling straight along the stated venue.
Suddenly, vehicle B, SLN4802K, came out of Sturdee Road
and collided onto my vehicle's front right portion.

DECLARATION

(We declare the foregoing particulars are true in every respect)


Policyholder's Signature
Date & Time


Driver's Signature
(If driver is not the policyholder)
Date & Time


Reporting Centre Personnel's Signature
Name
AMC/IN No.



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
 #08-1339 Singapore 470130
 Tel: 9450 7920
 * zoomautowerks@gmail.com

18 October 2019

ACCIDENT DATE : 17 OCTOBER 2019
 OWNER : GOH LIAN SOON GILBERT

1/5 \$6000 = 6 day
not authorized
18/10/19
take the attention

REG NO. : SKA 8937 J
 MAKE/MODEL : KIA CERATO

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	<u>LIST ITEMS</u>	
1	Front bonnet <i>765.20</i>	\$ <i>3uc</i> 778.80
2	Front bonnet hinges	\$ <i>See</i> 115.00 X
1	Front bonnet lock	\$ <i>See</i> 126.50 X
1	Front bonnet rubber -front	\$ <i>See</i> 38.50
1	Front bonnet rubber -rear	\$ <i>See</i> 42.50
1	Front headlamp <i>o/s 520.50</i>	\$ <i>See</i> 653.50
1	Front headlamp lower bracket <i>o/s 85.00</i>	\$ <i>See</i> 78.60
1	Front headlamp side garnish	\$ <i>17</i> 45.20 X
1	Front grille	\$ <i>See</i> 320.00
1	Front grille logo	\$ <i>17</i> 42.50 X
1	Front bumper <i>545.30</i>	\$ <i>D.S</i> 588.60
1	Front bumper clip (1 set) <i>45.00</i>	\$ <i>See</i> 55.00
1	Front bumper fog lamp <i>o/s 245.00</i>	\$ <i>See</i> 286.90
1	Front bumper fog lamp grille <i>o/s</i>	\$ <i>See</i> 85.00
1	Front bumper inner sponge	\$ <i>See</i> 123.60
1	Front bumper reinforcement <i>345.60</i>	\$ <i>See</i> 396.50
2	Front bumper side retainers <i>38.00</i>	\$ <i>o/s See</i> 85.00 (pc)
1	Front fender -R/H	\$ <i>See</i> 522.50
1	Front fender inner shield	\$ <i>See</i> 86.90
1	Front support panel <i>725.20</i>	\$ <i>See</i> 796.80
1	Front door -R/H	\$ <i>See</i> 752.00 X
1	Front door weatherstrip	\$ <i>17</i> 190.00 X
1	Front wiper tank	\$ <i>See</i> 145.80
1	Front wheel hub	\$ <i>See</i> 195.00
1	Front wheel bearing	\$ <i>See</i> 155.00
1	Front shock absorber	\$ <i>See</i> 282.00
1	Front knuckle arm	\$ <i>See</i> 325.00
1	Front lower arm	\$ <i>See</i> 295.00 X
1	Front drive shaft -R/H	\$ <i>17</i> 1,025.00 X
		\$ 8,632.70
	Less 10%	\$ 863.27
		\$ 7,769.43

8-5606.60
10%
7-5045.94
S.N-525.00
L-1950.00

7520.94
20%
6016.74

SPECIAL NETT ITEMS

1	Front bonnet sticker	\$ 11	250.00	X
1	Front bumper lower spoiler	\$ NT	650.00	X
1	Front fender inner shield clip (1 set)	\$ 21	45.00	✓
1	Front tyre -R/H	\$ 81	400.00	X
1	Front wheel rim -R/H	\$ 85/100	850.00	480
		\$	<u>2,195.00</u>	

S/N LABOUR CHARGES

1	To check wiring , lighting and resetting headlamps focusing.	\$	80.00	30
2	To remove and refit front undercarriage.	\$	450.00	120
3	To conduct wheel alignment.	\$	150.00	60
4	To apply undercoating.	\$	200.00	60
5	Panel beating.	\$	1,600.00	780
6	To re-spray painting on the affected areas.	\$	1,500.00	900
		\$	<u>3,980.00</u>	
				1250

GRAND TOTAL :

\$ 13,944.43

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Resurvey will be subject to confirmation
- Resurvey process is on a "Without Prejudice" basis
- No additional charges are allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19018424/UUF3N2

Date: 12/11/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D19MTPV01007256
Claimant Vehicle No :	SKA8937J	Insured Vehicle No :	SLN4802K
Date of Loss:	17/10/2019	Nature of Claim:	TP
		Claim No:	CMTD1904912

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKA8937J	Engine No:	G4FCAH217001
Make & Model:	KIA CERATO FORTE, 1.6 SX AT ABS D/AB 2WD 4DR (A)	Chassis No:	KNAFW411MA5268656
Reg. Date:	13/04/2011 (Man. Year: 2010)	Odometer:	257563 km
Colour:	Blue		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/45ZR17	Rear Tyre Size:	215/45ZR17
Front Left Side:	RADAR 6 mm	Rear Left Side:	RADAR 6 mm
Front Right Side:	RADAR 6 mm	Rear Right Side:	RADAR 6 mm

*The above values represent the remaining tyre treads depth.***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	9,964.43	5,570.94	4,393.49	44.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,980.00	1,950.00	2,030.00	51.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,944.43	7,520.94	6,423.49	46.06
Approved Total (Overridden) (S\$)		6,000.00		
Nett Amount (S\$)	13,944.43	6,000.00	7,944.43	56.97

INSPECTION

Date of Assignment:	18/10/2019	Inspected At:	Bik 15 Kaki Bukit Road 4 #01-53 Repairer: Zoom Autowerks Pte Ltd
Date Inspected:	18/10/2019		
Estimated Period of Repair:	6.0 days		

Adjuster: MARCUS CHUA

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 12 Nov 2019)
Parts: 143	KIA CERATO FORTE 1.6 SX AT ABS D/AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKA8937J)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Buckled	778.80 FL	*765.20 FL
2	2		*FRONT BONNET HINGES	Serviceable	115.00 FL	*- FL
3	1		*FRONT BONNET LOCK	Serviceable	126.50 FL	*- FL
4	1		*FRONT BONNET RUBBER-FRONT	Necessary	38.50 FL	*38.50 FL
5	1		*FRONT BONNET RUBBER-REAR	Necessary	42.50 FL	*42.50 FL
6	1		*FRONT HEADLAMP O/S	Cracked	653.50 FL	*520.50 FL
7	1		*FRONT HEADLAMP LOWER BRACKET O/S	Bent	78.60 FL	*55.00 FL
8	1		*FRONT HEADLAMP SIDE GARNISH	Not Necessary	45.20 FL	*- FL
9	1		*FRONT GRILLE	Cracked	320.00 FL	*320.00 FL
10	1		*FRONT GRILLE LOGO	Not Necessary	42.50 FL	*- FL
11	1		*FRONT BUMPER	Distorted	588.60 FL	*545.30 FL
12	1		*SET FRONT BUMPER CLIP	Necessary	55.00 FL	*45.00 FL
13	1		*FRONT BUMPER FOG LAMP O/S	Cracked	286.90 FL	*245.00 FL
14	1		*FRONT BUMPER FOG LAMP GRILLE O/S	Torn	85.00 FL	*85.00 FL
15	1		*FRONT BUMPER INNER SPONGE	Torn	123.60 FL	*123.60 FL
16	1		*FRONT BUMPER REINFORCEMENT	Bent	396.50 FL	*345.60 FL
17	1		*FRONT BUMPER SIDE RETAINERS	O/s Bent	85.00 FL	*38.00 FL
18	1		*FRONT FENDER-R/H	Buckled	522.50 FL	*522.50 FL
19	1		*FRONT FENDER INNER SHIELD	Torn	86.90 FL	*86.90 FL
20	1		*FRONT SUPPORT PANEL	Cracked	796.80 FL	*725.20 FL
21	1		*FRONT DOOR-R/H	Repair	752.00 FL	*- FL
22	1		*FRONT DOOR WEATHERSTRIP	Not Necessary	190.00 FL	*- FL
23	1		*FRONT WIPER TANK	Distorted	145.80 FL	*145.80 FL
24	1		*FRONT WHEEL HUB	Bent	195.00 FL	*195.00 FL
25	1		*FRONT WHEEL BEARING	Necessary	155.00 FL	*155.00 FL
26	1		*FRONT SHOCK ABSORBER	Bent	282.00 FL	*282.00 FL
27	1		*FRONT KNUCKLE ARM	Bent	325.00 FL	*325.00 FL
28	1		*FRONT LOWER ARM	Serviceable	295.00 FL	*- FL
29	1		*FRONT DRIVE SHAFT-R/H	Not Necessary	1,025.00 FL	*- FL
30	1		*FRONT BONNET STICKER	Not Necessary	250.00 FS	*- FS
31	1		*FRONT BUMPER LOWER SPOILER	Not fitted	650.00 FS	*- FS
32	1		*SET FRONT FENDER INNER SHIELD CLIP	Necessary	45.00 FS	*45.00 FS
33	1		*FRONT TYRE-R/H	Serviceable	400.00 FS	*- FS
34	1		*FRONT WHEEL RIM-R/H	Bent/Warped	850.00 FS	*480.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	10,827.70	6,131.60
- List Item Discount on L Items 10.00/10.00% (S\$)	863.27	560.66
Total Parts (S\$)	9,964.43	5,570.94

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING,LIGHTING AND RESETTING HEADLAMPS FOCUSING	New	80.00	30.00
2	TO REMOVE AND REFIT FRONT UNDERCARRIAGE	New	450.00	120.00
3	TO CONDUCT WHEEL ALIGNMENT	New	150.00	60.00
4	TO APPLY UNDERCOATING	New	200.00	60.00
5	PANEL BEATING	New	1,600.00	780.00
6	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,500.00	900.00
Gross Labour Cost (S\$)			3,980.00	1,950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >