

ASS. REC. BY:

REF:

08/CTI/19018429/Kqd3"

Special Instructions:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Elaine Cheong

of

CTI

Date/Time: 18/10/19 @ 3:11pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

JSE 9272

Insured:

PC 3097 X

at Workshop m/s

Yee Auto

Tel:

6457 5768

of

160 Sin Ming Drive # 02-17

Policy No:

PMB/15N30986719000

Claim No:

SNM19D20481202

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 10/10/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

3:29pm @ 18/10/19

Person Contacted:

Mr Chen

Vehicle IN/OUT

Date/Time

Action/Instruction

Tobin/1 ✓

JSE 9272 - X

PC 3097 X - X

22/11 6/12 @ 430d email to confirm (Real \$ 7359.10, 63%)

ASS. REC. BY:

REF:

104/0101

Kenneth

ASSIGNMENT

TSE 9272

28/6/2017

From: _____ Date: _____

Estimated Cost: _____

QD/TP/WS/TP RES/QD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____ Yee Auto

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2-3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 266 53354 Yr Regn: 28/6/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: M. 5200 C.C. 1991

Colour: M. White A/C: Insured / Std / NI / NA

Sp. Reading: 82382 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD 2130 426 L 000512

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: 245/45R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal: _____ mm R/Bal: _____ mm

L/Bal: _____ mm L/Bal: _____ mm

D.O.A. 10/10/19 D.O.I. 17/10/19

Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

01/1/19

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 19 DEC 2019

Data/Time, File Pass to?

☐

: Prel. Report

1) 19/12 typist

☐

: Final Report

Data/Time, File Return to?

2)

Report Format:

MER-TP

Lump Sum / I.B.I. (\$) 4300

Days Of Repair: 3

Resurvey No. of Trlp: 1

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ - RS. \$

Fees:

Others:

TOTAL

320

Nivitha (LKK Auto)

From: Elaine Cheong <elaine.cheong@sg.cntaiping.com>
Sent: Friday, 18 October 2019 3:11 PM
To: 'bonnie kwok'; assignments
Cc: Claims Dept of CTI
Subject: RE: OUR REF: SNM19D204812-PC3097X-CML- PRI - Acc Inv: JSE 9272 & PC 3097 X ON 10 OCTOBER 2019

WITHOUT PREJUDICE

Dear June,

We refer to your email of 16.10.19.

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please refer to the email below and proceed to survey the third party vehicle.

Thank you.

Regards,

Elaine Cheong
Executive (Motor Claims)
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6530
Fax: 6224 7478 / 6224 7175
Email: elaine.cheong@sg.cntaiping.com
Website: www.sg.cntaiping.com

From: bonnie kwok [mailto:litigation@bonniekwok.com]
Sent: Wednesday, 16 October, 2019 9:48 AM
To: Elaine Cheong <elaine.cheong@sg.cntaiping.com>
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: Re: OUR REF: SNM19D204812-PC3097X-CML- PRI - Acc Inv: JSE 9272 & PC 3097 X ON 10 OCTOBER 2019

Dear Elaine,

We refer to your email dated 15 October 2019.

Our client has no objection of appointing the motor surveyor Kenneth Kong stated in your said list to conduct the joint pre-repair survey as a single joint expert.

Regards,

June



Virus-free. www.avg.com

On Tue, 15 Oct 2019 at 16:36, Elaine Cheong <elaine.cheong@sg.entaiping.com> wrote:

WITHOUT PREJUDICE

Dear June,

We refer to your email of 15.10.19.

We would like to conduct pre-repair survey of the vehicle at the appointed workshop.

We propose the following list of surveyors to be nominated as the Single Joint Expert to conduct survey of the claimant's vehicle:-

1. ADRIAN LING	6. KENNETH KONG
2. Kelvin Ang	7. SIMON HO
3. SEE CHEW SENG	8. CHUA WEIJIE
4. MOHD FADHILAH BIN OSMAN	9. MARCUS CHUA
5. XING QUO QIANG	10. HENRY NG

If we do not hear from you within two days of this letter, you shall have deemed to have agreed that the surveyor appointed by us shall be Single Joint Expert for this matter.

As per the NIMA Protocol, the survey by our appointed surveyor would include survey of your vehicle pre-repair, after it is dismantled, and post repairs. Hence, you need to provide us / our surveyors with the list of items that were damaged and required to be replaced or repaired to facilitate an effective survey.

As stated above, please inform us and our surveyor after the claimant's vehicle had been repaired so that our surveyor can carry out post repair inspection before the vehicle is returned to your client. Please co-ordinate with our surveyor immediately after the repair is completed.

Regards,

Elaine Cheong

Executive (Motor Claims)

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 6389 6530

Fax: 6224 7478 / 6224 7175

Email: elaine.cheong@sg.cntaiping.com

Website: www.sg.cntaiping.com

From: Claims Dept of CTI

Sent: Tuesday, 15 October, 2019 2:36 PM

To: Elaine Cheong <elaine.cheong@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; litigation@bonniekwok.com

Subject: OUR REF: SNM19D204812-PC3097X-CML- PRI - Acc Inv: JSE 9272 & PC 3097 X ON 10 OCTOBER 2019

Dear Elaine,

Please conduct PRS for JSE9272.

Note : officer in charge – Elaine Cheong 63896530.

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: bonnie kwok [<mailto:litigation@bonniekwok.com>]
Sent: Tuesday, 15 October, 2019 10:58 AM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: PRI - Acc Inv: JSE 9272 & PC 3097 X ON 10 OCTOBER 2019

Dear Sir,

We refer to the above matter.

We hereby give you 2 days' notice to conduct a pre-repair inspection of vehicle JSE 9272 at M/s Yee Auto Pte Ltd, 160 Sin Ming Drive #02-17 Sin Ming Autocity Singapore 575722. Contact number 6457 5768.

Regards,

June

BONNIE KWOK LLC

Advocates & Solicitors

101A Upper Cross Street

#08-12 People's Park Centre

Singapore 058358

TEL: 6536 6026

FAX: 6536 2279

email : litigation@bonniekwok.com

GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.



Virus-free. www.avg.com

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

--

BONNIE KWOK LLC

Advocates & Solicitors

101A Upper Cross Street

#08-12 People's Park Centre

Singapore 058358

TEL: 6536 6026

FAX: 6536 2279

email : litigation@bonniekwok.com
GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



Smart Drive Private Car
POLICY SCHEDULE / JADUAL POLISI
RENEWAL / PEMBAHARUAN
Original / Asal

Office Of Issue / Pejabat : AXA AFFIN GENERAL INSURANCE BHD (23820-W)

Address / Alamat : Ground Floor Wisma Goldhill
No 67 Jalan Raja Chulan
50200 Kuala Lumpur

Telephone / Telefon : 03-21708282

Fax / Faks : 03-20317282

POLICY INFORMATION / Maklumat Polisi	Policy No. / Nombor Polisi: VPP/98029159/61/06/CCO
Source / Pengantara	(01) 23456 CYCLE & CARRIAGE BINTANG BHD - JB
Insured / Pihak Diinsuranskan I/C No. / No. KP	LOK KWAI HUA 621106015318
Address / Alamat	NO. 272 JALAN HIKMAT TAMAN BAHAGIA SENAI 81400 JOHOR
Period of Insurance / Tempoh Insurans	From 28/06/2019 To 27/06/2020 (Both Dates Inclusive) Dari Hingga /Termasuk Kedua-dua tarikh
Any subsequent period for which the insured shall pay and the Company shall agree to accept a renewal premium. /Sebarang tempoh yang berikut dimana Orang Yang Diinsuranskan akan membayar dan Syarikat akan bersetuju untuk menerima premium pembaharuan.	
Replacing Policy No. / Menggantikan No. Polisi	VPP/98029156/61/06/CCO
PREMIUM / Premium	
Annual Premium / Premium Tahunan	RM 4,367.26
Total Premium Due / Jumlah Premium	RM 4,367.26
Stamp Duty / Duti Setem	RM 10.00
RISK DETAILS / Butiran Risiko - THE MOTOR VEHICLE / Kenderaan Motor	
Cover Granted / Jenis Perlindungan	Comprehensive
Profession / Profesion	-
Regn No. / No. Pendaftaran	JSE9272
Type Of Use / Jenis Kegunaan	Private (Drive - Work/Daily)
Make / Model / Buatan / Model	MERCEDES BENZ E200 (W213)
Year Of Manufacture / Tahun Diperbuat	2017
Body Type / Jenis Badan Kenderaan	SALOON

CONFIRMATION OF PURCHASE OF INSURANCE

CYCLE & CARRIAGE BINTANG BERHAD

7378-D

LOT 19, JALAN 51A/219,
46100 PETALING JAYA, SELANGOR DARUL EHSAN
Tel: 03-7866 1131/2/4/5, Fax: 03-7872 8129
GST Reg.No: 000651034624

Date of Issue 12/06/2019

JPJ Code No. 07

CBC REGULATION - Section 84(1) of the Financial Services Act 2013: No licensed insurer shall assume any risk in respect of such description of policy as may be prescribed by the Bank unless and until the premium payable is received by the licensed insurer in such manner and within such time as may be prescribed by the Bank.

Insured's Name	: LOK KWAI HUA
Address	: NO. 272 JALAN HIKMAT TAMAN BAHAGIA SENAI 81400 JOHOR
NRIC/Passport/Business Reg.	: 621106015318
Cover Note Number	: 07469154
Vehicle Registration No.	: JSE9272
Make and Model	: MERCEDES BENZ E200 (W213)
Year of Manufacture	: 2017
Engine Number	: 27492030816011
Chassis Number	: WDD2130426L000512
C.C./Carrying Capacity(kg)	: 1991
Use of Vehicle	: Private
Period of Cover	: 28/06/2019 To 27/06/2020
Type of Cover	: Comprehensive
Sum of Insured	: MYR 255,000.00
Total Premium	: MYR 4,639.30
Excess	:
JPJ e-Insurance Status	: Accepted
Insurer	: AXA AFFIN GENERAL INSURANCE BHD -JB (23456)
Finance Company	: MERCEDES-BENZ SERVICES MALAYSIA SDN BHD
Named Drivers	: THE INSURED, CHONG AH KONG, CHONG WEI JIAN
Additional Covers	: LEGAL LIABILITY OF PASSENGER LEGAL LIABILITY TO PASSENGER NAMED DRIVER WINDSCREEN (MYR 10,000.00) AGREED VALUE

THIS IS A COMPUTER GENERATED FORM, SIGNATURE IS NOT REQUIRED



Police Station Of Origin:
Jurong NPP
158 Yung Loh Road #01-58 SINGAPORE
610158
Tel No: 1800-2659999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 11/10/2019 16:12			Vide Report No.:		Station Diary No.: 28
Informant's Particulars					
Name of Informant: CHONG AH KONG			Address: 7 TRACTOR RD SINGAPORE 627968		
ID Type / ID No.: FIN NO / G5635281W			Contact No.: Home/Office: Mobile: 97867799		
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 65	Date of Birth: 08/07/1954	Type of Informant: Driver		
Race: Chinese			Language:	Institution / School Name:	
Occupation: SERVICE CONSULTANT			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident				
Type of Accident:	Non-Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 10/10/2019 16:00	Type of Location: Car Park
Location: Along Road 1 BOON LAY WAY				
MCDONALD'S AT JURONG CENTRAL CAR PARK UNKNOWN LOT NUMBER				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
JSE9272	Car	MERCEDES BENZ		White	Slightly Damaged	0
PC3097X					Slightly Damaged	0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



Police Station Of Origin:
Jurong NPP
158 Yung Loh Road #01-58 SINGAPORE
610158
Tel No: 1800-2659999

CONTINUATION OF REPORT

Driver				
Name	CHONG AH KONG		ID No.	G5635281W
Related Vehicle	JSE9272 (Car)		Contact No.	97867799
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Driver				
Name	DARYL CHONG		ID No.	NIL
Related Vehicle	PC3097X		Contact No.	90940285
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL

Brief Details.

On 10/10/2019 at about 1600hrs, I parked my car JSE9272 at Mcdonald's Jurong Central Carpark at an unknown lot number and left the car park.

Later at about 1800hrs, I returned to my car and discovered a note on my windscreen. I noticed that there we some scratches and slight dent marks on front right side of my car. The note states " Dear Sir, Sorry that I hit on your car. I had wait for 10 mins but I had urgent to go 1st. Pls call me thru +6590940285 Daryl " I contacted the person and agreed to let insurance settle. The driver of the van PC3097X had given me his details. No one were injured.

I'm lodging this report for record and claiming purposes.



Police Station Of Origin:
Jurong NPP
158 Yung Loh Road #01-58 SINGAPORE
610158
Tel No: 1800-2659999

3 of 3



Report No. T/20191011/2105

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: J / Sgt 3 KUMARAVAL KIONG ANANTHAN	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 11/10/2019 16:12
Officer In Charge Of Case: TP / AEIT / SSI 2 JUREN BINTE AHMAD Contact No: 65476219	Classification Of Case:
Authentication Stamp NP168	Signature 

SN 124

Singapore Police Force



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S: China Taiping Insurance (Singapore) Pte Ltd

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

Estimate No: ES1900101

Date: 17 Oct 2019

Policy No:

Veh Reg No: JSE9272

Make/Model: MERCEDES BENZ E200

Chassis No: WDD2130426L000512

Engine No: 27492030816011

Reg. Date:

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Third Party

Accident Date: 10/10/2019

TP Veh Reg No: PC3097X

Estimate Repair Cost to Vehicle No :JSE9272

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
Net Price				
1 FRONT BUMPER SENSOR - CENTER RH	465.00	1 PC	<i>Bu</i> 465.00	X
2 FRONT BUMPER SENSOR - RH <i>312w</i>	465.00	1 PC	<i>Shor</i> 465.00	<i>2</i>
			930.00	930.00
Spare Parts				
3 FRONT BUMPER <i>1350</i>	1,812.50	1 PC	<i>Bu</i> 1,812.50	<i>✓</i>
4 FRONT BUMPER BRACKET - LH	162.00	1 PC	<i>Bu</i> 162.00	X
5 FRONT BUMPER BRACKET - RH	162.00	1 PC	<i>Bu</i> 162.00	X
6 FRONT BUMPER CLIPS	80.00	1 SET	<i>Bu</i> 80.00	<i>✓</i>
7 FRONT BUMPER INNER GARNISH <i>301</i>	395.10	1 PC	<i>CAT</i> 395.10	<i>2</i>
8 FRONT BUMPER INNER IMPACT BRACKET - LH	82.10	1 PC	<i>Bu</i> 82.10	X
9 FRONT BUMPER INNER IMPACT BRACKET - RH	82.10	1 PC	<i>Bu</i> 82.10	X
10 FRONT BUMPER SIDE RETAINER - LH	82.00	1 PC	<i>Bu</i> 82.00	X
11 FRONT BUMPER SIDE RETAINER - RH	82.00	1 PC	<i>Bu</i> 82.00	X
12 FRONT BUMPER SPONGE	335.10	1 PC	<i>CAT</i> 335.10	<i>2</i>
13 FRONT BUMPER TOWING COVER	121.50	1 PC	<i>Bu</i> 121.50	X
14 HEAD LAMP - RH <i>my cat</i>	2,885.90	1 PC	<i>Bu</i> 2,885.90	<i>✓</i>
15 FRONT TYRE RIM 18/45/245	850.00	1 PC	<i>Bu</i> 850.00	X
16 FRONT BONNET GRILLE - CENTRE	215.90	1 PC	<i>Bu</i> 215.90	X
17 FRONT BUMPER GRILLE - RH (CORNER) <i>109</i>	225.10	1 PC	<i>Bu</i> 225.10	X
18 FRONT FENDER - RH	955.80	1 PC	<i>Bu</i> 955.80	X
19 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	800.00	1 JOB	800.00	<i>2501</i>
20 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	800.00	1 JOB	800.00	<i>8001</i>
21 COMPUTER DIAGNOSTIC	350.00	1 JOB	<i>nn</i> 350.00	X
22 TO CHECK WIRING FUNCTIONS.	100.00	1 JOB	100.00	<i>201</i>
23 WHEEL ALIGNMENT	150.00	1 T	<i>nn</i> 150.00	X
			10,729.10	10,729.10

YEE AUTO CONTRIBUTION TO THE REPAIR OF THE FOLLOWING:

- To return vehicle to original condition
- To replace damaged parts with original
- Price prices are estimate - estimate
- To repair body work & paintwork
- To replace damaged parts with original
- To replace damaged parts with original
- To replace damaged parts with original
- To replace damaged parts with original
- To replace damaged parts with original
- To replace damaged parts with original

YEE AUTO CONTRIBUTION TO THE REPAIR OF THE FOLLOWING:

To return vehicle to original condition

To replace damaged parts with original

Price prices are estimate - estimate

To repair body work & paintwork

To replace damaged parts with original

To replace damaged parts with original

To replace damaged parts with original

To replace damaged parts with original

To replace damaged parts with original



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteitd@gmail.com

Registration No: 201719251W GST No: 201719251W

M/S : China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

ATTN: Motor Claim Department
Your Ref No: -
Claim Type: Third Party
Accident Date: 10/10/2019
TP Veh Reg No: PC3097X

Estimate No: ES1900101
Date: 17 Oct 2019
Policy No:
Veh Reg No: JSE9272
Make/Model: MERCEDES BENZ E200
Chassis No: WDD2130426L000512
Engine No: 27492030816011
Reg. Date:

Estimate Repair Cost to Vehicle No :JSE9272

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
			Total	S\$ 11,659.10
			Add GST @ 7%	816.14
			Total Amount Payable	S\$ 12,475.24

TOTAL: SINGAPORE DOLLAR TWELVE THOUSAND FOUR HUNDRED SEVENTY FIVE AND CENTS TWENTY FOUR ONLY

For Yee Auto Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119018429/KQD3N2
Date: 23/12/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SN30586719000
Claimant Vehicle No: JSE9272 Insured Vehicle No: PC3097X
Date of Loss: 10/10/2019 Nature of Claim: TP Claim No: SNM19D204812C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: JSE9272
Make & Model: MERCEDES-BENZ E200, 2.0 (A) Engine No: 27492030816011
Reg. Date: 28/06/2017 (Man. Year: 2017) Chassis No: WDD2130426L000512
Colour: Metallic White Odometer: 82382 km
Engine Capacity: 1991 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45 R18 Rear Tyre Size: 245/45 R18
Front Left Side: Pirelli 8 mm Rear Left Side: Pirelli 8 mm
Front Right Side: Pirelli 8 mm Rear Right Side: Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,459.10	4,768.80	4,690.30	49.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,200.00	670.00	1,530.00	69.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,659.10	5,438.80	6,220.30	53.35
Approved Total (Overridden) (S\$)		4,300.00		
(S\$)	11,659.10	4,300.00	7,359.10	63.12
+ GST 7.00/7.00% (S\$)	816.14	301.00	515.14	63.12
Nett Amount (S\$)	12,475.24	4,601.00	7,874.24	63.12

INSPECTION

Date of Assignment: 19/12/2019
Date Inspected: 17/10/2019 Inspected At: Yee Auto Pte Ltd (HQ)
160 SIN MING DRIVE, #02-17 SIN MING
AUTOCITY
Singapore 575722
Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Dec 2019)

Parts: 143 MERCEDES-BENZ E200 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for JSE9272)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	1,812.50 F	*1,350.00 FL
2	1		*FRONT BUMPER BRACKET-LH	Repair	162.00 F	*- FL
3	1		*FRONT BUMPER BRACKET-RH	Repair	162.00 F	*- FL
4	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 F	*80.00 FL
5	1		*FRONT BUMPER INNER GARNISH	Cracked	395.10 F	*301.00 FL
6	1		*FRONT BUMPER INNER IMPACT BRACKET-LH	Serviceable	82.10 F	*- FL
7	1		*FRONT BUMPER INNER IMPACT BRACKET-RH	Serviceable	82.10 F	*- FL
8	1		*FRONT BUMPER SIDE RETAINER-LH	Serviceable	82.00 F	*- FL
9	1		*FRONT BUMPER SIDE RETAINER-RH	Serviceable	82.00 F	*- FL
10	1		*FRONT BUMPER SPONGE	Cracked	335.10 F	*335.10 FL
11	1		*FRONT BUMPER TOWING COVER	Serviceable	121.50 F	*- FL
12	1		*HEAD LAMP-RH	Mtg Cracked	2,885.90 F	*2,885.90 FL
13	1		*FRONT TYRE RIM 18/45/245	Serviceable	850.00 F	*- FL
14	1		*FRONT BONNET GRILLE-CENTRE	Serviceable	215.90 F	*- FL
15	1		*FRONT BONNET GRILLE-RH (CORNER)	Serviceable	225.10 F	*- FL
16	1		*FRONT FENDER-RH	Repair	955.80 F	*- FL
17	1		*FRONT BUMPER SENSOR-CENTER RH	Serviceable	465.00 FS	*- FS
18	1		*FRONT BUMPER SENSOR-RH	Shorted	465.00 FS	*312.00 FS

F=Franchise part, S=Spchiett, L=ListItemDisc.

Sub Total (S\$)	9,459.10	5,264.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	495.20
Total Parts (S\$)	9,459.10	4,768.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE & REPLACE DAMAGED PARTS,PANEL BEAT WHERE NECESSARY	New	800.00	250.00
2	TO PUTTY,APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION	New	800.00	400.00
3	COMPUTER DIAGNOSTIC	New	350.00	0.00
4	TO CHECK WIRING FUNCTIONS	New	100.00	20.00
5	WHEEL ALIGNMENT	New	150.00	0.00
Gross Labour Cost (\$\$)			2,200.00	670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >