

22/03/2002

ASS. REC. BY:

REF: CS3/SMD1908444/1Gqf3c2

Special Instruction:

Survivor: GA

ASSIGNMENT (Office)

From (Person): Ruth Chun Gek Tang of SMD Date/Time: 18.10.19 14.56p.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBH 4132K Insured: SL L 6089A

at Workshop m/s Hrap Lat Automobile Tel: 96601347

of 160 San Ming Drive #05-17

Policy No: D19MTPV 01002911 Claim No: CND1904881

Sum Insured: Excess:

Make of Veh: D.O.A. 15.10.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 18.10.19 3.37p.m Person Contacted: Han Wei Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SL L 6089A: X
	GBH 4132K: X
	Submit PRS.
	Dismantle part: 21/10/2019

ASS. REC. BY:

REF: SMO

ASSIGNMENT

From:

Date:

18.10.2019

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

GBH 4132K

at Workshop m/s

Hrap Lek Auto Mobile

of

160 sin ming bar #105-17

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GBH 4132K

Yr Regn:

31 May 2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Hiace

C.C.

2982

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

43416

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195 R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

65

mm

R/Bal.

8

mm

L/Bal.

65

mm

L/Bal.

5

mm

D.O.A.

D.O.I.

18-10-19

Survey held at

w/s

5:30pm

Des. of Damages: Frt / Rear / D/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$4000 - \$5000

Date/Time, File Pass to?

☐

Preli. Report

1) 21/10 12:00

☐

Final Report

Date/Time, File Return to?

2)

Rep. Formed:

PR3

Lump Sum / L.B.C.

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

100

60

11

171

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Oct 2019		18 Oct 2019 14:55 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	LOH CHAO KIAT, ID: S8229418Z, Tel: +6582982433, Email: chaokiat@gmail.com		
Main Claimant:	DYNA COOL AIR PTE LTD		
Vehicle Reg. No.:	GBH4132K	Date of Loss:	15/10/2019 14:00 - :59
Claim Type:	TP / CMTD1904881	Policy/Cover Note No.:	D19MTPV01002911 (Comprehensive)
Vehicle Reg. No. (Insured):	SLL6089A	Policy No. (Claimant):	
		Excess:	
Repairer:	- Not Applicable - (-)		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Ruth Chua Gek Tiang - 6329 5153]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/10/2019]		
Driver/Custodian (Insured):	LOH CHAO KIAT (37 / Male), NRIC: S8229418Z, Tel: +6582982433 Email: chaokiat@gmail.com		

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

CPc**C PAGLAR & CO**

ADVOCATES & SOLICITORS

UEN NO. 53130985A GST REG NO. M90371275L

50 Chin Swee Road
#05-03 Thong Chai Building
Singapore 169874

Telephone: (65) 6536 5456

Facsimile: (65) 6836 2195

Email: pri@cpaglar.com.sg

SERVICE OF COURT DOCUMENTS BY FACSIMILE
WILL NOT BE ACCEPTED

PLEASE QUOTE OUR FILE REFERENCE WHEN REPLYING

Your Reference: SLL 6089A CMTD1A04881/RUC
Our Reference: CP/PRI/GBH4132/19.na(sc)Date : 18th October 2019**SOMPO INSURANCE SINGAPORE PTE LTD**
ATTN: MOTOR CLAIMS DEPT

BY FAX 6221 3147 ONLY

Dear Sirs,

CORRESPONDENCE PURSUANT TO PARAGRAPH 2.9 OF THE PRE-ACTION PROTOCOL FOR NIMA CASESWe refer to your email dated 18th October 2019.

Please note that the said vehicle can be inspected at:

HIAP LEK AUTOMOBILE TRADING

160 Sin Ming Drive

#05-17 Sin Ming Autocity

Singapore 575722

Contact No.: 9660-1347 (Hanwei)

(Please call the contact person within the next 2 days in advance)

Sampo Insurance Singapore Pte. Ltd.	
Claims	
18 OCT 2019	

KINDLY REPLY BY EMAIL ONLY: pri@cpaglar.com.sg

Please note that the vehicle will only be available for the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday, the said workshop will commence repairs thereafter without any further notice or reference to you. All our client's rights are expressly reserved.

Yours faithfully,

**C PAGLAR & CO**

cc. [Client by Fax 6266 8605 Only] - (GBH 4132K)

FOR SURVEYORPlease initial here after completion of
pre-repair inspection.
Thank you

Appointed Surveyor (Name & Signature)

Date & Time of Inspection

Date of Accident : 15/10/19 Accident Time: 2.35pm (24-HR-FORMAT)
Accident Place : Serangoon Garden way and Highton crescent.
Vehicle Reg. No (Car plate No.) : GRH 4132K
Vehicle Make/Model : Toyota Hiace
Insurance Company : NTUC Income Policy No. 5100981392-01
Owner or Company Names /IC NO: Dyna Cool Air pte Ltd
Owner or Company Contact No. : _____ Owner's HP _____ Company Tel _____
DRIVER'S Name & IC no. : Panchanathan Raghun / 62446528X
DRIVER'S Date of Birth : 01/07/1991 DRIVER'S License Pass Date 06 Apr 2017
Relationship bet. Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others: Employee
(Skytech Building)
DRIVER'S Address : 81k 2 Bukit Batok St 24 #06-07 (J) 659480
DRIVER'S Contact No./ Alt No. : 1) 84046140 2) 81286070
DRIVER'S Occupation : INDOOR OUTDOOR (eg. working inside or outside of an ofc)
Email Address : _____
Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET
Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Ins
Number of Passengers (including Driver): 4 All male
Was there any video Captured by car camera: YES \ NO
Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose

Other Party Driver's Particulars (if any)

Vehicle Reg No: 5LL 6089A
Vehicle Make/Model: Honda Shuttle
Name DRIVER: Loh Chao Kiat
IC No. DRIVER: 582294187
DRIVER'S Contact & add: _____

Vehicle Reg No: _____
Vehicle Make/Model: _____
Name DRIVER: _____
IC NO. DRIVER: _____
DRIVER'S Contact & add: _____

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Dyna Cool Air Pte Ltd
Blk 2 Bukit Batok St 24
#06-07 Skytech Building
Singapore 659480
Tel: 6564 4988 Fax: 6425 6850

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



Ⓐ 4BH 4132K

Ⓑ SL 6089A

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 15/10/19 @ about 2.35pm, I am travelling along Serangoon Garden way going straight within my own lane. When passed the junction of Serangoon Garden way and Brighton cres, a vehicle Ⓐ turning right and hit onto my vehicle rear right portion.

Tel: 6564 4988 or 6564 4989

We declare the foregoing particulars are true in every respect.

#06-07 Skytech Building
Bik 2 Bukit Batok St 24
Dyna Cool Air Pte Ltd

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	052K
Vehicle No.:	GBH4132K
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Oct 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE VAN TURBO 5DR MT
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	1KD2796806
Chassis No.:	JTFHT02P600242416
Maximum Power Output:	-
Open Market Value:	\$28,138.00
Original Registration Date:	31 May 2018
First Registration Date:	31 May 2018
Transfer Count:	0
Actual ARF Paid:	\$1,407.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	30 May 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$30,600.00
COE Rebate Amount:	\$26,347.00
Total Rebate Amount:	\$26,347.00

The information contained herein is correct as at 20 Oct 2019

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)













































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Oct 2019		18 Oct 2019 14:55 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: LOH CHAO KIAT , ID: S8229418Z, Tel: +6582982433, Email: chaokiat@gmail.com									
Main Claimant: DYNA COOL AIR PTE LTD									
Vehicle Reg. No.: GBH4132K		Date of Loss: 15/10/2019 14:00 - :59 [16 Months and 15 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / CMTD1904881		Policy/Cover Note No.: D19MTPV01002911 (Comprehensive)							
Vehicle Reg. No. (Insured): SLL6089A		Policy No. (Claimant):							
		Excess:							
Repairer: - Not Applicable - (-)									
Handling Insurer: Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Ruth Chua Gek Tiang - 6329 5153]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 30/10/2019]									
Driver/Custodian (Insured): LOH CHAO KIAT (37 / Male) , NRIC: S8229418Z, Tel: +6582982433 Email: chaokiat@gmail.com									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GBH4132K (CMTD1904881)
[SLL6089A]**

**TP
DYNA COOL AIR PTE LTD
Oct 15 2019 2:00PM
[LOH CHAO KIAT]**

Upload Documents Upload Photos Compose New Letter			View View in Browser ▼		
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	21/10/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>	
2	21/10/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>	
3	21/10/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>	
4	21/10/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>	
5	21/10/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>	
6	21/10/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>	
7	21/10/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>	
8	21/10/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>	
9	21/10/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>	
10	21/10/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>	
11	21/10/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>	
12	21/10/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>	
13	21/10/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>	
14	21/10/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>	
15	21/10/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>	
16	21/10/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>	
17	21/10/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>	
18	21/10/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>	
19	21/10/19 09:27	General View	 Load JPG	<input checked="" type="checkbox"/>	
20	21/10/19 09:27	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>	
21	21/10/19 09:27	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>	
22	21/10/19 17:31	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>	
23	21/10/19 17:31	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>	
24	21/10/19 17:31	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>	
25	21/10/19 17:31	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>	
26	21/10/19 17:31	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>	
27	21/10/19 17:31	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>	
28	21/10/19 17:31	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>	
29	21/10/19 17:31	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>	
30	21/10/19 17:31	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>	
31	21/10/19 17:31	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>	
32	21/10/19 17:31	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>	
33	21/10/19 17:31	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>	
34	21/10/19 17:31	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>	
35	21/10/19 17:31	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>	
36	21/10/19 17:31	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>	
37	21/10/19 17:31	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>	
38	21/10/19 17:31	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>	
39	21/10/19 17:31	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>	
40	21/10/19 17:31	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>	
41	21/10/19 17:31	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>	
42	21/10/19 17:31	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>	
43	21/10/19 17:31	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>	
44	21/10/19 17:31	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
45	21/10/19 17:31	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
46	21/10/19 17:31	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
47	21/10/19 17:31	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
48	21/10/19 17:31	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
49	21/10/19 17:31	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
50	21/10/19 17:31	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
51	21/10/19 17:31	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	16/10/19 10:30	PRI FAX DT 15.10.19 FR C PAGLAR W ENCLS - GBH4132K	Load PDF	
2	16/10/19 11:26	PRI - ACK	Load HTM	
3	17/10/19 09:26	FAX PRI DT 16.10.19 FR C PAGLAR & CO - GBH4132K FAX PRI DT 16.10.19 FR C PAGLAR & CO - GBH4132K	Load PDF	
4	18/10/19 11:09	PRI - No Consensus (pending for w/s address)	Load HTM	
5	18/10/19 14:49	FAX PRI DT 18.10.19 FR C PAGLAR & CO - GBH4132K FAX PRI DT 18.10.19 FR C PAGLAR & CO - GBH4132K	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO19018444/GQF3E2

Date: 23/10/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D19MTPV01002911
Claimant Vehicle No :	GBH4132K	Insured Vehicle No :	SLL6089A
Date of Loss:	15/10/2019	Nature of Claim:	TP
		Claim No:	CMTD1904881

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH4132K		
Make & Model:	TOYOTA HIACE, 3.0 (A)	Engine No:	1KD2796806
Reg. Date:	31/05/2018 (Man. Year: 2018)	Chassis No:	JTFHT02P600242416
Colour:	Silver	Odometer:	43416 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	18/10/2019	
Date Inspected:	18/10/2019 Inspected At:	160 SIN MING DRIVE #05-17 Repairer : HIAP LEK AUTOMOBILE TRADING
Estimated Period of Repair:	6.0 days	

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 - \$5,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 22 Oct 2019)

Parts: N/A TOYOTA HIACE 3.0 (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBH4132K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >