



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672



Date Generated : 29/10/2019

User ID : CatherineLee

Section A - Accident Details

Registration Number	SG1747K
Case Reference Number	BUS/10/19/6001
Registration Date	1/3/2016
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN NL320F(A22)
Name of Driver	Shahnan Bin Mohd Shariff
Type of Accident	Side Swipe
Accident Date and Time	18/10/2019 10:22 AM
Accident Reported Date and Time	18/10/2019 12:15 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24103954
Special Instruction to ARC, if any	SG1747K-RIGHT REAR PORTION SHD7251E (TP) INSURED WITH III
Prepared Date and Time	19/10/2019 9:28 AM
Chassis Number	WMAA22ZZXF7002871
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$795.00	\$530.00
Total Spray Cost	\$786.00	\$616.00
Total Spare Part Cost	\$0.00	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$1,581.00	\$1,146.00
Lump Sum Total	\$1,600.00	\$0.00
Number of Repair Days	3.0	2.0
Prepared / Adjusted By	Kok Khoon Goh	STEVE CHEN
ARC / Surveyor Sign Off Date	19/10/2019 11:08 AM	21/10/2019 3:05 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 29/10/2019

User ID : CatherineLee

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope			Quotation from AR				Adjusted by Surveyor, If applicable		
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.			\$795.00				\$530.00		
Total Labour			\$795.00				\$530.00		
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope			Quotation from ARC				Adjusted by Surveyor, If applicable		
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$786.00				\$616.00		
Total Spray Painting & Panel Beating			\$786.00				\$616.00		
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope			Quotation from ARC				Adjusted by Surveyor, If applicable		
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6009990	BODY RH	A01001-CW565	PANEL, SIDE:R9 WITH FRAME, FOR MAN A22 BUS	1.00	\$710.70	100.00	\$0.00	Repair	Repair
6009991	BODY RH	4000F06-ACCE4526	PANEL, SIDE:R10, FOR MAN A22 BUS	1.00	\$192.70	100.00	\$0.00	Repair	Repair
6009992	BODY RH	A01001-CW564	PANEL, SIDE:R11, FOR MAN A22 BUS	1.00	\$1,782.50	100.00	\$0.00	Repair	Repair
6010062	Body	F01001-CW273	COVER: REAR TAIL LAMP, RH, FOR MAN A22 BUS	1.00	\$974.70	100.00	\$0.00	Repair	Repair
Total					\$3,660.60		\$0.00		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 19/10/2019

User ID : GohKK2

Section A - Accident Details

Registration Number	SG1747K
Case Reference Number	BUS/10/19/6001
Registration Date	1/3/2016
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN NL320F(A22)
Name of Driver	Shahnan Bin Mohd Shariff
Type of Accident	Side Swipe
Accident Date and Time	18/10/2019 10:22 AM
Accident Reported Date and Time	18/10/2019 12:15 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SG1747K-RIGHT REAR PORTION SHD7251E (TP) INSURED WITH III
Prepared Date and Time	19/10/2019 9:28 AM
Chassis Number	WMAA22ZZXF7002871
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$795.00	\$0.00
Total Spray Cost	\$786.00	\$0.00
Total Spare Part Cost	\$0.00	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$1,581.00	\$0.00
Lump Sum Total	\$1,600.00	\$0.00
Number of Repair Days	3.0	
Prepared / Adjusted By	Kok Khoo Goh	2
ARC / Surveyor Sign Off Date		
Signature		
Remarks		

stere (LKK) 21/10/19, 9.00pm
WKL MVL
2 dy
LIS
RyAL sy

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 19/10/2019

User ID : GohKK2

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$795.00	\$800 530
Total Labour	\$795.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$766.00	616
Total Spray Painting & Panel Beating	\$766.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6009990	BODY RH	A01001-CW565	PANEL SIDE-R9 WITH FRAME, FOR MAN A22 BUS	1.00	\$710.70	100.00	\$0.00	Repair	XR
6009991	BODY RH	4000F06-ACCE4526	PANEL SIDE-R10, FOR MAN A22 BUS	1.00	\$192.70	100.00	\$0.00	Repair	XR
6009992	BODY RH	A01001-CW564	PANEL SIDE-R11, FOR MAN A22 BUS	1.00	\$1,782.50	100.00	\$0.00	Repair	XR
6010062	Body	F01001-CW273	COVER-REAR TAIL LAMP, RH, FOR MAN A22 BUS	1.00	\$974.70	100.00	\$0.00	Repair	XR
Total					\$3,660.60		\$0.00		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: