

INS. CASE OWNER:

CC 4 / AXA1901

LKK:
IDAC:

ASSIGNMENT

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :S\$

Is driver the owner?

FBQ 4297X

MUHAMMAD LIDHWAH bin ROSLI

HP:

D.O.A.:

(YES / NO)

Nature of Accident:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

S1M023WB / 142914

MN 3187F2

YAMAHA

JERING GATE WAY RD

If NO, Driver Name / Age:

Driver Tel No.:

(VL: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

SDF 8114.

INSRS:
WSP:
Tel:
Liability:
RMKS:

performan

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

2404.74

5 days

Reduction:

3329.86%

71

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

NIL.

Repair Cost:

S\$

2404.74

Loss of Rental (LOR):

S\$

-

1 days

Loss of Use (LOU):

S\$

400.00

(\$ 80 x 5 days)

Loss of Income (LOI):

S\$

-

(\$ x 5 days)

LOR only

LOU only

LOR + LOU

LOR + LO

(Tick only one)

GIA/LTA Search

S\$

7.45

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/ Independent)

Legal Cost

S\$

-

Total:

S\$

8394.72

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

8394.72

Name 1:

Performanance motors united

Payee 2: (Strike if N.A.)

S\$

-

Name 2:

-

Payee 3: (Strike if N.A.)

S\$

-

Name 3:

-

COPY SENT

18/11/2020

REG. BY: Paul

REG: ASMR AXA

9

4500

ASSIGNMENT

From: _____ Date: 4.11.2019

Estimated Cost: _____

OD: TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SDF 8114

at Workshop n/s Performance

of 303 Alexandra Road

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: 100m owner warranty

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 123K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 1-6-1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 1 day

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SDF 8114 Yr Regn: 2018 / MAY

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: B.M.W X1 DRIVE 18I C.C. 1499

Colour: R&O A/C: Insured / Std / NI / NA

Sp. Reading: 26254 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDA JA 12090EG 21078

Gen. Cont: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / Spin / STD A/Rim or

Tyre Size: F: 225/50R18

R: 1"

BB / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 11/10/19 D.O.I. 04/11/19

Survey held at PERFORMANCE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

0/3 FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

P/R \$7464.74 (Red = \$3399.86 / 31%)

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation

5 * RS. \$1

Photos

Notes

Total

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : West end (\$)

Pop. Form(s): _____

Emp. Sora / E.P. 1:17

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Rempang Arang Road
East Coast Centre
Singapore 438188
Fax: 63449773

319, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

14 OCT 2019

Estimate No. : b1 53066
Date Estimated : 14/10/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
LIM KWANG JOO
288B Bukit Batok Street 25
#09-04

Singapore 651288

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDF811Y	WBAJG12090EG21078	03/05/2018	X1 sDrive18i	0

DESCRIPTION

To replace front right fender, front right door, wing mirror right and attachments.

VALUE

1700 / 3400.00

Painting front right fender and front right door. wing mirror cover

2063 / 1996 2218.00

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

150 / 177.00

To transfer lock mechanism from old to new door including conduct checks on new door power window system for proper function. (1 door).

451 / 531.00

To carry out body cavity preservation.
(Per panel).

200 / 100 118.00

Sundries.

80 / 150.00

Total Labour 1: 6,594.00

DESCRIPTION

FRT RH DOOR *bt*
FRT RH SIDE PANEL *bt*
FRT RH SIDE PANEL *repaired x m*
LETTERING S DRIVE 18i *m*
RH MIRROR GLASS HEATED WIDE ANGLE *m*
RH OUTSIDE MIRROR COVER CAP PRIMED *repair m*
RH SUPPORTING RING *m*
RH LOWER HOUSING SECTION *m*
RH EXTERIOR MIRROR W/O MOUNTING PAR *m*
FRT DOOR EGDE PROTECTION *m*
FRT RH DOOR JOINT SEAL *m*

QTY	PRIC	VALUE
1	1,197.80	1161.87 1,197.80
1	664.00	664.00 664.00
1	664.00	664.00 664.00
1	96.15	93.75 96.15
1	680.35	659.79 680.35
1	121.40	117.76 121.40
1	53.20	51.60 53.20
1	25.05	24.70 25.05
1	488.55	473.85 488.55
1	171.00	171.00 171.00
1	59.15	59.15 59.15

Total Parts : 4,220.65

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401359M GST Reg. No. M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 53066
Date Estimated : 14/10/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDF811Y	WBAJG12090EG21078	03/05/2018	X1 sDrive18i	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 04/11/19 @ 1050 Excess S\$ _____

Surveyor's Name RPM Sign _____

Surveyor's Tel 90000068 Authorized Yes / No _____

Authorized Date _____ Time _____

REGN. NO. SUBMITS PHOTO BY SURVEYOR Yes / No _____

Surveyor's Email _____

How Many Recommendations 5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Labour 1	:	6,594.00
Parts	:	4,220.65
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	757.03
Grand Total	:	11,571.68

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

14 OCT 2019

Estimate No. : b1 53066
Date Estimated : 14/10/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
LIM KWANG JOO
288B Bukit Batok Street 25
#09-04
Singapore 651288

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDF811Y	WBAJG12090EG21078	03/05/2018	X1 sDrive18i	0

DESCRIPTION

To replace front right fender, front right door, wing mirror right and attachments.

1700 ~~3,400.00~~

Painting front right fender and front right door.

1996 ~~2,218.00~~

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

150 ~~177.00~~

To transfer lock mechanism from old to new door including conduct checks on new door power window system for proper function. (1 door).

451 ~~531.00~~

To carry out body cavity preservation.
(Per panel).

100 ~~118.00~~

Sundries.

? 150.00

Total Labour 1: 6,594.00

DESCRIPTION

✓ FRT RH DOOR *bt*
FRT RH SIDE PANEL *bt*
FRT RH SIDE PANEL *repeated x*
LETTERING S DRIVE 18i *ren*
✓ RH MIRROR GLASS HEATED WIDE ANGLE *cm*
✓ RH OUTSIDE MIRROR COVER CAP PRIMED *repair*
× RH SUPPORTING RING *ren*
✓ RH LOWER HOUSING SECTION *cm*
× RH EXTERIOR MIRROR W/O MOUNTING PAR *bt*
FRT DOOR EGDE PROTECTION *ren*
FRT RH DOOR JOINT SEAL *ren*

QTY	PRIC	VALUE
1	1,197.80	1,197.80
1	664.00	664.00
1	664.00	664.00
1	96.15	96.15
1	680.35	680.35
1	121.40	121.40
1	53.20	53.20
1	25.05	25.05
1	488.55	488.55
1	171.00	171.00
1	59.15	59.15

Total Parts : 4,220.65



383, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64787770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64786401 (AfterSales)
64786424 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 53066
Date Estimated : 14/10/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDF811Y	WBAJG12090EG21078	03/05/2018	X1 sDrive18i	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 04/11/19 @ 1050 Excess S\$ _____

Surveyor's Name Rahel Sign _____

Surveyor's Tel 90010068 Authorised Yes / No _____

Authorised Date _____ Time _____

REPAIR BY PARTS PHOTO BY SURVEYOR Yes / No _____ PM Yes / No _____

Surveyor's E-mail _____

Working Days Recommend 5 days

Labour 1	:	6,594.00
Parts	:	4,220.65
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	757.03
Grand Total	:	11,571.68

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

119, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64791224

281, Tampung Arang Road
East Coast Centre
Singapore 438199
Fax: 63447771

219, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64791224 (AfterSales)
64791224 (Workshop)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 53066
Date Estimated : 14/10/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

ESTIMATE REPAIR FOR -
M KWANG JOO
8B Bukit Batok Street 25
9-04

- ACCOUNT - 40000
Cash Sales - Service
Singapore

Singapore 651288

IN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
811Y	WBAJG12090EG21078	03/05/2018	X1 sDrive18i	0

DESCRIPTION

VALUE

To replace front right fender, front right door, wing mirror right and attachments.	PRD	1700	3,400.00
Painting front right fender and front right door.		1996	2,210.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	1180 98%	120	477.00
To transfer lock mechanism from old to new door including conduct checks on new door power window system for proper function. (1 door).		451	531.00
To carry out body cavity preservation. (Per panel). X2	EXCESS NIL.	100	440.00
Sundries.	T. T RAJAN (KRM AUTO) 5 DAYS. 04/11 @ 1330	80	460.00
	Total Labour 1:		6,594.00

DESCRIPTION

QTY

PRIC

VALUE

FRT RH DOOR - dent at	1	1,197.80	1,197.80
FRT RH SIDE PANEL - dent at	1	664.00	664.00
FRT RH SIDE PANEL X	1	664.00	664.00
LETTERING S DRIVE 18i - nec	1	96.15	96.15
RH MIRROR GLASS HEATED WIDE ANGLE - correct	1	680.35	680.35
RH OUTSIDE MIRROR COVER CAP PRIMED - repair	1	121.40	121.40
RH SUPPORTING RING - nec	1	53.20	53.20
RH LOWER HOUSING SECTION - nec	1	25.05	25.05
RH EXTERIOR MIRROR W/O MOUNTING PAR - broken	1	488.55	488.55
FRT DOOR EDGE PROTECTION - nec	1	171.00	171.00
FRT RH DOOR JOINT SEAL - nec	1	59.15	59.15
	Total Parts :		4,220.65



Final Report

Estimate No. : **b1 53066**
Date Estimated : **14/10/2019**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -
LIM KWANG JOO
288B Bukit Batok Street 25
#09-04

Singapore 651288

- ACCOUNT - 238
AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDF811Y	WBAJG12090EG2107	03/05/2018	X1 sDrive18i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace front right door and attachments, front right fender, right wing mirror including to remove and install body parts in order to carry out painting job.	1,700.00	10.00	1,530.00
* To respray front right door, front right fender and right wing mirror cover.	2,063.00	10.00	1,856.70
To check electrical wiring systems at the front section for proper function.	150.00	10.00	135.00
To transfer lock mechanism from old to new door including conduct checks on new door power window system for proper function.	451.00	10.00	405.90
* To carry out body cavity preservation.	200.00	10.00	180.00
Sundries.	80.00	0.00	80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING NUT	2.10	2.00	3.00	4.07
# PLUG IN RETAINER	4.00	4.00	3.00	15.52
FRT RH DOOR	1,197.80	1.00	3.00	1,161.87
FRT RH SIDE PANEL	664.00	1.00	3.00	644.08
LETTERING S DRIVE 18i	96.65	1.00	3.00	93.75
RH MIRROR GLASS HEATED WIDE ANGLE	680.35	1.00	3.00	659.94
RH OUTSIDE MIRROR COVER CAP PRIMED	121.40	1.00	3.00	117.76
RH SUPPORTING RING	53.20	1.00	3.00	51.60
RH LOWER HOUSING SECTION	25.05	1.00	3.00	24.30
RH EXTERIOR MIRROR W/O MOUNTING PAR	488.55	1.00	3.00	473.89
# PLUG IN NUT	1.65	2.00	3.00	3.20
# EXPANDING RIVET BLACK	1.40	20.00	3.00	27.16

SUPPLEMENTARY ITEMS

Total Labour :	4,187.60
Total Parts :	3,277.14
Total Labour & Parts :	7,464.74
GST @7%:	522.53
Grand Total :	7,987.27

LOSS OF USE = \$80 X 5 DAYS
LTA SEARCH FEE - \$7.45



Supplementary

Estimate No. : b1 53066
Date Estimated : 14/10/2019
Prepared By : Inthiran A/L Thurasamy

- ESTIMATE REPAIR FOR -
LIM KWANG JOO
288B Bukit Batok Street 25
#09-04

Singapore 651288

- ACCOUNT - 238
AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDF811Y	WBAJG12090EG2107	03/05/2018	X1 sDrive18i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING NUT <i>per</i>	2.10	2.00	3.00	4.07
# PLUG IN RETAINER <i>per</i>	4.00	4.00	3.00	15.52
# PLUG IN NUT <i>per</i>	1.65	2.00	3.00	3.20
# EXPANDING RIVET BLACK <i>per</i>	1.40	20.00	3.00	27.16

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	49.95
Total Labour & Parts :	49.95

CERTIFICATE OF INSURANCE Pg. 1

QBE Insurance (Singapore) Pte Ltd

A member of the worldwide QBE Insurance Group - Unique Entity No: 198401363C

1 Raffles Quay, #29-10 South Tower, Singapore 048583
Tel: 65-6224 6633 Fax: 65-6533 3270
GST Registration No.: M200644018
www.qbe.com.sg



Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULE, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate No. **8-V0022067-MVA** Account Name **PANA HARRISON (ASIA) PTE LTD** MCI Type **MX1**

- 1 Index Mark and Registration Number of Vehicle or Chassis No: **SDF811Y**
- 2 Name of Policyholder **LIM KWANG JOO**
- 3 Effective date of Commencement of Insurance for the purpose of the Regulations **03/05/2019**
- 4 Date of Expiry **02/05/2020**
- 5 Person or Classes of Person entitled to drive*

(a) The Policyholder

The Policyholder may also drive a motor car not belonging to him/her and not hired to him/her under a hire purchase agreement.

(b) Any person who is driving on the Policyholder's order or with his/her permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from the driving the Motor Vehicle

And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage

6 Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover use for hire or reward, racing, pace-making, reliability trial, speed-testing or the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

7 Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risk and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act 1987 (Malaysia) are not to be included under these headings

I/WE HEREBY CERTIFY that the Policy to which this certificate relates is issued in accordance with the provisions of the Motor Vehicle (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

QBE Insurance (Singapore) Pte Ltd

Authorized Signature

Date of Issue: 11/04/2019



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 20/12/2019

Survey Details:

Date of loss	11-Oct-19
Date of appointment	21-Oct-19
Date of survey	4-Nov-19
Location of survey	PERFORMANCE MOTORS LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SDF 811Y
Make and Model	B.M.W. X1 SDRIVE18I LED NAV
Date of registration	3/5/2018
Excess	
Market Value	\$123,000
Parf Rebate	\$62,576
Nett Loss	\$60,424

Repair details:

Initial Estimate	\$ 10,814.65
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 3,277.14
Check items (estimate)	\$ -
Labour	\$ 4,187.60
Total	\$ 7,464.74
Lump Sum(if applicable)	\$ -
Number of days for repair	5



Auto
Consultants
Pte Ltd

Company Registration No. 199607196R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

--

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 7,987.27	W/GST
Loss of use	\$ 400.00	5days x \$80
Loss of rental	\$ -	
Loss of income	\$ -	
LTA search fees	\$ 7.45	
Others	\$ -	
Proposed Total	\$ 8,394.72	

 <MANDATE IA> - S9M023WB {ACCIDENT INVOLVING
FBQ 4297X & SDF 811Y ON 11/10/2019}

Type

 Question

Message

LIABILITY: 100% OI DRIVING ON MIDDLE LANE OF 1 & 2 HIT ONTO TPV. INFORM OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$8,394.72 (CLAIMING LOU). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CCL 20/12/2019

[Reply](#)

◀ Service Request Details

Claim

S9M023WB

Reference

None 

Loss Date

October 11, 2019

Report Date

Oct 16, 2019 12:59:56 PM

Request Date

October 18, 2019

Due Date

October 18, 2020

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

SDF 8117

P: Caroline

T: 2.05pm

V: OK

E: ✓

Actions

Next Step

Finish the work

[Complete Work](#)[More ▾](#)

Insured

ROSLI MUHAMAD RIDHWAN BIN

530 JELAPANG ROAD #04-19 470530 Singapore

Vehicle Information

Incident Vehicle Registration #
SDF811Y

Make
BMW

Model
X1 SDRIVE18I-1.5 LED NAV (A)

Service Address

...

Primary Contact

PERFORMANCE MOTORS LIMITED
303 Alexandra Road, Sime Darby Performance, Centre, Alexandra, 159941, Singapore
64743229
lu.yee.jet@simedarby.com.sg

Claim Handler

ANG Richard

richard.angbs@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

 Re:<MANDATE IA> - S9M023WB {ACCIDENT INVOLVING FBQ 4297X & SDF 811Y ON 11/10/2019}

Type

 Question

Message

Hi, pls proceed as per mandate. TY.

[Reply](#)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19018522/R1ga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:RICHARD ANG

Date : 17-01-2020



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBQ 4297X	Veh. Inspected	SDF 811Y
Policy No.	AN3178272	Coverage (\$)	0.00
Claim No.	S9M023WB	Excess (\$)	0.00
Assign From		Assign Date	18/10/2019

2. Vehicle Particulars & Condition

Make & Model	B.M.W. X1 SDRIVE18i	c.c	1499
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	WBAJG12090EG21078	Colour	RED
Odometer	26254	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50 R18	BRIDGESTONE	6 mm
L/H Front Tyre	225/50 R18	BRIDGESTONE	6 mm
R/H Rear Tyre	225/50 R18	BRIDGESTONE	6 mm
L/H Rear Tyre	225/50 R18	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/10/2019	Inspection Date	04/11/2019
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDF 811Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	✓ 150.00	80.00
1	FRT RH DOOR (SN) (CONSISTENT)	BENT	✓ 1,197.80	1,161.87
1	FRT RH SIDE PANEL (SN) (CONSISTENT)	BENT	✓ 664.00	644.08
1	FRT RH SIDE PANEL (SN) (CONSISTENT)	NOT NECESSARY	✓ 664.00	-
1	LETTERING S DRIVE 18I (SN) (CONSISTENT)	NECESSARY	✓ 96.15	93.75
1	RH MIRROR GLASS HEATED WIDE ANGLE (SN) (CONSISTENT)	CRACKED	✓ 680.35	659.94
1	RH OUTSIDE MIRROR COVER CAP PRIMED (SN) (CONSISTENT)	CRACKED	✓ 121.40	117.76
1	RH SUPPORTING RING (SN) (CONSISTENT)	NECESSARY	✓ 53.20	51.60
1	RH LOWER HOUSING SECTION (SN) (CONSISTENT)	CRACKED	✓ 25.05	24.30
1	RH EXTERIOR MIRROR W/O MOUNTING PAR (SN) (CONSISTENT)	BROKEN	✓ 488.55	473.89
1	FRT DOOR EDGE PROTECTION (SN) (CONSISTENT)	NOT NECESSARY	✓ 171.00	-
1	FRT RH DOOR JOINT SEAL (SN) (CONSISTENT)	NOT NECESSARY	✓ 59.15	-
2	EXPANDING NUT (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	✓ 4.07	4.07
4	PLUG IN RETAINER (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	✓ 15.52	15.52
2	PLUG IN NUT (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	✓ 3.20	3.20
20	EXPANDING RIVET BLACK (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	✓ 27.16	27.16
			4,420.60	3,357.14
LABOUR				
TO REPLACE FRONT RIGHT FENDER ,FRONT RIGHT DOOR ,WING MIRROR RIGHT AND ATTACHMENTS.			✓ 3,400.00	1,530.00
PAINTING FRONT RIGHT FENDER AND FRONT RIGHT DOOR ,(WING MIRROR COVER).			✓ 2,218.00	1,856.70
TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS.			✓ 177.00	135.00
TO TRANSFER LOCK MECHANISM FROM OLD TO NEW DOOR INCLUDING CONDUCT CHECKS ON NEW DOOR POWER WINDOW SYSTEM FOR PROPER FUNCTION (1 DOOR).			✓ 531.00	405.90

Report Ref No. CC4/ASM19018522/R1ga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL).		180.00	180.00
			6,506.00	4,107.60
GRAND TOTAL			10,926.60	7,464.74
RECOMMENDED COST OF REPAIRS				7,464.74

Report Ref No. CC4/ASM19018522/R1ga3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part does so at his or her own risk.

<< Service Request Details

Claim

59H023WB

Reference

CCA/ASM19018522/R1.g3q2

Loss Date

11 October 2019

Report Date

16 Oct 2019 12:59:56 PM

Request Date

18 October 2019

Due Date

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Vehicle Information

Incident Vehicle Registration #

SDF811Y

Make

BMW

Model

X1 SDRIVE18i-1.5 LED NAV (A)

Service Address

...

Primary Contact

PERFORMANCE MOTORS LIMITED

303 Alexandra Road, Sime Darby Performance Centre, Alexandra, 159941, Singapore

64743229

ku.yee.jet@simepardarby.com.sg

Claim Handler

ANG Richard

richard.angbs@axa.com.sg

Actions

Next Step

Wait for Approve Invoice

Approve Invoice

Insured

ROSLI MUHAMMAD RIDHWAN BIN

530 JELAPANG ROAD, #04-49, 670530, Singapore

Additional Instructions

Messages	Invoices	History	Documents	Assessment	Metrics	Notes
Document Type			Document SubType			
+ Upload Documents						
NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED		
LKKInvoice1 (5).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	20 January 2020		

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
PAYMENT BREAKDOWN_LKK.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 January 2020
LTA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 January 2020
LOD.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 January 2020
LKKInspection.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 January 2020
LKKAdjustment1a (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 January 2020
WORKSHOP INVOICE_0001.pdf	Invoice	Repairer	LKK AUTO CONSULTANTS PTE LTD (TP)	20 January 2020
DISCHARGE VOUCHER.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	20 January 2020
AUTHORIZATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	20 January 2020
LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	20 January 2020
LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
LKK RESURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
LOD AND OTHER DOCUMENTS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
MANDATE IA DO 20122019.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
PARF COE REBATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 TP FINAL EST LIST.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
 TP-IA 811.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	6 November 2019
 TP-IA 2523.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	6 November 2019
 SJFS62U GIA REPORT.PDF	Reports & Statement	GIA Report	DHIWAR Namrata	16 October 2019
 FBQ4297X INS GIA.PDF	Reports & Statement	GIA Report	DHIWAR Namrata	16 October 2019
 ESTIMATE & SDFB11Y TP GIA.pdf	Forms / Claim Documents	Estimate / Quotation	DHIWAR Namrata	16 October 2019
 TP PRE EMAIL FROM WORKSHOP.pdf	Letters and Correspondence	Workshop	DHIWAR Namrata	16 October 2019