

22/03/2003

ASS. REC. BY:

REF:

08/CTE/19018527/65 d302

Special Instruction:

Surveyor: 99

ASSIGNMENT (Office)

From (Person): Chong Boon Sen

of

CTE

Date/Time: 21/10/19 11:45pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SML 9483 M

Insured:

SME 9813G

at Workshop m/s

Auburn Auto

Tel:

9093 8998

of

176 En Ming Drive # 04-18

Policy No:

Claim No:

SNM 19 D204945

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

21/10/19 11:45am

Person Contacted:

Charles

Vehicle IN / OUT

Date/Time

Action/Instruction

Johnnie /

MV - \$ 331K

LTA - \$ 26,580.00

Nett - \$ 6,420.00

ASS. REC. BY:

Bil.

REF:

CTE

## ASSIGNMENT

(-2020)

From:

Date:

25/10/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SME9813G

at Workshop m/s

Auburn Auto

of

176 Sn Ming Drive # 04-18

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Charles @ 90938498  
After 3pm

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$82K 24K 33K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SML9483M

Regn:

01 Apr 2010

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 525i XL C.C. 2497

Colour:

black

A/C:

Insured / Std / NI / NA

Sp. Reading

228338

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WBA NU52000 C228774

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 245/45R17

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

W/S

D.O.I.

25-10-19

Survey held at

3pm

Des. of Damages (Fr) / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

25/10

\$6000 - \$7000

RECEIVED 20 NOV 2019

GIA will Give later, estimate not sure.

COT: 26580

13/11

Finalized \$6200 with George.

(\$8,195.39 Rod - 57%)

Amount  
19/11/2019

Date/Time, File Pass to?

20/11/19



Preli. Report



Final Report

1) Typ: 4

Date/Time, File Return to?

2)

Days Of Repair:

6

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

220

Transportation:

\$ + RS, \$

Photos

Others

TOTAL

220

Report Format:

Lump Sum / I.B.I. (\$

\$6,200/- L/S

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	883W
Vehicle Details	
Vehicle No.:	SML9483M
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Nov 2019
Vehicle Make:	B.M.W.
Vehicle Model:	525I XL
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	74954548N52B25AF
Chassis No.:	WBANU52000C228774
Maximum Power Output:	160.0 kW (214 bhp)
Open Market Value:	\$51,339.00
Original Registration Date:	01 Apr 2010
First Registration Date:	01 Apr 2010
Transfer Count:	2
Actual ARF Paid:	\$51,339.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Mar 2020
PARF Rebate Amount:	\$25,669.00
Intended COE Rebate Details	
COE Expiry Date:	31 Mar 2020
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$24,229.00
COE Rebate Amount:	\$911.00
<b>Total Rebate Amount:</b>	<b>\$26,580.00</b>

The information contained herein is correct as at 13 Nov 2019

OK

## ► bmw 525i Used Vehicle List (11 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabi
<b>BMW 5 Series 525i XL (COE till 10/2022)</b>	<b>\$22,800</b>	<b>\$7,810 /yr</b>	<b>15-Oct-2007</b>	<b>2,497 cc</b>	<b>-</b>	<b>Car World Automobile</b>	<b>Availal</b>

Office No. - 64712822

Jeff Liu - 91155437 | Vincent Lim - 96338877 | Alan Seow - 90129110 | Ambrose - 97912121

<b>BMW 5 Series 525i XL</b>	<b>\$32,888</b>	<b>-</b>	<b>27-Jan-2010</b>	<b>2,497 cc</b>	<b>132,888 km</b>	<b>A Asset Automobile Pte Ltd</b>	<b>Availal</b>
-----------------------------	-----------------	----------	--------------------	-----------------	-------------------	-----------------------------------	----------------

2 Owner, Car Is In Immaculate Condition!. All Wear And Tear Parts Replaced As Per Workshop Advise. Loan/Trade In Available. Please Call/5 Now! Thanks.

Office No. - 67411911

Eddy - 83019659 | Andrew - 94521119

<b>BMW 5 Series 525i (COE till 10/2024)</b>	<b>\$43,000</b>	<b>\$8,650 /yr</b>	<b>06-Nov-2004</b>	<b>2,494 cc</b>	<b>110,000 km</b>		<b>Availal</b>
---	-----------------	--------------------	--------------------	-----------------	-------------------	--	----------------

New 6 Months Road Tax.

Office No. - -

Andy - 97256600

<b>BMW 5 Series 525i XL (COE till 05/2029)</b>	<b>\$57,800</b>	<b>\$6,050 /yr</b>	<b>16-Oct-2009</b>	<b>2,497 cc</b>	<b>-</b>	<b>D&amp;L Auto Trading</b>	<b>Availal</b>
--	-----------------	--------------------	--------------------	-----------------	----------	-----------------------------	----------------

80% Loan At 3.18%, Guaranteed Loan For Bad Credit/Ex Bankruptcy, View After Lunch Till 11PM Daily, Please Call To Arrange Viewing.

Office No. - 62960188

Darren Low - 96236322

<b>BMW 5 Series 525i XL (COE till 01/2029)</b>	<b>\$65,800</b>	<b>\$7,150 /yr</b>	<b>23-Jan-2009</b>	<b>2,497 cc</b>	<b>103,000 km</b>		<b>Availal</b>
--	-----------------	--------------------	--------------------	-----------------	-------------------	--	----------------

Directors Owners, Covered Parking. Well Kept Interior. COE Till 22/1/2029. Dents On The Doors Yet To Touch Up. Full PML Till 2017, VAG Ti Date. Serviced Records And Repairs Back-Up With Receipts. Ne...

Office No. - -

Lee - 97666260

<b>BMW 5 Series 525i XL (New 10-yr COE)</b>	<b>\$72,888</b>	<b>\$7,280 /yr</b>	<b>22-Mar-2010</b>	<b>2,497 cc</b>	<b>92,951 km</b>	<b>ABS Auto Capital Pte Ltd</b>	<b>Availal</b>
---	-----------------	--------------------	--------------------	-----------------	------------------	---------------------------------	----------------

We Are The COE Specialists, No Gimmicks, Honest Dealing, Low Mileage Clocked. Car In Good Condition, Full Loan Available! 100% Approva Trade In Welcome, Bank Loan Available. Call Us At Our Showroom ...

Office No. - 64753423

Alex - 82298229 | Ken - 91196006 | Kenny - 98259995 | Roy - 83158315

<b>BMW 5 Series 525i (New 10-yr COE)</b>	<b>\$73,500</b>	<b>\$7,340 /yr</b>	<b>29-Oct-2009</b>	<b>2,497 cc</b>	<b>98,830 km</b>	<b>RPM Automobile Pte Ltd</b>	<b>Availal</b>
--	-----------------	--------------------	--------------------	-----------------	------------------	-------------------------------	----------------

New Battery, New Brake Pads, \$3k New Paintwork Frozen Gray Exterior Spray. Special Indent BMW M5. LTA Compliant Eisenmann Exhaust System, Stock Exhaust Available And Come Together. Very Expensive Auth...

Office No. - 67790012

Chris - 83885794 | SB Chia - 91825555

<b>BMW 5 Series 525i XL (New 10-yr COE)</b>	<b>\$73,800</b>	<b>\$7,370 /yr</b>	<b>05-Feb-2010</b>	<b>2,497 cc</b>	<b>-</b>	<b>DJ Automobile SG Pte Ltd</b>	<b>Availal</b>
---	-----------------	--------------------	--------------------	-----------------	----------	---------------------------------	----------------

Absolutely Good Condition, Powerful And Spacious. Perfect Family Car That Fulfills Practicality And Power! Good 10 Years More To Go! Loan Insurance Available, Trade-Ins Welcome! Viewing Via Appoin...

Office No. - 62595088

Denson Ong - 90552293

<b>BMW 5 Series 525i XL (New 10-yr COE)</b>	<b>\$76,500</b>	<b>\$7,640 /yr</b>	<b>08-Dec-2009</b>	<b>2,497 cc</b>	<b>151,000 km</b>		<b>Availal</b>
---	-----------------	--------------------	--------------------	-----------------	-------------------	--	----------------

One And Only Owner, Accident Free. Please Whatsapp Or SMS To Arrange Viewing. Please Do Not Call.

## Nivitha (LKK Auto)

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Monday, 21 October 2019 1:45 PM  
**To:** Auburn Auto  
**Cc:** assignments  
**Subject:** RE: OUR REF: SNM19D204945-SME9813G-CBS- Accident Claim - SML9483M

WITHOUT PREJUDICE

Dear Sir

We will be assigning M/s LKK AUTO CONSULTANTS to survey your client's vehicle.

Aside to LKK AUTO CONSULTANTS,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

### Chong Boon Sen

Claims Executive  
Department

#### China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平狮城 Taiping SG 3 Anson  
Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**From:** Auburn Auto [mailto:auburnauto.insurance@gmail.com]  
**Sent:** Monday, October 21, 2019 1:39 PM  
**To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Subject:** Re: OUR REF: SNM19D204945-SME9813G-CBS- Accident Claim - SML9483M

Dear Sir,

We would like Adrian Ling to be our surveyor for this case.

Kindly contact Charles Lim at 9093 8998 **before** the surveyor comes down to the workshop.

Regards,

On Mon, Oct 21, 2019 at 1:30 PM Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)> wrote:

Without Prejudice

Dear Sir,

Pls choose one.

**Chong Boon Sen**

Claims Executive

Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**From:** Auburn Auto [mailto:[auburnauto.insurance@gmail.com](mailto:auburnauto.insurance@gmail.com)]

**Sent:** Monday, October 21, 2019 1:26 PM

**To:** Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>

**Subject:** Re: OUR REF: SNM19D204945-SME9813G-CBS- Accident Claim - SML9483M

Dear Sir,

Please send your surveyor down on the 25th October 2019.

Kindly contact Charles at 9093 8998 **before** the surveyor comes down to the workshop.

Auburn Auto  
176, Sin Ming Drive  
#04-18 Sin Ming Autocare  
Singapore 575721

On Mon, Oct 21, 2019 at 10:58 AM Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)> wrote:

Without prejudice  
Dear Sir,  
LKK  
STA  
LBS

**Chong Boon Sen**

Claims Executive

Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

---

**From:** Claims Dept of CTI

**Sent:** Friday, October 18, 2019 3:25 PM

**To:** Auburn Auto <[auburnauto.insurance@gmail.com](mailto:auburnauto.insurance@gmail.com)>; Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>;  
Chee So Chow <[sochow.chee@sg.cntaiping.com](mailto:sochow.chee@sg.cntaiping.com)>

**Subject:** OUR REF: SNM19D204945-SME9813G-CBS- Accident Claim - SML9483M

Dear Boon Sen,

Please conduct PRS for SML9483M.

Note : officer in charge – Boon Sen 63896171.

Regards,

Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909

T: (65) 63896116 | F: (65) 62247175

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

**From:** Auburn Auto [<mailto:auburnauto.insurance@gmail.com>]

**Sent:** Friday, 18 October, 2019 2:40 PM

**To:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>

**Subject:** Accident Claim - SML9483M

Dear Officer,

Your client's vehicle SME9813G was involved in an accident with our vehicle SML9483M which is pending repair.

In this regard, please provide us a list of your surveyors which we can select one to go on a Single Joint Expert survey. Kindly contact Charles 9742 8009 for survey appointment at :

Auburn Auto  
176, Sin Ming Drive  
#04-18 Sin Ming Autocare  
Singapore 575721

Thank you.  
Claims Department

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---



---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	17/10/2019 15:02
Date Of Accident	15/10/2019 08:50
Exact Location Of Accident	BALMORAL ROAD TOWARDS DUNEARN ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SML9483M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	GEN CAPITAL PTE. LTD.
Co Reg No	201542883W
Email Address	IMIN84@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-87978998
Alternative Phone No	OFFICE-87978998

### Vehicle Particulars

Manufacturer	BMW
Model	525I
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	5108973687 (TP)
Cover Note Number	

### Driver

Name of Driver	KARLMAL IMIN
NRIC No	S8400305J
Date Of Birth	04/01/1984
Occupation	OUTDOOR
Date Of Driving Pass	19/03/2010
Driving Experience	9 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91631574
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 732 TAMPINES STREET 71 #08-105
Postcode	520732
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : PASSENGER
	GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TANGLIN POLICE DIVISIONAL HQ ( 'E' DIVISION )
Police Station Address	ROAD: 21 KAMPONG JAVA ROAD , POSTCODE: 228892 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-3910000 - FAX NO: 63964900
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER STATEMENT AND POLICE REPORT (ATTENDED BY: JAMES NG)

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SME9813G
Vehicle Make/Model/Colour	LEXUS ES250
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	JANE
NRIC/Passport Number	
Contact Number	96963120
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name	KARLMAL IMIN
Approximate Age	35
Injuries Sustain	NECK, SHOULDER AND LOWER BACK PAIN
Injured person in which vehicle?	SML9483M
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	BLK 732 TAMPINES STREET 71 #08-105
Postcode	520732

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by Interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:


Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

17 OCT 2019

**NG WING KIN JAMES**  
admin.vac@vicom.com.sg

25051881E NG WING KIN JAMES



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 15/10/2019 at about 0850 Hours, I was driving my BMW 525 bearing plate number SML9483M along Balmoral Road towards Dunearn Road.

Upon green light, I turned right after the car in front drove off. I stopped, looked left and right to ensure clearance and drove on. A car came speeding towards my left and collided into my front. She failed to slow down as I was already turning having my right of way. She apologised for the accident. We exchanged particulars. It caused severe damages to my car.

Due to the accident, I suffered neck, shoulder and lower back pain. I have seen a doctor and was given 3 days MC with strong medications.

DECLARATION  
I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

17 OCT 2019

**NG WING KIN JAMES**  
admin.vac@vicom.com.sg



**SINGAPORE  
POLICE FORCE**



E/20191016/7007

1 of 2

**POLICE REPORT (NP299)**

Report No. E/20191016/7007

Police Station Of Origin  
Tanglin Division HQ  
21 Kampong Java Road SINGAPORE  
228892  
Tel No: 1800-3910000

Date/Time Report Made 16/10/2019 12:30	Vide Report No.	Station Diary No.
Name Of Informant KARLMAL IMIN	Address APT BLK 732 TAMPINES STREET 71 #08-105 SINGAPORE 520732	
ID Type / ID No. NRIC NO / S8400305J	Contact No. Home/Office:	Mobile: 91631574
Nationality SINGAPORE CITIZEN	Email Address imin84@hotmail.com	
Occupation Driver	Sex Male	Age 35
Institution/School Name	Date of Birth 04/01/1984	Race Javanese
Date/Time Of Incident 15/10/2019 08:55 - 15/10/2019 09:00	Location Of Incident DUNEARN ROAD	

**Brief details.**

On 15/10/2019 at about 0855hrs, I was driving my BMW525 bearing plate number SML9483M along Balmoral Road towards Dunearn Road upon green light, I turned right after the car in front drove off. I stopped, looked left and right to ensure clearance and drove on. A car came speeding towards my left and collided into my front. She failed to slow down as I was already turning having my right of way. She apologised for the accident. We exchanged particulars. It caused severe damages to my car. Due to the accident, I suffered neck, shoulder and lower back pain. I have seen a doctor and was given 3 days MC with strong medications.

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 16/10/2019 12:30
Officer In-Charge Of Case:	Classification Of Case:

Authentication Stamp



**SINGAPORE  
POLICE FORCE**



E/20191016/7007

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. E/20191016/7007

Subjects Involved			
Victim			
Person Name	KARLMAL IMIN		
ID Type	NRIC NO	ID No	S8400305J
Gender	Male	Age	35
Race	Javanese	Language	English
Occupation	Driver	Address Type	
Address	APT BLK 732 TAMPINES STREET 71 #08-105 SINGAPORE 520732		Mobile No 91631574
Is Informant A Victim?	Yes		
Person Name	KARLMAL IMIN (Informant)		

Signature Of Officer Recording The Report:

Not applicable

Signature Of Interpreter:

Not applicable

Officer In-Charge Of Case:

Authentication Stamp

Signature Of Informant:

The identity of the person making this report has been authenticated by SingPass. No signature is required.

Date/Time:

16/10/2019 12:30

Classification Of Case:



AUBURN AUTO PTE LTD

UEN : 200805305G

176 Sin Ming Drive Autocare #04-18, Singapore 575721

Tel : 8797 8998

Email : auburnauto.insurance@gmail.com

Vehicle Number : SML9483M

Make & Model : BMW 525i XL

Quantity	Description	Repairer's Estimate
<b>FRONT</b>		
1	Front bumper Tow Cover	\$150 53.2
1	Right Headlight Clip	\$150 30
1	Fog light Cover	\$250 65.85
1	Front Bumper UnderTray Cover	\$250 155.1
1	Front Grill Right	\$250 118
1	Front Grill Left	\$250 118
1	Right Side Headlamp Bracket	\$450 26
1	Left Chasis Garnish	\$500 201.6
1	Right Chasis Garnish	\$500 201.6
1	Front Rear Enforcement Bar	\$500 376.5
1	Right Indicators	\$500 234.65
1	Left Indicators	\$500 X
1	Right Side Headlight	\$500 X
1	Front Driver Side Panel	\$800 X
1	Front Support	\$800 X
1	Aircon condenser	\$1,000 /
1	Front Reinforcement	\$1,000 673.85
1	Left Headlight	\$1,500 X
1	Right Headlight	\$1,500 /
1	Front Bumper	\$1,200 /
<b>LABOUR &amp; MISC</b>		
1	Tow	\$200
	Checking of wiring, lighting and resetting	\$850
	Remove and refit rear undercarriage	\$500
	Wheel alignment	\$300
	Remove and replace damaged parts	\$1,000
	Apply undercoating on repaired and replaced panel	\$800
	Workmanship to dismantle above damaged parts, repairs including cut and weld, realign body structure	\$1,200

- mis.  
 7 - m/c  
 - m/c  
 X - CRA  
 X - BR  
 X - SDR  
 X - BT  
 X - CRA  
 X - NN  
 X - repeat.  
 X - repair.  
 X - BT  
 X - NN  
 - CRA  
 - CRA. 779.74  
 X 50  
 30 - 5% 7409.75  
 X - NN  
 X - NN  
 100  
 X 60  
 400

Donnet \$1845.39 / BT

	Respray including polishing and waxing on the changed body parts, repaired portions where consistent to the accident	\$1,000
	<b>GRAND TOTAL</b>	<b>\$12,550</b>

~~400~~ 600

1240

14,395.39

4 Days.

Long run repair.

After repair photos.

Guo Qiang - 82880282

25/10/19.

8649.75

20% 6200

**UK Auto Concords hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

20245.39

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Nov 2019		19 Nov 2019 13:41 <a href="#">Edit Adj Rpt</a>	<b>\$6,200.00</b> <a href="#">Edit Estimates</a>	<b>\$6,200.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main		Reference		Claim Details		Documents		Show All
------	--	-----------	--	---------------	--	-----------	--	----------

<b>CLAIM SUBFOLDER DETAILS</b>				<b>[Created by insurer]</b>			
Insured:	-, Co. Reg. No.: -						
Main Claimant:	GEN CAPITAL PTE. LTD., Co. Reg. No.: 201542883W						
Vehicle Reg. No.:	SML9483M			Date of Loss:	15/10/2019 08:00 - :59 [114 Months and 14 Days From LTA Reg Date (Man Yr)]		
Claim Type:	TP / SNM19D204945C02			Policy/Cover Note No.:	DMPCSN18345918000		
Vehicle Reg. No. (Insured):	SME9813G			Policy No. (Claimant):	5108973687 (TP)		
				Excess:	S\$0.00		
Repairer:	Auburn Auto Pte Ltd (HQ) 176 SIN MING DRIVE, #04-18 SIN MING AUTOCARE, 575721 Sin Ming - Tel:						
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]						
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:						
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 28/11/2019]						

<b>ASSOCIATED MAIL RECEIVED</b>				<a href="#">View All</a>		<a href="#">Compose Case Mail</a>	
There are no mail for this case.							

<b>ALL ASSOCIATED TASKS</b>				<a href="#">View All</a>		<a href="#">Search Tasks</a>		<a href="#">Create New Task</a>		<a href="#">Complete</a>	
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?		
No results.											

## Claim Documents

\*SML9483M (SNM19D204945C02)

[SME9813G]

TP

GEN CAPITAL PTE. LTD.

Oct 15 2019 8:00AM

[-]

Auburn Auto Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Assessment Reports

1 per page
























































No	Finalized On	VAC (Sin Ming)		Thumbnail	Print
1	18/10/19 09:54	Accident Statement		Load HTM	











































Photos/Images

3 per page



No	Finalized On	VAC (Sin Ming)		Thumbnail	Print
1	17/10/19 15:17	Accident Photo [Linked Accident Report Documents]		Load JPG	
2	17/10/19 15:17	Accident Photo [Linked Accident Report Documents]		Load JPG	
3	17/10/19 15:17	Accident Photo [Linked Accident Report Documents]		Load JPG	
4	17/10/19 15:18	Accident Photo [Linked Accident Report Documents]		Load JPG	
5	17/10/19 15:18	Accident Photo [Linked Accident Report Documents]		Load JPG	
6	17/10/19 15:18	Accident Photo [Linked Accident Report Documents]		Load JPG	

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	20/11/19 09:33	General View		Load JPG	
2	20/11/19 09:33	General View		Load JPG	
3	20/11/19 09:33	General View		Load JPG	
4	20/11/19 09:33	General View		Load JPG	
5	20/11/19 09:33	General View		Load JPG	
6	20/11/19 09:33	General View		Load JPG	
7	20/11/19 09:33	General View		Load JPG	
8	20/11/19 09:33	General View		Load JPG	
9	20/11/19 09:33	General View		Load JPG	
10	20/11/19 09:33	General View		Load JPG	
11	20/11/19 09:33	General View		Load JPG	
12	20/11/19 09:33	General View		Load JPG	
13	20/11/19 09:33	General View		Load JPG	
14	20/11/19 09:33	General View		Load JPG	
15	20/11/19 09:33	General View		Load JPG	
16	20/11/19 09:33	General View		Load JPG	
17	20/11/19 09:33	General View		Load JPG	
18	20/11/19 09:33	General View		Load JPG	
19	20/11/19 09:33	General View		Load JPG	
20	20/11/19 09:33	General View		Load JPG	
21	20/11/19 09:33	General View		Load JPG	
22	20/11/19 09:33	General View		Load JPG	
23	20/11/19 09:33	General View		Load JPG	
24	20/11/19 09:33	General View		Load JPG	
25	20/11/19 09:33	General View		Load JPG	
26	20/11/19 09:33	General View		Load JPG	
27	20/11/19 09:33	General View		Load JPG	
28	20/11/19 09:33	General View		Load JPG	
29	20/11/19 09:33	General View		Load JPG	
30	20/11/19 09:33	General View		Load JPG	
31	20/11/19 09:33	General View		Load JPG	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
				<input checked="" type="checkbox"/>
32	20/11/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
33	20/11/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
34	20/11/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
35	20/11/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
36	20/11/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
37	20/11/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
38	20/11/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
39	20/11/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
40	20/11/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
41	20/11/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
42	20/11/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
43	20/11/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
44	20/11/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
45	20/11/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
46	20/11/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
47	20/11/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
48	20/11/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
49	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
87	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	20/11/19 09:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
1	18/10/19 09:53	<b>Sketch Plan</b> [Linked Accident Report Documents]	 Load TIF	
2	18/10/19 09:53	<b>Sketch Plan #2</b> [Linked Accident Report Documents]	 Load TIF	
3	18/10/19 09:53	<b>Sketch Plan #3</b> [Linked Accident Report Documents]	 Load TIF	
4	18/10/19 09:53	<b>Sketch Plan #4</b> [Linked Accident Report Documents]	 Load TIF	

### Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
1	18/10/19 09:54	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
1	17/10/19 15:17	Accident Photo	 Load JPG	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
				<input checked="" type="checkbox"/>
2	17/10/19 15:17	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	17/10/19 15:17	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	17/10/19 15:18	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	17/10/19 15:18	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	17/10/19 15:18	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
1	18/10/19 09:53	Sketch Plan	Load TIF	
2	18/10/19 09:53	Sketch Plan #2	Load TIF	
3	18/10/19 09:53	Sketch Plan #3	Load TIF	
4	18/10/19 09:53	Sketch Plan #4	Load TIF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119018527/GSD3E2

Date: 02/12/2019

## REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN18345918000

Claimant Vehicle No : SML9483M Insured Vehicle No : SME9813G

Date of Loss: 15/10/2019 Nature of Claim: TP Claim No: SNM19D204945C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SML9483M**

Make & Model: BMW 525i, 2.5 XL (E60) (A) Engine No: 74954548N52B25AF

Reg. Date: 01/04/2010 (Man. Year: 2009) Chassis No: WBANU52000C228774

Colour: Black Odometer: 228338 km

Engine Capacity: 2497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 245/45 R17 Rear Tyre Size: 245/45 R17

Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,395.39	7,409.75	6,985.64	48.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,850.00	1,240.00	4,610.00	78.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>20,245.39</b>	<b>8,649.75</b>	<b>11,595.64</b>	<b>57.28</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,200.00</b>		
<b>Nett Amount (S\$)</b>	<b>20,245.39</b>	<b>6,200.00</b>	<b>14,045.39</b>	<b>69.38</b>

## INSPECTION

Date of Assignment: 19/11/2019

Date Inspected: 25/10/2019 Inspected At:

Auburn Auto Pte Ltd (HQ)  
176 SIN MING DRIVE, #04-18 SIN  
MING AUTOCARE  
Singapore 575721

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.





MARKET VALUE: \$33,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$26,580.00 =NETT VALUE: \$6,420.00

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 02 Dec 2019)
<b>Parts:</b>	143	BMW 525i 2.5 XL (E60) (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SML9483M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER TOW COVER	Missing	150.00 F	*53.20 FL
2	1		*RIGHT HEADLIGHT CLIP	Necessary	150.00 F	*30.00 FL
3	1		*FOG LIGHT COVER	Missing	250.00 F	*65.85 FL
4	1		*FRONT BUMPER UNDERTRAY COVER	Cracked	250.00 F	*155.10 FL
5	1		*FRONT GRILL RIGHT	Cracked	250.00 F	*118.00 FL
6	1		*FRONT GRILL LEFT	Cracked	250.00 F	*118.00 FL
7	1		*RIGHT SIDE HEADLAMP BRACKET	Broken	450.00 F	*26.00 FL
8	1		*LEFT CHASIS GARNISH	Deformed	500.00 F	*201.60 FL
9	1		*RIGHT CHASIS GARNISH	Deformed	500.00 F	*201.60 FL
10	1		*FRONT REAR ENFORCEMENT BAR	Bent	500.00 F	*376.50 FL
11	1		*RIGHT INDICATORS	Cracked	500.00 F	*234.65 FL
12	1		*LEFT INDICATORS	Not Necessary	500.00 F	*- FL
13	1		*RIGHT SIDE HEADLIGHT	Repeated	500.00 F	*- FL
14	1		*FRONT DRIVER SIDE PANEL	Repair	800.00 F	*- FL
15	1		*FRONT SUPPORT	Repair	800.00 F	*- FL
16	1		*AIRCON CONDENSER	Bent	1,000.00 F	*1,000.00 FL
17	1		*FRONT REINFORCEMENT	Bent	1,000.00 F	*673.85 FL
18	1		*LEFT HEADLIGHT	Not Necessary	1,500.00 F	*- FL
19	1		*RIGHT HEADLIGHT	Cracked	1,500.00 F	*1,500.00 FL
20	1		*FRONT BUMPER	Cracked	1,200.00 F	*1,200.00 FL
21	1		*BONNET	Bent	1,845.39 F	*1,845.39 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>14,395.39</b>	<b>7,799.74</b>
<b>- List Item Discount on L Items 0.00/5.00% (S\$)</b>	<b>0.00</b>	<b>389.99</b>
<b>Total Parts (S\$)</b>	<b>14,395.39</b>	<b>7,409.75</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CHECKING OF WIRING, LIGHTING AND RESETTNG	New	850.00	30.00
2	REMOVE AND REFIT REAR UNDERCARRIAGE	New	500.00	0.00
3	WHEEL ALIGNMENT	New	300.00	0.00
4	REMOVE AND REPLACE DAMAGED PARTS	New	1,000.00	100.00
5	APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL	New	800.00	60.00
6	WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS, REPAIRS INCLUDING CUT AND WIELD, REALIGN BODY STRUCTURE	New	1,200.00	400.00
7	RESPRAY INCLUDING POLISHING AND WAXING ON THE CHANGED BODY PARTS, REPAIRED PORTORTIONS WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	600.00
8	TOW	New	200.00	50.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,850.00</b>	<b>1,240.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >