



## SMRT Accident Vehicle Repair Estimates

|                                                   |
|---------------------------------------------------|
| SMRT Automotive Services Pte Ltd                  |
| 60 Woodlands Industrial Park E4, Singapore 757705 |
| FAX Number : 63685592                             |
| Estimator Telephone Number : 68662623             |
| Accident Reporting Number : 68662672              |

Date Generated : 22/11/2019

User ID : CatherineLee

| Section A - Accident Details       |                                                                              |
|------------------------------------|------------------------------------------------------------------------------|
| Registration Number                | SMB77P                                                                       |
| Case Reference Number              | BUS/10/19/5012                                                               |
| Registration Date                  | 30/6/2009                                                                    |
| Company Type                       | SMRT Buses Ltd                                                               |
| Make                               | MERCEDES                                                                     |
| Model                              | MBOC500                                                                      |
| Name of Driver                     | Mohamad Naqib Bin Mohamed Khalid                                             |
| Type of Accident                   | Head To Side                                                                 |
| Accident Date and Time             | 14/10/2019 12:27 PM                                                          |
| Accident Reported Date and Time    | 14/10/2019 2:15 PM                                                           |
| Is Surveyor Required?              | Yes                                                                          |
| Survey by                          |                                                                              |
| Vehicle is Towed Back?             | No                                                                           |
| Towed Back Date and Time           |                                                                              |
| Replacement Vehicle issued?        | No                                                                           |
| Job Card Number                    | 24103933                                                                     |
| Special Instruction to ARC, if any | SMB77P - RIGHT CENTRE TO REAR PORTION<br>SJL5388S (TP) - INSURED WITH LONPAC |
| Prepared Date and Time             | 15/10/2019 4:45 PM                                                           |
| Chassis Number                     | WEB63442021000186                                                            |
| Mileage                            |                                                                              |
| Work Shop                          |                                                                              |
| Repair Completion Date and Time    |                                                                              |

| Section B - Summary of Repair Estimates |                                                                                     |                                                                                     |
|-----------------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| Summary of Repair Estimates             |                                                                                     |                                                                                     |
|                                         | Quotation from ARC                                                                  | Adjusted by Surveyor, if applicable                                                 |
| Total Labour Cost                       | \$2,120.00                                                                          | \$1,855.00                                                                          |
| Total Spray Cost                        | \$1,112.00                                                                          | \$942.00                                                                            |
| Total Spare Part Cost                   | \$3,967.94                                                                          | \$2,648.39                                                                          |
| Total Other Cost                        | \$0.00                                                                              | \$0.00                                                                              |
| <b>TOTAL COST</b>                       | <b>\$7,199.94</b>                                                                   | <b>\$5,446.39</b>                                                                   |
| Lump Sum Total                          | \$0.00                                                                              | \$5,450.00                                                                          |
| Number of Repair Days                   | 5.0                                                                                 | 5.0                                                                                 |
| Prepared / Adjusted By                  | Jeong Choon Hwee                                                                    | STEVE CHEN                                                                          |
| ARC / Surveyor Sign Off Date            | 15/10/2019 5:12 PM                                                                  | 18/10/2019 5:42 PM                                                                  |
| Signature                               |  |  |
| Remarks                                 |                                                                                     |                                                                                     |

| Section C - Quotation and Accident Invoice Details |  |                |  |
|----------------------------------------------------|--|----------------|--|
| Quotation Number                                   |  | Invoice Number |  |
| Quotation Date                                     |  | Invoice Date   |  |
| Invoice Amount                                     |  | Prepared Date  |  |



## SMRT Accident Vehicle Repair Estimates

|                                                   |
|---------------------------------------------------|
| SMRT Automotive Services Pte Ltd                  |
| 80 Woodlands Industrial Park E4, Singapore 757705 |
| FAX Number : 63685592                             |
| Estimator Telephone Number : 68662623             |
| Accident Reporting Number : 68662672              |

Date Generated : 22/11/2019

User ID : CatherineLee

### Section D - Details of Repair Estimates

| Part 1 - Labour Works                                                         |                   |                                     |
|-------------------------------------------------------------------------------|-------------------|-------------------------------------|
| Job Scope                                                                     | Quotation from AR | Adjusted by Surveyor, if applicable |
| TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS. | \$2,120.00        | \$1,855.00                          |
| Total Labour                                                                  | \$2,120.00        | \$1,855.00                          |

| Part 2 - Spray Painting & Panel Beating Related Works |                    |                                     |
|-------------------------------------------------------|--------------------|-------------------------------------|
| Job Scope                                             | Quotation from ARC | Adjusted by Surveyor, if applicable |
| TO PUTTY & RESPRAY                                    | \$1,112.00         | \$942.00                            |
| Total Spray Painting & Panel Beating                  | \$1,112.00         | \$942.00                            |

| Part 3 - Other Costs - Accident and Accident Repair Related Expense |                    |                                     |
|---------------------------------------------------------------------|--------------------|-------------------------------------|
| Job Scope                                                           | Quotation from ARC | Adjusted by Surveyor, if applicable |
| Total Other Costs                                                   |                    |                                     |

| Part 4 - Spare Parts / Material Usage |            |                 |                                         |          |                 |              |                  |                    |                   |
|---------------------------------------|------------|-----------------|-----------------------------------------|----------|-----------------|--------------|------------------|--------------------|-------------------|
| Part Number                           | Portion    | Stock Number    | Part Name                               | Quantity | List Price (\$) | Discount (%) | Final Price (\$) | Estimator Approved | Surveyor Approved |
| 6010227                               | BODY RH    | 5019            | PANEL SKIRT:R4, FOR MB OC500 BUS        | 1.00     | \$1,442.10      | 10.00        | \$1,297.89       | Replace            | Replace           |
| 6010229                               | BODY RH    | 5021            | PANEL SKIRT:R6, FOR MB OC500 BUS        | 1.00     | \$518.20        | 100.00       | \$0.00           | Repair             | Repair            |
| 6010232                               | BODY RH    | 5024            | PANEL SKIRT:R9, FOR MB OC500 BUS        | 1.00     | \$307.10        | 10.00        | \$276.39         | Replace            | Replace           |
| 6010234                               | BODY RH    | 5026            | PANEL SKIRT:R11, FOR MB OC500 BUS       | 1.00     | \$642.80        | 10.00        | \$578.52         | Replace            | Replace           |
| 6010235                               | BODY RH    | 5027            | PANEL SKIRT:R12, FOR MB OC500 BUS       | 1.00     | \$2,430.20      | 100.00       | \$0.00           | Replace            | Repair            |
| 6010244                               | Body       | 5039            | FRAME SKIRT PANEL:R11, FOR MB OC500 BUS | 1.00     | \$365.70        | 10.00        | \$329.13         | Replace            | Replace           |
| 4021335                               | CONSUMABLE | Sikaflex-265    | SEALANT.SIKATAK-MOVE TRANSPORTATION     | 10.00    | \$37.00         | 0.00         | \$370.00         | Replace            | Replace           |
| 4006315                               | CONSUMABLE | Aktivator - 100 | ACTIVATOR                               | 1.00     | \$80.00         | 0.00         | \$80.00          | Replace            | Replace           |
| 4006313                               |            |                 | PRIMER                                  | 1.00     | \$80.00         | 0.00         | \$80.00          | Replace            | Replace           |
|                                       |            |                 | SMRT STCKER                             | 1.00     | \$75.00         | 0.00         | \$75.00          | Replace            | Replace           |
| 6010330                               |            |                 | WHEEL ARCH TRIM                         | 2.00     | \$124.20        | 10.00        | \$223.56         | Replace            | Replace           |
| 6010411                               |            |                 | GAS SPRING 22N                          | 2.00     | \$94.90         | 100.00       | \$0.00           | Replace            | Repair            |
| Total                                 |            |                 |                                         |          | \$6,197.20      |              | \$3,310.49       |                    |                   |

Supp / REC  
Supp / REC  
Supp / REC  
Supp / REC

| Added Spare Parts / Material Usage After Surveyor Signed off |         |              |           |          |                 |              |                  |           |                |
|--------------------------------------------------------------|---------|--------------|-----------|----------|-----------------|--------------|------------------|-----------|----------------|
| Part Number                                                  | Portion | Stock Number | Part Name | Quantity | List Price (\$) | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check |
| Total                                                        |         |              |           |          |                 |              |                  |           |                |

3310.49  
L/S - 2648.39  
2797  
5445.39  
= 5450



## SMRT Accident Vehicle Repair Estimates

|                                                   |
|---------------------------------------------------|
| SMRT Automotive Services Pte Ltd                  |
| 60 Woodlands Industrial Park E4, Singapore 757705 |
| FAX Number : 63685592                             |
| Estimator Telephone Number : 68662623             |
| Accident Reporting Number : 68662672              |

Date Generated : 16/10/2019

User ID : JeongCH

### Section A - Accident Details

|                                    |                                                                              |
|------------------------------------|------------------------------------------------------------------------------|
| Registration Number                | SMB77P                                                                       |
| Case Reference Number              | BUS/10/19/5012                                                               |
| Registration Date                  | 6/30/2009                                                                    |
| Company Type                       | SMRT Buses Ltd                                                               |
| Make                               | MERCEDES                                                                     |
| Model                              | MBOC500                                                                      |
| Name of Driver                     | Mohamad Naqib Bin Mohamed Khalid                                             |
| Type of Accident                   | Head To Side                                                                 |
| Accident Date and Time             | 10/14/2019 12:27 PM                                                          |
| Accident Reported Date and Time    | 10/14/2019 2:15 PM                                                           |
| Is Surveyor Required?              | No                                                                           |
| Survey by                          |                                                                              |
| Vehicle is Towed Back?             | No                                                                           |
| Towed Back Date and Time           |                                                                              |
| Replacement Vehicle issued?        | No                                                                           |
| Job Card Number                    |                                                                              |
| Special Instruction to ARC, if any | SMB77P - RIGHT CENTRE TO REAR PORTION<br>SJL5388S (TP) - INSURED WITH LONPAC |
| Prepared Date and Time             | 10/15/2019 4:45 PM                                                           |
| Chassis Number                     | WEB63442021000186                                                            |
| Mileage                            |                                                                              |
| Work Shop                          |                                                                              |
| Repair Completion Date and Time    |                                                                              |

### Section B - Summary of Repair Estimates

| Summary of Repair Estimates  |                    |                                     |
|------------------------------|--------------------|-------------------------------------|
|                              | Quotation from ARC | Adjusted by Surveyor, if applicable |
| Total Labour Cost            | \$2,120.00         | \$0.00                              |
| Total Spray Cost             | \$0.00             | \$0.00                              |
| Total Spare Part Cost        | \$3,320.88         | \$0.00                              |
| Total Other Cost             | \$0.00             | \$0.00                              |
| TOTAL COST                   | \$3,320.88         | \$0.00                              |
| Lump Sum Total               | \$0.00             | \$0.00                              |
| Number of Repair Days        | 5.0                | 5                                   |
| Prepared / Adjusted By       | Jeong Choon Hwee   |                                     |
| ARC / Surveyor Sign Off Date | 15/10/2019 5:12 PM |                                     |
| Signature                    |                    |                                     |
| Remarks                      |                    |                                     |

### Section C - Quotation and Accident Invoice Details

|                  |  |                |  |
|------------------|--|----------------|--|
| Quotation Number |  | Invoice Number |  |
| Quotation Date   |  | Invoice Date   |  |
| Invoice Amount   |  | Prepared Date  |  |

18/10/19, 4.00 pm  
Steve (LKK) WM Mual  
S dy  
L/S  
My AL SM

SMRT Auto Collision Centre Notice

The Repair of the following vehicle is subject to the following conditions:

- The vehicle must be repaired at the SMRT Auto Collision Centre.
- The vehicle must be repaired within 14 days of the accident.
- The vehicle must be repaired by a qualified technician.
- The vehicle must be repaired using original equipment manufacturer (OEM) parts.

Accepted by:

Signature:

Date:





# SMRT Accident Vehicle Repair Estimates

|                                                   |
|---------------------------------------------------|
| SMRT Automotive Services Pte Ltd                  |
| 60 Woodlands Industrial Park E4, Singapore 757705 |
| FAX Number : 63685592                             |
| Estimator Telephone Number : 68662623             |
| Accident Reporting Number : 68662672              |

Date Generated : 16/10/2019

User ID : JeongCH

## Section D - Details of Repair Estimates

### Part 1 - Labour Works

| Job Scope                                                                     | Quotation from AR | Adjusted by Surveyor, if applicable |
|-------------------------------------------------------------------------------|-------------------|-------------------------------------|
| TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS. | \$2,120.00        | 1855                                |
| Total Labour                                                                  | \$2,120.00        |                                     |

### Part 2 - Spray Painting & Panel Beating Related Works

| Job Scope                            | Quotation from ARC | Adjusted by Surveyor, if applicable |
|--------------------------------------|--------------------|-------------------------------------|
| TO PUTTY & RESPRAY                   | \$0.00             | 942                                 |
| Total Spray Painting & Panel Beating | \$0.00             |                                     |

### Part 3 - Other Costs - Accident and Accident Repair Related Expense

| Job Scope         | Quotation from ARC | Adjusted by Surveyor, if applicable |
|-------------------|--------------------|-------------------------------------|
| Total Other Costs |                    |                                     |

### Part 4 - Spare Parts / Material Usage

| Part Number | Portion | Stock Number | Part Name                               | Quantity | List Price (\$) | Discount (%) | Final Price (\$) | Estimator Approved | Surveyor Approved |
|-------------|---------|--------------|-----------------------------------------|----------|-----------------|--------------|------------------|--------------------|-------------------|
| 6010227     | BODY RH | 5019         | PANEL SKIRT R4, FOR MB OC500 BUS        | 1.00     | \$1,442.10      | 10.00        | \$1,297.89       | Replace            | / DD              |
| 6010229     | BODY RH | 5021         | PANEL SKIRT R6, FOR MB OC500 BUS        | 1.00     | \$518.20        | 100.00       | \$0.00           | Repair             | X R               |
| 6010232     | BODY RH | 5024         | PANEL SKIRT R9, FOR MB OC500 BUS        | 1.00     | \$307.10        | 10.00        | \$276.39         | Replace            | / DD              |
| 6010234     | BODY RH | 5026         | PANEL SKIRT R11, FOR MB OC500 BUS       | 1.00     | \$642.80        | 10.00        | \$578.52         | Replace            | /                 |
| 6010235     | BODY RH | 5027         | PANEL SKIRT R12, FOR MB OC500 BUS       | 1.00     | \$2,430.20      | 10.00        | \$2,187.18       | Replace            | / DD              |
| 6010244     | Body    | 5039         | FRAME SKIRT PANEL R11, FOR MB OC500 BUS | 1.00     | \$365.70        | 10.00        | \$329.13         | Replace            | / DD              |
|             |         |              | SMRT STCKER                             | 1.00     | \$75.00         | 0.00         | \$75.00          | Replace            | / MC              |
| Total       |         |              |                                         |          | \$5,781.10      |              | \$4,744.11       |                    |                   |

### Added Spare Parts / Material Usage After Surveyor Signed off

| Part Number | Portion | Stock Number | Part Name | Quantity | List Price \$ | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check |
|-------------|---------|--------------|-----------|----------|---------------|--------------|------------------|-----------|----------------|
| Total       |         |              |           |          |               |              |                  |           |                |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: