

12/03/19

ASS. REC. BY:

REF: CS3/MSG 19014091/Ty 43-1

Special Instructions:

Survivor: Taufik H

ASSIGNMENT (Office)

From (Person): Irene Tan Cat Jng of MS16

Date/Time: 19.10.2019

Estimated Cost:

Bill to:

OD (TP) WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKL 8327U

Insured: SKA 76024

at Workshop m/s Eng Hup Seng

Tel: 9622 1030

of BIK 1 NO 2 Pandan Loop

Policy No: 80424427AVW

Claim No: 602241

Sun Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 6.8.2019

CA / REV / REP. / REV 24 HRS

Date/Time: 14.8.2019 10.30.00

Person Contacted:

Mr Lai

H.O.D. Endorsement:

Vehicle-IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SKL 8327U ->
	SKA 76024 - VBA / MSG 13013031/1
	Before paint: 16/8/2019
	After paint: 21/8/2019

31/10/19 Typist



23/10/2019

Do Not Finalise

 \$3205.04, 4 days
 (Red \$610, 16%)

RECEIVED 3 OCT 2019

Signature

Tan Jie

REF: MS9

ASSIGNMENT

From: (Date) 15.8.2019

Estimated Cost:

OD TP WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKL 3327U

at Workshop m/s Eng Hup Seng

at Bkt 1 Pandan Loop #01-02

Insured

Policy No

Claims No

Sum Insured


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / FR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: % 3 Vol: Yes or No

CA / REV / REP. / 24 HRS

my"

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKL 3327U - 1st Regn

20/6 April

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel Hybrid 1496

Colour: Blue - AC Insured / Std / NI / NA

Sp. Reading: 84/87 T/Std: Insured / Std / NI / NA

Eng No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A: 15/8/19 012.5

Survey held at: Eng Hup Seng

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Roof Top or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

- MV - 69000

- PV - 39388

- NV - 79600

MV - 68-69

Range - \$25-3K
repair days - 4 days

Date/Time, File Pass to?

☐ : Proli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Report Format: PRG.

Lump Sum / I.B.I: (\$)

Survey Fee

Transportation

3 - RS - SI

Phone

Others

TOTAL

120
11
131

5/9/2015

Nivitha (LKK Auto)

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Monday, 21 October 2019 7:44 AM
To: Irene Tan; Shiao Chan (LKKAuto); Denise Tay (LKKAuto); Celine Fong (LKKAuto); assignments
Cc: Admin-D (LKKAuto); Olivia Lau (LKKAuto); Shirley Hiew (LKK Auto)
Subject: RE: Please prepare paper survey report on SKL3327U; Our claim no.: 602241/IT

Dear Irene,

Thank you for the email.

Dear Assignment Team,

FYNA

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Irene Tan <irene_tan@sg.msig-asia.com>
Sent: Saturday, 19 October 2019 6:43 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Shiao Chan (LKKAuto) <siewsc@lkkauto.com>; Denise Tay (LKKAuto) <denisetay@lkkauto.com>; Celine Fong (LKKAuto) <celinefong@lkkauto.com>
Cc: Admin-D (LKKAuto) <admin-d@lkkauto.com>; Olivia Lau (LKKAuto) <olivialau@lkkauto.com>; Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Subject: Please prepare paper survey report on SKL3327U; Our claim no.: 602241/IT
Importance: High

Good evening Veron,

We refer to your PRI report dated 23.9.19.

Please upload your paper survey report asap.

Irene Tan
Senior Executive, Motor Claims Services
D: +65 6594 2541 | F: +65 6225 7402 | irene_tan@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

Nivitha (LKK Auto)

From: Accounts (LKKAuto) <account@lkkauto.com>
Sent: Monday, 21 October 2019 1:53 PM
To: Admin-D (LKKAuto)
Cc: Accounts (LKKAuto)
Subject: RE: Report Send Back Alerts - SKL3327U (TP)

Dear Nivitha,

FYNA Please...

Pending for Survey Report-CS3/MSG19014091/T1CF3E2

28 19 Oct 2019 18:44	Ins Send Back Adj Rpt	Please prepare paper survey report.	[I] Irene Tan Gek Ing
29 19 Oct 2019 18:44	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/10/22	[I] Merimen Administrator
30 19 Oct 2019 18:44	Adj Mandate Set	Maintained.	[I] Merimen Administrator

Best Regards,



SuthaShelia (Shelia) | Accounts Dept.

LKK Auto Consultants Pte Ltd

Phone: 6841 1891 | email: account@lkkauto.com | fax: 6844-8805

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Do-Not-Reply <do-not-reply@merimen.com>

Sent: Saturday, 19 October 2019 7:00 PM

To: account@lkkauto.com

Subject: Report Send Back Alerts - SKL3327U (TP)

Dear Sir / Madam,

Please login to Merimen Online at www.merimen.com.sg for more information.

Thanks,

The Merimen Team



This email has been checked for viruses by AVG antivirus software.
www.avg.com

10 OCT 2019

K. K. CHENG & CO

Advocates & Solicitors
 101 Upper Cross Street #05-21
 People's Park Centre
 Singapore 058357
 Tel: 6227 1272 Fax: 6227 5563

Our Ref: CKK/ck/ACC/10567/19
 Your Ref: SKQ 7602Y
 (Please quote our reference number when replying)

- 8 OCT 2019

MSIG INSURANCE (SINGAPORE) PTE LTD
 Singapore

PDX Intercompany Exchange Pte Ltd
 010808799429
 FROM K K CHENG & CO.
 PDX Box No. 8921

BY PDX: 8173

Attention: Motor Claims Department

Dear Sirs

TAN HOCK TIAM
BLK 63 CHESTNUT AVENUE #20-13 SE (679523)

We are instructed by the above named to claim damages against your insured driver in connection with a road traffic accident on 06.08.2019 at about 5.15pm along Bukit Timah Road involving our client's vehicle registration number SKL 3327U and vehicle SKQ 7602Y owned by your insured at the material time.

We are instructed that the accident was caused by your insured driver's negligent driving and/or management of your insured's vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:-

(1)	costs of repairs	\$3,815.04
(2)	loss of use for 5days @ \$150 per day	\$ 750.00
(3)	further loss of use for 2 days of PRI	\$ 300.00
(4)	survey fees	\$ 620.00
(5)	GIA report	\$ 29.00
(6)	LTA search	\$ 8.50
(7)	coloured photographs	\$ 6.00
(8)	photocopying, postages, transport and other incidentals	\$ 50.00
(9)	costs	\$ 900.00
		<u>\$6,478.54</u>


A copy each of the following supporting documents is enclosed:

- (1) Plaintiff's GIA report
- (2) GIA report of SKQ 7602Y
- (3) Repair Bill
- (4) Surveyor's report attached with 23 coloured photographs of our client's damaged vehicle
- (5) Vehicle Owner Particulars and Vehicle & Owner Information
- (6) LTA search

Please note that you or your insured should send to us an acknowledgement of receipt of this letter within 14 days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against your insured without further notice to you or your insured.

Please also note that if your insured has a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

Yours faithfully



CHENG KIM KUAN
Encs

c.c. SCOTTS LEE COOPER
c.c. client
(Ref: SKL 3327U)

K. K. CHENG & CO

Advocates & Solicitors
101 Upper Cross Street #05-21
People's Park Centre
Singapore 058357
Tel: 6227 1272 Fax: 6227 5563

Our Ref: CKK/ck/ACC/10567/19
Your Ref: SKQ 7602Y
(Please quote our reference number when replying)

- 8 OCT 2019

BY CERTIFICATE OF POSTING

SCOTT LEE COOPER

Block 135 Sunset Way
#10-03
Singapore 597158

Dear Sirs

TAN HOCK TIAM

BLK 63 CHESTNUT AVENUE #20-13 SE (679523)

We are instructed by the above named to claim damages against you in connection with a road traffic accident on 06.08.2019 at about 5.15pm along Bukit Timah Road involving our client's vehicle registration number SKL 3327U and vehicle SKQ 7602Y owned and driven by you at the material time.

We are instructed that the accident was caused by your negligent driving and/or management of your vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:-

(1)	costs of repairs	\$3,815.04
(2)	loss of use for 5days @ \$150 per day	\$ 750.00
(3)	further loss of use for 2 days of PRI	\$ 300.00
(4)	survey fees	\$ 620.00
(5)	GIA report	\$ 29.00
(6)	LTA search	\$ 8.50
(7)	coloured photographs	\$ 6.00
(8)	photocopying, postages, transport and other incidentals	\$ 50.00
(9)	costs	<u>\$ 900.00</u>
		<u>\$6,478.54</u>

永 合 成 摩 哆
ENG HUP SENG MOTOR

Block 1, No. 2, Pandan Loop, Pandan Light Industries Park, Singapore 128219
Tel: 777 2755 Fax: 778 5243

Your ref:

Our ref:

Date:

30 August 2019

TAN HOCK TIAM

C/O Block 1, No.2 Pandan Loop,

Pandan Light Industries Park, Singapore 128219

FINAL REPAIR BILL FOR VEHICLE NO. SKL 3327 U

Part – By – Part Repair \$3,815.04

Enquire Vehicle & Owner Information (Vehicle No. SKQ7602Y As At 06 Aug 2019 / 00:00:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: EHS/SKL3327U

Current Owner Details

Owner ID Type: Singapore NRIC
Owner ID: S2706876F
Owner Name: SCOTT LEE COOPER
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.: 135
Registered Street Name: SUNSET WAY
Registered Unit No.: # 10 - 03
Registered Building Name: -
Registered Postal Code: 597158

Current Vehicle Details

Vehicle No.: SKQ7602Y
Make Description/Model: VOLKSWAGEN / JETTA 1.4 TSI A/T ABS D/AIRBAG 2WD
Insurance Company Name: MSIG INSURANCE (SINGAPORE) PTE LTD

Print OK

PRECISION APPRAISAL SERVICES



Insurance Loss Assessors/ Adjusters Cargo Surveyors & Licensed Appraisers

227 Simei St 4 #06-42 Singapore 520227 Fax: 6444 4886 Company Registration No. 53139926E

To:

TAN HOCK TIAM
C/O Block 1, No.2 Pandan
Loop, Pandan Light Industries
Park, Singapore 128219

Invoice No.: 190813**DATE : 30 August 2019**

<u>DESCRIPTION</u>		AMOUNT
Vehicle Registration No. : SKL 3327 U		\$620.00
Type of Claims : Third Party Claims		
Our Reference No. : PAS/EHS/190813/TP		
Your Reference No. : -		
Inspection Report Fees : (including transportation charges & photographs)		
Reinspection Report Fees : -		
Transportation Charges : -		
(ditional Photographs : -		
Others (Specify) : -		
DOLLARS	SIX HUNDRED AND TWENTY ONLY	TOTAL: \$620.00



PRECISION APPRAISAL SERVICES

PRECISION APPRAISAL SERVICES

Insurance Loss Assessors/ Adjusters Cargo Surveyors & Licensed Appraisers

227 Simei St 4 #06-42 Singapore 520227 Fax: 64444886 Company Registration No. 53139926E



AUTOMOBILE INSPECTION REPORT

To:

TAN HOCK TIAM

**C/O Block 1, No.2 Pandan Loop,
Pandan Light Industries Park,
Singapore 128219**

INSURANCE DETAILS

Insured : -
Policy No. / Claim No. : -
Sum Insured : -
Excess Clause : -
Windscreen Coverage : -
Type of Claims : Third Party Claims
Third Party Insurer : -
Third Party Policy No. : -

REFERENCE

Assigned By : As Above
Accident Date : 06 AUGUST 2019
Assignment Date : 14 AUGUST 2019
Inspection Date : 14 AUGUST 2019
Our Reference No. : PAS/EHS/190813/TP

Inspection Report Date : 30 August 2019

Workshop Name :

ENG HUP SENG MOTOR

Inspection Address :

**Block 1, No.2 Pandan Loop, Pandan Light
Industries Park, Singapore 128219**

PARTICULARS OF VEHICLE

Registration No.	: SKL 3327 U	Mileage	: 84187	Km/h
Make/Model	: HONDA VEZEL 1.5Z HYBRID CVT ABS D/AIRBAG 2WD	Radio/Cassette	: Fitted	
Yr of Manuf/Regn	: 2015 / 2016	CD Disc Player	: Fitted	
Carrying Capacity	: 4Seater	Air Conditioner	: Fitted	
Chassis No.	: RU31125307	Clock	: Fitted	
Engine No.	: LEB5075325	Seat Belt	: Fitted	
Colour	: Metallic Blue	Wing Mirror Other	: Fitted	
Class	: Passenger (Private)	Accessories	: Fitted	

PRE-ACCIDENT CONDITION (Static Check Only)

Body Work : Good
Paint Work : Good
Handbrake : Serviceable
Footbrake : Serviceable
Steering : Serviceable
Any Apparent : None
Eng Modifications

VEHICLE VALUE

Market Value : -
Wreck Value (Parf) : -

TYRE SIZE & CONDITION

Front N/s Size : 215/55R17 80 %
Make : CONTINENTAL
Rear N/s size : 215/55R17 80 %
Make : CONTINENTAL
Spare Size : 215/55R17 80 %
Make : CONTINENTAL

Front O/s Size : 215/55R17 80 %
Make : CONTINENTAL
Rear O/s Size : 215/55R17 80 %
Make : CONTINENTAL
Spare Size :
Make :

VEHICLE REGISTRATION NO. : SKL 3327 U


APPENDIX A

3

POINT OF IMPACT

Direction of Impact/damage marked (→) (X)

The vehicle sustained impact On its Rear Portion. (see Diagram B)



GENERAL DESCRIPTION OF DAMAGES

Parts damaged were :

The bootlid, rear bumper and panel were dented.

ADJUSTMENTS & RECOMMENDATIONS

A static inspection was carried out on 14/08/2019 & our report is here with enclosed for your perusal.

The Repairs Estimate submitted by M/s Eng Hup Seng Motor as per attached Appraisal Schedule have been revised and scrutinised thoroughly by us & in our opinion, we consider it to be fair and reasonable. The repairer has agreed to effect repairs to the owners satisfaction & to roadworthy condition on an agreed Part - By - Part Repair Basis of \$ 3,815.04 after deducting the Policy Excess Clause of \$ NA. As instructed, we have not authorised any of the repairs on your behalf.

	Repairer's		Our	
	Estimate	Amount	Revised	Amount
Parts	2408	00	1785	04
Towing Charges	X	X	X	X
PB Labour Charges	800	00	680	00
Others Misc Charges	830	00	550	00
Paintwork	980	00	800	00
Total	\$ 5018	00	\$ 3815	04

Under normal circumstances, the duration of repairs should not exceed Four (04) days excluding Pre - Repair Inspection (PRI) / Pre - Repair Survey (PRS) waiting time frame & Public Holidays

Attached photographs taken during inspection Twenty - Three (23) Photographs.

SPECIAL REMARKS

1. The inspection was conducted on a 'without prejudice' basis
2. On 15/08/2019, we examined the extent of damages
3. On 16/08/2019, we examined the new replacement parts.
4. On 19/08/2019, we examined the repaired vehicle.

Yours Faithfully,

Ce



T F NG PHILIP FOO

SKL 3327 U

VEHICLE REGN NO :

OUR REFERENCE : PAS/EHS/190813/TP

APPRAISEMENT SCHEDULE

INSPECTION REPORT DATE: 30-Aug-19

CONTINUATION SHEET NO :

1

S/No	Qty	Parts / Labour Descriptions	Remarks / Condition	Repairer's Estimate Amount	Recommendation / Revised Amount
		<u>PARTS SUPPLY - LIST ITEMS</u>		\$ cts	\$ cts
1	1pc	Rear bumper	Badly dented	463.70	463.70 ✓
2	8pcs	Rear bumper clips@\$3.9	Necessary	31.20	31.20 ✓
3	1pc	Bootlid	Badly dented	983.30	983.30 ✓
4	1pc	Bootlid centre logo	Necessary	33.40	33.40 ✓
5	1pc	Bootlid 'Vezel' emblem	Necessary	58.50	58.50 ✓
6	1pc	Bootlid upper lock	Serviceable	151.70	-
7	1set	Rear windscreen mldg	Necessary	198.00	198.00 ✓
8	10pcs	Rear bumper under cover clip@\$3.5	Necessary	35.00	35.00 ✓
9	1pc	Bootlid 'Hybrid' emblem	Necessary	53.20	53.20 ✓
				<u>2008.00</u>	<u>1856.30</u>
		Less: 20% discount		-	<u>371.26</u>
				2008.00	1485.04
		<u>SPECIAL NETT ITEMS</u>			
1	1set	Rear bumper sensor	Dented/Cracked	350.00	250.00 ²⁰⁰
2	1set	Rear windscreen sealant	Necessary	50.00	50.00 ✓ ²⁵⁰
				2408.00	1785.04
		<u>LABOUR & MISC. CHARGES</u>			
1		Remove the necessary affected parts, straighten rear panel and replace parts		800.00	680.00 ⁵⁰⁰
2		Putty and spraypaint on all affected parts		980.00	800.00 ⁶⁰⁰
3		Rewire rear portion		50.00	30.00 ✓
4		Remove and refit rear bumper sensors		100.00	60.00 ³⁰
5		Check electrical		80.00	50.00 ^{xnn}
6		Tuff Kote		50.00	30.00 ✓
7		Remove and refit bootlid components		100.00	80.00 ⁶⁰
8		Remove and refit rear reverse camera		100.00	60.00 ⁵⁰
9		Rewire reverse camera		50.00	30.00 ⁵⁰
10		Remove and refit rear windscreen		150.00	120.00 ✓
11		Remove and refit rear cctv-in-car camera		100.00	60.00 ⁵⁰
12		Rewire rear cctv-in-car camera		50.00	30.00 ⁵⁰
				<u>5018.00</u>	<u>3815.04</u> ¹⁴⁷⁰

SUB / GRAND TOTAL

PRECISION APPRAISAL SERVICES

33205.04

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 471A

Vehicle Details

Vehicle No.: SKL3327U
Vehicle to be Exported: Yes
Intended Deregistration Date: 14 Aug 2019
Vehicle Make: HONDA
Vehicle Model: VEZEL 1.5Z HYBRID CVT ABS D/AIRBAG 2WD
Primary Colour: Blue
Manufacturing Year: 2015
Engine No.: LEB5075325
Chassis No.: RU31125307
Maximum Power Output: 112.0 kW (150 bhp)
Open Market Value: \$25,973.00
Original Registration Date: 05 Apr 2016
First Registration Date: 05 Apr 2016
Transfer Count: 0
Actual ARF Paid: \$18,363.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 04 Apr 2026
PARF Rebate Amount: \$13,772.00

Intended COE Rebate Details

COE Expiry Date: 04 Apr 2026
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$38,610.00
COE Rebate Amount: \$25,637.00
Total Rebate Amount: \$39,409.00

The information contained herein is correct as at 14 Aug 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/08/2019 08:37
Date Of Accident	06/08/2019 17:15
Exact Location Of Accident	BT TIMAH RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKL3327U
Insured/Policyholder	
Name Of Registered Owner	TAN HOCK TIAM
NRIC No	S1647471A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98771153
Alternative Phone No	OFFICE-98771153

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A29075734 QMY
Cover Note Number	

Driver

Name of Driver	TAN CHUN HAN, CALVERK
NRIC No	S8843792F
Date Of Birth	02/11/1988
Occupation	INDOOR
Date Of Driving Pass	31/03/2008
Driving Experience	11 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98771153
Fax Number	
Contact Number	

Address	BLK 550B SEGAR RD #15-632
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : -- GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER ATTACHED ACCIDENT REPORT FROM THE DRIVER.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKQ7602Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

7/8/2019
0840hs

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

TDAC BUKIT BATOK (VAC)

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

at traffic light junction along bukit timah road
 waiting for light to turn green. driver of
 vehicle SKQ 7602Y behind claimed that
 he stepped on the wrong pedal and accelerated
 and hit the back of my vehicle SKL3327U
 instead of braking to stop. on Tuesday 6th August 2019
 at 1715hrs.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

0840hrs 2/8/19

IDAC BUKIT RATOK (VAC)

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	21/08/2019 16:53
Date Of Accident	07/08/2019 17:00
Exact Location Of Accident	ALONG BUKIT TIMAH ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKQ7602Y
Insured/Policyholder	
Name Of Registered Owner	SCOTT LEE COOPER
NRIC No	S2706876F
Email Address	SCOOPER711@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98251688
Alternative Phone No	OFFICE-98251688
Vehicle Particulars	
Manufacturer	VOLKSWAGEN
Model	JETTA
Exact Purpose for which vehicle was being used at time of accident	PERSONAL USE.
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A80424427AVW
Cover Note Number	
Driver	
Name of Driver	SCOTT LEE COOPER
NRIC No	S2706876F
Date Of Birth	30/09/1959
Occupation	INDOOR
Date Of Driving Pass	02/07/2001
Driving Experience	18 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-98251688
Fax Number	(LOCAL) +65-98251688
Contact Number	OFFICE-98251688

Address	APT BLK 135 SUNSET WAY #10-03 SINGAPORE
Postcode	597158
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKL3327U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

21/7/17
10:00 AM

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN

217
A√6

FRQ76027 24633271

10

BUKIT TIMAH

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

STOPPED AT TRAFFIC SIGNAL. FOOT
SLIPPED OFF BRAKE PEDAL, ROLLING FORWARD

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____

Date & Time: _____

21/8/19

10:00 AM

Driver's Signature _____

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature _____

Name: _____

NR/CIPEN No. _____

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Aug 2019		13 Aug 2019 17:48 Edit Adj Rpt	\$53,205.04 Edit Estimates	\$53,205.04 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	SCOTT LEE COOPER , ID: 52706876F								
Main Claimant:	TAN HOCK TIAM , ID: S1647471A								
Vehicle Reg. No.:	SKL3327U	Date of Loss:	06/08/2019 00:00 - :59 [40 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 602241	Policy/Cover Note No.:	80424427AVW (Comprehensive) Coverage: 20/01/2019 - 19/01/2020						
Vehicle Reg. No. (Insured):	SKQ7602Y	Policy No. (Claimant):							
		Excess:							
Repairer:	Eng Hup Seng Motor (HQ) Blk 1, No. 2 Pandan Loop, Pandan Light Industries Park, 128219 Clementi - Tel: 6777 2755								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 22/10/2019]								
Adj Asg. Remarks:	on WP, Q1:Grab, Liab: Dispute(NR). Disagree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: My Lye @ 9622 1030.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• MSIG_SG (19/10/2019): Report Send Back Alerts - SKL3327U (TP)									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKL3327U (602241)
[SKQ7602Y]
TP
TAN HOCK TIAM
Aug 6 2019 12:00AM
[SCOTT LEE COOPER]
Eng Hup Seng Motor

Upload Documents

Upload Photos































Compose New Letter

View

View in Browser






Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	20/08/19 14:41	General View		 Load JPG	<input checked="" type="checkbox"/>
2	20/08/19 14:41	General View		 Load JPG	<input checked="" type="checkbox"/>
3	20/08/19 14:41	General View		 Load JPG	<input checked="" type="checkbox"/>
4	20/08/19 14:41	General View		 Load JPG	<input checked="" type="checkbox"/>
5	20/08/19 14:41	General View		 Load JPG	<input checked="" type="checkbox"/>
6	20/08/19 14:41	General View		 Load JPG	<input checked="" type="checkbox"/>
7	20/08/19 14:41	General View		 Load JPG	<input checked="" type="checkbox"/>
8	20/08/19 14:41	General View		 Load JPG	<input checked="" type="checkbox"/>
9	20/08/19 14:41	General View		 Load JPG	<input checked="" type="checkbox"/>
10	20/08/19 14:41	General View		 Load JPG	<input checked="" type="checkbox"/>
11	20/08/19 14:41	General View		 Load JPG	<input checked="" type="checkbox"/>
12	20/08/19 14:41	General View		 Load JPG	<input checked="" type="checkbox"/>
13	20/08/19 14:41	General View		 Load JPG	<input checked="" type="checkbox"/>
14	20/08/19 14:41	General View		 Load JPG	<input checked="" type="checkbox"/>
15	20/08/19 14:41	General View		 Load JPG	<input checked="" type="checkbox"/>
16	20/08/19 14:41	General View		 Load JPG	<input checked="" type="checkbox"/>
17	20/08/19 14:41	General View		 Load JPG	<input checked="" type="checkbox"/>
18	20/08/19 14:41	General View		 Load JPG	<input checked="" type="checkbox"/>
19	20/08/19 14:41	General View		 Load JPG	<input checked="" type="checkbox"/>
20	20/08/19 14:41	General View		 Load JPG	<input checked="" type="checkbox"/>
21	20/08/19 14:41	General View		 Load JPG	<input checked="" type="checkbox"/>
22	20/08/19 14:45	Reinspection Photo		 Load JPG	<input checked="" type="checkbox"/>
23	20/08/19 14:45	Reinspection Photo		 Load JPG	<input checked="" type="checkbox"/>
24	20/08/19 14:45	Reinspection Photo		 Load JPG	<input checked="" type="checkbox"/>
25	20/08/19 14:45	Reinspection Photo		 Load JPG	<input checked="" type="checkbox"/>
26	04/09/19 16:00	Photo After Spray		 Load JPG	<input checked="" type="checkbox"/>
27	04/09/19 16:00	Photo After Spray		 Load JPG	<input checked="" type="checkbox"/>
28	04/09/19 16:00	Photo After Spray		 Load JPG	<input checked="" type="checkbox"/>
29	04/09/19 16:00	Photo After Spray		 Load JPG	<input checked="" type="checkbox"/>
30	04/09/19 16:00	Photo After Spray		 Load JPG	<input checked="" type="checkbox"/>



Documentation

1 per page

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	16/08/19 20:18	TP report		 Load PDF	
2	24/08/19 10:50	OI GIA		 Load PDF	
3	19/10/19 18:37	LOD		 Load PDF	
4	19/10/19 18:37	Survey report & pictures		 Load PDF	
5	19/10/19 18:44	Instruction to LKK to prepare paper survey report		 Load PDF	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	01/11/19 08:55	Colour Photo		 Load PDF	
2	01/11/19 08:55	PRS Invoice		 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19014091/T1YF3E2-1

Date: 01/11/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 80424427AVW

Claimant Vehicle No: SKL3327U

Insured Vehicle No: SKQ7602Y

Date of Loss: 06/08/2019

Nature of Claim: TP

Claim No: 602241

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKL3327U

Make & Model: HONDA VEZEL HYBRID, 1.5 Z (A)

Engine No: LEB5075325

Reg. Date: 05/04/2016 (Man. Year: 2015)

Chassis No: RU31125307

Colour: Blue

Odometer: 84187 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17

Rear Tyre Size: 215/55 R17

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,408.00	1,735.04	672.96	27.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,610.00	1,470.00	1,140.00	43.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	5,018.00	3,205.04	1,812.96	36.13

INSPECTION

Date of Assignment: 13/08/2019

Date Inspected: 15/08/2019 Inspected At:

Eng Hup Seng Motor (HQ)
Blk 1, No. 2 Pandan Loop, Pandan
Light Industries Park
Singapore 128219

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Nov 2019)

Parts: M1-SUV HONDA VEZEL HYBRID 1.5 Z (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKL3327U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Badly Dented	463.70 F	*463.70 FL
2	8		*REAR BUMPER CLIPS	Necessary	31.20 F	*31.20 FL
3	1		*BOOTLID	Badly Dented	983.30 F	*983.30 FL
4	1		*BOOTLID CENTRE LOGO	Necessary	33.40 F	*33.40 FL
5	1		*BOOTLID VEZEL EMBLEM	Necessary	58.50 F	*58.50 FL
6	1		*BOOTLID UPPER LOCK	Serviceable	151.70 F	*- FL
7	1		*SET REAR WINDSCREEN MLDG	Necessary	198.00 F	*198.00 FL
8	10		*REAR BUMPER UNDER COVER CLIP	Necessary	35.00 F	*35.00 FL
9	1		*BOOTLID HYBRID EMBLEM	Necessary	53.20 F	*53.20 FL
10	1		*SET REAR BUMPER SENSOR	Cracked / Dented	350.00 FS	*200.00 FS
11	1		*SET REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 2,408.00 2,106.30

- List Item Discount on L Items 0.00/20.00% (S\$) 0.00 371.26

Total Parts (S\$) 2,408.00 1,735.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE THE NECESSARY AFFECTED PARTS, STRAIGHTEN REAR PANEL AND REPLACE PARTS	New	800.00	500.00
2	PUTTY AND SPRAYPAINT ON ALL AFFECTED PARTS	New	980.00	600.00
3	REWIRE REAR PORTION	New	50.00	30.00
4	REMOVE AND REFIT REAR BUMPER SENSORS	New	100.00	30.00
5	CHECK ELECTRICAL	New	80.00	0.00
6	TUFF KOTE	New	50.00	30.00
7	REMOVE AND REFIT REAR REVERSE CAMERA }	New	100.00	50.00
8	REWIRE REVERSE CAMERA }	New	50.00	0.00
9	REMOVE AND REFIT REAR WINDSCREEN	New	150.00	120.00
10	REMOVE AND REFIT REAR CCTV-IN-CAR CAMERA }	New	100.00	50.00
11	REWIRE REAR CCTV-IN-CAR CAMERA }	New	50.00	0.00
12	REMOVE AND REFIT BOOTLID COMPONENTS	New	100.00	60.00
Gross Labour Cost (S\$)			2,610.00	1,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >