

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

PREMIER RENT A CAR PTE LTD  
23 CHANGI SOUTH AVE 2  
#01-01  
SINGAPORE 486443  
TEL : 6214 1101


Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Sketch Plan #2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

refer attach

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

PREMIER RENT A CAR PTE LTD  
23 CHANGI SOUTH AVE 2, #01-01  
SINGAPORE 486443  
TEL: 6214 1101

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

### Sketch Plan #3

- Describe Circumstance of the Accident.

ON THE DAY 24.12.18 @1312HRS, I WAS DRIVING MY VEHICLE SJF6957A, TRAVELING ALONG AYE ON THE 1<sup>ST</sup> LANE.

AS I WAS TRAVELING NEAR CLEMENTI AVE 6 EXIT, VEHICLE B(SJX7211S) AHEAD OF ME SUDDENLY BRAKE. I WAS UNABLE TO REACT IN TIME, I TRIED TO SWERVE TO MY LEFT TO AVOID COLLISION HOWEVER THE FRONT RIGHT PORTION OF MY VEHICLE STILL COLLIDED ONTO THE REAR LEFT PORTION OF VEHICLE B(SJX7211S)


DUE TO THE IMPACT, MY VEHICLE WAS DAMAGE ON THE FRONT RIGHT PORTION.


VEHICLE B DAMAGE ON THE REAR LEFT PORTION.

NO INJURY INVOLVED

BOTH VEHICLE NO PASSENGER ON BOARD.

DAMAGES FOUND ON VEHICLE A & B





Driver's Signature  
Monday, December 24, 2018

Accident Photo



Accident Photo



Accident Photo



Accident Photo







# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529090)

Mobile 9295 2204 Fax 6722 8508 Email pasvos@hotmail.com

Business Reg. 201404434D

## INVOICE

Mr Derek Lau Han Young  
C/o. 25 Kaki Bukit Road 4  
Synergy@KB #06-37  
Singapore 417800

Invoice No. : HA/1901-33

Date : 19/01/2019

Descriptions	Amount (SGD)
Services rendered for appraiser / inspection report :-	
Survey Fee	
Photographs	
Transport Fees	
Re-inspection Fees	
Total :	SGD : \$ 444.00
SGD Dollar : Four Hundred Forty Four Dollars Only.	
Our Reference : PAS/TP/0641218	
Vehicle No. : SJX7211S	
Make & Model : Volkswagen Scirocco	
Your Claim No. : Third Party Claim	

### Notes:

All cheque payment should be Crossed and made payable to "PROMINENT APPRAISER SERVICES PTE LTD".

Please indicate our "INVOICE NO." on the reverse side of the cheque.

Should you have any enquiries, please do not hesitate to contact us.



For PROMINENT APPRAISER SERVICES PTE LTD



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)  
Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

## VEHICLE INSPECTION REPORT

Report No. : PAS/TP/0641218

To : Mr Derek Lau Han Young  
C/o. 25 Kaki Bukit Road 4  
Synergy@KB #06-37  
Singapore 417800

Date of Report : 19/01/2019  
Date of Assignment : 27/12/2018  
Report requested by : Mr Derek Lau Han Young  
Date of Accident : 24/12/2018  
Date of Inspection : 27/12/2018  
Claim No. : Third Party Claim  
Policy No. : -

### PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No. : SJX7211S  
Make & Model : Volkswagen Scirocco  
Date of Registration : 06/07/2010  
Colour : Met. Grey

Engine Capacity (cc) : 1390cc  
Mileage (km) : 71298km  
Chassis / Frame No. : WVVZZZ13ZAV443100  
Engine No. : CAV190400

### TYRE CONDITION

Front LH : 6 mm  
Make : Pirelli

Front RH : 6 mm  
Make : Pirelli

Rear LH : 6 mm  
Make : Pirelli

Rear RH : 6 mm  
Make : Pirelli

Road wheels Type : Alloy

(The above represents the approximate remaining life of tyre treads)

### PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork : Good  
Paintwork : Good  
Handbrake : Serviceable  
Footbrake : Serviceable  
Steering : Serviceable  
Apparent Engine Modification : Nil

### PLACE OF REPAIRER OFFICE/WORKSHOP

Location : M/s. Monster Tune LLP  
25, Kaki Bukit Road 4, Synergy@KB, #06-37, Singapore 417800

### ASSESSMENT

Repairer's Estimate : \$ 6,507.03  
Revised Amount : \$ 4,538.85  
Less Excess : \$ -  
Recommended Reserve : \$ 3,630.00 (Lump Sum)

Estimated Normal Period of Repairs : 6 Working Days



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No : SJX7211S

Report No. : PAS/TP/0641218

## GENERAL REMARKS

WITHOUT PREJUDICE

### THE ASSIGNMENT

The survey was conducted at M/s. Monster Tune LLP, 25, Kaki Bukit Road 4, Synergy@KB, #06-37, Singapore 417800.

(Subsequent inspections have been conducted)

### POINT OF IMPACT

At the rear LH portion.

### DAMAGES

The boot lid, rear bumper, rear end panel, rear floor panel, LHR chassis member, rear exhaust muffler, LH taillamp, etc.

*Other parts were also found damaged. (See schedule for details)*

### ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$4,538.85.

### CONCLUSION


The repairer has agreed to undertake the repairs at a lump sum of SGD \$3,630.00.

This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,  
Prominent Appraiser Services Pte Ltd

  
Andrew How  
Automobile Appraiser  
MSAAA  
Licensed Appraiser



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201407434D

Vehicle No. : SJX7211S

Report No. : PAS/TP/0641218

## APPRAISEMENT SCHEDULE

S/No.	Qty	Parts Descriptions	Condition	Repairer's Estimate (S\$)	Our Assessment (S\$)
1	1 pc	Taillamp LH	Cracked	\$ 513.70	\$ 513.70 ✓
2	1 pc	Rr bumper	Dented	\$ 1,128.60	\$ 1,128.60 ✓
3	1 pc	Rr bumper reflector LH	Broken	\$ 105.70	\$ 105.70 ✓
4	2 pcs	Rr bumper no.plate lamp	Refit	\$ 164.60	\$ -
5	2 pcs	Rr bumper guide R/L	Cracked/Necessary	\$ 82.30	\$ -
6	1 pc	Rr bumper center guide	Cracked/Necessary	\$ 87.20 ✓	\$ 174.40
7	1 pc	Rr bumper reinforcement	Dented/Cracked	\$ 94.00	\$ 94.00 X
8	1 pc	Rr end panel	Dented	\$ 420.30	\$ 420.30 ✓
9	1 pc	Rr end panel garnish	Dented/Distorted	\$ 639.80	\$ 639.80 X
10	1 pc	Rr exhaust muffler	Refit	\$ 132.00	\$ -
			Dented/Repair	\$ 923.60	\$ -
				\$ 4,296.70	\$ 3,076.50
			Less Discount : 10%	\$ 429.67	\$ 307.65
			List Parts Sub-Total :	\$ 3,867.03	\$ 2,768.85
1	1 set	Rr reverse sensor	Dented/Damaged	\$ 250.00	\$ 220.00 ✓
2	1 pc	Rr end panel sealant	Necessary	\$ 50.00	\$ 40.00 X
			Special Nett Sub-Total :	\$ 300.00	\$ 260.00
			Parts Total :	\$ 4,167.03	\$ 3,028.85

2202.6  
10%: 1982.34



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simel St.3 #02-24 S(529690)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 2014044340

Vehicle No. : SJX7211S

Report No. : PAS/TP/0641218

S/No.	Labour Descriptions	Repairer's Estimate (S\$)	Our Assessment (S\$)
1	To check rear electrical wiring system.	\$ 50.00	\$ / 30.00
2	To remove and reinstall rear interior trims, garnishes, etc. for necessary repairs.	\$ 100.00	\$ 60 80.00
3	To straighten, repair and realign rear exhaust muffler.	\$ 80.00	\$ X 60.00
4	To remove, replace and reinstall rear reverse sensors & control unit.	\$ 60.00	\$ 40 50.00
5	To straighten, repair, realign on affected area and replace damaged parts.	\$ 1,000.00	\$ 500 660.00
6	To spray painting, blending on affected and adjacent area.	\$ 1,000.00	\$ 400 600.00
7	To spray anti-rust coating on new and affected panels.	\$ 50.00	\$ X 30.00
Labour Total :		\$ 2,340.00	\$ 1,510.00
Total (Parts & Labour) :		\$ 6,507.03	\$ 4,538.85

## For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$ 3,630.00

Under normal circumstances, the repairs should be completed within a reasonable period of 6 Working Days. (Exclude waiting days of PRI, Sunday, Public Holiday and awaiting of shipment for spare parts)

44 Photographs were taken at the time of inspection.

**N.B:** By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall have the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.

3232.34  
20% : 2550

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Dec 2018 18:29		31 Dec 2018 09:19 <a href="#">Edit Adj Rpt</a>	<b>S\$2,550.00</b> <a href="#">Edit Estimates</a>	<b>S\$2,550.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	PREMIER RENT A CAR PTE LTD, Co. Reg. No.: 200612929E		
Main Claimant:	DEREK LAU HAN YOUNG, ID: S7928113A		
Vehicle Reg. No.:	SJX7211S	Date of Loss:	24/12/2018 13:00 - :59 [101 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 580382	Policy/Cover Note No.:	B29080721TMC (Third Party Only) Coverage: 01/05/2018 - 30/04/2019
Vehicle Reg. No. (Insured):	SJF6957A	Policy No. (Claimant):	
		Excess:	
Repairer:	Monster Tune (HQ) 25 Kaki Bukit Road 4, #06-37 Synergy@Kaki Bukit, 417800 Kaki Bukit - Tel: 83331487		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 22/10/2019]		
Driver/Custodian (Insured):	DAKSHINAMOORTHY SUBRAMANIAN (), NRIC: S2691303I Email:		
Adj Asg. Remarks:	Liability down. TP disagree with our SJE list. Proceed to appoint LKK Auto Consultants as the SJE. Contact Person: Mr Derrick / 9018 4170		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- MSIG\_SG (19/10/2019): Report Send Back Alerts - SJX7211S (TP)

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**\*SJX7211S (580382)**  
**[SJF6957A]**  
**TP**  
**DEREK LAU HAN YOUNG**  
**Dec 24 2018 1:00PM**  
**[PREMIER RENT A CAR PTE LTD]**  
**Monster Tune**

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

### Assessment Reports

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	1 per page ▼	Thumbnail	Print
1	31/12/18 09:45	<b>Accident Statement</b> From: SC - Reg. No: SJF6957A, Claimant: PREMIER RENT A CAR PTE LTD		Load HTM	

### Photos/Images

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	3 per page ▼	Thumbnail	Print
1	03/01/19 14:50	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
2	03/01/19 14:50	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
3	03/01/19 14:50	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
4	03/01/19 14:50	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
5	03/01/19 14:50	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
6	03/01/19 14:50	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
7	03/01/19 14:50	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
8	03/01/19 14:50	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
9	03/01/19 14:50	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
10	03/01/19 14:50	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
11	03/01/19 14:50	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
12	03/01/19 14:50	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
13	03/01/19 14:50	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
14	03/01/19 14:50	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
15	03/01/19 14:50	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
16	03/01/19 14:50	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
17	03/01/19 14:50	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
18	03/01/19 14:50	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
19	03/01/19 14:50	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
20	03/01/19 14:50	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>
21	03/01/19 14:50	<b>Photographs of Damaged Parts</b>		Load JPG	<input checked="" type="checkbox"/>
22	03/01/19 14:50	<b>Photographs of Damaged Parts</b>		Load JPG	<input checked="" type="checkbox"/>
23	03/01/19 14:50	<b>Photographs of Damaged Parts</b>		Load JPG	<input checked="" type="checkbox"/>
24	03/01/19 14:50	<b>Photographs of Damaged Parts</b>		Load JPG	<input checked="" type="checkbox"/>
25	03/01/19 14:50	<b>Photographs of Damaged Parts</b>		Load JPG	<input checked="" type="checkbox"/>
26	03/01/19 14:50	<b>Photographs of Damaged Parts</b>		Load JPG	<input checked="" type="checkbox"/>
27	03/01/19 14:50	<b>Photographs of Damaged Parts</b>		Load JPG	<input checked="" type="checkbox"/>
28	03/01/19 14:50	<b>Photographs of Damaged Parts</b>		Load JPG	<input checked="" type="checkbox"/>
29	03/01/19 14:50	<b>Photographs of Damaged Parts</b>		Load JPG	<input checked="" type="checkbox"/>
30	03/01/19 14:50	<b>Photographs of Damaged Parts</b>		Load JPG	<input checked="" type="checkbox"/>
31	03/01/19 14:50	<b>Photographs of Damaged Parts</b>		Load JPG	<input checked="" type="checkbox"/>
32	03/01/19 14:50	<b>Photographs of Damaged Parts</b>		Load JPG	<input checked="" type="checkbox"/>
33	03/01/19 14:50	<b>Photographs of Damaged Parts</b>		Load JPG	<input checked="" type="checkbox"/>
34	03/01/19 14:50	<b>Photographs of Damaged Parts</b>		Load JPG	<input checked="" type="checkbox"/>
35	03/01/19 14:50	<b>Photographs of Damaged Parts</b>		Load JPG	<input checked="" type="checkbox"/>
36	03/01/19 14:50	<b>Photographs of Damaged Parts</b>		Load JPG	<input checked="" type="checkbox"/>



**Assessment Reports**

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	1 per page ▼	✓
			Thumbnail	Print
37	03/01/19 14:50	Photographs of Damaged Parts	Load JPG	✓
38	03/01/19 14:50	Photographs of Damaged Parts	Load JPG	✓
39	03/01/19 14:50	Photographs of Damaged Parts	Load JPG	✓
40	03/01/19 14:50	Photographs of Damaged Parts	Load JPG	✓

**Documentation**

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	1 per page ▼	✓
			Thumbnail	Print
1	28/12/18 18:34	Email - PRI	Load PDF	
2	28/12/18 18:36	TP workshop details	Load PDF	
3	28/12/18 18:41	TP disagree with our SJE list, Proceed to appoint LKK as the SJE	Load PDF	
4	31/12/18 09:45	SJX7211S GIA Rpt	Load PDF	
5	16/10/19 15:06	TPD SJX7211S - SURVEY REPORT & COLOUR PHOTO	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/11/19 13:38	PRS INVOICE	Load PDF	

**Documents Checklist****DOCUMENTS CHECKLIST**
[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18023321/GTD3S2-1  
Date: 11/11/2019

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: B29080721TMC  
Claimant Vehicle No: SJX7211S Insured Vehicle No: SJF6957A  
Date of Loss: 24/12/2018 Nature of Claim: TP Claim No: 580382

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJX7211S**  
Make & Model: VOLKSWAGEN SCIROCCO, 1.4 L (A) Engine No: CAV190400  
Reg. Date: 06/07/2010 (Man. Year: 2010) Chassis No: WVWZZZ13ZAV443100  
Colour: Grey Odometer: 71298 km  
Engine Capacity: 1390 cc  
Market Value/New Car Price: N/A  
Sum Insured (\$\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 235/40Z R18 Rear Tyre Size: 235/40Z R18  
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm  
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

### COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,167.03	2,202.34	1,964.69	47.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,340.00	1,030.00	1,310.00	55.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>6,507.03</b>	<b>3,232.34</b>	<b>3,274.69</b>	<b>50.33</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>2,550.00</b>		
<b>(\$\$)</b>	6,507.03	2,550.00	3,957.03	60.81
<b>+ GST 7.00/7.00% (\$\$)</b>	455.49	178.50	276.99	60.81
<b>Nett Amount (\$\$)</b>	<b>6,962.52</b>	<b>2,728.50</b>	<b>4,234.02</b>	<b>60.81</b>

### INSPECTION

Date of Assignment: 31/12/2018  
Date Inspected: 31/12/2018 Inspected At: Monster Tune (HQ)  
25 Kaki Bukit Road 4, #06-37 Synergy@Kaki Bukit  
Singapore 417800  
Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 11 Nov 2019)
<b>Parts:</b> 144	VOLKSWAGEN SCIROCCO 1.4 L (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJX7211S)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILLAMP LH	Cracked	513.70 FL	*460.80 FL
2	1		*RR BUMPER	Dented	1,128.60 FL	*1,128.60 FL
3	1		*RR BUMPER REFLECTOR LH	Broken	105.70 FL	*105.70 FL
4	2		*RR BUMPER NO PLATE LAMP	Refit	164.60 FL	*- FL
5	1		*RR BUMPER GUIDE R/L	N/s /N/s Not Necessary	174.40 FL	*87.20 FL
6	1		*RR BUMPER CENTER GUIDE	Serviceable	94.00 FL	*- FL
7	1		*RR BUMPER REINFORCEMENT	Dented	420.30 FL	*420.30 FL
8	1		*RR END PANEL	Serviceable	639.80 FL	*- FL
9	1		*RR END PANEL GARNISH	Refit	132.00 FL	*- FL
10	1		*RR EXHAUST MUFFLER	Repair	923.60 FL	*- FL
11	1		*SET RR REVERSE SENSOR	Dented/Damaged	250.00 FS	*220.00 FS
12	1		*RR END PANEL SEALANT	Serviceable	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,596.70</b>	<b>2,422.60</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	429.67	220.26
<b>Total Parts (\$\$)</b>	<b>4,167.03</b>	<b>2,202.34</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK REAR ELECTRICAL WIRING SYSTEM	New	50.00	30.00
2	TO REMOVE AND REINSTALL REAR INTERIOR TRIMS,GARNISHES,ETC.FOR NECESSARY REPAIRS	New	100.00	60.00
3	TO STRAIGHTEN,REPAIR AND REALIGN REAR EXHAUST MUFFLER	New	80.00	0.00
4	TO REMOVE,REPLACE AND REINSTALL REAR REVERSE SENSORS & CONTROL UNIT	New	60.00	40.00
5	TO STRAIGHTEN,REPAIR,REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS	New	1,000.00	500.00
6	TO SPRAY PAINTING,BLENDING ON AFFECTED AND ADJACENT AREA	New	1,000.00	400.00
7	TO SPRAY ANTI-RUST COATING ON NEW AND AFFECTED PANELS	New	50.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,340.00</b>	<b>1,030.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >