

ASS. REC. BY:

REF:

CS/MSG 19018565/UYF302

Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Irene Tan Gek Ing

of

MSG

Date/Time: 21.10.19 16.39pm

photo O.K

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GX 1884A

Insured:

YM 9942H

at Workshop m/s

Hock Wah Motor

Tel:

64415655

of

Blk 3011 Bedok Industrial Park C, #01-208

Policy No:

29119383

Claim No:

609684

Sum Insured:

Excess:

Make of Veh:

D.O.A.

14.10.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

21.10.19 4.46pm

Person Contacted:

Anyis for

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓) Estimate

GX 1884A - N/A 1/1/2001/187/1

D.O.A - 15/01/2010

YM 9942H - X

ASS. REC. BY:

REF: MS19

Marcus

ASSIGNMENT

From:

Date: 22-10-2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GX 1884A

at Workshop m/s Hock Wah motor
of BUC 3011 Blok Industrial Park E A01-208

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 27,500

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

mp

Vehicle: IN / OUT

Date: Person Contacted:

495. Fals not 5163

Date / Time Action / Instruction

29/10 0226-2-2024 LRA 22340
Sent Preli by Merimen

4.1/18 L/S # 5000 conf. and v.l. Anysig. (Red \$8377-93, 62%)

RECEIVED 07 NOV 2019

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

1/11/19 Typist

Rep. Form(s):

Lump Sum L.P. 1: \$5000f

Veh No:

GX1884A Regn: 204

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (M / 2/06)

Make:

Nissan Pick-up C.C. 2664

Colour:

Orange A/C: Insured / Std / NI / NA

Sp. Reading:

502536 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JNICHGD2280071733

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: M / S/Rim / STD A/Rim or

Tyre Size: F:

R: 185 R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Green - max

Front

R/Bal. 6 mm

Rear

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 14/10/19

D.O.I. 22/10/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Beer & Lf.

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

1/11/19 Typist

Rep. Form(s):

Lump Sum L.P. 1: \$5000f

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee: 200

Transportation:

S + RS. \$1

Photos

Others

TOTAL

211

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Oct 2019 09:39		21 Oct 2019 16:39 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	PHOON HUAT PTE LTD, Co. Reg. No.: 201604649G								
Main Claimant:	CEMENTAID (SEA) PTE LTD, Co. Reg. No.: 197000896H								
Vehicle Reg. No.:	GX1884A	Date of Loss:	14/10/2019 14:00 - :59 [187 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 608684	Policy/Cover Note No.:	29119383 (Third Party Only) Coverage: 27/03/2019 - 26/03/2020						
Vehicle Reg. No. (Insured):	YM9942H	Policy No. (Claimant):							
		Excess:							
Repairer:	Hock Wah Motor Workshop Pte Ltd (Bedok) Blk 3011, Bedok Industrial Park E,, #01-2008/2010/2012, 489977 Bedok - Tel: 6441 5655								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 22/10/2019]								
Adj Asg. Remarks:	on WP. Car in 22/10/19, survey after 10am at Bedok w/shop. Please contact us ASAP if you cannot attend this assignment. Liab: clear. Contact: Anyisia Foo @ 6441 5655.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 24 Oct 2019

Preliminary Advice

Insured Vehicle No	: YM9942H	Accident Date	: 14/10/2019
TP Vehicle No	: GX1884A	Assignment Date	: 21/10/2019
Make	: NISSAN P/UP D/CAB	Est. Duration of Repair	: 6.00
Date of Inspection	: 22/10/2019		
Inspection At	: HOCK WAH MOTOR WORKSHOP PTE LTD (BEDOK) BLK 3011, BEDOK INDUSTRIAL PARK E., #01-2008/2010/2012 SINGAPORE 489977		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear & front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,314.39
Revised Amount	:S\$	6,757.99
Check Items (Estimated)	:S\$	1,655.87
Total	:S\$	8,413.86

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/10/2019 17:00
Date Of Accident	14/10/2019 13:55
Exact Location Of Accident	ALONG AYE AT JURONG TOWN HALL SLIP ROAD EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GX1884A
Insured/Policyholder	
Name Of Registered Owner	CEMENTAID (SEA) PTE LTD
Co Reg No	197000896H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90215702
Alternative Phone No	OFFICE-68969801

Vehicle Particulars

Manufacturer	NISSAN
Model	P/UP D/CAB
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5018365551-12
Cover Note Number	27/02/2019 - 26/02/2020

Driver

Name of Driver	TAN ENG GUAN
NRIC No	S7908408E
Date Of Birth	10/03/1979
Occupation	INDOOR
Date Of Driving Pass	29/09/2017
Driving Experience	2 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90215702
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 38A BENDEMEER ROAD #07-826
Postcode	331038
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON THE STATED DATE AND TIME, I WAS DRIVING ALONG AYE AT JURONG TOWN HALL SLIP ROAD EXIT. MY VEHICLE WAS AT THE EXTREME RIGHT LANE WAITING FOR GREEN LIGHT, SUDDENLY VEHICLE B (YM9942H) HIT ONTO THE REAR OF MY VEHICLE CAUSING MY VEHICLE TO MOVE FORWARD AND HIT ONTO THE REAR OF VEHICLE C (SKQ1457P).

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YM9942H
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	LEE KUNG WEI
NRIC/Passport Number	
Contact Number	93889172
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKQ1457P
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE C
Vehicle Category	PRIVATE CAR
Name of Driver	MR TEO
NRIC/Passport Number	
Contact Number	90270281
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	TAN ENG GUAN
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	GX1884A
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20191015/7006

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3
Report No. T/20191015/7006

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 15/10/2019 12:02		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: TAN ENG GUAN			Address: APT BLK 38A BENDEMEER ROAD #07-826 SINGAPORE 331038		
ID Type / ID No.: NRIC NO / S7908408E			Contact No.: Home/Office: Mobile: 90215702		
Nationality: SINGAPORE CITIZEN			Email: tan_engguan@hotmail.com		
Sex: Male	Age: 40	Date of Birth: 10/03/1979	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: LABORATORY SUPERVISOR			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 14/10/2019 13:55	Type of Location: ALONG AYE AT JURONG TOWN HALL SLIP ROAD EXIT
Location: AYER RAJAH EXPRESSWAY				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control: Traffic Light - Working		Traffic Volume:
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GX1884A	Lorry					0
SKQ1457P	Car					0
YM9942H	Lorry					0



**SINGAPORE
POLICE FORCE**



T/20191015/7006

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20191015/7006

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	TAN ENG GUAN	ID No.	S7908408E
Related Vehicle	GX1884A (Lorry)	Contact No.	90215702
Hospital/Clinic	SINGAPORE GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	14/10/2019	Date Discharge	14/10/2019
No. of Days granted Medical Leave	02	Degree of Injury	Slight

Brief Details.

ON THE STATED DATE AND TIME, I WAS DRIVING ALONG AYE AT JURONG TOWN HALL SLIP ROAD EXIT. MY VEHICLE WAS AT THE EXTREME RIGHT LANE WAITING FOR GREEN LIGHT, SUDDENLY VEHICLE B (YM9942H) HIT ONTO THE REAR OF MY VEHICLE CAUSING MY VEHICLE TO MOVE FORWARD AND HIT ONTO THE REAR OF VEHICLE C (SKQ1457P).



**SINGAPORE
POLICE FORCE**



T/20191015/7006

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3
Report No. T/20191015/7006

CONTINUATION OF REPORT

Sketch Plan
Informant is not able to provide sketch plan

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 15/10/2019 12:02
Officer In Charge Of Case: TP / TPHQ / YEO GEAK ENG CECILIA Contact No.: 65476404	Classification Of Case:
Authentication Stamp NP168	

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	896H
Vehicle Details	
Vehicle No.:	GX1884A
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Oct 2019
Vehicle Make:	NISSAN
Vehicle Model:	P/UP D/CAB
Primary Colour:	Orange
Manufacturing Year:	2003
Engine No.:	TD27724017
Chassis No.:	JN1CHGD22Z0071733
Maximum Power Output:	-
Open Market Value:	\$20,302.00
Original Registration Date:	27 Feb 2004
First Registration Date:	27 Feb 2004
Transfer Count:	0
Actual ARF Paid:	\$26,393.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	26 Feb 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$51,418.00
COE Rebate Amount:	\$22,340.00
Total Rebate Amount:	\$22,340.00

The information contained herein is correct as at 22 Oct 2019

OK

SGCARMART.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

nissan pick up

Price Range

Depreciation

> 10 year

Vehicle Type

Submit

Advanced Search

Home » Used Cars » Wunder Auto Pte Ltd » Nissan Double-Cab Pickup (New 5-yr COE)

Nissan Double-Cab Pickup (New 5-yr COE)

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price

\$29,800

Lifespan

10-Feb-2026

Depreciation

\$5,950 /yr

Reg Date

11-Feb-2006
(5yrs COE left)

Mileage

N.A.

Manufactured

2005

Road Tax

N.A.

Transmission

Manual

Dereg Value

N.A.

OMV

\$18,307

COE

N.A.

ARF

\$20,138

Engine Cap

2,664 cc

No. of Owners

4

Curb Weight

1,490 kg

Type of Vehicle

Truck

Features

New 5 Years COE



Shortlist

Report Error

Compare

More Actions

Add note

Description
Drive Like A Car, 5 Seaters, Reliable Heavy-Duty Double Cab Pickup! New 5 Years Coe, Free 1 Year Road Tax. High Loan Approval For Weak Credit! Call To View Now!

Category
COE Car

Status
Available

Resources

Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more

Car Valuation - Free

Find out the market value of your existing car for free. Get started

Seller Information

Company

Wunder Auto Pte Ltd

» dealer's pricelist

» 4 vehs sold | 5 vehs available

Address

7030 Ang Mo Kio Avenue 5 #01-01

Search cars nearby this location

Location

Northstar @ AMK

Office No

63838222

Contact Person(s)

Qas87984626

Joe Chen94278222

Thomass Ang97688222

Posted on: 19-Oct-2019 | Last Updated on: 19-Oct-2019

Upfront Payment		» more Financial Info
Transfer Fee	\$25	
Down Payment	\$2,980 (change)	Maximum 90% Loan
1st Instalment	\$659	Based on 4.5% interest rate
Insurance		

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 197000896H
CEMENTAID (SEA) PTE LTD
NO

SINGAPORE
TEL : 68969801 FAX :
PH :
ATTN :

ESTIMATE BILL

Number : EB00005302
Date : 15/10/2019
Case No : AD00010727
Vehicle No : GX1884A
Chassis : JN1CHGD22Z0071733
Year of Mfr : 2003
Policy No : 5018365551-12
Model : NISSAN P/UP D/CAB

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	TAILGATE	1.0	917.90	10	826.11
2	TAILGATE LOGO	1.0	46.10	10	41.49
3	REAR BUMPER	1.0	900.00	10	810.00
4	REAR BUMPER TOP STEP GARNISH	1.0	336.00	10	302.40
5	REAR BUMPER TOP STEP PANEL	1.0	174.00	10	156.60
6	REAR BUMPER CENTER STEP PANEL	1.0	275.00	10	247.50
7	REAR BUMPER CENTER STEP PANEL GARNISH	1.0		10	
8	REAR NUMBER LAMP LH	1.0	56.40	10	50.76
9	REAR NUMBER LAMP RH	1.0	56.40	10	50.76
10	TAILGATE LOCK	1.0	54.90	10	49.41
11	END PANEL	1.0		10	
12	BONNET	1.0	775.50	10	697.95
13	BONNET LOCK	1.0	94.00	10	84.60
14	FRONT WIPER TANK MOTOR	1.0		10	
15	SUPPORT PANEL	1.0	517.60	10	465.84
16	HEADLAMP LH	1.0	338.20	10	304.38
17	HEADLAMP RH	1.0	338.20	10	304.38
18	BRACE PANEL	1.0	65.30	10	58.77
19	FRONT GRILLE	1.0	375.80	10	338.22
20	FRONT GRILLE EMBLEM	1.0	59.70	10	53.73
21	FRONT BUMPER BRACKET RH	1.0	86.60	10	77.94
22	FRONT BUMPER BRACKET LH	1.0	86.60	10	77.94
23	FRONT BUMPER REINFORCEMENT	1.0	387.50	10	348.75
24	FRONT BUMPER	1.0	441.80	10	397.62
Nett Price - Parts Sub Total					5,745.15
25	REAR BUMPER BRACKET RH	1.0	149.10	10	134.19
26	REAR BUMPER BRACKET LH	1.0	149.10	10	134.19
27	FRONT WIPER TANK	1.0	181.40	0	181.40
28	AIR CON CONDENSER	1.0	517.90	0	517.90
29	RADIATOR	1.0	761.10	0	761.10
30	RADIATOR SPARE TANK	1.0	74.00	0	74.00
31	FRONT NUMBER PLATE	1.0	30.00	0	30.00
32	REAR NUMBER PLATE	1.0	30.00	0	30.00

E. & O. E.

P- 4331.70

10%

P- 3898.53

S.N- 48.00

CUSTOMER SIGNATURE

L- 2570.00

* N = Item not subjected to GST

6496.53

5197.22

HOCK WAH MOTOR WORKSHOP PTE LTD

AUTHORISED SIGNATURE



Issued by : Anyisia

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 197000896H
CEMENTAID (SEA) PTE LTD
NO

SINGAPORE
TEL : 68969801 FAX :
PH :
ATTN :

ESTIMATE BILL

Number : EB00005302
Date : 15/10/2019
Case No : AD00010727
Vehicle No : GX1884A
Chassis: JN1CHGD22Z0071733
Year of Mfr 2003
Policy No 5018365551-12
Model : NISSAN P/UP D/CAB

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
33	TAILGATE STICKER - 5PAX <i>NI</i>	1.0	30.00	0	30.00
34	TAILGATE STICKER - 70KM/H <i>NI</i>	1.0	30.00	0	30.00
35	SIDE PANEL - PTE LTD STICKER <i>NI</i>	1.0	250.00	0	250.00
36	TAILGATE - PTE LTD STICKER <i>NI</i>	1.0	250.00	0	250.00
37	REAR FLOOR PANEL - REPAIR <i>NI</i>	1.0			
38	SIDE PANEL LH - REPAIR <i>NI</i>	1.0			
Special Nett Price - Parts Sub Total					2,422.78
Parts Total					8,167.93
39	LABOUR TO REMOVE & REFIT NECESSARY PARTS (REAR)	1.0	1,500.00	0	1,500.00
40	SPRAY PAINT ON THE AFFECTED AREAS (REAR)	1.0	1,000.00	0	1,000.00
41	ANTI-RUST COATING (REAR)	1.0	300.00	0	300.00
Labour 1 Sub Total					2,800.00
42	LABOUR TO REMOVE & REFIT NECESSARY PARTS (FRONT)	1.0	1,000.00	0	1,000.00
43	SPRAY PAINT ON THE AFFECTED AREAS (FRONT)	1.0	900.00	0	900.00
44	ANTI-RUST COATING (FRONT)	1.0	250.00	0	250.00
45	TO SERVICE & TOP-UP AIR-CON GAS	1.0	180.00	0	180.00
46	WIRING (FRONT)	1.0	80.00	0	80.00
Labour 2 Sub Total					2,410.00
SINGAPORE DOLLARS : FOURTEEN THOUSAND THREE HUNDRED FOURTEEN AND CENTS THIRTY-NINE ONLY					0.00
Less Excess					
SUBTOTAL					13,377.93
GST 7.00%					936.46
TOTAL					14,314.39

Date of accident : 14/10/2019 01:55 PM. Place : AYE AT JURONG TOWN HALL SLIP ROAD EXIT

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Oct 2019 09:39		21 Oct 2019 16:39 Edit Adj Rpt	S\$5,000.00 Edit Estimates	S\$5,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	PHOON HUAT PTE LTD, Co. Reg. No.: 201604649G								
Main Claimant:	CEMENTAID (SEA) PTE LTD, Co. Reg. No.: 197000896H								
Vehicle Reg. No.:	GX1884A	Date of Loss:	14/10/2019 14:00 - :59 [187 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 608684	Policy/Cover Note No.:	29119383 (Third Party Only) Coverage: 27/03/2019 - 26/03/2020						
Vehicle Reg. No. (Insured):	YM9942H	Policy No. (Claimant):							
		Excess:							
Repairer:	Hock Wah Motor Workshop Pte Ltd (Bedok) Blk 3011, Bedok Industrial Park E,, #01-2008/2010/2012, 489977 Bedok - Tel: 6441 5655								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 20/11/2019]								
Adj Asg. Remarks:	on WP. Car in 22/10/19, survey after 10am at Bedok w/shop. Please contact us ASAP if you cannot attend this assignment. Liab: clear. Contact: Anysia Foo @ 6441 5655.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GX1884A (608684)
 [YM9942H]
 TP
 CEMENTAID (SEA) PTE LTD
 Oct 14 2019 2:00PM
 [PHOON HUAT PTE LTD]
 Hock Wah Motor Workshop Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Assessment Reports























































1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	24/10/19 08:55	Adjuster Immediate Advice		Load HTM	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	22/10/19 19:18	Chassis Number		Load JPG	
2	22/10/19 19:18	Odometer Reading		Load JPG	
3	22/10/19 19:20	General View		Load JPG	
4	22/10/19 19:20	General View		Load JPG	
5	22/10/19 19:20	General View		Load JPG	
6	22/10/19 19:20	General View		Load JPG	
7	22/10/19 19:20	General View		Load JPG	
8	22/10/19 19:20	General View		Load JPG	
9	22/10/19 19:20	General View		Load JPG	
10	22/10/19 19:20	General View		Load JPG	
11	22/10/19 19:20	General View		Load JPG	
12	22/10/19 19:20	General View		Load JPG	
13	22/10/19 19:20	General View		Load JPG	
14	22/10/19 19:20	General View		Load JPG	
15	22/10/19 19:20	General View		Load JPG	
16	22/10/19 19:20	General View		Load JPG	
17	22/10/19 19:20	General View		Load JPG	
18	22/10/19 19:20	General View		Load JPG	
19	22/10/19 19:20	General View		Load JPG	
20	22/10/19 19:20	General View		Load JPG	
21	22/10/19 19:20	General View		Load JPG	
22	22/10/19 19:20	General View		Load JPG	
23	22/10/19 19:20	General View		Load JPG	
24	22/10/19 19:20	General View		Load JPG	
25	22/10/19 19:20	General View		Load JPG	
26	22/10/19 19:20	General View		Load JPG	
27	22/10/19 19:20	General View		Load JPG	
28	22/10/19 19:20	General View		Load JPG	
29	22/10/19 19:20	General View		Load JPG	
30	22/10/19 19:20	General View		Load JPG	
31	22/10/19 19:20	General View		Load JPG	
32	22/10/19 19:20	General View		Load JPG	
33	22/10/19 19:21	General View		Load JPG	
34	22/10/19 19:21	General View		Load JPG	
35	22/10/19 19:21	General View		Load JPG	
36	22/10/19 19:21	General View		Load JPG	
37	22/10/19 19:21	General View		Load JPG	
38	22/10/19 19:21	General View		Load JPG	
39	22/10/19 19:21	General View		Load JPG	
40	22/10/19 19:21	General View		Load JPG	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
41	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
42	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
43	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
44	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
45	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
46	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
47	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
48	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
49	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
50	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
51	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
52	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
53	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
54	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
55	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
56	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
57	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
58	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
59	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
60	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
61	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
62	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
63	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
64	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
65	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
66	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
67	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
68	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
69	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
70	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
71	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
72	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
73	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
74	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
75	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
76	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
77	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
78	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
79	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
80	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
81	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
82	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
83	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
84	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
85	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
86	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
87	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
88	22/10/19 19:21	General View	 Load JPG	<input checked="" type="checkbox"/>
89	04/11/19 08:37	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
90	04/11/19 08:37	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
91	04/11/19 08:37	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
92	04/11/19 08:37	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
93	04/11/19 08:37	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
94	04/11/19 08:37	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	17/10/19 09:41	REPAIR EST		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19018565/UYF3E2

Date: 13/11/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29119383

Claimant

Vehicle No : GX1884A

Insured Vehicle No : YM9942H

Date of Loss: 14/10/2019

Nature of Claim:

TP

Claim No: 608684

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GX1884A**

Make & Model: NISSAN P/UP D/CAB, 2.7 D (M)

Engine No: TD27724017

Reg. Date: 27/02/2004 (Man. Year: 2003)

Chassis No: JN1CHGD22Z0071733

Colour: Orange

Odometer: 502536 km

Engine Capacity: 2664 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185 R14

Rear Tyre Size: 185 R14

Front Left Side: GREEN-MAX 6 mm

Rear Left Side: GREEN-MAX 6 mm

Front Right Side: GREEN-MAX 6 mm

Rear Right Side: GREEN-MAX 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,167.93	3,887.76	4,280.17	52.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,210.00	2,550.00	2,660.00	51.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,377.93	6,437.76	6,940.17	51.88
Approved Total (Overridden) (S\$)		5,000.00		
(S\$)	13,377.93	5,000.00	8,377.93	62.63
+ GST 7.00/7.00% (S\$)	936.46	350.00	586.46	62.63
Nett Amount (S\$)	14,314.39	5,350.00	8,964.39	62.63

INSPECTION

Date of Assignment: 21/10/2019

Date Inspected: 22/10/2019 Inspected At:

Hock Wah Motor Workshop Pte Ltd
(Bedok)
Blk 3011, Bedok Industrial Park E.,
#01-2008/2010/2012
Singapore 489977

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 13 Nov 2019)	
Parts:	N/A	NISSAN P/UP D/CAB 2.7 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GX1884A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented/Bent	917.90 FL	*917.90 FL
2	1		*TAILGATE LOGO	Necessary	46.10 FL	*46.10 FL
3	1		*REAR BUMPER	Distorted	900.00 FL	*791.60 FL
4	1		*REAR BUMPER TOP STEP GARNISH	Distorted	336.00 FL	*336.00 FL
5	1		*REAR BUMPER TOP STEP PANEL	Bent	174.00 FL	*174.00 FL
6	1		*REAR BUMPER CENTER STEP PANEL }	Distorted	275.00 FL	*275.00 FL
7	1		*REAR BUMPER CENTER STEP PANEL GARNISH }	Distorted	0.00 FL	*- FL
8	1		*REAR NUMBER LAMP LH	Not Necessary	56.40 FL	*- FL
9	1		*REAR NUMBER LAMP RH	Not Necessary	56.40 FL	*- FL
10	1		*TAILGATE LOCK	Not Necessary	54.90 FL	*- FL
11	1		*END PANEL (NPA)	Repair	0.00 FL	*- FL
12	1		*BONNET	Repair	775.50 FL	*- FL
13	1		*BONNET LOCK	Twisted	94.00 FL	*94.00 FL
14	1		*FRONT WIPER TANK MOTOR (NPA)	Not Necessary	0.00 FL	*- FL
15	1		*SUPPORT PANEL	Repair	517.60 FL	*- FL
16	1		*HEADLAMP LH	Cracked	338.20 FL	*321.10 FL
17	1		*HEADLAMP RH	Cracked	338.20 FL	*321.10 FL
18	1		*BRACE PANEL	Repair	65.30 FL	*- FL
19	1		*FRONT GRILLE	Cracked	375.80 FL	*375.80 FL
20	1		*FRONT GRILLE EMBLEM	Necessary	59.70 FL	*59.70 FL
21	1		*FRONT BUMPER BRACKET RH	Not Necessary	86.60 FL	*- FL
22	1		*FRONT BUMPER BRACKET LH	Not Necessary	86.60 FL	*- FL
23	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	387.50 FL	*- FL
24	1		*FRONT BUMPER	Dented	441.80 FL	*405.00 FL
25	1		*REAR BUMPER BRACKET RH	Not Necessary	149.10 FL	*- FL
26	1		*REAR BUMPER BRACKET LH	Bent	149.10 FL	*149.10 FL
27	1		*FRONT WIPER TANK	Not Necessary	181.40 FS	*- FS
28	1		*AIR CON CONDENSER	Not Necessary	517.90 FS	*- FS
29	1		*RADIATOR	Not Necessary	761.10 FS	*- FS
30	1		*RADIATOR SPARE TANK	Not Necessary	74.00 FS	*- FS
31	1		*FRONT NUMBER PLATE	Bent	30.00 FS	*14.00 FS
32	1		*REAR NUMBER PLATE	Bent	30.00 FS	*14.00 FS
33	1		*TAILGATE STICKER-5PAX	Necessary	30.00 FS	*10.00 FS
34	1		*TAILGATE STICKER-70KM/H	Necessary	30.00 FS	*10.00 FS
35	1		*SIDE PANEL-PTE LTD STICKER	Not Necessary	250.00 FS	*- FS
36	1		*TAILGATE-PTE LTD STICKER	Not fitted	250.00 FS	*- FS
37	1		*REAR FLOOR PANEL (NPA)	Repair	0.00 FS	*- FS
38	1		*SIDE PANEL LH (NPA)	Repair	0.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **8,836.10** **4,314.40**
 - List Item Discount on L Items 10.00/10.00% (\$\$) **668.17** **426.64**

Total Parts (\$\$) 8,167.93 3,887.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS (REAR)	New	1,500.00	680.00
2	SPRAY PAINT ON THE AFFECTED AREAS (REAR)	New	1,000.00	550.00
3	ANTI-RUST COATING (REAR)	New	300.00	50.00
4	LABOUR TO REMOVE & REFIT NECESSARY PARTS (FRONT)	New	1,000.00	520.00
5	SPRAY PAINT ON THE AFFECTED AREAS (FRONT)	New	900.00	600.00
6	ANTI-RUST COATING (FRONT)	New	250.00	20.00
7	TO SERVICE & TOP-UP AIR-CON GAS	New	180.00	100.00
8	WIRING (FRONT)	New	80.00	30.00
Gross Labour Cost (S\$)			5,210.00	2,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >