

ASS. REC. BY:

REF: CS/CT1 1908568 / T1 + f3

Special Instruction:

Survivor: Taufik

ASSIGNMENT (Office)

From (Person): Tan Kah Leong

of C12

Date/Time: 21.10.19 16.26pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKK 7390P

Insured: GBG 18605

at Workshop m/s Performance Motor

Tel: 63190177

of 303 Alexandra Road

Policy No: GBG 18605

Claim No: SM191720494702

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 16.10.2019

CA / REV / REP. / REV 24 HRS

rup

H.O.D. Endorsement:

Date/Time: 21.10.19 4.33pm

Person Contacted:

Caroline

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SKK 7390P - X</u>
	<u>GBG 18605 - X</u>

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Enc Auth'd	Status
Main	21 Oct 2019		21 Oct 2019 16:26 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:									
Main Claimant: KOH SWEE LIM, ID: S0002397C									
Vehicle Reg. No.: SKK7390P		Date of Loss: 16/10/2019 12:00 - :59							
Claim Type: TP / SNM19D204947C02		Policy/Cover Note No.: G8G1860S							
Vehicle Reg. No. (Insured): G8G1860S		Policy No. (Claimant): 27572060							
		Excess: S\$350.00							
Repairer: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]									
Claimant's Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 31/10/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
☐ ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	397C
Vehicle Details	
Vehicle No.:	SKK7390P
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Jan 2020
Vehicle Make:	B.M.W.
Vehicle Model:	520i AT D/AB 2WD 4DR LED NAV
Primary Colour:	Brown
Manufacturing Year:	2013
Engine No.:	B4300553N20B20B
Chassis No.:	WBA5A32030D333543
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$47,864.00
Original Registration Date:	27 Aug 2013
First Registration Date:	27 Aug 2013
Transfer Count:	0
Actual ARF Paid:	\$54,010.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Aug 2023
PARF Rebate Amount:	\$35,106.00
Intended COE Rebate Details	
COE Expiry Date:	26 Aug 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$76,607.00
COE Rebate Amount:	\$27,780.00
Total Rebate Amount:	\$62,886.00

The information contained herein is correct as at 10 Jan 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/10/2019 18:07
Date Of Accident	16/10/2019 12:00
Exact Location Of Accident	BEDOK CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKK7390P
Insured/Policyholder	
Name Of Registered Owner	KOH SWEE LIM
NRIC No	S0002397C
Email Address	JSLKOH@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-98184234
Alternative Phone No	OTHERS-98184234

Vehicle Particulars

Manufacturer	BMW
Model	520I-2.0 AT D/AB 2WD 4DR LED NAV (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	27572060
Cover Note Number	

Driver

Name of Driver	KOH SWEE LIM
NRIC No	S0002397C
Date Of Birth	05/01/1953
Occupation	INDOOR
Date Of Driving Pass	24/11/1972
Driving Experience	46 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98184234
Fax Number	
Contact Number	OTHERS-98184234
Email Address	JSLKOH@HOTMAIL.COM

Address	6 BEDOK TERRACE
Postcode	469165
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 16/10/19 ABOUT 12PM, I WAS REVERSING INTO PARKING LOT. HALFWAY THRU, VEHICLE B CAME UP FROM THE SLOPE AND COLLIDED INTO MY FRONT RIGHT BUMPER AND HEADLIGHT. NOBODY WAS INJURED. MY FRONT RIGHT BUMPER AND HEADLIGHT IS DAMAGE. I WISH TO STATE THAT MY CAR DAY-RUNNING HEADLIGHTS ARE SET ON PERMANENTLY AT THE TIME OF ACCIDENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBG1860S
Vehicle Make/Model/Colour	TOYOTA
Details Of Properties	VEH B
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	KHOO CHOON HUA
NRIC/Passport Number	S7121086C
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



A SKK7390P
B GGG18605

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 16/10/19 ABOUT 12pm, I WAS REVERSING INTO PARKING LOT. HALFWAY THRU, VEH B CAME UP FROM THE SLOPE AND COLLIDED INTO MY FRONT RIGHT BUMPER AND HEADLIGHT. NOBODY WAS INJURED. MY FRONT RIGHT BUMPER AND HEADLIGHT IS DAMAGE.

16/10/19
1546

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 436180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64795601 (AfterSales)
64795624 (MOBICAR)



Survey only
30/10/19

GST REG. NO : M2 - 0020081 - X

21 OCT 2019

ESTIMATE # CAR-IN

Estimate No. : b1 53146
Date Estimated : 19/10/2019
Prepared By : Joseph Yaguel

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Koh Swee Lim
6 Bedok Terrace

Singapore 469165

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKK7390P	WBA5A32030D333543	27/08/2013	5201A	0

DESCRIPTION

Replacing front bumper panel and attachments

VALUE
850 1,275.00

Spray front bumper

934 1,038.00

To replace right headlight.

408 481.00

To check electrical wiring systems at the front section
for proper function including adjustments of headlights.

150 177.00

Sundries

? 150.00

Total Labour 1: 3,121.00

DESCRIPTION

FRT BUMPER CARRIER
FRT BUMPER LH SPACER
FRT BUMPER RH SPACER
RH OPEN GRILLE AIR INLET (LINES)
FRT SHOCK ABSORBER
FRT BUMPER RH PROTECTIVE RUBBER STR
FRT BUMPER RH PROTECTIVE RUBBER STR
FRT BUMPER PANEL PRIMED (PDC)
RH COVERING PRIMEND
FRT RH GRILLE (BASIS)
RH HIGH PRESSURE NOZZLE
RH HEADLIGHT LED TECHNOLOGY
RH FOG LIGHT LED

QTY	PRIC	VALUE
1	715.90	? 715.90
1	29.90	X 29.90
1	29.90	? 29.90
1	95.05	cut? 95.05
1	60.00	? 60.00
1	65.50	? 65.50
1	65.50	? 65.50
1	1,351.15	del? 1,351.15
1	47.60	cut? 47.60
1	141.45	? 141.45
1	183.80	? 183.80
1	4,203.70	cut? 4,203.70
1	450.95	cut? 450.95

Total Parts : 7,440.40

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438100
Fax: 63449775

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 53146
Date Estimated : 19/10/2019
Prepared By : Joseph Yaguel

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKK7390P	WBA5A32030D333543	27/08/2013	520iA	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 30/10/19 @ 1140 Excess S\$ _____

Surveyor's Name Taufik Sign Taufik

Surveyor's Tel 97495749 Authorised Yes / No _____

Authorised Date WP Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail taufik @ Marto.com

No. of Working Days Recommend 03 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____



Labour 1	:	3,121.00
Parts	:	7,440.40
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	739.30
Grand Total	:	11,300.70

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **