

03/MSG19018597/utd3n2

ASS. REC. Bt: *Marcus*

REF:

*MS161*

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: *SLW 4091Y*  
 at Workshop m/s *L4*  
 of *SKU 60004*  
 Insured: *80404807QMY.*  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: *724.*  
 IDAC Accident Report: Consistent? : Yes or No  
☒ PR Seen: Consistent? : Yes or No  
 Est. Repairs: days Res.: Yes or No  
 Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: *035A*  
 Vehicle: IN / OUT

Date / Time Action / Instruction *LTA 42218 RJS3m*

*22/10 @ 9:59am email Accident Report*

*30/10/19 \$6500 Confirmed with Aln. Cred. 128161 66%*

RECEIVED 04 NOV 2019

*23/10/2019*

Veh No: *SLW 4091Y* Yr Regn: *218*  
 Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or *CA1*  
 Make: *Honda* *Verde* C.C. *1496*  
 Colour: *Red* A/C: Insured / Std / NI / NA  
 Sp. Reading: *19393* T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: *RU11232592*  
 Gen. Cond: ☒ Good / Fair / Poor / Burnt  
 Steering: ☒ In order / Jammed / Leaked / Burnt or  
 Brake: ☒ In order / Jammed / Leaked / Burnt or  
 Modi: ☒ Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: *215/60R16*  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or  
 Front *7* mm R/Bal. *7* mm  
 L/Bal. *7* mm L/Bal. *7* mm  
 D.O.A. *19/10/19* D.O.I. *21/10/19*  
 Survey held at \_\_\_\_\_  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
*Rear*  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to? ☐ : Preli. Report

*1) 8/10 Typist* ☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: *5*

Resurvey No. of Trip: *1*

Survey Feet:

Transportation: *200*

*11*

Photos

Others

TOTAL

200
11
211

Report Format : *TP*

Lump Sum / I.B.I: (\$ *6500*)

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech. Invs (\$ \_\_\_\_\_)

☐ : Weekend (\$ \_\_\_\_\_)

**Denise Tay (LKKAuto)**

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Tuesday, 22 October 2019 9:59 AM  
**To:** 'motorsurvey@sg.msig-asia.com'; SUR  
**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 19/10/2019, SLW 4091Y (TP VEHICLE), SKV 6000U (OI VEHICLE)  
**Attachments:** ACCIDENT REPORT.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SLW 4091Y at M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 on 21/10/2019

Enclosed herewith a copy of TP's GIA report and estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

All Fuel Discounts,  
Coupons, Promotions,  
Offers Thread

COE Bidding – 2nd  
Round of October 2019

Post an Advertisement  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

ATTRACTIVE BMW 523i DEAL!



Top Condition: Metallic Blue  
With Classy Beige Interior!  
Warranty Covered!  
StarAd

**AutoInn**  
An Inspiration For Car Buyers

click here to view  
our **PRISTINE USED CARS**  
at **GREAT PRICES**

Post an Ad

Advertiser Login

Ways of Selling

Browse by Category

« Back ( 1 2 ) Next »








Sort by Date Posted

20 results/page

27 vehicles

vezel

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	vezel		Any	Any	2018	Any	Any	Any	Available
	Honda	Vezel Hybrid 1.5A	\$95,800	\$10,120 /yr	27-Jun-2018	1,496 cc	5,000 km	SUV	Available
<b>Fuel Type:</b> Petrol-Electric Almost New 2018 New Facelifted Honda Vezel Hybrid. Best Fuel Consumption SUV In Town. 10 Years Repayment, In House Loan Or Ball... Trust Motoring Posted: 20-Oct-2019 Tags: 2018 Honda Vezel, 2018 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									
	Honda	Vezel 1.5A X	\$79,800	\$7,820 /yr	31-Dec-2018	1,496 cc	-	SUV	Available
2018 New Facelifted Honda Vezel. Low Fuel Consumption. 10 Years Repayment, In House Loan Or Balloon Scheme Available. Make And... Trust Motoring Posted: 20-Oct-2019 Tags: 2018 Honda Vezel, 2018 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									
	Honda	Vezel 1.5A X	\$75,800	\$8,310 /yr	08-Mar-2018	1,496 cc	39,900 km	SUV	Available
Excellent Condition In And Out White Unit Previously Owned By One Meticulous Owner. Well Spaced Interior And One Of The Top Sellin... Benefit Auto Enterprise Pte Ltd Posted: 19-Oct-2019 Tags: 2018 Honda Vezel, 2018 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									
	Honda	Vezel Hybrid 1.5A	\$92,800	\$9,800 /yr	18-Jun-2018	1,496 cc	-	SUV	Available
<b>Fuel Type:</b> Petrol-Electric New Facelifted Honda Vezel Hybrid. Best Fuel Consumption SUV In Town., In House Loan Available. Trade In Always Welcome! Posted: 19-Oct-2019 Tags: 2018 Honda Vezel, 2018 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									
	<b>Tailgate LED Light</b> Tailgate LED Light for Honda Vezel with 1 year warranty More info about this product								
	Honda	Vezel Hybrid 1.5A X Honda Sensing	\$92,800	\$9,680 /yr	06-Jun-2018	1,496 cc	18,236 km	SUV	Available
<b>Fuel Type:</b> Petrol-Electric 1 Owner. Low Mileage. Well Kept. Accident Free. Bank Loans And In-house Financing Available. 100% Financing Available. View Now! Posted: 19-Oct-2019 Tags: 2018 Honda Vezel, 2018 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									
	Honda	Vezel 1.5A X Honda Sensing	\$78,800	\$8,360 /yr	29-Jun-2018	1,496 cc	8,237 km	SUV	Available
Interest Rate Offer At 2.28%! 1 Owner! Super Low Mileage, Owner Second Car, Not A PHV Unit! In House Financing Available! High Loa... Posted: 19-Oct-2019 Tags: 2018 Honda Vezel, 2018 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									
Compare			\$75,800	\$8,270 /yr	09-Mar-2018	1,496 cc	8,800 km	SUV	Available

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 035A

**Vehicle Details**

Vehicle No.: SLW4091Y

Vehicle to be Exported: No

Intended Deregistration Date: 21 Oct 2019

Vehicle Make: HONDA

Vehicle Model: VEZEL 1.5X CVT

Primary Colour: Red

Manufacturing Year: 2017

Engine No.: L15B4432596

Chassis No.: RU11232592

Maximum Power Output: 96.0 kW (128 bhp)

Open Market Value: \$21,447.00

Original Registration Date: 09 Feb 2018

First Registration Date: 09 Feb 2018

Transfer Count: 0

Actual ARF Paid: \$12,026.00 6013

**Intended PARF Rebate Details**

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 08 Feb 2028

PARF Rebate Amount: \$9,019.00

**Intended COE Rebate Details**

COE Expiry Date: 08 Feb 2028

COE Category: A - Car up to 1600cc &amp; 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$40,000.00

COE Rebate Amount: \$33,199.00

**Total Rebate Amount: \$42,218.00**

The information contained herein is correct as at 21 Oct 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	21/10/2019 11:38
Date Of Accident	19/10/2019 16:00
Exact Location Of Accident	HOUGANG GREEN TWDS SENGKANG(JCT OF HOUGANG AVE 4)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLW4091Y
<b>Insured/Policyholder</b>	
Name Of Registered Owner	WANG CHONG NONG
NRIC No	S0202035A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90677211
Alternative Phone No	Others-90677211

### Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL 1.5X CVT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VA1/GA441903
Cover Note Number	

### Driver

Name of Driver	WANG CHONG NONG
NRIC No	S0202035A
Date Of Birth	01/01/1949

Occupation	INDOOR
Date Of Driving Pass	29/04/1985
Driving Experience	34 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90677211
Fax Number	
Contact Number	OTHERS-90677211
EMail Address	NOEMAIL
Address	229 SERANGOON AVENUE 4 #04-43 SPORE 550229
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

**General Information of the Accident**

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

**Other Information**

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	Name: : WONG MOI LEE Gender: : Female

**Details of Police Action**

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

**Circumstances of Accident**

REFER TO SKETCH PLAN

**Attachment(s)**

Are accident photos available for attachment?	YES
---	-----

Date of Accident : 19.10.2019 Accident Time: 16.00 (24-HR-Format)

Accident Place : Hougang Green Towards Sengkang (junction of Hougang Ave 4)

Vehicle No. (Car Plate No.) : SLW 4091Y Make/Model: Honda Vezel

Insurance Company : Axa Policy No: VAI/EA44903

Owner or Company Name /IC No. : Wang Chong Hong (S0202035A)

Owner or Company Contact No. : 906 77211 Owner's Hp Company Tel

DRIVER'S Name / IC No. : as above

DRIVER'S Date Of Birth : 1949 DRIVER'S License Pass Date

Relationship of Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others: Owner

DRIVER'S Address : Blk 229 Serangoon Avenue 4 #04-43 (S)

DRIVER'S Contact No / Alt No. : 1) 2)

DRIVER'S Occupation : INDOOR \ OUTDOOR (e.g. working inside or outside office)

Email Address :

Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET

Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Insurance

Number of Passengers (Including Driver): 1 passengers x 1 Driver

Was there any video Captured by car camera: YES \ NO

Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose

Any Injury (If YES, Pls state): No

Other Party Driver's Particular (if any)

Vehicle No: SW 6000 U Vehicle No:

Vehicle Make\Model: Vehicle Make\Model:

Name Driver: Name Driver:

IC No. Driver/Contact: IC No. Driver/Contact:

\* NEW - Passenger's name & gender:

\* Wong Moi Lee - Female.





## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



# SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 19.10.2019 at about 4pm, I was driving my vehicle A along Hougang Green Towards Pongkang (junction of Hougang Ave 4)

In front of the vehicle slow down due to traffic, suddenly vehicle B hit my rear portion.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

Not Authorized  
21/10/19  
1/5 # 6500

Sdy.

Qty Particular SLW 40911 Amount S\$

## List Item:

1 PCS	REAR WINDSCREEN MOULDING	
1 PCS	TAILGATE	953.00
1 PCS	TAILGATE OUTER HANDLE GARNISH	
1 PCS	TAILGATE 'H' LOGO	
2 PCS	TAILGATE REFLECTORS @\$280	
1 PCS	TAILGATE 'VEZEL' EMBLEM	
1 PCS	TAILGATE INNER LOCK	
1 PCS	TAILGATE LOCK STRIKER	
1 PCS	TAILGATE INNER TRIM BOARD	
1 SET	TAILGATE INNER TRIM BOARD CLIPS	
1 PCS	TAILGATE WEATHERSTRIP	
1 PCS	TAILGATE KEYLESS SENSOR	
1 PCS	REAR BUMPER CENTRE	
2 PCS	REAR BUMPER SIDES @\$235.10	
2 PCS	REAR BUMPER SIDE RETAINERS @\$35.20	
2 PCS	REAR BUMPER SCREW SPACERS @\$12	
2 PCS	REAR BUMPER REFLECTORS @\$151.20	
2 PCS	TAILLAMPS @\$460.60	
2 PCS	TAILLAMP HOUSING PANELS @\$195	
1 PCS	REAR END PANEL	
1 PCS	REAR END PANEL TOP GARNISH	
1 PCS	REAR BUMPER LOWER DIFFUSER	
1 SET	REAR BUMPER LOWER DIFFUSER CLIPS	
1 PCS	REAR EXHAUST	
2 PCS	REAR EXHAUST MOUNTINGS @\$45	
1 PCS	REAR EXHAUST HEAT SHIELD	
2 PCS	REAR FENDER INNER TRIMS @\$295.30	
1 SET	REAR FENDER INNER TRIM CLIPS	
2 PCS	REAR FENDER OUTER GARNISH @\$195.80	
1 PCS	REAR FLOOR PANEL top board	315.50
1 PCS	REAR FLOOR PANEL TOOLS SPONGE	488.20
2 PCS	REAR FENDERS @\$1100	

List Item Total:

121.30	
1,100.90	
285.30	X
35.80	X
560.00	
56.20	
198.50	
25.50	X
321.70	
50.00	
135.70	
180.00	
762.70	
470.20	4PC
70.40	1PC
24.00	X
302.40	12C
921.20	
390.00	X
514.00	
125.00	
348.20	
50.00	
899.20	X
90.00	X
98.30	X
590.60	1PC
50.00	X
391.60	10C
912.30	
685.00	
2,200.00	X
12,966.00	

## Special Nett Item:

1 SET	REAR BUMPER REVERSER SENSOR
1 PCS	REAR REVERSE CAMERA
1 PCS	REAR WINDSCREEN SEALANT
1 PCS	REAR END PANEL SEALANT
1 PCS	REAR FLOOR PANEL INSULATOPR

Special Nett Total:

280.00	200
500.00	X
50.00	40
50.00	
180.00	X
1,060.00	

## Labour Charge:

TO CHECK WIRING

\$ 80.00 30

701080  
576264

TO DISMANTLE & REPLACE REVERSE SENSOR	\$	80.00	50
TO TRANSFER TAILGATE MECHANISM	\$	100.00	60
TO DISMANTLE & REFIX REAR WINDSCREEN	\$	150.00	120
TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY	\$	150.00	80
TO DISMANTLE & REPLACE REAR EXHAUST	11 \$	100.00	X
TO SPRAY RUST PROOFING	\$	150.00	60
TO MOUNT VEHICLE ON CAR O-LINER	11 \$	380.00	X
TO DISMANTLE & REFIX PETROL TANK	11 \$	100.00	X
LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS	\$	2,000.00	800
TO PUTTY & SPRAY PAINTING	\$	2,000.00	1050
Labour Charge Total:	\$	5,290.00	2250

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 19,316.00 8148.64

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG19018597/UTD3N2

Date: 06/11/2019

**REFERENCE**

<b>Handling Insurer:</b>	MSIG Insurance (Singapore) Pte. Ltd.	<b>Policy No:</b>	80404807QMY
<b>Claimant Vehicle No :</b>	SLW4091Y	<b>Insured Vehicle No :</b>	SKU6000U
<b>Date of Loss:</b>	19/10/2019	<b>Nature of Claim:</b>	TP
		<b>Claim No:</b>	N/A

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

<b>Reg No:</b>	SLW4091Y	<b>Engine No:</b>	L15B4432596
<b>Make &amp; Model:</b>	HONDA VEZEL, 1.5 1.5X CVT (A)	<b>Chassis No:</b>	RU11232592
<b>Reg. Date:</b>	09/02/2018 (Man. Year: 2017)	<b>Odometer:</b>	19393 km
<b>Colour:</b>	Red		
<b>Engine Capacity:</b>	1496 cc		
<b>Market Value/New Car Price:</b>	N/A		
<b>Sum Insured (\$\$):</b>	Market Value/New Car Price		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

<b>General Condition:</b>	<b>Steering (Serviceable):</b>	Yes	<b>Footbrake (Serviceable):</b>	Yes
<b>Handbrake (Serviceable):</b>	Yes	<b>Engine Modification:</b>	No	<b>Pre-accident Condition:</b>

**CONDITION OF TYRES**

<b>Front Tyre Size:</b>	215/60R16	<b>Rear Tyre Size:</b>	215/60R16
<b>Front Left Side:</b>	Dunlop 7 mm	<b>Rear Left Side:</b>	Dunlop 7 mm
<b>Front Right Side:</b>	Dunlop 7 mm	<b>Rear Right Side:</b>	Dunlop 7 mm

The above values represent the remaining tyre treads depth

**COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	14,026.00	5,901.04	8,124.96	57.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,290.00	2,250.00	3,040.00	57.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>19,316.00</b>	<b>8,151.04</b>	<b>11,164.96</b>	<b>57.80</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>6,500.00</b>		
<b>(\$\$)</b>	19,316.00	6,500.00	12,816.00	66.35
<b>+ GST 7.00/7.00% (\$\$)</b>	1,352.12	455.00	897.12	66.35
<b>Nett Amount (\$\$)</b>	<b>20,668.12</b>	<b>6,955.00</b>	<b>13,713.12</b>	<b>66.35</b>

**INSPECTION**

<b>Date of Assignment:</b>	23/10/2019	
<b>Date Inspected:</b>	21/10/2019	<b>Inspected At:</b>
		Fastech Auto Pte Ltd (HQ)
		1 Kaki Bukit Ave 6, #01-46/48/50
		Autobay
		Singapore 417883
<b>Estimated Period of Repair:</b>	5.0 days	

**Adjuster:** MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

*knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 06 Nov 2019)
<b>Parts:</b>	M1-SUV	HONDA VEZEL 1.5 1.5X CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLW4091Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *	

## Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR WINDSCREEN MOULDING	Necessary	121.30 F	*121.30 FL
2	1	*TAILGATE	Badly Dented	1,100.90 F	*953.00 FL
3	1	*TAILGATE OUTER HANDLE GARNISH	Not Necessary	285.30 F	*- FL
4	1	*TAILGATE H LOGO	Not Necessary	35.80 F	*- FL
5	2	*TAILGATE REFLECTORS	Cracked	560.00 F	*560.00 FL
6	1	*TAILGATE VEZEL EMBLEM	Necessary	56.20 F	*56.20 FL
7	1	*TAILGATE INNER LOCK	Twisted	198.50 F	*198.50 FL
8	1	*TAILGATE LOCK STRIKER	Not Necessary	25.50 F	*- FL
9	1	*TAILGATE INNER TRIM BOARD	Deformed/Cracked	321.70 F	*321.70 FL
10	1	*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 F	*50.00 FL
11	1	*TAILGATE WEATHERSTRIP	Twisted	135.70 F	*135.70 FL
12	1	*TAILGATE KEYLESS SENSOR	Cracked	180.00 F	*180.00 FL
13	1	*REAR BUMPER CENTRE	Distorted	762.70 F	*762.70 FL
14	1	*REAR BUMPER SIDES	N/s Distorted	470.20 F	*235.10 FL
15	1	*REAR BUMPER SIDE RETAINERS	N/s Bent	70.40 F	*35.20 FL
16	2	*REAR BUMPER SCREW SPACERS	Not Necessary	24.00 F	*- FL
17	1	*REAR BUMPER REFLECTORS	N/s Cracked	302.40 F	*151.20 FL
18	2	*TAILLAMPS	Cracked/Cut	921.20 F	*921.20 FL
19	2	*TAILLAMP HOUSING PANELS	Repair	390.00 F	*- FL
20	1	*REAR END PANEL	Badly Dented	514.00 F	*514.00 FL
21	1	*REAR END PANEL TOP GARNISH	Twisted	125.00 F	*125.00 FL
22	1	*REAR BUMPER LOWER DIFFUSER	Deformed/Twisted	348.20 F	*348.20 FL
23	1	*SET REAR BUMPER LOWER DIFFUSER CLIPS	Necessary	50.00 F	*50.00 FL
24	1	*REAR EXHAUST	Repair	899.20 F	*- FL
25	2	*REAR EXHAUST MOUNTINGS	Not Necessary	90.00 F	*- FL
26	1	*REAR EXHAUST HEAT SHIELD	Not Necessary	98.30 F	*- FL
27	1	*REAR FENDER INNER TRIMS	N/s Deformed	590.60 F	*295.30 FL
28	1	*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	50.00 F	*- FL
29	1	*REAR FENDER OUTER GARNISH	N/S Torn	391.60 F	*195.80 FL
30	1	*REAR FLOOR PANEL TOP BOARD	Torn	912.30 F	*315.50 FL
31	1	*REAR FLOOR PANEL TOOLS SPONGE	Torn	685.00 F	*488.20 FL
32	2	*REAR FENDERS	Repair	2,200.00 F	*- FL
33	1	*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
34	1	*REAR REVERSE CAMERA	Serviceable	500.00 FS	*- FS
35	1	*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
36	1	*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
37	1	*REAR FLOOR PANEL INSULATOR	Not Necessary	180.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **14,026.00**    **7,303.80**  
 - List Item Discount on L Items 0.00/20.00% (\$\$)    0.00    1,402.76

**Total Parts (\$\$) 14,026.00    5,901.04**

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACE REVERSE SENSOR	New	80.00	50.00
3	TO TRANSFER TAILGATE MECHANISM	New	100.00	60.00
4	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
5	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY	New	150.00	80.00
6	TO DISMANTLE & REPLACE REAR EXHAUST	New	100.00	0.00
7	TO SPRAY RUST PROOFING	New	150.00	60.00
8	TO MOUNT VEHICLE ON CAR O-LINER	New	380.00	0.00
9	TO DISMANTLE & REFIX PETROL TANK	New	100.00	0.00
10	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS	New	2,000.00	800.00
11	TO PUTTY & SPRAY PAINTING	New	2,000.00	1,050.00
<b>Gross Labour Cost (S\$)</b>			<b>5,290.00</b>	<b>2,250.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >