

ASS. REC. BY:

REF: CS/SMO19018606/Kyf3

Special Instruction:

Survivor: Kenneth

## ASSIGNMENT (Office)

From (Person): Grah Paul Long of SMO Date/Time: 24.10.19 17.32p.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKP 2197M Insured: SKX 5162X

at Workshop m/s Chew Gao motor Tel: 64841626

of BIR 10 AME Industrial Park 2A 101-15/16 or 17

Policy No: D18MTPV01019415 Claim No: CMT121904866

Sum Insured: Excess:

Make of Veh: D.O.A. 13.10.2019  
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 22.10.19 927a.m Person Contacted: Kelly - Vehicle: IN/OUT

Date/Time	Action/Instruction ( ✓ ) Estimate
	SKP 2197M - X
	SKX 5162X - X
23/10	Sent Preli by Merimer
17/12/19	Kenneth confirmed RS \$1800f and 3 days with Kelly. (Ref 737f, 292)

ASS. REC. BY:

REF: SMD

## ASSIGNMENT

From:

Date 22.10.2019

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKP 2197m

at Workshop m/s Chew Guan Motor

at Blk 10 Amk Industrial Park 2A 101-15

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 03 days Res: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKP 2197m

Yr Regn:

08, 14

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volkswagen Golf TR 1395

Colour:

n. Blue

A/C: Insured / Std / NI / NA

Sp. Reading

25059

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WVW 888 44 ZFW 010277

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/40ZR18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / DHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

8 mm

Rear

R/Bal.

8 mm

L/Bal.

8 mm

L/Bal.

8 mm

D.O.A.

13/10/19

D.O.I.

22/10/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear n/s down

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 20 JAN 2020

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

Rep. Format:

TP

Lump Sum / F.E.R.T:

1800

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Meal end (\$)

Survey Fee:

Transportation:

S + RS \$

Phone:

Other:

TOTAL

200

11

261

**Note: This document has not been finalised.**

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompoo Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: GNOH PAU LOONG

Date: 23 Oct 2019

**Preliminary Advice**

Insured Vehicle No	: SKX5262X	Accident Date	: 13/10/2019
TP Vehicle No	: SKP2197M	Assignment Date	: 21/10/2019
Make	: VOLKSWAGEN GOLF	Est. Duration of Repair	: 3.00
Date of Inspection	: 22/10/2019		
Inspection At	: CHEW GOON MOTOR (AMK) BLK 10 ANG MO KIO INDUSTRIAL PARK 2A, #01-15/16 & 17, AMK AUTOPOINT SINGAPORE 568047		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear n/s door portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,537.00
Revised Amount	:S\$	2,095.00
Check Items (Estimated)	:S\$	220.00
Total	:S\$	2,315.00

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : The above survey was conducted on a without "prejudice" basis.

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Oct 2019		21 Oct 2019 17:32 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

## CLAIM SUBFOLDER DETAILS

Insured:	LIW WEIJIAN NICK, ID: S8538000A, Tel: +6594871010, Email: nickliw@yahoo.com [Created by insurer]		
Main Claimant:	UNKNOWN		
Vehicle Reg. No.:	SKP2197M		
Claim Type:	TP / CMTD1904866	Date of Loss:	13/10/2019 10:00 - :59
Vehicle Reg. No. (Insured):	SKX5262X	Policy/Cover Note No.:	D18MTPV01019415 (Comprehensive)
		Policy No. (Claimant):	
		Excess:	
Reparer:	Chew Goon Motor (AMK) Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64841626		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 31/10/2019]		
Driver/Custodian (Insured):	LIW WEIJIAN NICK (33 / Male) , NRIC: S8538000A, Tel: +6594871010 Email: nickliw@yahoo.com		
Adj Asg. Remarks:	Please assign to Mr Kenneth Kong		

## ASSOCIATED MAIL RECEIVED

There are no mail for this case.

View All

Compose Case Mail

## ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View All

Search Tasks

Create New Task

Complete

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	237I
<b>Vehicle Details</b>	
Vehicle No.:	SKP2197M
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Oct 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	GOLF A7 1.4 TSI AT 5G13GZ SR HID
Primary Colour:	Blue
Manufacturing Year:	2014
Engine No.:	CXS211229
Chassis No.:	WVWZZZAUZFW010277
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$22,710.00
Original Registration Date:	25 Aug 2014
First Registration Date:	25 Aug 2014
Transfer Count:	0
Actual ARF Paid:	\$8,794.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Aug 2024
PARF Rebate Amount:	\$6,155.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	24 Aug 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$62,890.00
COE Rebate Amount:	\$30,565.00
<b>Total Rebate Amount:</b>	<b>\$36,720.00</b>

The information contained herein is correct as at 14 Oct 2019

OK

## Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)  
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960  
ROAD TRANSPORT ACT, 1987 (MALAYSIA)  
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

**Certificate Number:** 5102488581-01

**Cover :** drivo CLASSIC

- |   |                     |
|---|---------------------|
| 1. Index mark and Registration Number of Vehicle  | : SKP2197M          |
| Chassis Number  | : WVVZZZAUZFW010277 |
| 2. Name of Policyholder   | : YEOW SWEE KIM     |
| 3. Effective Date of Insurance  | : 25 Aug 2019       |
| 4. Expiry Date of Insurance   | : 24 Aug 2020       |
| 5. Persons or Classes of Persons entitled to drive#   |                     |
| (a) The Policyholder.   |                     |
| (b) Any other person who is driving on the Policyholder's order or with his/her permission.   |                     |
| Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. |                     |
| 6. Limitations as to Use#   |                     |
| (a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.   |                     |

**This Policy does not cover**

- (a) Use for hire or reward.
- (b) Use for racing, pace-making, reliability trial or speed-testing.
- (c) Use for the carriage of goods (other than samples) in connection with any trade or business.
- (d) Use for any purpose in connection with the Motor Trade.

# Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$600
EXCESS (SECTION 2)	: N/A
WINDSCREEN EXCESS	: S\$100
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	: NO
INSURE WITH COE	: YES
NCD PROTECTION	: NO
TRANSPORT ALLOWANCE	: NO
EXCESS WAIVER	: NO
PRIMARY DRIVER	: YEOW SWEE KIM
NAMED DRIVER (1)	: N/A
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : ZEAL INSURANCE AGENCY (00000614483)  
Date of Issue : 18 Jul 2019 14:47 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:



Authorised Officer



Chief Executive

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	14/10/2019 11:07
Date Of Accident	13/10/2019 10:35
Exact Location Of Accident	BLK 262 SERANGOON CENTRAL CAR PARK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKP2197M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	YEOW SWEE KIM
NRIC No	S1544237I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96918192
Alternative Phone No	HOME-67420313

### Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	GOLF A7 1.4 TSI AT 5G13GZ SR HID
Exact Purpose for which vehicle was being used at time of accident	PRIVATR
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5102488581-01
Cover Note Number	

### Driver

Name of Driver	YEOW JUN YI
NRIC No	S9643332H
Date Of Birth	27/11/1996
Occupation	OUTDOOR
Date Of Driving Pass	29/09/2015
Driving Experience	4 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96193447
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	7 SERANGOON GARDEN WAY
Postcode	555906
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PARENT
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - OPENING DOOR OF VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : YEOW SWEE KIM GENDER: : MALE
Passenger 2	NAME: : XIA GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

ON SUNDAY 13/10/19 I WAS INSIDE OF THE CAR ALONG WITH MY FATHER AND MOTHER, AS I WAS MOVING OFF THE OWNER OF THE CAR BESIDE ME OPENED HIS DOOR TOO WIDE THUS THE CAR DOOR OF HIS VEHICLE CATCHES ON TO THE SIDE OF ME CAR I WAS DRIVING AND DAMAGED ME SIDE AS WELL AS THE DOOR.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKX5262X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:




Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 14/01/14



Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No:

# Sketch Plan #2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On Sunday 13/10/19 I was inside of the car along with my father & mother, as I was moving off the owner of the car beside me opened his door too wide thus the car door of his vehicle catches on to the side of the car I was driving & damaged the side as well as the door.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 16/10/19

Reporting Centre Personnel's Signature  
Name:  
NRIC/ID No.:

# 趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5  
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047  
Tel: 6484 1626 (24Hrs) Fax: 6484 0465  
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: Sompo Insurance Singapore Pte Ltd

Policy No: Third Party

Date: 21.10.2019

**ACCIDENT DATE : 13.10.2019**

Specialised in Car Painting, Welding,  
Panel-Beating and Insurance Claim

## ESTIMATE

承接汽车烧焊喷漆及  
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 額 \$ cts.
	<b>Estimate Cost of Repair to "Volkswagen Golf" Reg. No. SKP2197M Claiming Against Your Insured Veh. No. SKX5262X</b>		
1pc	Rear Door LH		1,420.00
1pc	Rear Door Sticker		40.00
1pc	Rear Door Outer Handle		140.00
12pcs	Rear Door Outer Handle Inner Base Bracket		100.00
1pc	Rear Door Weatherstrip		210.00
1pc	Rear Door Inner Insulation		120.00
			2,030.00
	Less 10%		203.00
			1,827.00
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		60.00
	Labour Charge - Panel Beating, Transferring of Door Fitting, Accessories and Parts Replacement		350.00
	To Spray Painting Affected Areas		300.00
	<b>Total :</b>		<b>2,537.00</b>

Not Authorized  
L1 by B?  
Money After Paint  
3day

LKK Auto Consultants hereby notify  
the Repairer of the following:  
• To resurvey before/after spray painting  
• To display damaged parts during resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No illegal modification(s) is allowed  
• Supplementary sum(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

# 趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5  
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047  
Tel: 6484 1626 (24Hrs) Fax: 6484 0465  
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: Sompo Insurance Singapore Pte Ltd

Policy No: Third Party

Date: 21.10.2019

ACCIDENT DATE : 13.10.2019

Specialised in Car Painting, Welding,  
Panel-Beating and Insurance Claim.

## ESTIMATE

承接汽车烧焊喷漆及  
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost of Repair to "Volkswagen Golf" Reg. No. SKP2197M Claiming Against Your Insured Veh. No. SKX5262X		
1pc	Rear Door LH		By 1,420.00
1pc	Rear Door Sticker		mc 40.00
1pc	Rear Door Outer Handle		Not by 140.00
12pcs	Rear Door Outer Handle Inner Base Bracket		cm 100.00
1pc	Rear Door Weatherstrip	105JN	mc 210.00
1pc	Rear Door Inner Insulation		NEC 120.00
			2,030.00
	Less 10%		203.00
			1,827.00
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		60.00
	Labour Charge - Panel Beating, Transferring of Door Fitting, Accessories and Parts Replacement		350.00
	To Spray Painting Affected Areas		300.00
		Total :	2,537.00

Not Notified  
L1 by 8/800h ✓ ok  
Money After Pair  
3clay

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19018606/KYF3N2

Date: 21/01/2020

## REFERENCE

Handling Insurer: Sompo Insurance Singapore Pte. Ltd. Policy No: D18MTPV01019415  
 Claimant Vehicle No: SKP2197M Insured Vehicle No: SKX5262X  
 Date of Loss: 13/10/2019 Nature of Claim: TP Claim No: CMTD1904866

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SKP2197M  
 Make & Model: VOLKSWAGEN GOLF, 1.4 TSI (A7) (5G13GZ) (A) Engine No: CXS211229  
 Reg. Date: 25/08/2014 (Man. Year: 2014) Chassis No: WWWZZZAUZFW010277  
 Colour: Metallic Blue Odometer: 25859 km  
 Engine Capacity: 1395 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 225/40ZR18 Rear Tyre Size: 225/40ZR18  
 Front Left Side: Michelin 8 mm Rear Left Side: Michelin 8 mm  
 Front Right Side: Michelin 8 mm Rear Right Side: Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,827.00	1,695.00	132.00	7.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	710.00	550.00	160.00	22.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,537.00</b>	<b>2,245.00</b>	<b>292.00</b>	<b>11.51</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,800.00</b>		
(S\$)	2,537.00	1,800.00	737.00	29.05
<b>+ GST 7.00/7.00% (S\$)</b>	<b>177.59</b>	<b>126.00</b>	<b>51.59</b>	<b>29.05</b>
<b>Nett Amount (S\$)</b>	<b>2,714.59</b>	<b>1,926.00</b>	<b>788.59</b>	<b>29.05</b>

## INSPECTION

Date of Assignment: 21/10/2019  
 Date Inspected: 22/10/2019 Inspected At: Chew Goon Motor (AMK)  
 17, AMK Autopoint  
 Singapore 568047  
 Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG    **Version:** 1.0 (Last Synchronised: 21 Jan 2020)

**Parts:** 144    VOLKSWAGEN GOLF 1.4 TSI (A7) (5G13GZ) (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's    (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SKP2197M)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR LH	Bent	1,420.00 FL	*1,420.00 FL
2	1		*REAR DOOR STICKER	Necessary	40.00 FL	*40.00 FL
3	1		*REAR DOOR OUTER HANDLE	Dented/Cut	140.00 FL	*140.00 FL
4	1		*REAR DOOR OUTER HANDLE INNER BASE BRACKET (12 Pcs)	Cracked	100.00 FL	*100.00 FL
5	1		*REAR DOOR INNER INSULATION	Necessary	108.00 FS	*60.00 FS
6	1		*REAR DOOR WEATHERSTRIP (50%)	Necessary	189.00 FS	*105.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>1,997.00</b>	<b>1,865.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>170.00</b>	<b>170.00</b>
<b>Total Parts (\$\$)</b>	<b>1,827.00</b>	<b>1,695.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO APPLY RUST PROOFING/RESEAL TUFF COATING TREATMENT TO RESPRAY/REPLACED/REPAIR PANEL	New	60.00	30.00
2	LABOUR CHARGE-PANEL BEATING,TRANSFERRING OF DOOR FITTING,ACCESSORIES AND PARTS REPLACEMENT	New	350.00	260.00
3	TO SPRAY PAINTING AFFECTED AREAS	New	300.00	260.00
Gross Labour Cost (S\$)			710.00	550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >