

22/03/2002

ASS. REC. BY:

REF: CS3/MSG 19018611/Hgf302

Special Instruction:

SUPERVISOR: Hock Ann

ASSIGNMENT (Office)

From (Person): Katharine Wong

of

MSG

Date/Time: 21.10.19 17:12p.m

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMC 1076E

Insured: SLR 2813X

at Workshop m/s Paul Hoe Batteries & Motor Services

Tel: 96235069

of Kati But but L #01-109

Policy No: 29003533

Claim No: 608804

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 15.10.2019

CA / REV / REP. / REV 24 HRS

Date/Time: 22.10.19 9:28a.m

Person Contacted:

Paul Hoe

H.O.D. Endorsement:

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SMC 1076E X
	SLR 2813X X
06/11/19	Submit PRS.

ASS. REC. BY:

H. ANN

REF:

MS16

PRS

ASSIGNMENT

From:

Date: 22.10.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMC 1076E

at Workshop m/s

Paul Hoe Bottom's Motor

of

1 Kaki Bukit Ave 6 # 01-109

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

After 12.00 p.m

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMC 1076E

Yr Regn:

26/06/18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

H. Venzel 1.5x CVT cc 1496

Colour

Brown

A/C:

Insured / Std / NI / NA

Sp. Reading

027608/km

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

RU11303702

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60/R16

R:

215/60/R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front and Rear same → (Dun)

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

15/10/19

D.O.I.

22/10/19

Survey held at

Paul Hoe Bottom's motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

2-3K

SMC 1076E

Range → 1.2 - 1.7K

(PRS case)

repair days → 3 day

MV - 75000

PV - 38675

NV - 36000

RECEIVED 06 NOV 2019

25/10/2019

Date/Time, File Pass to?

☐

: Preli. Report

1) 06/11/19

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Rep. Form:

Lump Sum / L.B. / C.

120

11

131

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Oct 2019		21 Oct 2019 17:12 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS		[Created by insurer]																						
Insured:	HAN YONG TENG, ID: S8175727E, Tel: +6596494262, Email: YTHAN.81@YAHOO.COM																							
Main Claimant:	LEONG KOK MAY, ID: S7041399Z																							
Vehicle Reg. No.:	SMC1076E	Date of Loss:	15/10/2019 17:00 - :59 [15 Months and 19 Days From LTA Reg Date (Man Yr)]																					
Claim Type:	TP / 608804	Policy/Cover Note No.:	29003533 (Comprehensive) Coverage: 08/08/2019 - 07/08/2020																					
Vehicle Reg. No. (Insured):	SLR2813X	Policy No. (Claimant):																						
		Excess:																						
Repairer:	Paul Hoe Batteries & Motor Services (HQ) 1 KAKI BUKIT AVE 6 #01-109, 417883 Kaki Bukit - Tel:																							
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong - 6594 2544]																							
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 22/10/2019]																							
Driver/Custodian (Insured):	HAN YONG TENG (38 / Male) , NRIC: S8175727E, Tel: +6596494262 Email: YTHAN.81@YAHOO.COM																							
Adj Asg. Remarks:	on WP. Liab: unclear. Disagree on SJE. Contact: Paul Hoe @ 9623 5068.																							
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail																						
There are no mail for this case.																								
<div> <div> <div>ALL ASSOCIATED TASKS</div> <div> <div>View All</div> <div>Search Tasks</div> <div>Create New Task</div> <div>Complete</div> </div> </div> <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table> </div>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	399Z
Vehicle Details	
Vehicle No.:	SMC1076E
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Oct 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Brown
Manufacturing Year:	2018
Engine No.:	L15B5553709
Chassis No.:	RU11303702
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$21,536.00
Original Registration Date:	26 Jun 2018
First Registration Date:	26 Jun 2018
Transfer Count:	0
Actual ARF Paid:	\$12,151.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Jun 2028
PARF Rebate Amount:	\$9,113.00
Intended COE Rebate Details	
COE Expiry Date:	25 Jun 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$34,110.00
COE Rebate Amount:	\$29,562.00
Total Rebate Amount:	\$38,675.00

The information contained herein is correct as at 25 Oct 2019

OK

Enquire Vehicle Transfer Fee

Vehicle Details

Vehicle No. SMC1076E	
Make / Model HONDA / VEZEL 1.5X CVT	
Vehicle Type : P10 - Passenger Motor Car	Vehicle Attachment 1 : No Attachment
Vehicle Scheme : Normal	Chassis No. : RU11303702
Propellant : Petrol	Engine No. : L15B5553709
Motor No. : -	Engine Capacity : 1496 cc
Power Rating : -	Maximum Power Output : 96.0 kW (128 bhp)
Maximum Laden Weight : 1465 kg	Unladen Weight : 1190 kg
Year Of Manufacture : 2018	Original Registration Date : 26 Jun 2018
Lifespan Expiry Date : -	COE Category : A - Car up to 1600cc & 97kW (130bhp)
Quota Premium : \$34,110.00	COE Expiry Date : 25 Jun 2028
Road Tax Expiry Date : 25 Jun 2020	PARF Eligibility Expiry Date : 25 Jun 2028
Inspection Due Date : 25 Jun 2021	Intended Transfer Date : 25 Oct 2019
CO2 Emission : 123.00 (g/km)	CEV/VES Rebate Utilised Amount : \$10,000.00
CO Emission : 0.037000 (g/km)	HC Emission : 0.009000 (g/km)
NOx Emission : 0.002000 (g/km)	PM Emission : 2.200000 (mg/km)

Fees To Be Paid For Transfer

Transfer Fees \$25.00

Print

Save as PDF

Copy as Text

OK →

DOA = 15/10/19

MV - 75000

PV - 38675

NV - 36000

Balance 8yr 8month

Open = 8000 yr

$8000 \div 12 = 666$

$64000 + 5328 + 6075$

$= 75403$



Honda Vezel

Price Range ▾

Depreciation ▾

2018 ▾

Vehicle Type ▾



Home » Used Cars » Benefit Auto Enterprise Pte Ltd » Honda Vezel 1.5A X

Honda Vezel 1.5A X

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

PREM

Our Accreditations:



Member of:



Location Map

Price \$75,800

Depreciation ⓘ \$8,320 /yr
View models with similar depreReg Date 08-Mar-2018
(8yrs 4mths 11days COE left)

Mileage 39,900 km (24.4k /yr)

Manufactured ⓘ 2017

Road Tax ⓘ \$682 /yr

Transmission Auto

Dereg Value ⓘ \$42,589 as of today (change)

OMV ⓘ \$21,600

COE ⓘ \$39,903

ARF ⓘ \$12,240

Engine Cap 1,496 cc

Power 96.0 kW (128 bhp)

Curb Weight ⓘ 1,190 kg

No. of Owners ⓘ 1

Type of Vehicle SUV

Features

Powered By 4 Cylinders Inline DOHC I-VTEC Engine, CVT Transmission, 128Bhp, FWD, Fuel Tank 40L, Traction Control, Cruise Control, Airbags. View specs of the Honda Vezel (2014)

Accessories

Keyless Entry/Start. Fog Lamps. Leather Seats. DVD Player With Bluetooth, Solar Films. Car Mat. Reverse Sensors. Reverse Camera.

Description

Excellent Condition In And Out White Unit Previously Owned By One Meticulous Owner. Well Spaced Interior And One Of The Top Selling Models By Honda. Flexible Loan Available, Price Negotiable, All Offer Considered. High Trade In. It Is Available For Viewing At Our Showroom. Make It Yours Today.

Category

PARF Car, Premium Ad Car

Status

Available

Resources


Compare

- Free

Get value of your existing car for free. Get started

Price Chart

Summary



Click on the point to view the vehicle

Shortlist

Compare

Add nc

Report Error

More Actions

Seller Information

Company

Benefit Auto Enterprise

Ltd



» dealer's pricelist

MSME19137415 / SME Motor Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME: 16/10/2019 16:20
 SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/10/2019 16:20
Date Of Accident	15/10/2019 17:10
Exact Location Of Accident	JOHOR CUSTOM BEFORE IMMIGRATION CHECKPOINT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMC1076E
Insured/Policyholder	
Name Of Registered Owner	LEONG KOK MAY
NRIC No	S7041399Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98622983
Alternative Phone No	OFFICE-98622983

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5101648190-01
Cover Note Number	

Driver

Name of Driver	OOI ENG THYE
NRIC No	S7109043D
Date Of Birth	09/03/1971
Occupation	INDOOR
Date Of Driving Pass	17/06/1988
Driving Experience	31 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98622983
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 23 CANBERRA DRIVE #04-48
 Postcode 768077
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured SPOUSE
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

ON 15/10/2019 AT 1710HRS, I WAS DRIVING TOWARDS JOHOR IMMIGRATION CHECKPOINT ALONG MIDDLE LANE. IT WAS HEAVY JAM DURING THE INCIDENT HAPPENED. SUDDENLY, I FELT A JERK AT THE FRONT OF MY CAR AND I NOTICED MY CAR COLLIDED WITH THE OTHER CAR ON MY LEFT.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLR2813X
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)


SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature: 
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

TOP PLAN



DESCRIBE THE CIRCUMSTANCES OF THE ACCIDENT

On 15 Oct 19, 1710H, I ~~was~~ driving along toward Johore
~~immigration~~ immigration check point along middle lane. It was
 heavy jam during the incident happened. Suddenly I felt a
 jerk at the front of my car and I noticed my car was
 collided with the other car on my left.

DECLARATION

We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature
 Date & Time:

[Signature]

Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 16/10/18

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:









































...CLAIM SUBFOLDER...(Pending for Survey Report)

























































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Oct 2019		21 Oct 2019 17:12 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case




Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	HAN YONG TENG, ID: S8175727E, Tel: +6596494262, Email: YTHAN.81@YAHOO.COM								
Main Claimant:	LEONG KOK MAY, ID: S7041399Z								
Vehicle Reg. No.:	SMC1076E	Date of Loss:	15/10/2019 17:00 - :59 [15 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 608804	Policy/Cover Note No.:	29003533 (Comprehensive) Coverage: 08/08/2019 - 07/08/2020						
Vehicle Reg. No. (Insured):	SLR2813X	Policy No. (Claimant):							
		Excess:							
Repairer:	Paul Hoe Batteries & Motor Services (HQ) 1 KAKI BUKIT AVE 6 #01-109, 417883 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong - 6594 2544]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Imm.Advice due 22/10/2019]								
Driver/Custodian (Insured):	HAN YONG TENG (38 / Male), NRIC: S8175727E, Tel: +6596494262 Email: YTHAN.81@YAHOO.COM								
Adj Asg. Remarks:	on WP. Liab: unclear. Disagree on SJE. Contact: Paul Hoe @ 9623 5068.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMC1076E (608804)**
[SLR2813X]
TP
LEONG KOK MAY
Oct 15 2019 5:00PM
[HAN YONG TENG]
Paul Hoe Batteries & Motor Services

Upload Documents		Upload Photos	Compose New Letter	View View in Browser <input type="button" value="v"/>	
Assessment Reports				1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	21/10/19 14:25	Accident Statement Addm. #1 From:SC - Reg. No: SLR2813X, Claimant: HAN YONG TENG		Load HTM	<input type="checkbox"/>
Photos/Images				3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	25/10/19 09:29	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
2	25/10/19 09:30	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>
3	25/10/19 09:30	General View		Load JPG	<input checked="" type="checkbox"/>
4	25/10/19 09:30	General View		Load JPG	<input checked="" type="checkbox"/>
5	25/10/19 09:30	General View		Load JPG	<input checked="" type="checkbox"/>
6	25/10/19 09:30	General View		Load JPG	<input checked="" type="checkbox"/>
7	25/10/19 09:30	General View		Load JPG	<input checked="" type="checkbox"/>
8	25/10/19 09:30	General View		Load JPG	<input checked="" type="checkbox"/>
9	25/10/19 09:30	General View		Load JPG	<input checked="" type="checkbox"/>
10	25/10/19 09:30	General View		Load JPG	<input checked="" type="checkbox"/>
11	25/10/19 09:30	General View		Load JPG	<input checked="" type="checkbox"/>
12	25/10/19 09:30	General View		Load JPG	<input checked="" type="checkbox"/>
13	25/10/19 09:30	General View		Load JPG	<input checked="" type="checkbox"/>
14	25/10/19 09:30	General View		Load JPG	<input checked="" type="checkbox"/>
15	25/10/19 09:30	General View		Load JPG	<input checked="" type="checkbox"/>
16	25/10/19 09:30	General View		Load JPG	<input checked="" type="checkbox"/>
17	25/10/19 09:30	General View		Load JPG	<input checked="" type="checkbox"/>
18	25/10/19 09:30	General View		Load JPG	<input checked="" type="checkbox"/>
19	25/10/19 09:30	General View		Load JPG	<input checked="" type="checkbox"/>
20	25/10/19 09:30	General View		Load JPG	<input checked="" type="checkbox"/>
21	25/10/19 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
22	25/10/19 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
23	25/10/19 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
24	25/10/19 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
25	25/10/19 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
26	25/10/19 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
27	25/10/19 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
28	25/10/19 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
29	25/10/19 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
30	25/10/19 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
31	25/10/19 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
32	25/10/19 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
33	25/10/19 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
34	25/10/19 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
35	25/10/19 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
36	25/10/19 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
37	25/10/19 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
38	25/10/19 09:31	General View		Load JPG	<input checked="" type="checkbox"/>
39	25/10/19 09:31	General View		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
40	25/10/19 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
41	25/10/19 09:31	General View	 Load JPG	<input checked="" type="checkbox"/>
42	07/11/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	07/11/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	07/11/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	07/11/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	07/11/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	07/11/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	07/11/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	07/11/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	07/11/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	07/11/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	07/11/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	07/11/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	07/11/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	07/11/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	07/11/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	07/11/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	07/11/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	07/11/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	07/11/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	07/11/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	07/11/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	07/11/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	07/11/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	07/11/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	07/11/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	07/11/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	07/11/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	07/11/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	07/11/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	07/11/19 09:20	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	07/11/19 09:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	07/11/19 09:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	07/11/19 09:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	07/11/19 09:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	07/11/19 09:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	07/11/19 09:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	07/11/19 09:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	07/11/19 09:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	07/11/19 09:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	07/11/19 09:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	07/11/19 09:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	07/11/19 09:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	07/11/19 09:21	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	07/11/19 09:21	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
86	07/11/19 09:21	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
87	07/11/19 09:21	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
88	07/11/19 09:21	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
89	07/11/19 09:21	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
90	07/11/19 09:21	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
91	07/11/19 09:21	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
92	07/11/19 09:21	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
93	07/11/19 09:21	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
94	07/11/19 09:21	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
95	07/11/19 09:21	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	21/10/19 14:25	TP SMC1076E GIA REPORT From:SC - Reg. No: SLR2813X, Claimant: HAN YONG TENG	 Load PDF	
2	21/10/19 14:28	PRI from Tommy Choo, Mark Go LLC	 Load PDF	
3	21/10/19 16:42	Disagree on SJE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19018611/HCF3E2

Date: 08/11/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29003533

Claimant Vehicle No : SMC1076E

Insured Vehicle No : SLR2813X

Date of Loss: 15/10/2019

Nature of Claim: TP

Claim No: 608804

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMC1076E**

Make & Model: HONDA VEZEL, 1.5 X CVT (A)

Engine No: L15B5553709

Reg. Date: 26/06/2018 (Man. Year: 2018)

Chassis No: RU11303702

Colour: Brown

Odometer: 27608 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 21/10/2019

Date Inspected: 22/10/2019 Inspected At:

Paul Hoe Batteries & Motor Services
(HQ)
1 KAKI BUKIT AVE 6 #01-109
Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: LEE HOCK ANN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Nov 2019)

Parts: M1-SUV HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMC1076E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >