

INS. CASE OWNER: MingYao.Lee

CC3/AIG19018666/R1da3

LKK:

IDAC:

## ASSIGNMENT

Surveyor: RASUL

DOI: 24/10/2019

Date / Time: 22/10/2019

Registered in Merimen: 22/10/2019

## Pre-assign / CCU / FTE



Insured Vehicle No. : SLU 7636S  
 Name of Insured : KINETIC HOLDINGS PTE. LTD.

Claim No. : 8898958660SG

Policy No. : 999994104

Insured Tel No. : HP: \_\_\_\_\_  
 Excess Sec II :SS D.O.A : 21/10/2019 11:15

Make / Model : TOYOTA SIENTA

Place of Accident : ALONG HILLVIEW AVE

Is driver the owner? ( YES / NO ) Nature of Accident :

If NO, Driver Name / Age : MUHAMMAD FAHMIN BIN ABDUL KADIR

Driver Tel No. : +65-90214279

(V/L: YES / NO )

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

SLU 7636S

SKJ 4568U

SDN 807T

FX 6547C

-&gt; SG 5454D



INSRS:  
WSP:  
Tel :  
Liability :  
RMKS:

OI



INSRS:  
WSP:  
Tel : VOLKSWAGEN  
Liability :  
RMKS: TP



INSRS:  
WSP:  
Tel :  
Liability :  
RMKS:



INSRS:  
WSP:  
Tel :  
Liability :  
RMKS:

| Date/ Time                                                                                                                                           | STAGE                                 | DATE / PIC                                                              |
|------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------|-------------------------------------------------------------------------|
|                                                                                                                                                      | Non-Reporting ltr (1st):              |                                                                         |
|                                                                                                                                                      | Non-Reporting ltr (2nd):              |                                                                         |
|                                                                                                                                                      | Non-Reporting ltr (Final):            |                                                                         |
|                                                                                                                                                      | Notification ltr (if non-pickup):     |                                                                         |
|                                                                                                                                                      | Call OE:                              |                                                                         |
|                                                                                                                                                      | After call ltr to OE:                 |                                                                         |
|                                                                                                                                                      | Documentation Check List:             | Handler Typist                                                          |
|                                                                                                                                                      | Notification ltr (if non-pickup)      | <input type="checkbox"/>                                                |
|                                                                                                                                                      | After call ltr to OE:                 | <input checked="" type="checkbox"/>                                     |
|                                                                                                                                                      | Authorisation To Act:                 | <input checked="" type="checkbox"/>                                     |
|                                                                                                                                                      | Release Voucher:                      | <input checked="" type="checkbox"/>                                     |
|                                                                                                                                                      | Final Repair Bill:                    | <input checked="" type="checkbox"/>                                     |
|                                                                                                                                                      | Car Rental Invoice:                   | <input type="checkbox"/>                                                |
|                                                                                                                                                      | Towing Invoice:                       | <input type="checkbox"/>                                                |
|                                                                                                                                                      | LTA / GIA :                           | <input checked="" type="checkbox"/>                                     |
|                                                                                                                                                      | Medical Bill:                         | <input type="checkbox"/>                                                |
|                                                                                                                                                      | PIR:                                  | <input type="checkbox"/>                                                |
|                                                                                                                                                      | Mandate/Reject Instruction:           | <input type="checkbox"/>                                                |
|                                                                                                                                                      | LOD                                   | <input checked="" type="checkbox"/>                                     |
|                                                                                                                                                      | Payment Breakdown Form:               | <input type="checkbox"/>                                                |
|                                                                                                                                                      | Post-Repair Photos:                   | <input type="checkbox"/>                                                |
|                                                                                                                                                      | Others:                               | <input type="checkbox"/>                                                |
| PRELIMINARY ADVICE Date/Time:                                                                                                                        | Sent By:                              |                                                                         |
| FINALIZATION Date/Time:                                                                                                                              | Confirm with:                         | Confirm by:                                                             |
| Repair Cost: SS                                                                                                                                      | ( days) Reduction: %                  | Email <input type="checkbox"/> Call <input type="checkbox"/>            |
| FINAL SETTLEMENT Date/Time: 12/2/2020                                                                                                                | Confirm with: me.g                    | Email <input checked="" type="checkbox"/> Call <input type="checkbox"/> |
| Final Liability: % 100                                                                                                                               | (Agreed / Assessed) BOLA S/N No. : 28 | If NO or B 28, Ass. Lia : 1002                                          |
| Repair Cost: (w/451) SS 13861.82                                                                                                                     |                                       | 3rd C.C. 02 was last                                                    |
| Loss of Rental (LOR): SS -                                                                                                                           | ( days)                               |                                                                         |
| Loss of Use (LOU): SS 1140.00                                                                                                                        | (\$ 60 x 19 days)                     |                                                                         |
| Loss of Income (LOI): SS -                                                                                                                           | (\$ x days)                           |                                                                         |
| LOR only <input type="checkbox"/> LOU only <input checked="" type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> | [Tick only one]                       |                                                                         |
| GIA/LTA Search: SS 7.49                                                                                                                              |                                       |                                                                         |
| Medical: SS -                                                                                                                                        |                                       |                                                                         |
| Disbursement: SS -                                                                                                                                   | (e.g. Tow/ Independent )              |                                                                         |
| Legal Cost: SS -                                                                                                                                     |                                       |                                                                         |
| Total: SS 15009.31                                                                                                                                   | Global Sum SS:                        |                                                                         |
| FINAL PAYMENT Date/Time:                                                                                                                             | Confirm with:                         | Email <input type="checkbox"/> Call <input type="checkbox"/>            |
| Payee 1: SS 15009.31                                                                                                                                 | Name 1: Volkswagen Centre Singapore   |                                                                         |
| Payee 2: (Strike if N.A.) SS                                                                                                                         | Name 2:                               |                                                                         |
| Payee 3: (Strike if N.A.) SS                                                                                                                         | Name 3:                               |                                                                         |



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Information           |                          |
|-------------------------------|--------------------------|
| Owner ID Type:                | Singapore NRIC           |
| Owner ID:                     | 079D                     |
| Vehicle Details               |                          |
| Vehicle No.:                  | SKJ4568U                 |
| Vehicle to be Exported:       | No                       |
| Intended Deregistration Date: | 25 Oct 2019              |
| Vehicle Make:                 | VOLKSWAGEN               |
| Vehicle Model:                | POLO 1.2 TSI AT 6R13H7   |
| Primary Colour:               | White                    |
| Manufacturing Year:           | 2012                     |
| Engine No.:                   | CBZ612684                |
| Chassis No.:                  | WVWZZZ6RZCU057834        |
| Maximum Power Output:         | 66.0 kW (88 bhp)         |
| Open Market Value:            | \$15,574.00              |
| Original Registration Date:   | 31 Mar 2013              |
| First Registration Date:      | 31 Mar 2013              |
| Transfer Count:               | 1                        |
| Actual ARF Paid:              | \$5,574.00               |
| Intended PARF Rebate Details  |                          |
| PARF Eligibility:             | Yes                      |
| PARF Eligibility Expiry Date: | 30 Mar 2023              |
| PARF Rebate Amount:           | \$3,623.00               |
| Intended COE Rebate Details   |                          |
| COE Expiry Date:              | 30 Mar 2023              |
| COE Category:                 | A - Car (1600cc & below) |
| COE Period(Years):            | 10                       |
| QP Paid:                      | \$78,301.00              |
| COE Rebate Amount:            | \$26,858.00              |
| <b>Total Rebate Amount:</b>   | <b>\$30,481.00</b>       |

The information contained herein is correct as at 25 Oct 2019

OK

|        |        |
|--------|--------|
| 40,000 | 44,000 |
| 30,481 | 30,481 |
| <hr/>  | <hr/>  |
| 9,519  | 13,519 |

## VOLKSWAGEN CENTRE SINGAPORE

17 Tuas Avenue  
Singapore 639176  
Biz. Reg. No.: 199101494Z  
GST No.: M200985052



Volkswagen SKODA

Commercial Vehicles

## Quotation

Non binding - Preview

Page 1/3

Company  
AIG ASIA PACIFIC INSURANCE P/L  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

Customer Details:  
Mr  
Lou  
Kok Yong  
Singapore 598750

Document no.  
Document date 22-10-2019  
Customer no. 5211043795  
Customer GST-ID 201009404M  
Dealer 39999  
Job order number 2019002418/ 1  
Job order date 21-10-2019  
Service Advisor YEN MEI WONG

| License plate | Model code | First registration | VIN               | Model                 | Mileage |
|---------------|------------|--------------------|-------------------|-----------------------|---------|
| SKJ4568U      | 6R13H7     | 31-03-2013         | WVWZZZ6RZCU057834 | POLO 1.2 COMFO 66 D7F | 48,681  |

| Position no.   | Description                          | Quantity | Unit | Unit price<br>excl. GST | Tax code | Total amount<br>excl. GST | Total amount<br>incl. GST |
|----------------|--------------------------------------|----------|------|-------------------------|----------|---------------------------|---------------------------|
|                | Check Short Circuit / Harness Repair | 1        | pcs. | 280.00                  | #1       | 215.69                    | 280.00                    |
|                | Diagnostic and Programming           | 1        | pcs. | 480.00                  | #1       | 369.60                    | 480.00                    |
| 6R6827025C     | Rear Trunk Lid                       | 1        | pcs. | 1,706.09                | #1       | 1,706.09                  | 2,177.41                  |
|                | REAR BOOT LID                        |          |      |                         |          |                           | 2,177.41                  |
| D 169300M2     | 1k Window Adhesive                   | 2        | pcs. | 49.88                   | #1       | 99.76                     | 126.89                    |
| 6R0827505E 9B9 | Hood Latch Satin Black               | 1        | pcs. | 180.14                  | #1       | 180.14                    | 225.06                    |
|                | REAR BOOT LID LOCK                   |          |      |                         |          |                           | 225.06                    |
| 6R6827705C     | Gasket                               | 1        | pcs. | 138.26                  | #1       | 138.26                    | 174.94                    |
|                | BOOT WETHERSTRIP                     |          |      |                         |          |                           | 174.94                    |
| 6C0853687 2ZZ  | Inscription Bright Chrome            | 1        | pcs. | 58.46                   | #1       | 58.46                     | 74.31                     |
|                | NAME PLATE - POLO                    |          |      |                         |          |                           | 74.31                     |
| 6R0853675F 739 | Inscription Chrome                   | 1        | pcs. | 54.92                   | #1       | 54.92                     | 70.71                     |
|                | NAME PLATE - TSI                     |          |      |                         |          |                           | 70.71                     |
| 5G0945087B     | Additional Brake Light W             | 1        | pcs. | 155.54                  | #1       | 155.54                    | 198.99                    |
|                | 3RD BRAKE LIGHT                      |          |      |                         |          |                           | 198.99                    |
| 1K8943021      | License Plate Light                  | 2        | pcs. | 37.19                   | #1       | 74.38                     | 94.59                     |
| 6R6807421BKGRU | Cover For Bumper Primed              | 1        | pcs. | 932.40                  | #1       | 932.40                    | 1,178.58                  |
|                | REAR BUMPER                          |          |      |                         |          |                           | 1,178.58                  |
| 6R0807305A     | Cross Member                         | 1        | pcs. | 401.95                  | #1       | 401.95                    | 510.88                    |
|                | REAR REINFORCEMENT                   |          |      |                         |          |                           | 510.88                    |
| 6R6807863B     | Attachment Strip                     | 1        | pcs. | 68.06                   | #1       | 68.06                     | 86.82                     |
|                | BUMPER CENTRE BRACKET                |          |      |                         |          |                           | 86.82                     |
| 6R6807393A     | Guide Piece                          | 1        | pcs. | 57.41                   | #1       | 57.41                     | 72.83                     |
|                | BUMPER SIDE BRACKET LH               |          |      |                         |          |                           | 72.83                     |
| 6R6807394A     | Guide Piece                          | 1        | pcs. | 57.41                   | #1       | 57.41                     | 72.83                     |
|                | BUMPER SIDE BRACKET RH               |          |      |                         |          |                           | 72.83                     |
| 6R0819465B     | Vent Trim                            | 2        | pcs. | 36.38                   | #1       | 72.76                     | 92.74                     |
|                | AIR DUCT                             |          |      |                         |          |                           | 92.74                     |
| 6R6813309A     | Rear Apron                           | 1        | pcs. | 181.34                  | #1       | 181.34                    | 228.03                    |
|                | END PANEL OUTER                      |          |      |                         |          |                           | 228.03                    |
| 6R6813301C     | End Plate                            | 1        | pcs. | 617.14                  | #1       | 617.14                    | 783.34                    |
|                | END PANEL INNER                      |          |      |                         |          |                           | 783.34                    |
| D 476KD1M2     | Sealant Can Be Sprayed               | 1        | pcs. | 62.20                   | #1       | 62.20                     | 78.85                     |
| D 007500A2     | Zinc Spray                           | 1        | pcs. | 62.88                   | #1       | 62.88                     | 80.28                     |
| D 180003M2     | 2k-Body Adhesive                     | 1        | pcs. | 398.47                  | #1       | 398.47                    | 506.36                    |
| 6R6863459D 82V | Cover For Lock Carrier T1            | 1        | pcs. | 138.38                  | #1       | 138.38                    | 175.07                    |
|                | END PANEL TRIM COVER                 |          |      |                         |          |                           | 175.07                    |
| 6Q0803899A     | Bolt For Spare Wheel Moun            | 1        | pcs. | 15.51                   | #1       | 15.51                     | 19.76                     |
| 323863950      | Sound Absorber                       | 1        | pcs. | 65.68                   | #1       | 65.68                     | 83.96                     |
|                | FLOOR PAN INSULATOR                  |          |      |                         |          |                           | 83.96                     |
| 6R6253609AT    | Exhaust Silencer Rear                | 1        | pcs. | 472.09                  | #1       | 472.09                    | 598.14                    |
| 1K0253141K     | Dual Clamp                           | 1        | pcs. | 55.81                   | #1       | 55.81                     | 70.72                     |
| 6R0823031G     | Hood                                 | 1        | pcs. | 905.91                  | #1       | 905.91                    | 1,148.32                  |
|                | FRT BONNET                           |          |      |                         |          |                           | 1,148.32                  |
| 6R0823186C     | Retaining Bracket                    | 1        | pcs. | 69.82                   | #1       | 69.82                     | 88.71                     |
|                | BONNET LATCH                         |          |      |                         |          |                           | 88.71                     |

# VOLKSWAGEN CENTRE SINGAPORE

17 Tuas Avenue  
Singapore 639176  
Biz. Reg. No.: 199101494Z  
GST No.: M200985052

Auto Consultants hence notify  
the repairer of the following:  
1. Damaged part(s) during resurvey  
2. Damaged part(s) are subject to confirmation  
3. Resurvey is on a "Without Prejudice" basis  
4. Confirmation(s) is allowed  
5. Damaged part(s) must be resurveyed and  
6. Approval from Insurance Company



## Quotation Non binding - Preview

Page 2/3  
Document no.  
Document date 22-10-2019  
Customer no. 5211043795  
Customer GST-ID 201009404M  
Dealer 399999  
Job order number 2019002418/ 1  
Job order date 21-10-2019  
Service Advisor YEN MEI WONG

Company  
AIG ASIA PACIFIC INSURANCE P/L  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120  
Customer Details:  
Mr  
Lou  
Kok Yong  
Singapore 598750

| License plate | Model code | First registration | VIN               | Model                 | Mileage |
|---------------|------------|--------------------|-------------------|-----------------------|---------|
| SKJ4568U      | 6R13H7     | 31-03-2013         | WVWZZZ6RZCU057834 | POLO 1.2 COMFO 66 D7F | 48,681  |

| Position no.   | Description                       | Quantity | Unit | Unit price<br>excl. GST | Tax code | Total amount<br>excl. GST | Total amount<br>incl. GST |
|----------------|-----------------------------------|----------|------|-------------------------|----------|---------------------------|---------------------------|
| 6R0807221R GRU | Cover For Bumper Primed           | 1        | pcs. | 925.31                  | #1       | 925.31                    | 990.08                    |
| 6R0807109D     | FRT BUMPER                        | 1        | pcs. | 470.30                  | #1       | 470.30                    | 503.22                    |
| 6R0853651T FOD | Impact Beam                       | 1        | pcs. | 353.17                  | #1       | 353.17                    | 377.89                    |
| 6R0853677A 9B9 | FRT REINFORCEMENT                 | 1        | pcs. | 176.10                  | #1       | 176.10                    | 188.43                    |
| 6R0805071E     | Radiator Grille Black Hig         | 1        | pcs. | 99.37                   | #1       | 99.37                     | 106.33                    |
| 6R0805072E     | Cooling Air Grill Satin B         | 1        | pcs. | 99.37                   | #1       | 99.37                     | 106.33                    |
|                | BUMPER CENTRE LOWER GRILLE        | 1        | pcs. | 840.00                  | #1       | 840.00                    | 898.80                    |
|                | Mounting For Headlamps            | 1        | pcs. | 80.00                   | #1       | 80.00                     | 85.60                     |
|                | FRT BUMPER SIDE BRACKET LH        | 1        | pcs. | 840.00                  | #1       | 840.00                    | 898.80                    |
|                | Mounting For Headlamps            | 1        | pcs. | 80.00                   | #1       | 80.00                     | 85.60                     |
|                | FRT BUMPER SIDE BRACKET RH        | 1        | pcs. | 840.00                  | #1       | 840.00                    | 898.80                    |
|                | LABOUR REAR                       | 1        | pcs. | 400.00                  | #1       | 400.00                    | 428.00                    |
|                | Spray Painting REAR               | 1        | pcs. | 80.00                   | #1       | 80.00                     | 85.60                     |
|                | R&R REAR BOOT LID GLASS           | 1        | pcs. | 840.00                  | #1       | 840.00                    | 898.80                    |
|                | TRANSFER BOOT LID MECHANISM       | 1        | pcs. | 840.00                  | #1       | 840.00                    | 898.80                    |
|                | R&R REAR LUGGAGE TRIM             | 1        | pcs. | 840.00                  | #1       | 840.00                    | 898.80                    |
|                | R&R REAR EXHAUST PIPE             | 1        | pcs. | 400.00                  | #1       | 400.00                    | 428.00                    |
|                | Reverse Sensor                    | 1        | pcs. | 80.00                   | #1       | 80.00                     | 85.60                     |
|                | REAR NUMBER PLATE                 | 1        | pcs. | 840.00                  | #1       | 840.00                    | 898.80                    |
|                | REAR WATER LEAK TEST              | 1        | pcs. | 80.00                   | #1       | 80.00                     | 85.60                     |
|                | LABOUR FRT                        | 2        | pcs. | 840.00                  | #1       | 1,680.00                  | 1,793.60                  |
|                | Spray Painting FRT                | 2        | pcs. | 800.00                  | #1       | 1,600.00                  | 1,705.60                  |
|                | FRT NUMBER PLATE                  | 1        | pcs. | 80.00                   | #1       | 80.00                     | 85.60                     |
|                | HL ASSURANCE CLAIMS AGAINST AIG @ |          |      |                         |          |                           |                           |
|                | VEHICLE SLU7636S                  |          |      |                         |          |                           |                           |
|                | D.O.A. 21-10-19                   |          |      |                         |          |                           |                           |

Quotation valid till 28-10-2019

| Tax Code | Labour | Material  | GST % | GST      | Total amount<br>excl. GST | Total amount<br>incl. GST |
|----------|--------|-----------|-------|----------|---------------------------|---------------------------|
| #1       | 760.00 | 28,046.39 | 7%    | 2,016.45 | 28,806.39                 | 30,822.84                 |
| Total    | 760.00 | 28,046.39 |       | 2,016.45 | 28,806.39                 | 30,822.84                 |

Customer

Service Advisor

24/10/19 @ 1440

Resurvey before paint

24/12/2019

## VOLKSWAGEN CENTRE SINGAPORE

17 Tuas Avenue  
Singapore 639176  
Biz. Reg. No.: 199101494Z  
GST No.: M200985052



Volkswagen



SKODA



Commercial Vehicles

### Quotation

Non binding - Preview

Page 3/3

Company  
AIG ASIA PACIFIC INSURANCE P/L  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

Customer Details:  
Mr  
Lou  
Kok Yong  
Singapore 598750

Document no.  
Document date  
Customer no.  
Customer GST-ID  
Dealer  
Job order number  
Job order date  
Service Advisor

22-10-2019  
5211043795  
201009404M  
39999  
2019002418/ 1  
21-10-2019  
YEN MEI WONG

| License plate | Model code | First registration | VIN               | Model                 | Mileage |
|---------------|------------|--------------------|-------------------|-----------------------|---------|
| SKJ4568U      | 6R13H7     | 31-03-2013         | WVWZZZ6RZCU057834 | POLO 1.2 COMFO 66 D7F | 48,681  |

—VISIT OUR WEBSITE: [aftersales.vw.com.sg](http://aftersales.vw.com.sg) (for online service appointments) and [volkswagen.com.sg](http://volkswagen.com.sg) and [www.skoda.com.sg](http://www.skoda.com.sg) (for additional services, products and promotions).—





| MODEL | POLO |
|-------|------|
|-------|------|

|   | LABOUR DESCRIPTION | AMOUNT |      |        |
|---|--------------------|--------|------|--------|
|   |                    | Qty    | Unit | Amount |
| 1 |                    |        |      |        |
| 2 |                    |        |      |        |
|   |                    |        |      |        |
|   |                    |        |      |        |
|   |                    |        |      |        |
|   | Total              |        |      | \$0.00 |

**\$714.71**

Internal

## VOLKSWAGEN CENTRE SINGAPORE

17 Tuas Avenue  
Singapore 639176  
Biz. Reg. No.: 199101494Z  
GST No.: M200985052

Tax invoice  
Preview

Page 1/3

Company  
AIG ASIA PACIFIC INSURANCE P/L  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

Customer Details:  
Mr  
Lou  
Kok Yong  
Singapore 598750

Document no.  
Document date 30-12-2019  
Customer no. 5211043795  
Customer GST-ID 201009404M  
Dealer 39999  
Job order number 2019002538/ 1  
Job order date 01-11-2019  
Service Advisor YEN MEI WONG

| License plate | Model code | First registration | VIN               | Model                 | Mileage |
|---------------|------------|--------------------|-------------------|-----------------------|---------|
| SKJ4568U      | 6R13H7     | 31-03-2013         | WWWZZZ6RZCU057834 | POLO 1.2 COMFO 66 D7F | 61,773  |

| Position no.   | Description                          | Quantity | Unit | Unit price<br>excl. GST | Tax code  | Total amount<br>excl. GST | Total amount<br>incl. GST |
|----------------|--------------------------------------|----------|------|-------------------------|-----------|---------------------------|---------------------------|
|                | Check Short Circuit / Harness Repair | 1        | pcs. | 280.00                  | 23.00% #1 | 215.60                    | 230.69                    |
|                | Diagnostic and Programming           | 1        | pcs. | 480.00                  | 23.00% #1 | 369.60                    | 395.47                    |
| 6R6827025C     | Rear Trunk Lid                       | 1        | pcs. | 1,706.09                | 55.00% #1 | 767.74                    | 821.48                    |
|                | REAR BOOT LID XR-4/11/2019           |          |      |                         |           |                           |                           |
| D 169300M2     | 1k Window Adhesive                   | 2        | pcs. | 49.88                   | 55.00% #1 | 44.89                     | 48.03                     |
|                | XR-4/11/2019                         |          |      |                         |           |                           |                           |
| 6C0853687 ZZZ  | Inscription Bright Chrome            | 1        | pcs. | 58.46                   | 55.00% #1 | 26.31                     | 28.15                     |
|                | NAME PLATE - POLO SEA-5/11/2019      |          |      |                         |           |                           |                           |
| 6R0853675F 739 | Inscription Chrome                   | 1        | pcs. | 54.92                   | 55.00% #1 | 24.71                     | 26.44                     |
|                | NAME PLATE - TSI SEA-5/11/2019       |          |      |                         |           |                           |                           |
| 5G0945087B     | Additional Brake Light W/            | 1        | pcs. | 155.54                  | 55.00% #1 | 69.99                     | 74.89                     |
|                | 3RD BRAKE LIGHT XR-5/11/2019         |          |      |                         |           |                           |                           |
| 6R6807421BKGRU | Cover For Bumper Primed              | 1        | pcs. | 932.40                  | 55.00% #1 | 419.58                    | 448.95                    |
|                | REAR BUMPER XR-4/11/2019             |          |      |                         |           |                           |                           |
| 6R0807305A     | Cross Member                         | 1        | pcs. | 401.95                  | 55.00% #1 | 180.88                    | 193.54                    |
|                | REAR REINFORCEMENT XR-4/11/2019      |          |      |                         |           |                           |                           |
| 6R6807393A     | Guide Piece                          | 1        | pcs. | 57.41                   | 55.00% #1 | 25.83                     | 27.64                     |
|                | BUMPER SIDE BRACKER LH               |          |      |                         |           |                           |                           |
|                | SEA-5/11/2019                        |          |      |                         |           |                           |                           |
| 6R6807394A     | Guide Piece                          | 1        | pcs. | 57.41                   | 55.00% #1 | 25.83                     | 27.64                     |
|                | BUMPER SIDE BRACKET RH               |          |      |                         |           |                           |                           |
|                | SEA-5/11/2019                        |          |      |                         |           |                           |                           |
| 6R0819465B     | Vent Trim                            | 2        | pcs. | 36.38                   | 55.00% #1 | 32.74                     | 35.03                     |
|                | AIR DUCT O/S-4/11/2019 BY AIR ORDER  |          |      |                         |           |                           |                           |
| 323863950      | Sound Absorber                       | 1        | pcs. | 65.68                   | 55.00% #1 | 29.56                     | 31.63                     |
|                | FLOOR PAN INSULATOR O/S-4/11/2019    |          |      |                         |           |                           |                           |
|                | BY A/O ORDER                         |          |      |                         |           |                           |                           |
| 6R0807221R GRU | Cover For Bumper Primed              | 1        | pcs. | 925.31                  | 55.00% #1 | 416.39                    | 445.54                    |
|                | FRT BUMPER SEA-5/11/2019             |          |      |                         |           |                           |                           |
| 6R0807109D     | Impact Beam                          | 1        | pcs. | 470.30                  | 55.00% #1 | 211.64                    | 226.45                    |
|                | FRT REINFORCEMENT SEA-5/11/2019      |          |      |                         |           |                           |                           |
| 6R0853651T FOD | Radiator Grille Black Hig            | 1        | pcs. | 353.17                  | 55.00% #1 | 158.93                    | 170.06                    |
|                | SEA-5/11/2019                        |          |      |                         |           |                           |                           |
| 6R0853677A 9B9 | Cooling Air Grill Satin B            | 1        | pcs. | 176.10                  | 55.00% #1 | 79.25                     | 84.80                     |
|                | BUMPER CENTRE LOWER GRILLE           |          |      |                         |           |                           |                           |
|                | SEA-5/11/2019                        |          |      |                         |           |                           |                           |
| 6R0805072E     | Mounting For Headlamps               | 1        | pcs. | 99.37                   | 55.00% #1 | 44.72                     | 47.85                     |
| 6R2941008F     | Twin Halogen Headlamps               | 1        | pcs. | 577.34                  | 55.00% #1 | 259.80                    | 277.99                    |
|                | SEA-12/12/2019                       |          |      |                         |           |                           |                           |
| 6R0853666C 9B9 | Cooling Air Grill Satin B            | 1        | pcs. | 63.10                   | 55.00% #1 | 28.40                     | 30.39                     |
|                | FOG LAMP GRILLE RH SEA-12/12/2019    |          |      |                         |           |                           |                           |
| 8K0973702      | Flat Contact Housing With            | 1        | pcs. | 5.39                    | 55.00% #1 | 2.43                      | 2.60                      |
|                | RR NUMBER PLATE LIGHT WIRE           |          |      |                         |           |                           |                           |
|                | HOUSING SEA-12/12/2019               |          |      |                         |           |                           |                           |
| D 00920002     | Primer                               | 1        | pcs. | 25.92                   | 55.00% #1 | 11.66                     | 12.48                     |
|                | XR-12/12/2019                        |          |      |                         |           |                           |                           |



## VOLKSWAGEN CENTRE SINGAPORE

17 Tuas Avenue  
Singapore 639176  
Biz. Reg. No.: 199101494Z  
GST No.: M200985052



## Tax invoice

Preview

Page 2/3

Company  
AIG ASIA PACIFIC INSURANCE P/L  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

Customer Details:  
Mr  
Lou  
Kok Yong  
Singapore 598750

Document no.  
Document date 30-12-2019  
Customer no. 5211043795  
Customer GST-ID 201009404M  
Dealer 39999  
Job order number 2019002538/ 1  
Job order date 01-11-2019  
Service Advisor YEN MEI WONG

|                           |                      |                                  |                         |                                |                   |
|---------------------------|----------------------|----------------------------------|-------------------------|--------------------------------|-------------------|
| License plate<br>SKJ4568U | Model code<br>6R13H7 | First registration<br>31-03-2013 | VIN<br>WWZZZ6RZCU057834 | Model<br>POLO 1.2 COMFO 66 D7F | Mileage<br>61,773 |
|---------------------------|----------------------|----------------------------------|-------------------------|--------------------------------|-------------------|

| Position no.   | Description                                                                                                         | Quantity | Unit | Unit price<br>excl. GST | Tax code  | Total amount<br>excl. GST | Total amount<br>incl. GST |
|----------------|---------------------------------------------------------------------------------------------------------------------|----------|------|-------------------------|-----------|---------------------------|---------------------------|
| D 00950025     | Applicator<br>XR-12/12/2019                                                                                         | 2        | pcs. | (5) 9.48                | 55.00% #1 | 8.53                      | 9.13                      |
| D 181802M1     | Activator For Precoated W<br>XR-12/12/2019                                                                          | 1        | pcs. | (5) 24.00               | 55.00% #1 | 10.80                     | 11.56                     |
| 6R0827505E 9B9 | Hood Latch Satin Black                                                                                              | 1        | pcs. | 160.14                  | 55.00% #1 | 72.06                     | 77.10                     |
|                | LABOUR REAR                                                                                                         | 4        | pcs. | 840.00                  | 23.00% #1 | 2,587.20                  | 2,768.30                  |
|                | Spray Painting REAR                                                                                                 | 4        | pcs. | 800.00                  | 23.00% #1 | 2,464.00                  | 2,636.48                  |
|                | R&R REAR BOOT LID GLASS                                                                                             | 1        | pcs. | 840.00                  | 23.00% #1 | 646.80                    | 692.08                    |
|                | TRANSFER BOOT LID MECHANISM                                                                                         | 0.5      | pcs. | 840.00                  | 23.00% #1 | 323.40                    | 346.04                    |
|                | R&R REAR LUGGAGE TRIM                                                                                               | 0.5      | pcs. | 840.00                  | 23.00% #1 | 323.40                    | 346.04                    |
|                | Reverse Sensor                                                                                                      | 1        | pcs. | 400.00                  | 23.00% #1 | 308.00                    | 329.56                    |
|                | REAR NUMBER PLATE                                                                                                   | 1        | pcs. | 80.00                   | 23.00% #1 | 61.60                     | 65.91                     |
|                | LABOUR FRT                                                                                                          | 2        | pcs. | 840.00                  | 23.00% #1 | 1,293.60                  | 1,384.15                  |
|                | Spray Painting FRT                                                                                                  | 2        | pcs. | 800.00                  | 23.00% #1 | 1,232.00                  | 1,318.24                  |
|                | FRT NUMBER PLATE                                                                                                    | 1        | pcs. | 80.00                   | 23.00% #1 | 61.60                     | 65.91                     |
|                | REAR WATER LEAK TEST                                                                                                | 1        | pcs. | 150.00                  | 23.00% #1 | 115.50                    | 123.59                    |
|                | HL ASSURANCE CLAIMS AGAINST AIG @<br>VEHICLE SLU7636S<br>D.O.A: 21-10-19 REPAIR LIMIT: \$13K<br>SURVEYOR: LKK RASUL |          |      |                         |           |                           |                           |

| Tax Code | Labour | Labour Discount | Material  | Material Discount | GST % | GST    | Total Discount | Total amount<br>excl. GST | Total amount<br>incl. GST |
|----------|--------|-----------------|-----------|-------------------|-------|--------|----------------|---------------------------|---------------------------|
| #1       | 585.20 | 174.80          | 12,369.77 | 6,421.71          | 7%    | 906.85 | 6,596.51       | 12,954.97                 | 13,861.82                 |
| Total    | 585.20 | 174.80          | 12,369.77 | 6,421.71          |       | 906.85 | 6,596.51       | 12,954.97                 | 13,861.82                 |

Customer

Service Advisor

Please inspect your vehicle prior to leaving our premises; we seek your understanding that we are not able to honour claims on scratches, dents etc. after your car has left our premises.

—VISIT OUR WEBSITE: [aftersales.vw.com.sg](http://aftersales.vw.com.sg) (for online service appointments) and [volkswagen.com.sg](http://volkswagen.com.sg) and [www.skoda.com.sg](http://www.skoda.com.sg) (for additional services, products and promotions).—

## VOLKSWAGEN CENTRE SINGAPORE

17 Tuas Avenue  
Singapore 639176  
Biz. Reg. No.: 199101494Z  
GST No.: M200985052



Volkswagen



SKODA



Commercial  
Vehicles

### Tax invoice

Preview

|                  |               |
|------------------|---------------|
| Page             | 3/3           |
| Document no.     |               |
| Document date    | 30-12-2019    |
| Customer no.     | 5211043795    |
| Customer GST-ID  | 201009404M    |
| Dealer           | 39999         |
| Job order number | 2019002538/ 1 |
| Job order date   | 01-11-2019    |
| Service Advisor  | YEN MEI WONG  |

|               |            |                    |                   |                       |         |
|---------------|------------|--------------------|-------------------|-----------------------|---------|
| License plate | Model code | First registration | VIN               | Model                 | Mileage |
| SKJ4568U      | 6R13H7     | 31-03-2013         | WWWZZZ6RZCU057834 | POLO 1.2 COMFO 66 D7F | 61,773  |

All fund transfer payments should be made payable to Volkswagen Group Singapore Pte Ltd; Bank Name: Deutsche Bank AG (Singapore Branch), Bank Account: 2528214002, Swift Code: DEUTSGSG. Please indicate Customer Number (eg. 521XXXXXX), Customer Name and Invoice Number in the payments.

Until payment of all goods (parts, accessories etc.) has been made in full to and received by Volkswagen Group Singapore (VGS), the goods remain in legal possession of VGS, irrespective if they have already been installed into your vehicle. However, the warranty of the goods (where applicable) starts with the issuance of the invoice or the collection of your car, whichever is earlier.

For warranty terms and conditions please visit our website [www.volkswagen.com.sg](http://www.volkswagen.com.sg)

This is an authorised document. No signature is required.

40,000

46,000

03-13

03-13  
04  
05-14  
05-18  
03-16  
03-17  
03-18

(Reg. yr on 2013)  
Depre. for - \$11,000 only left  
Divided 12 mths x 43 mths + Actual ARF Paid \$5574

2023  
2013

44,000

30,481

14,500

LIMITED: \$13K.

4

3.70

D: \$11,000.

43MTH

=

Subject to our principal approval

## View Received Message

This mail is associated with :

**\*SKJ4568U (8898958660SG)  
[SLU7636S]**

TP  
LOU KOK YONG  
Oct 21 2019 11:00AM  
[KINETIC HOLDINGS PTE. LTD.]  
Volkswagen Centre Singapore

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG\_SG\_EXPRESS), sent on 12/02/2020 09:20 AM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$15009.31) - SKJ4568U - Claim Handler: Lee, Ming-Yao

Approved:15009.31.

### DOCUMENTS SUMMARY

There are no documents.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

## CLAIM SUBFOLDER TRACKING

| Case | Notified                                | Est Submitted | Adj Assigned                                      | Adj Rpt                                               | Adj Submitted                                   | Ins Auth'ed | Status                                                          |
|------|-----------------------------------------|---------------|---------------------------------------------------|-------------------------------------------------------|-------------------------------------------------|-------------|-----------------------------------------------------------------|
| Main | 21 Oct 2019<br><a href="#">Edit Reg</a> |               | 24 Oct 2019 00:00<br><a href="#">Edit Adj Rpt</a> | <b>S\$12,954.97</b><br><a href="#">Edit Estimates</a> | <b>S\$12,954.97</b><br><a href="#">View Rpt</a> |             | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

Main

Reference

Claim Details

Documents

[Show All](#)

## CLAIM SUBFOLDER DETAILS

[Created by adjuster]

|                             |                                                                                                                               |                        |                                                                              |
|-----------------------------|-------------------------------------------------------------------------------------------------------------------------------|------------------------|------------------------------------------------------------------------------|
| Insured:                    | KINETIC HOLDINGS PTE. LTD., Co. Reg. No.: 201618392N                                                                          |                        |                                                                              |
| Main Claimant:              | LOU KOK YONG, ID: S1506079D                                                                                                   |                        |                                                                              |
| Vehicle Reg. No.:           | SKJ4568U                                                                                                                      | Date of Loss:          | 21/10/2019 11:00 - :59<br>[78 Months and 21 Days From LTA Reg Date (Man Yr)] |
| Claim Type:                 | TP / 8898958660SG                                                                                                             | Policy/Cover Note No.: | (Third Party Only)                                                           |
| Vehicle Reg. No. (Insured): | SLU7636S                                                                                                                      | Policy No. (Claimant): | MP305103                                                                     |
|                             |                                                                                                                               | Excess:                |                                                                              |
| Repairer:                   | Volkswagen Centre Singapore (HQ) 247 Alexandra Road, 159934 Alexandra - Tel: 63057288                                         |                        |                                                                              |
| Handling Insurer:           | AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by <b>Lee, Ming-Yao</b> ] MingYao.Lee@aig.com |                        |                                                                              |
| Claimant's Insurer:         | HL Assurance Pte Ltd (HQ) - Tel: 69226030                                                                                     |                        |                                                                              |
| Adjuster:                   | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... [Final Rpt due 01/11/2019]         |                        |                                                                              |

## ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG\_SG\_EXPRESS (12/02/2020): Alert - Adj Mandate Approved (S\$15009.31) - SKJ4568U - Claim Handler: Lee, Ming-...

## ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |





## Claim Documents

\*SKJ4568U (8898958660SG)  
[SLU7636S]  
TP  
LOU KOK YONG  
Oct 21 2019 11:00AM  
[KINETIC HOLDINGS PTE. LTD.]  
Volkswagen Centre Singapore

|                         |                 |  |                                                    |  |  |                    |  |  |              |  |  |              |  |  |            |           |  |                                     |  |  |
|-------------------------|-----------------|--|----------------------------------------------------|--|--|--------------------|--|--|--------------|--|--|--------------|--|--|------------|-----------|--|-------------------------------------|--|--|
| Upload Documents        |                 |  | Upload Photos                                      |  |  | Compose New Letter |  |  | Upload Video |  |  | Upload Audio |  |  | View       |           |  | View in Browser                     |  |  |
| Letters/Correspondences |                 |  |                                                    |  |  |                    |  |  |              |  |  |              |  |  | 1 per page |           |  | <input checked="" type="checkbox"/> |  |  |
| No                      | Finalized On    |  | LKK Auto Consultants Pte Ltd (HQ)                  |  |  |                    |  |  |              |  |  |              |  |  |            | Thumbnail |  | Print                               |  |  |
| 1                       | (Draft)         |  | Third Party Express Settlement – Payment Breakdown |  |  |                    |  |  |              |  |  |              |  |  | 1          | Edit      |  |                                     |  |  |
|                         |                 |  |                                                    |  |  |                    |  |  |              |  |  |              |  |  |            |           |  |                                     |  |  |
| Photos/Images           |                 |  |                                                    |  |  |                    |  |  |              |  |  |              |  |  | 3 per page |           |  | <input checked="" type="checkbox"/> |  |  |
| No                      | Relabel/Reorder |  | LKK Auto Consultants Pte Ltd (HQ)                  |  |  |                    |  |  |              |  |  |              |  |  |            | Thumbnail |  | Print                               |  |  |
| 1                       | 31/01/20 14:32  |  | Odometer Reading                                   |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG  |  | <input checked="" type="checkbox"/> |  |  |
| 2                       | 31/01/20 14:32  |  | Chassis Number                                     |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG  |  | <input checked="" type="checkbox"/> |  |  |
| 3                       | 31/01/20 14:32  |  | General View                                       |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG  |  | <input checked="" type="checkbox"/> |  |  |
| 4                       | 31/01/20 14:32  |  | General View                                       |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG  |  | <input checked="" type="checkbox"/> |  |  |
| 5                       | 31/01/20 14:32  |  | General View                                       |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG  |  | <input checked="" type="checkbox"/> |  |  |
| 6                       | 31/01/20 14:32  |  | General View                                       |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG  |  | <input checked="" type="checkbox"/> |  |  |
| 7                       | 31/01/20 14:32  |  | General View                                       |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG  |  | <input checked="" type="checkbox"/> |  |  |
| 8                       | 31/01/20 14:32  |  | General View                                       |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG  |  | <input checked="" type="checkbox"/> |  |  |
| 9                       | 31/01/20 14:32  |  | General View                                       |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG  |  | <input checked="" type="checkbox"/> |  |  |
| 10                      | 31/01/20 14:32  |  | General View                                       |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG  |  | <input checked="" type="checkbox"/> |  |  |
| 11                      | 31/01/20 14:32  |  | General View                                       |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG  |  | <input checked="" type="checkbox"/> |  |  |
| 12                      | 31/01/20 14:32  |  | General View                                       |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG  |  | <input checked="" type="checkbox"/> |  |  |
| 13                      | 31/01/20 14:32  |  | General View                                       |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG  |  | <input checked="" type="checkbox"/> |  |  |
| 14                      | 31/01/20 14:32  |  | General View                                       |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG  |  | <input checked="" type="checkbox"/> |  |  |
| 15                      | 31/01/20 14:32  |  | General View                                       |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG  |  | <input checked="" type="checkbox"/> |  |  |
| 16                      | 31/01/20 14:32  |  | General View                                       |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG  |  | <input checked="" type="checkbox"/> |  |  |
| 17                      | 31/01/20 14:32  |  | General View                                       |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG  |  | <input checked="" type="checkbox"/> |  |  |
| 18                      | 31/01/20 14:32  |  | General View                                       |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG  |  | <input checked="" type="checkbox"/> |  |  |
| 19                      | 31/01/20 14:32  |  | General View                                       |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG  |  | <input checked="" type="checkbox"/> |  |  |
| 20                      | 31/01/20 14:32  |  | General View                                       |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG  |  | <input checked="" type="checkbox"/> |  |  |
| 21                      | 31/01/20 14:32  |  | General View                                       |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG  |  | <input checked="" type="checkbox"/> |  |  |
| 22                      | 31/01/20 14:32  |  | General View                                       |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG  |  | <input checked="" type="checkbox"/> |  |  |
| 23                      | 31/01/20 14:32  |  | General View                                       |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG  |  | <input checked="" type="checkbox"/> |  |  |
| 24                      | 31/01/20 14:32  |  | General View                                       |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG  |  | <input checked="" type="checkbox"/> |  |  |
| 25                      | 31/01/20 14:32  |  | General View                                       |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG  |  | <input checked="" type="checkbox"/> |  |  |
| 26                      | 31/01/20 14:32  |  | General View                                       |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG  |  | <input checked="" type="checkbox"/> |  |  |
| 27                      | 31/01/20 14:32  |  | General View                                       |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG  |  | <input checked="" type="checkbox"/> |  |  |
| 28                      | 31/01/20 14:32  |  | General View                                       |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG  |  | <input checked="" type="checkbox"/> |  |  |
| 29                      | 31/01/20 14:32  |  | General View                                       |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG  |  | <input checked="" type="checkbox"/> |  |  |
| 30                      | 31/01/20 14:32  |  | General View                                       |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG  |  | <input checked="" type="checkbox"/> |  |  |
| 31                      | 31/01/20 14:32  |  | General View                                       |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG  |  | <input checked="" type="checkbox"/> |  |  |
| 32                      | 31/01/20 14:32  |  | General View                                       |  |  |                    |  |  |              |  |  |              |  |  | 1          | Load JPG  |  | <input checked="" type="checkbox"/> |  |  |

| Letters/Correspondences |                |                                   | 1 per page ▼                                                                                   | ✓     |
|-------------------------|----------------|-----------------------------------|------------------------------------------------------------------------------------------------|-------|
| No                      | Finalized On   | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail                                                                                      | Print |
| 33                      | 31/01/20 14:32 | General View                      |  Load JPG   | ✓     |
| 34                      | 31/01/20 14:32 | General View                      |  Load JPG   | ✓     |
| 35                      | 31/01/20 14:32 | General View                      |  Load JPG   | ✓     |
| 36                      | 31/01/20 14:32 | General View                      |  Load JPG   | ✓     |
| 37                      | 31/01/20 14:32 | General View                      |  Load JPG   | ✓     |
| 38                      | 31/01/20 14:32 | General View                      |  Load JPG   | ✓     |
| 39                      | 31/01/20 14:32 | General View                      |  Load JPG   | ✓     |
| 40                      | 31/01/20 14:32 | General View                      |  Load JPG   | ✓     |
| 41                      | 31/01/20 14:32 | General View                      |  Load JPG   | ✓     |
| 42                      | 31/01/20 14:32 | General View                      |  Load JPG   | ✓     |
| 43                      | 31/01/20 14:32 | General View                      |  Load JPG   | ✓     |
| 44                      | 31/01/20 14:32 | General View                      |  Load JPG   | ✓     |
| 45                      | 31/01/20 14:32 | General View                      |  Load JPG   | ✓     |
| 46                      | 31/01/20 14:32 | General View                      |  Load JPG   | ✓     |
| 47                      | 31/01/20 14:32 | General View                      |  Load JPG   | ✓     |
| 48                      | 31/01/20 14:32 | General View                      |  Load JPG   | ✓     |
| 49                      | 31/01/20 14:32 | General View                      |  Load JPG   | ✓     |
| 50                      | 31/01/20 14:32 | General View                      |  Load JPG   | ✓     |
| 51                      | 31/01/20 14:32 | General View                      |  Load JPG  | ✓     |
| 52                      | 31/01/20 14:32 | General View                      |  Load JPG | ✓     |
| 53                      | 31/01/20 14:32 | General View                      |  Load JPG | ✓     |
| 54                      | 31/01/20 14:32 | General View                      |  Load JPG | ✓     |
| 55                      | 31/01/20 14:32 | General View                      |  Load JPG | ✓     |
| 56                      | 31/01/20 14:32 | General View                      |  Load JPG | ✓     |
| 57                      | 31/01/20 14:32 | General View                      |  Load JPG | ✓     |
| 58                      | 31/01/20 14:32 | General View                      |  Load JPG | ✓     |
| 59                      | 31/01/20 14:32 | General View                      |  Load JPG | ✓     |
| 60                      | 31/01/20 14:32 | General View                      |  Load JPG | ✓     |
| 61                      | 31/01/20 14:32 | General View                      |  Load JPG | ✓     |
| 62                      | 31/01/20 14:32 | General View                      |  Load JPG | ✓     |
| 63                      | 31/01/20 14:32 | General View                      |  Load JPG | ✓     |
| 64                      | 31/01/20 14:32 | General View                      |  Load JPG | ✓     |
| 65                      | 31/01/20 14:32 | General View                      |  Load JPG | ✓     |
| 66                      | 31/01/20 14:32 | General View                      |  Load JPG | ✓     |
| 67                      | 31/01/20 14:32 | General View                      |  Load JPG | ✓     |
| 68                      | 31/01/20 14:34 | Reinspection Photo                |  Load JPG | ✓     |
| 69                      | 31/01/20 14:34 | Reinspection Photo                |  Load JPG | ✓     |
| 70                      | 31/01/20 14:34 | Reinspection Photo                |  Load JPG | ✓     |
| 71                      | 31/01/20 14:34 | Reinspection Photo                |  Load JPG | ✓     |
| 72                      | 31/01/20 14:34 | Reinspection Photo                |  Load JPG | ✓     |
| 73                      | 31/01/20 14:34 | Reinspection Photo                |  Load JPG | ✓     |
| 74                      | 31/01/20 14:34 | Reinspection Photo                |  Load JPG | ✓     |
| 75                      | 31/01/20 14:34 | Reinspection Photo                |  Load JPG | ✓     |
| 76                      | 31/01/20 14:34 | Reinspection Photo                |  Load JPG | ✓     |
| 77                      | 31/01/20 14:34 | Reinspection Photo                |  Load JPG | ✓     |
| 78                      | 31/01/20 14:34 | Reinspection Photo                |  Load JPG | ✓     |
| 79                      | 31/01/20 14:34 | Reinspection Photo                |  Load JPG | ✓     |
| 80                      | 31/01/20 14:34 | Reinspection Photo                |  Load JPG | ✓     |

| Letters/Correspondences |                 |                                   | 1 per page                                                                                     | <input checked="" type="checkbox"/> |
|-------------------------|-----------------|-----------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| No                      | Finalized On    | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail                                                                                      | Print                               |
| 81                      | 31/01/20 14:34  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 82                      | 31/01/20 14:34  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 83                      | 31/01/20 14:34  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 84                      | 31/01/20 14:34  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 85                      | 31/01/20 14:34  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 86                      | 31/01/20 14:34  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 87                      | 31/01/20 14:34  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 88                      | 31/01/20 14:34  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 89                      | 31/01/20 14:34  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 90                      | 31/01/20 14:34  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 91                      | 31/01/20 14:34  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 92                      | 31/01/20 14:34  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 93                      | 31/01/20 14:34  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 94                      | 31/01/20 14:34  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 95                      | 31/01/20 14:34  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 96                      | 31/01/20 14:34  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 97                      | 31/01/20 14:34  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 98                      | 31/01/20 14:34  | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 99                      | 31/01/20 14:34  | Reinspection Photo                |  Load JPG  | <input checked="" type="checkbox"/> |
| 100                     | 31/01/20 14:34  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 101                     | 31/01/20 14:34  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 102                     | 31/01/20 14:34  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 103                     | 31/01/20 14:34  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 104                     | 31/01/20 14:34  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 105                     | 31/01/20 14:34  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 106                     | 31/01/20 14:34  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 107                     | 31/01/20 14:34  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 108                     | 31/01/20 14:34  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 109                     | 31/01/20 14:34  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 110                     | 31/01/20 14:34  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 111                     | 31/01/20 14:34  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 112                     | 31/01/20 14:34  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 113                     | 31/01/20 14:34  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 114                     | 31/01/20 14:34  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 115                     | 31/01/20 14:34  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 116                     | 31/01/20 14:34  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 117                     | 31/01/20 14:34  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 118                     | 31/01/20 14:34  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 119                     | 31/01/20 14:34  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 120                     | 31/01/20 14:34  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 121                     | 31/01/20 14:34  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 122                     | 31/01/20 14:34  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 123                     | 31/01/20 14:34  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 124                     | 31/01/20 14:34  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 125                     | 31/01/20 14:34  | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| Documentation           |                 |                                   | 1 per page                                                                                     | <input checked="" type="checkbox"/> |
| No                      | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail                                                                                      | Print                               |
| 1                       | 22/10/19 15:37  | TP ESTIMATE                       |  Load PDF |                                     |

| Letters/Correspondences |                |                                           | 1 per page ▼ | <input checked="" type="checkbox"/> |
|-------------------------|----------------|-------------------------------------------|--------------|-------------------------------------|
| No                      | Finalized On   | LKK Auto Consultants Pte Ltd (HQ)         | Thumbnail    | Print                               |
| 2                       | 22/10/19 15:37 | <b>TP GIA REPORT</b>                      | Load PDF     |                                     |
| 3                       | 25/10/19 14:56 | <b>TP ESTIMATE - MARKED</b>               | Load PDF     |                                     |
| 4                       | 29/01/20 14:18 | <b>LETTER TO OI</b>                       | Load PDF     |                                     |
| 5                       | 29/01/20 14:18 | <b>LOD</b>                                | Load PDF     |                                     |
| 6                       | 26/02/20 11:44 | <b>Authorisation to Act</b>               | Load PDF     |                                     |
| 7                       | 26/02/20 11:44 | <b>Release Voucher</b>                    | Load PDF     |                                     |
| 8                       | 26/02/20 11:44 | <b>WORKSHOP INVOICE</b>                   | Load PDF     |                                     |
| 9                       | 26/02/20 11:44 | <b>LTA SEARCH</b>                         | Load PDF     |                                     |
| No                      | Finalized On   | AIG Asia Pacific Insurance Pte. Ltd. (SG) | Thumbnail    | Print                               |
| 1                       | 23/10/19 14:49 | <b>OI GIA REPORT</b>                      | Load PDF     |                                     |

## Documents Checklist

| DOCUMENTS CHECKLIST                          | Reset | Save | Print |
|----------------------------------------------|-------|------|-------|
| There are no document checklists configured. |       |      |       |

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

|                   |                     |        |                             |
|-------------------|---------------------|--------|-----------------------------|
| Vehicle No:       | SLU7636S (Insd veh) | Model: | VOLKSWAGEN POLO 1.2 TSI (A) |
|                   | SKJ4568U (TP veh)   |        |                             |
| Date of Accident: | 21/10/2019          |        |                             |

|                       |   |         |          |                               |
|-----------------------|---|---------|----------|-------------------------------|
| Global Sum Settlement | : | [ ] Yes | [ X ] No |                               |
| Repair Estimate       | : | \$      |          | 31,166.97                     |
| Final Repair Cost     | : | \$      |          | 13,861.82                     |
| Loss of Use           | : | \$      |          | 1,140.00                      |
| Rental (if any)       | : | \$      |          | 19.00 days at \$60.00 per day |
| LTA / GIA Search Fee  | : | \$      |          | 7.49                          |
| Others:               | : | \$      |          |                               |
|                       | : | \$      |          |                               |
| Final Settlement Sum  | : | \$      |          | 15,009.31                     |

**Is Third Party Workshop GIA Registered?** [ ] YES [ X ] NO (Kindly indicate below)

**A) For Non GIA Registered Workshop:** Agreed Liability \_\_\_\_\_ 100 \_\_\_\_\_ (%)

**B) For GIA Registered Workshop:** BOLA Applicable: Yes/ No BOLA Scenario No: \_\_\_\_\_

BOLA Liability: \_\_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_\_ 100 \_\_\_\_\_ (%)

*\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks \_\_\_\_\_

| Payment Instruction: Payee's Breakdown |                             |   |    |           |
|----------------------------------------|-----------------------------|---|----|-----------|
| 1)                                     | Volkswagen Centre Singapore | : | \$ | 15,009.31 |
| 2)                                     |                             | : | \$ |           |
| 3)                                     |                             | : | \$ |           |
| 4)                                     |                             | : | \$ |           |

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

26 Feb  
2020

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19018666/R1DA3S2  
Date: 26/02/2020

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:  
Claimant Vehicle No: SKJ4568U Insured Vehicle No: SLU7636S  
Date of Loss: 21/10/2019 Nature of Claim: TP Claim No: 8898958660SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SKJ4568U  
Make & Model: VOLKSWAGEN POLO, 1.2 TSI (A) Engine No: CBZ612684  
Reg. Date: 31/03/2013 (Man. Year: 2012) Chassis No: WVVZZZ6RZCU057834  
Colour: White Odometer: 61018 km  
Engine Capacity: 1197 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16  
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm  
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                                   | Repairer's       | Adjuster's       | Difference       | Diff %       |
|--------------------------------------------------|------------------|------------------|------------------|--------------|
| Parts                                            | 10,088.01        | 3,383.87         | 6,704.14         | 66.46        |
| Miscellaneous Items                              | 0.00             | 0.00             | 0.00             |              |
| Labour                                           | 19,040.00        | 9,571.10         | 9,468.90         | 49.73        |
| Paintwork Labour                                 | 0.00             | 0.00             | 0.00             |              |
| Towing                                           | 0.00             | 0.00             | 0.00             |              |
| <b>Gross Total (S\$)</b>                         | <b>29,128.01</b> | <b>12,954.97</b> | <b>16,173.04</b> | <b>55.52</b> |
| <b>+ GST 7.00/7.00% (S\$)</b>                    | <b>2,038.96</b>  | <b>906.85</b>    | <b>1,132.11</b>  | <b>55.52</b> |
| <b>Nett Amount (S\$)</b>                         | <b>31,166.97</b> | <b>13,861.82</b> | <b>17,305.15</b> | <b>55.52</b> |
| <b>+ Loss of Use (19.0 x S\$60.00/day) (S\$)</b> |                  | <b>1,140.00</b>  |                  |              |
| <b>+ Doc/Search Fee (S\$)</b>                    |                  | <b>7.49</b>      |                  |              |
| <b>Nett Liability (S\$)</b>                      |                  | <b>15,009.31</b> |                  |              |

## INSPECTION

Date of Assignment: 24/10/2019  
Date Inspected: 24/10/2019 Inspected At: Volkswagen Centre Singapore (HQ)  
247 Alexandra Road  
Singapore 159934  
Estimated Period of Repair: 12.0 days

Adjuster: MOHD RASUL

Manager: CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Recommended Parts

| No. | Qty | Part No. Particulars                                   | Condition     | Repairer's  | Amount     |
|-----|-----|--------------------------------------------------------|---------------|-------------|------------|
| 1   | 1   | *REAR TRUNK LID: REAR BOOT LID                         | Bent          | 1,706.09 FS | *767.74 FS |
| 2   | 1   | *1K WINDOW ADHESIVE<br>2pcs                            | Necessary     | 99.76 FS    | *44.89 FS  |
| 3   | 1   | *HOOD LATCH SATIN BLACK: REAR BOOT LID LOCK            | Scratched     | 160.14 FS   | *72.06 FS  |
| 4   | 1   | *GASKET: BOOT WEATHERSTRIP                             | Not Necessary | 138.26 FS   | *- FS      |
| 5   | 1   | *INSCRIPTION BRIGHT CHROME: NAME PLATE - POLO          | Necessary     | 58.46 FS    | *26.31 FS  |
| 6   | 1   | *INSCRIPTION CHROME: NAME PLATE - TSI                  | Necessary     | 54.92 FS    | *24.71 FS  |
| 7   | 1   | *ADDITIONAL BRAKE LIGHT WI: 3RD BRAKE LIGHT            | Necessary     | 155.54 FS   | *69.99 FS  |
| 8   | 2   | *LICENSE PLATE LIGHT                                   | Serviceable   | 74.38 FS    | *- FS      |
| 9   | 1   | *COVER FOR BUMPER PRIMED: REAR BUMPER                  | Deformed      | 932.40 FS   | *419.58 FS |
| 10  | 1   | *CROSS MEMBER: REAR REINFORCEMENT                      | Bent          | 401.95 FS   | *180.88 FS |
| 11  | 1   | *ATTACHMENT STRIP: BUMPER CENTRE BRACKET               | Serviceable   | 68.06 FS    | *- FS      |
| 12  | 1   | *GUIDE PIECE: BUMPER SIDE BRACKET LH                   | Cracked       | 57.41 FS    | *25.83 FS  |
| 13  | 1   | *GUIDE PIECE: BUMPER SIDE BRACKET RH                   | Cracked       | 57.41 FS    | *25.83 FS  |
| 14  | 2   | *VENT TRIM: AIR DUCT                                   | Cracked       | 72.76 FS    | *32.74 FS  |
| 15  | 1   | *REAR APRON: END PANEL OUTER                           | Repair        | 181.34 FS   | *- FS      |
| 16  | 1   | *END PLATE: END PANEL INNER                            | Repair        | 617.14 FS   | *- FS      |
| 17  | 1   | *SEALANT CAN BE SPRAYED                                | Not Necessary | 62.20 FS    | *- FS      |
| 18  | 1   | *ZINC SPRAY                                            | Not Necessary | 62.88 FS    | *- FS      |
| 19  | 1   | *2K - BODY ADHESIVE                                    | Not Necessary | 398.47 FS   | *- FS      |
| 20  | 1   | *COVER FOR TRIM COVER: END PANEL TRIM COVER            | Serviceable   | 138.38 FS   | *- FS      |
| 21  | 1   | *BOLT FOR SPARE WHEEL MOUN                             | Not Necessary | 15.51 FS    | *- FS      |
| 22  | 1   | *SOUND ABSORBER: FLOOR PAN INSULATOR                   | Necessary     | 65.68 FS    | *29.56 FS  |
| 23  | 1   | *EXHAUST SILENCER REAR                                 | Serviceable   | 472.09 FS   | *- FS      |
| 24  | 1   | *DUAL CLAMP                                            | Serviceable   | 55.81 FS    | *- FS      |
| 25  | 1   | *HOOD: FRT BONNET                                      | Repair        | 905.91 FS   | *- FS      |
| 26  | 1   | *RETAINING BRACKET: BONNET LATCH                       | Serviceable   | 69.82 FS    | *- FS      |
| 27  | 1   | *COVER FOR BUMPER PRIMED: FRT BUMPER                   | Cracked       | 925.31 FS   | *416.39 FS |
| 28  | 1   | *IMPACT BEAM: FRT REINFORCEMENT                        | Bent          | 470.30 FS   | *211.64 FS |
| 29  | 1   | *RADIATOR GRILLE BLACK HIG                             | Cracked       | 353.17 FS   | *158.93 FS |
| 30  | 1   | *COOLING AIR GRILL SATIN B: BUMPER CENTRE LOWER GRILLE | Cracked       | 176.10 FS   | *79.25 FS  |
| 31  | 1   | *MOUNTING FOR HEADLAMPS: FRT BUMPER SIDE BRACKET LH    | Cracked       | 99.37 FS    | *44.72 FS  |
| 32  | 1   | *MOUNTING FOR HEADLAMPS: FRT BUMPER SIDE BRACKET RH    | Serviceable   | 99.37 FS    | *- FS      |
| 33  | 1   | *REVERSE SENSOR                                        | Not Working   | 400.00 FS   | *308.00 FS |
| 34  | 1   | *REAR NUMBER PLATE                                     | Bent          | 80.00 FS    | *61.60 FS  |
| 35  | 1   | *FRT NUMBER PLATE                                      | Bent          | 80.00 FS    | *61.60 FS  |
| 36  | 1   | *TWIN HALOGEN HEADLAMPS                                | Cracked       | 259.80 FS   | *259.80 FS |
| 37  | 1   | *FOG LAMP GRILLE RH                                    | Cracked       | 28.40 FS    | *28.40 FS  |
| 38  | 1   | *RR NUMBER PLATE LIGHT WIRE HOUSING                    | Cracked       | 2.43 FS     | *2.43 FS   |
| 39  | 1   | *PRIMER                                                | Necessary     | 11.66 FS    | *11.66 FS  |
| 40  | 1   | *APPLICATOR<br>2pcs                                    | Necessary     | 8.53 FS     | *8.53 FS   |
| 41  | 1   | *ACTIVATOR FOR PRECOATED W                             | Necessary     | 10.80 FS    | *10.80 FS  |

F=Franchise part. S=SpcNett.

Total Parts (S\$) 10,088.01 3,383.87

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                           | Lab.Type | Repairer's       | Amount          |
|---------------------------------|---------------------------------------|----------|------------------|-----------------|
| <b>Labour Items</b>             |                                       |          |                  |                 |
| 1                               | CHECK SHORT CIRCUIT / HARNESS REPAIR. | New      | 280.00           | 215.60          |
| 2                               | DIAGNOSTIC AND PROGRAMMING.           | New      | 480.00           | 369.60          |
| 3                               | LABOUR REAR.                          | New      | 6,720.00         | 2,587.20        |
| 4                               | SPRAY PAINTING REAR.                  | New      | 800.00           | 2,464.00        |
| 5                               | R&R REAR BOOT LID GLASS.              | New      | 840.00           | 646.80          |
| 6                               | TRANSFER BOOT LID MECHANISM.          | New      | 840.00           | 323.40          |
| 7                               | R&R REAR LUGGAGE TRIM.                | New      | 840.00           | 323.40          |
| 8                               | R&R REAR EXHAUST PIPE.                | New      | 840.00           | 0.00            |
| 9                               | REAR WATER LEAK TEST.                 | New      | 840.00           | 115.50          |
| 10                              | LABOUR FRT.                           | New      | 3,360.00         | 1,293.60        |
| 11                              | SPRAY PAINTING FRT.                   | New      | 3,200.00         | 1,232.00        |
| <b>Gross Labour Cost (\$\$)</b> |                                       |          | <b>19,040.00</b> | <b>9,571.10</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >