

INS. CASE OWNER: MingYao.Lee

CC3/AIG19018666/R1da3

LKK:

IDAC:

ASSIGNMENTSurveyor: RASULDOI: 24/10/2019Date / Time : 22/10/2019Registered in Merimen: 22/10/2019

Pre-assign / CCU / FTE

Insured Vehicle No. : SLU 7636SClaim No. : 8898958660SGName of Insured : KINETIC HOLDINGS PTE. LTD.Policy No. : 999994104

Insured Tel No. : _____ HP: _____

Make / Model : TOYOTA SIENTA

Excess Sec II :S\$

D.O.A : 21/10/2019 11:15Place of Accident : ALONG HILLVIEW AVE

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age : MUHAMMAD FAHMIN BIN ABDUL KADIR

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : +65-90214279 (V/L: YES / NO)

Insured Liability : % Final ? Yes / No

SLU 7636SSKJ 4568USDN 807TFX 6547C-> SG 5454D

INSRS:

WSP:

Tel :

Liability :

RMKS:

OI



INSRS:

WSP:

Tel : VOLKSWAGEN

Liability :

RMKS:

TP



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time		STAGE	DATE / PIC
	SKJ 4568U - CC3/AIG18004401/T1pb3q2; DOA: 04.03.18	Non-Reporting ltr (1st):	
	SLU 7636S - CS/INC19011761/Uqd3n2; DOA: 28.06.19	Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OI:	
		After call ltr to OI:	
		Documentation Check List: Handler Typist	
		Notification ltr (if non-pickup)	☐
		After call ltr to OI:	☐
		Authorisation To Act:	☐
		Release Voucher:	☐
		Final Repair Bill:	☐
		Car Rental Invoice:	☐
		Towing Invoice	☐
		LTA / GIA :	☐
		Medical Bill:	☐
		PIR:	☐
		Mandate/Reject Instruction:	☐
		LOD	☐
		Payment Breakdown Form:	☐
		Post-Repair Photos:	☐
		Others:	☐

PRELIMINARY ADVICE		Date/Time:	Sent By:	Post-Repair Photos:	☐	Others:	☐
FINALIZATION		Date/Time:	Confirm with:	Confirm by:			
Repair Cost:	S\$	(days)	Reduction:	%	Email ☐	Call ☐	
FINAL SETTLEMENT		Date/Time:	Confirm with:	Email ☐	Call ☐		
Final Liability:	%	(Agreed / Assessed) BOLA S/N No. :			If NO or B 28, Ass. Lia :		
Repair Cost:	S\$						
Loss of Rental (LOR):	S\$	(days)					
Loss of Use (LOU):	S\$	(\$ x days)					
Loss of Income (LOI):	S\$	(\$ x days)					
LOR only ☐	LOU only ☐	LOR + LOU ☐	LOR + LOI ☐	[Tick only one]			
GIA/LTA Search	S\$						
Medical:	S\$						
Disbursement:	S\$	(e.g. Tow/ Independent)			1) Claim status: Normal/Reject/Private Settle		
Legal Cost	S\$				2) Report Format:		
					3) Survey fee:		
Total:	S\$	Global Sum S\$:					
FINAL PAYMENT		Date/Time:	Confirm with:	Email ☐	Call ☐		
Payee 1:	S\$	Name 1:					
Payee 2: (Strike if N.A.)	S\$	Name 2:					
Payee 3: (Strike if N.A.)	S\$	Name 3:					

ASS. REC. BY:

REF:

ALG

0790

ASSIGNMENT

From:

Date:

24/10/2019

Estimated Cost:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

8KJ45684

at Workshop m/s

volkswagen

of

247 Alexandra Road

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

2.30pm (weekend)

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{1up}

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKJ 45684

Yr Regn: 2013 / MAR

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

VOLKSWAGEN POLO 1.2 TSI AT c.c 1197

Colour

WHITE

A/C: Insured / Std / NI / NA

Sp. Reading

6018

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WVWZ226RZCU057834

Gen. Cond: Good / ☒ Fair / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size:

F:

205/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

21/10/19

D.O.I.

24/10/19

Survey held at

Volkswagen

Des. of Damages ☒ Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

repair limit 9k

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$)

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	079D
Vehicle Details	
Vehicle No.:	SKJ4568U
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Oct 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	POLO 1.2 TSI AT 6R13H7
Primary Colour:	White
Manufacturing Year:	2012
Engine No.:	CBZ612684
Chassis No.:	WVWZZZ6RZCU057834
Maximum Power Output:	66.0 kW (88 bhp)
Open Market Value:	\$15,574.00
Original Registration Date:	31 Mar 2013
First Registration Date:	31 Mar 2013
Transfer Count:	1
Actual ARF Paid:	\$5,574.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Mar 2023
PARF Rebate Amount:	\$3,623.00
Intended COE Rebate Details	
COE Expiry Date:	30 Mar 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$78,301.00
COE Rebate Amount:	\$26,858.00
Total Rebate Amount:	\$30,481.00

The information contained herein is correct as at 25 Oct 2019

OK

40,000
30,481

9,519