

INS. CASE OWNER:

NORSIAH

CC4/AIG19018681/Uda3

LKK:

IDAC:

REJECT

Surveyor:

MARCUS


DOI: 22/10/2019

ASSIGNMENT

Date / Time : 21.10.2019

Registered in Merimen: 22.10.2019

Pre-assign / CCU / FTE



Insured Vehicle No. : SJJ 2367H

Claim No. :

Name of Insured : CHUA SENG HIAP

Policy No. :

Insured Tel No. : HP: 12/10/2019 09:20

Make / Model : MINI COOPER S CLUBMAN-2.0 (A)

Excess Sec II : \$\$

D.O.A : 12/10/2019 09:20

Place of Accident : BLK 247 JURONG EAST ST 24 CARPARK

Is driver the owner? (YES / NO) Nature of Accident :


If NO, Driver Name / Age : CHUA WAVERLY

OI GIA REPOR'

Driver Tel No. : +65-82283942 (V/L: YES / NO)

Insured Liability

SJW 7628D

→ Reject chp
→ Close.INSRS:
WSP: ASIA
Tel: MOTORSPORTS
Liability :
RMKS:INSRS:
WSP:
Tel:
Liability :
RMKS:INSRS:
WSP:
Tel:
Liability :
RMKS:

Date/ Time	STAGE	DATE / PIC
SJJ 2367H } NA/AIG19018087/z4; DOA: 12.10.19	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List: Handler Typist	
	Notification ltr (if non-pickup)	
	After call ltr to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice	
	LTA / GIA :	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	

PRELIMINARY ADVICE	Date/Time:	Sent By:
FINALIZATION	Date/Time:	Confirm with:
Repair Cost:	\$\$	(days) Reduction: %
FINAL SETTLEMENT	Date/Time:	Confirm with:
Final Liability:	%	(Agreed / Assessed) BOLA S/N No. :
Repair Cost:	\$\$	
Loss of Rental (LOR):	\$\$	(days)
Loss of Use (LOU):	\$\$	(\$ x days)
Loss of Income (LOI):	\$\$	(\$ x days)
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]		
GIA/LTA Search	SS	
Medical:	SS	
Disbursement:	SS	(e.g. Tow/ Independent)
Legal Cost	SS	
Total:	SS	Global Sum \$:
FINAL PAYMENT	Date/Time:	Confirm with:
Payee 1:	SS	Name 1:
Payee 2: (Strike if N.A.)	SS	Name 2:
Payee 3: (Strike if N.A.)	SS	Name 3:

COPY SENT
21/10/2019

(08/11/13) wef

ASS. REC. BY: *Marcus*

REF:

*A16/***ASSIGNMENT**

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

Veh No:

Yr Regn:

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.L.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐

: Preli. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) S + RS, SI

) Photos

) Others

Report Format:

Lump Sum / I.B.I. (\$

TOTAL

23/10/18 Confund 1/5 \$ 2000 w.e. AH/ony.
(Red \$ 7690.31 / 797.)

ASIA MOTORSPORTS SOLUTION PTE LTD

• 5 Jalan Masjid, #01-14, (Kembangan Court), Singapore 418924

H/P: 9622 0160 (SG Loo) // Tel: 6745 3811 // Fax: 6746 5110

Email: asiamotorsports@hotmail.com

SJW 7628D

Vehicle number: SJW7628D

Vehicle Made & Model: TOYOTA ALTIS

Qty	List Items	Amount \$
1	Rear bumper	de/to 512.60 ✓
2	Rear bumper side retainers - L/R @ 64.43	17 128.86 X
10	Rear bumper clips @ 4.50	new 45.00 ✓
1	Rear fender - LH	2 1,260.50 X
1	Rear fender inner shield	17 151.43 X
1	Rear door - LH	2 1,210.50 X
1	Rear door protector	cut/new 126.20 ✓
1	Rear door protector moulding	new 61.50 ✓
1	Rear door w/strip	17 132.60 X
1	Rear shock absorber - LH	17 321.60 X
1	Rear wheel hub bearing	17 671.50 X
1	Rear axle beam	17 1,895.60 X
1	Rear windscreen moulding	17 120.60 X
1	Side sill panel skirt - LH	2 681.92 X
Sub-total		7,320.41
Less 25%		1,830.10
Total List		5,490.31

Special Nett Items

1	Rear sport wheel - LH	cut/seat 550.00 350 S.W
1	Rear tyre - LH	800 350.00 X
1 set	Rear windscreen sealant	17 80.00 X
1 set	Rear door black tape	17 80.00 X
Total Special Nett		1,060.00

Not Allowed
L/L
L/S \$2000 H/L
Wh. the After rep.

Vehicle number: SJW7628D

Vehicle Made & Model: TOYOTA ALTIS

Labour charges

To check front electrical wiring	50.00	20
To remove, refix rear interior trims to assist repair	120.00	80
To remove, refix rear undercarriage	11 300.00	X
To check wheel alignment	120.00	60
To respray undercoating	1 1 150.00	X
To respray painting and etc	1,200.00	800
Panel beating, cut, weld remove & replacing above parts	1,200.00	650
Total Labour	3,140.00	

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 9,690.31

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P - 745.30
257
P - 558.57
S.W - 350.00
L - 1610.00
2578.97
202
201517