

ASS. REC. BY:

REF: CS/INC1908685/Rlvdbn2

Special Instruction:

Surveyor: RCBUI

ASSIGNMENT (Office)

From (Person): Theresa Vimalan

of INC

Date/Time: 9.43am 22/10/2014

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBC 2399Y

Insured:

YK 9262Y

at Workshop m/s

Sin sheng

Tel:

6863 9595

of

No. 8 trans Ave 18

Policy No:

Claim No:

MT/1064166-002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23/09/2014

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10.13am 22/10/14

Person Contacted:

pei Jin

Vehicle IN / OUT

Date/Time	Action/Instruction	Isimple ✓
	<u>GBC 2399Y - 83/FCI 14606033 / Kgm 33</u>	<u>DOA: 24/12/2013</u>
	<u>YK 9262Y - CC3 / MSU15019 688 / Avbn2</u>	<u>DOA: 17/11/2015</u>
<u>1/11/14</u>	<u>Final fig \$273.63 confirmed by email (Ref 1131.66, 8190) (Ho LS)</u>	

Pass

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: ABC 23994
 at Workshop m/s: SIN S HENG
 of: 8, TUNAS AVE 18 # 05 - W
 Insured: NTUC
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

N/S	O/S

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: ABC 23994 Yr Regt: 2011 / 84P
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: MITSUBISHI FB 70 c.c. 2977
 Colour: Red A/C: Insured / Std / NI / NA
 Sp. Reading: 212683 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: FB70BBA70382
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195R15C
 R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or AUSTONE

Front	Rear
R/Bal. <u>7</u> mm	R/Bal. <u>7/7</u> mm
L/Bal. <u>7</u> mm	L/Bal. <u>7/7</u> mm
D.O.A. <u>23/09/19</u>	D.O.I. <u>22/10/19</u>
Survey held at <u>SIN S HENG</u>	<u>5.32</u>

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
FRONT O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 04 NOV 2019

[Signature]
 1/11/2019

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 1

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + PS: \$

Photos:

Others:

TOTAL

250

1) _____
 Date/Time, File Return to?

2) 1/11 - typist

Report Format:

TP

Lump Sum / L.B. / L.C.

P/P \$273.63

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Wash and

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 1 November 2019 2:17 PM
To: sinsheng engineeringservices
Cc: SUR
Subject: RE: GBC 2399Y-DOA: 23/9/2019

Dear Pei Jin,

Noted with thanks.

Kindly send Final invoice and all supporting documents directly to NTUC INCOME

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: sinsheng engineeringservices <sinsheng1981@gmail.com>
Sent: Friday, 1 November 2019 2:06 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: Re: GBC 2399Y-DOA: 23/9/2019

Hi Veron,

We are accepted your offer.

**** KINDLY NOTE THAT WE ARE ALLOCATED AT NO 8 TUAS AVE 18 (LEVEL 5), SINGAPORE 638892 WITH IMMEDIATE EFFECT ****

Thank You
Regards

Pei Jin
Sin Sheng Engineering Services
No 8 Tuas Ave 18
Singapore 638892
(Level 3_Office)
(Level 5_Workshop)
Tel: 6863 9595
Fax: 6863 6477

On Fri, 1 Nov 2019 at 10:03, Veron Chen (LKKAUTO) <veronchen@lkkauto.com> wrote:

Dear Pei Jin,

WITHOUT PREJUDICE

Finalise amount \$273.63 @ 1 working day.

Please check and confirm

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: sinsheng engineering services <sinsheng1981@gmail.com>

Sent: Thursday, 31 October 2019 2:56 PM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Subject: Re: GBC 2399Y-DOA: 23/9/2019

Hi Veron,

Please find attached the after repair photos and have your finalized.

**** KINDLY NOTE THAT WE ARE ALLOCATED AT NO 8 TUAS AVE 18 (LEVEL 5), SINGAPORE 638892 WITH IMMEDIATE EFFECT ****

Thank You
Regards

Pei Jin

Sin Sheng Engineering Services
No 8 Tuas Ave 18

Singapore 638892

(Level 3_Office)

(Level 5_Workshop)

Tel: 6863 9595
Fax: 6863 6477

On Wed, 30 Oct 2019 at 15:58, Veron Chen (LKKAuto) <veronchen@lkkauto.com> wrote:

Dear Pei Jin,

WITHOUT PREJUDICE

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Nivitha (LKK Auto)

From: Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>
Sent: Tuesday, 22 October 2019 11:21 AM
To: assignments
Cc: Theresa Vimala D/O Balagangadharan
Subject: RE: TP CASES FARMED OUT TO LKK ON 22/10/2019

Dear LKK, here is the list of the OIC details , etc.

With Regards

Theresa Vimala
Senior Administrator
Motor Insurance
www.income.com.sg

income
made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

From: Theresa Vimala D/O Balagangadharan
Sent: Tuesday, 22 October 2019 9:43 AM
To: assignments <assignments@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>
Subject: RE: TP CASES FARMED OUT TO LKK ON 22/10/2019

Dear LKK

Please assist to survey the following vehicles :-

SN	OIC	Claim No.	Survey Date	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	chryllis	MT/1067445-002	22/10/2019	GBJ2611Y	CHENG AUTO BODYWORKS	5 SOON LEE STREET #01-62 PIONEER POINT	Rachel Lai / 8666 7775		YP4499M	17/10	
2	JESSIE	MT/1067536-002	22/10/2019	SHC7193U	DING AUTOMOTIVE PTE LTD	31 CORPORATION ROAD SINGAPORE 649825	VADIVELAN MOHAN / 96891857	10:00-12:00	SIL9322E	18/10	
3	AIRWAN	MT/1067304-002	22/10/2019	SLR2813X	HITACHI CAPITAL (S) PTE LTD	8 FOURTH LOK YANG ROAD SINGAPORE 629705	Vonn Siow / 96435107	10:00-12:00	SMK1076E	15/10	
4	FIONA	MT/1064166-002	22/10/2019	GBC2399Y	SIN SHENG ENGINEERING SERVICES	NO 8 TUAS AVENUE 18, #05-00 SINGAPORE 638892	Pei Jin / 6863 9595		YK9262Y	23/9	
5	HELENA	MT/1066828-002	22/10/2019	SMA478X	VANTAGE AUTOMOTIVE LIMITED	305 ALEXANDRA ROAD SINGAPORE 159942	CHUA SYASYA / 64777409	14:00-16:00	SLM8134J	11/10	
6	CHARLOTTE	MT/1067439-001	22/10/2019	SMP7810U	VOLKSWAGEN CENTRE SINGAPORE	247 ALEXANDRA ROAD SINGAPORE 159934	Charmaine Kong / 6305 7176	14:00-16:00	SGT4461M	17/10	


Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

With Regards

Theresa Vimala
Senior Administrator
Motor Insurance
T +65 6430 7898
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.

Find out more at Income.com.sg/careers

in with you

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

196N

Vehicle Details

Vehicle No.:

GBC2399Y

Vehicle to be Exported:

Yes

Intended Deregistration Date:

31 Dec 2019

Vehicle Make:

MITSUBISHI

Vehicle Model:

FB70BB1SRDEA

Primary Colour:

White

Manufacturing Year:

2011

Engine No.:

4M42A87814

Chassis No.:

FB70BBA20382

Maximum Power Output:

\$28,455.00

Open Market Value:

08 Sep 2011

Original Registration Date:

08 Sep 2011

First Registration Date:

0

Transfer Count:

\$1,423.00

Actual ARF Paid:

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

07 Sep 2021

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

10

QP Paid:

\$29,006.00

COE Rebate Amount:

\$4,890.00

Total Rebate Amount:

\$4,890.00

The information contained herein is correct as at 21 Oct 2019

OK

18,000
4,890

13,110

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/09/2019 15:57
Date Of Accident	23/09/2019 14:30
Exact Location Of Accident	ALONG TONG LEE BUILDING B 37 KALLANG PUDDING ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBC2399Y
Insured/Policyholder	
Name Of Registered Owner	GOLDBELL LEASING PTE LTD
Co Reg No	199001196N
Email Address	ISAACNGCL@GOLDBELLCORP.COM
Mobile Phone No	
Alternative Phone No	OFFICE-64942897

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	FB70BB1SRDEA
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	29131844
Cover Note Number	N.A

Driver

Name of Driver	MUHAMMAD FIRDAUS BIN ASANAR
NRIC No	S9207008E
Date Of Birth	05/03/1992
Occupation	OUTDOOR
Date Of Driving Pass	30/11/2011
Driving Experience	7 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87480489
Fax Number	
Contact Number	
Email Address	FIRDAUSM486@GMAIL.COM

Address NA
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 0

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I was park my lorry along Tong Lee Building B, 37 Kallang Pudding Road. I was taking my stuff into my lorry. Suddenly I felt some shaking to my lorry. Subsequently I came down and checked, they was another lorry reversing and hit onto my lorry right side mirror. Damages of my lorry right side mirror. No injuries were involved.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YK9262Y
 Vehicle Make/Model/Colour NISSAN / MKB212NHRA
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver) 1

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER
VOO CHEON YEE

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

23-9-2019

Sketch Plan #2

A. 63L2390Y
B. 7X9262Y



Along Long Lee Building B
at Railway Station Road.

DETERMINE CIRCUMSTANCES OF THE ACCIDENT

REFER TO ATTACHED STATEMENT

CONCLUSION

© 2000 Blackwell Science Ltd *Journal of Internal Medicine* 247: 391–397

YES/YES/ALAK NARS (ARCTIC)

REPORTING OFFICER _____

NOVEMBER 2005

Sketch Plan #3 Pg. 1

ACCIDENT STATEMENT (2000 characters)

I was park my lorry along Tong Lee Building B, 37 Kallang Pudding Road. I was taking my stuff into my lorry, Suddenly I felt some shaking into my lorry. Subsequently I came down and checked, they was another lorry reversing and hit onto my lorry right side mirror. Damages of my lorry right side mirror. No injuries were involved.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
JOHNNY VOO CHEON YEE

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

23 September 2019 at 3:36 PM

Date/Time:

23 September 2019 at 3:36 PM

SIN SHENG ENGINEERING SERVICES

NO 8, TUAS AVE 18,
(Level 3), SINGAPORE 638892
Tel No. : 6863-9595 Fax No. : 6863-6477
E-Mail : sinsheng1981@gmail.com
Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD
59 SENOKO ROAD
SINGAPORE 758123

Attention : Motor Claim Department
Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002987

Date : 22/10/2019
Vehicle Num. : GBC2399Y
Make/Model : MITSUBISHI FB 70-2011
Chassis/Eng# : FB70BBA20382/4M42A87814
Accident Date : 23/09/2019
Claim No. :
Reference : YK9262Y
Policy No. : 29131844

S/N	Quantity	Particular	Unit Price	Amount S\$
<div>LIST ITEMS :</div> <div>1. 1 MIRROR STAY, RHS X SUC</div> <div>2. 1 SIDE MIRROR, RHS SUC</div> <div>3. 1 MIRROR STAY COVER X SUC</div> <div>4. 1 MIRROR STAY CAP AMIS</div> <div>5. 1 CORNER PANEL, RHS AMIS X SUC</div> <div>23/10/19 Resul Hp 90010068</div> <div>1 day</div> <div>22/10/19 @ 1730</div> <div>Resul new mirror</div>				
				439.02
				165.60
				123.50
				65.90
				546.37
		List Total S\$:		1,340.39
		25.00% Discount S\$:		335.10
				1,005.29
		LABOUR :		
		TO PANEL BEAT AND REPAIR RIGHT SIDE BODY	100	250.00
		TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS		
		TO SPRAY PAINTING	150	150.00
		LOSS OF USE : 2 DAYS @ S\$120/DY		240.00
		Labour Total S\$:		400.00

Total S\$: 1,405.29

SIN SHENG ENGINEERING SERVICES

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

173.62
100.00
273.62

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19018685/R1vd3n2
73 BRAS BASAH ROAD Date: 04-11-2019
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556



ATTN: FIONA

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YK 9262Y	Veh. Inspected	GBC 2399Y
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1064166-002	Excess (\$)	0.00
Assign From	THERESA VIMALA	Assign Date	22/10/2019

2. Vehicle Particulars & Condition

Make & Model	mitsubishi FB70	c.c	2977
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	FB70BBA20382	Colour	RED
Odometer	212683 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15C	AUSTONE	7 mm
L/H Front Tyre	195 R15C	AUSTONE	7 mm
R/H Rear Tyre	195 R15C (D)	AUSTONE	7/7 mm
L/H Rear Tyre	195 R15C (D)	AUSTONE	7/7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	23/09/2019	Inspect Date / Time	22/10/2019 (05:32 PM)
Survey held at	NO 8 TUAS AVENUE 18		
Repairer	SIN SHENG ENGINEERING SERVICES		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	1 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 2399Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	MIRROR STAY,RHS	SERVICEABLE	439.02	-
1	SIDE MIRROR,RHS	SCRATCHED	165.60	165.60
1	MIRROR STAY COVER	SERVICEABLE	123.50	-
1	MIRROR STAY CAP	MISSING	65.90	65.90
1	CORNER PANEL,RHS	SERVICEABLE	546.37	-
	LESS 25% DISCOUNT		-335.10	-57.87
			1,005.29	173.63
	LABOUR			
	TO PANEL BEAT AND REPAIR RIGHT SIDE BODY TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS.		250.00	100.00
	TO SPRAY PAINTING.	NOT NECESSARY	150.00	-
			400.00	100.00
	GRAND TOTAL		1,405.29	273.63
	RECOMMENDED COST OF REPAIRS (CONFIRMED)			273.63

Report Ref No. CS/INC19018685/R1vd3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.