

Asher



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 21/10/2019

User ID : BoonChewTay

Section A - Accident Details	
Registration Number	SMB1364D
Case Reference Number	BUS/10/19/1043
Registration Date	17/5/2013
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Paw Seng Yong
Type of Accident	Side Swipe
Accident Date and Time	19/10/2019 5:09 PM
Accident Reported Date and Time	19/10/2019 6:48 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB1364D-RIGHT REAR PORTION SUJ041A (TP) INSURED WITH
Prepared Date and Time	21/10/2019 1:31 PM
Chassis Number	WMAA22ZZ6D7001813
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$795.00	\$0.00
Total Spray Cost	\$786.00	\$0.00
Total Spare Part Cost	\$1,739.38	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$3,320.38	\$0.00
Lump Sum Total	\$3,300.00	\$0.00
Number of Repair Days	3.0	2
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	21/10/2019 2:13 PM	
Signature		
Remarks		

21/10/19, 2:15pm
Store (LKK) via Pp/L
2 LG
L/S
Ry AL sy

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 21/10/2019

User ID : BoonChewTay

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$795.00	530
Total Labour	\$795.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$786.00	616
Total Spray Painting & Panel Beating	\$786.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010299	VE	88-25320-6008	LAMP INDICATOR LED (MAN BUS)	1.00	\$1,274.10	10.00	\$1,146.69	Replace	UR
6010298	VE	88-25225-6039	LAMP STOP LED (MAN BUS)	1.00	\$1,141.70	10.00	\$1,027.53	Replace	UR
5009991	BODY RH	4000F06-ACCE4526	PANEL SIDE R10, FOR MAN A22 BUS	1.00	\$192.70	100.00	\$0.00	Repair	LR
6009992	BODY RH	A01001-CW564	PANEL SIDE R11, FOR MAN A22 BUS	1.00	\$1,782.50	100.00	\$0.00	Repair	LR
6010062	Body	F01001-CW273	COVER REAR TAIL LAMP RH, FOR MAN A22 BUS	1.00	\$974.70	100.00	\$0.00	Repair	LR
Total					\$5,365.70		\$2,174.22		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672



Date Generated : 29/10/2019

User ID : CatherineLee

Section A - Accident Details

Registration Number	SMB1364D
Case Reference Number	BUS/10/19/1043
Registration Date	17/5/2013
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Paw Seng Yong
Type of Accident	Side Swipe
Accident Date and Time	19/10/2019 5:09 PM
Accident Reported Date and Time	19/10/2019 6:48 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24103939
Special Instruction to ARC, if any	SMB1364D-RIGHT REAR PORTION SJUB041A (TP) INSURED WITH
Prepared Date and Time	21/10/2019 1:31 PM
Chassis Number	WMAA22ZZ6D7001813
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$795.00	\$530.00
Total Spray Cost	\$786.00	\$616.00
Total Spare Part Cost	\$1,739.38	\$1,739.38
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$3,320.38	\$2,885.38
Lump Sum Total	\$3,300.00	\$2,900.00
Number of Repair Days	3.0	2.0
Prepared / Adjusted By	Boon Chew Tay	STEVE CHEN
ARC / Surveyor Sign Off Date	21/10/2019 2:13 PM	21/10/2019 3:10 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 29/10/2019

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$795.00	\$530.00
Total Labour	\$795.00	\$530.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$786.00	\$616.00
Total Spray Painting & Panel Beating	\$786.00	\$616.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010299	VE	88-25320-6008	LAMP,INDICATOR:LED (MAN BUS)	1.00	\$1,274.10	10.00	\$1,146.69	Replace	Replace
6010298	VE	88-25225-6039	LAMP,STOP:LED (MAN BUS)	1.00	\$1,141.70	10.00	\$1,027.53	Replace	Replace
6009991	BODY RH	4000F06-ACCE4526	PANEL,SIDE:R10,FOR MAN A22 BUS	1.00	\$192.70	100.00	\$0.00	Repair	Repair
6009992	BODY RH	A01001-CW564	PANEL,SIDE:R11,FOR MAN A22 BUS	1.00	\$1,782.50	100.00	\$0.00	Repair	Repair
6010062	Body	F01001-CW273	COVER:REAR TAIL LAMP,RH,FOR MAN A22 BUS	1.00	\$974.70	100.00	\$0.00	Repair	Repair
Total					\$5,365.70		\$2,174.22		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									