

ASS. REC. BY:

REF:

08/01/2019 8:16/11/23

Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

Minister

From (Person): Ruth Chua Gek-hang

of

SMD

Date/Time: 22/10/2019 6:42pm

Estimated Cost:

Bill to:

OD / ET / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No:

SFZ 8892G

Insured:

SLD 424Y

at Workshop m/s

Liu's Brother

Tel:

67411736

of

1 Kaki Bukit Ave 6 # 01-01

Policy No:

DIAM TPR 01008145

Claim No:

CHTD 1904961

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21/10/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9:07am 23/10/19

Person Contacted:

Suen

Vehicle IN / OUT

Date/Time

Action/Instruction

Estimated /

SFZ 8892G - X

SLD 424Y - X

23/10/19 @

11am informed Ruth Chua, we are pending estimate from repairer.

04/11/19 @

11.5am revised to Ruth Chua via Messenger.

ASS. REC. BY:

MCRWJ

Ref:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

1586

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SFZ 8892G

Yr Regn:

11/14

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAI

Make:

Toyota Corolla Altis 1598

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading

78383

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MR053REH104.518991

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIO / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

21/10/19

D.O.I.

24/10/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LTA 4522 Dep 9k. 4th 8478

LTA 3500 Conf. with Subm. (Ref 5891.60, 6316)

RECEIVED: 2019

Date/Time, File Pass to?

11/11/19 10:00 AM

Prel. Report

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Weld and

Survey Fee:

250

Transportation:

S + RS, SI

Photos

Others

Total

Report Format:

MER-7P

Lump Sum / H.R.:

3500

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Oct 2019		22 Oct 2019 18:42 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	NANG KHAM, ID: G1461611Q, Tel: +6582647609, Email: richard20080126@gmail.com		
Main Claimant:	VU MEI I, ID: S2596783F		
Vehicle Reg. No.:	SFZ8892G	Date of Loss:	21/10/2019 10:00 - :59
Claim Type:	TP / CMTD1904961	Policy/Cover Note No.:	D19MTPV01008145 (Comprehensive)
Vehicle Reg. No. (Insured):	SLD424Y	Policy No. (Claimant):	
		Excess:	
Repairer:	Liu's Brother Auto Engineering Workshop (HQ) BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel:		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Ruth Chua Gek Tiang - 6329 5153]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 01/11/2019]		
Driver/Custodian (Insured):	NANG KHAM (33 / Female) , NRIC: G1461611Q, Tel: +6582647609 Email: richard20080126@gmail.com		
Adj Asg. Remarks:	Susan Low-67411730		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: IRENE JAMES HENRY

Date: 04 Nov 2019

Preliminary Advice

Insured Vehicle No	: SLD424Y	Accident Date	: 21/10/2019
TP Vehicle No	: SFZ8892G	Assignment Date	: 22/10/2019
Make	:	Est. Duration of Repair	: 4.00
Date of Inspection	: 22/10/2019		
Inspection At	: LIU'S BROTHER AUTO ENGINEERING WORKSHOP (HQ) BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,391.60
Revised Amount	:S\$	4,387.58
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,387.58

Lump Sum Repair	:S\$	3,500.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Wednesday, 23 October 2019 11:00 AM
To: do-not-reply@merimen.com
Cc: SUR
Subject: TP VEHICLE SFZ 8892G (YOUR REF: CMTD1904961)

This mail is associated with :

***SFZ8892G (CMTD1904961)**

[SLD424Y]

TP

VU MEI I

Oct 21 2019 10:00AM

[NANG KHAM]

Liu's Brother Auto Engineering Workshop

Dear Ruth,

Please be informed that we have inspected the vehicle SFZ 8892G on 22/10/2019.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)

MSMEP191206547 SME Motor Pte Ltd - Kaki Bukit
ENTRY DATE & TIME: 21/10/2019 17:58
SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent in the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/10/2019 17:58
Date Of Accident	21/10/2019 10:05
Exact Location Of Accident	HDB HUB CARPARK (TOA PAYOH)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SF28892G
Insured/Policyholder	
Name Of Registered Owner	VU MEI I
NRIC No	S2596783F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98562008
Alternative Phone No	OFFICE-98562008

Vehicle Particulars

Manufacturer	TOYOTA
Model	ALTIS

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100392839
Cover Note Number	

Driver

Name of Driver	VU MEI I
NRIC No	S2596783F
Date Of Birth	01/05/1953
Occupation	INDOOR
Date Of Driving Pass	16/05/1990
Driving Experience	29 YEARS AND 4 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98562008
Fax Number	
Contact Number	OFFICE-98562008
Email Address	NOEMAIL

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firm, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police) for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and;
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulatory, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders;



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

LIAISON BROKER

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	783F
Vehicle Details	
Vehicle No.:	SFZ8892G
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Oct 2019
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA COROLLA ALTIS 1.6L CVT
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	1ZRY113854
Chassis No.:	MR053REH104518991
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$19,144.00
Original Registration Date:	19 Nov 2014
First Registration Date:	19 Nov 2014
Transfer Count:	0
Actual ARF Paid:	\$14,144.00 7072
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Nov 2024
PARF Rebate Amount:	\$10,608.00
Intended COE Rebate Details	
COE Expiry Date:	18 Nov 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$64,900.00
COE Rebate Amount:	\$32,914.00
Total Rebate Amount:	\$43,522.00

The information contained herein is correct as at 22 Oct 2019

OK

altis Price Range Depreciation 2014 Vehicle Type Submit

Advanced Search

Home » Used Cars » Car Times Automobile Pte Ltd » Toyota Corolla Altis 1.6A

Toyota Corolla Altis 1.6A

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map



An Award-Winning Premier Automotive House



Price	\$52,800		
Depreciation	\$9,300 /yr View models with similar depre	Reg Date	01-Oct-2014 (4yrs 11mths 8days COE left)
Mileage	99,000 km (19.6k /yr)	Manufactured	2014
Road Tax	\$742 /yr	Transmission	Auto
Dereg Value	\$41,501 as of today (change)	OMV	\$18,650
COE	\$64,600	ARF	\$13,650
Engine Cap	1,598 cc	Power	90.0 kW (120 bhp)
Curb Weight	1,205 kg	No. of Owners	2

Type of Vehicle Mid-Sized Sedan

Features

1.6L Dual VVT-i 4 Cylinder Inline 16 Valves Engine With Super CVT Auto Transmission, ABS, Airbags, Keyless Start/Entry, Etc. [View specs of the Toyota Corolla Altis \(2014\)](#)

Accessories

Keyless Entry, Sports Rims, Front&Back Recording Cam, Original Toyota Player, Auto Headlight, LED

Description

In-House Warranty, Free Servicing Before Delivery, \$0 Drive Away Available! View To Believe Condition! Buy From Trustworthy Dealer And We Will Workout A Win Win Package For Your Dream Car. Unit Is Available For Viewing Now!

Category

PARF Car

Status

Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. [Find out more](#)

Compare

Car Valuation - Free



Location Map

Price Chart

Summary

[Click on the point to view the vehicle](#)

Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Company

Car Times Automobile Pte Ltd

* dealer's pricelist

* 27 vehs sold | 20 vehs available

Address

61 Ubi Avenue 2 #03-16

[Search cars nearby this location](#)



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-19-173993

Date of Request: 22/10/2019

Your Ref No:

Online Purchase

LIU'S BROTHER AUTO WORKSHOP

1 Kaki Bukit Ave 6 #01-01

Auto Bay@Kaki Bukit

Singapore 417883

Dear Sir/Madam,

Enquiry Date 22/10/2019
Enquiry By Susan Low Siew Yian
TP Vehicle No. SLD424Y
Accident Date 21/10/2019

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLD424Y	Sompo Insurance Singapore Pte. Ltd.	31/05/2019-30/05/2020	6461 6555

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 532917931, Tel: 6741-1730 / 731, Fax: 6744-5746, Email: liusbros@gmail.com

Invoice/Ref No: SFZ8892G191021

Estimate

Customer

Name: Somp Insurance Singapore Private Limited

Date: 22-10-19

Address: Motor Claims Department

Vehicle No: SFZ8892G

50 Raffles Place #05-01 / 06

Model/Make: Toyota Corolla

Singapore Land Tower Singapore 048623

Altis 1.6 Dual

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Fender <i>Body</i>	\$ 766.10	
2	Fender "VVTI" Emblem <i>new</i>	\$ 48.20	
3	Fender Inner Shield <i>Del/To-1</i>	\$ 181.50	
4	Fender Inner Shield Clips 1 Set <i>new</i>	\$ 50.00	
5	Sport Rim <i>cut/beat</i>	\$ 680.00	
6	Knuckle Arm <i>su</i>	\$ 545.10	X
7	Knuckle Arm Bearing <i>77</i>	\$ 185.20	X
8	Lower Arm <i>su</i>	\$ 488.50	X
9	Door <i>DD/beat</i>	\$ 1,099.10	
10	Door Frame "Black" Sticker 1 Set <i>new</i>	\$ 89.90	
11	Door Inner Rubber <i>new</i>	\$ 209.20	
12	Door Inner Lock <i>su</i>	\$ 399.50	X
13	Door Hinges 02 pcs (@ \$575.50) <i>lower beat</i>	\$ 151.00	X
14	Door Checker <i>twl</i>	\$ 139.10	
15	Door Mirror <i>su</i>	\$ 866.50	X
16	Door Glass Regulator <i>beat/su</i>	\$ 311.50	X
17	Rear Door <i>R</i>	\$ 1,021.20	X
	To check all wiring & electrical component for proper function	\$ 50.00	20
	To remove, replace and transfer door panel, fitting and mechanisms	\$ 80.00	60
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 80.00	60
	To check and re-adjust wheel alignment	\$ 120.00	80
	To Dismantle & Replacing Undercarriage parts & components	\$ 150.00	11X
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 680.00	550
	To putty & spray painting & including touch up paint on accident affected	\$ 1,000.00	880

Total Parts & Labour of estimate for damaged vehicle

\$ 9,391.60

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Authorized
26/10/19
22/10/19
Whe ph. After repair
2/5 to 3500/
4 day.

P-3650.10

252

2737.57

4387.57

3510.05

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Oct 2019		22 Oct 2019 18:42 Edit Adj Rpt	S\$3,500.00 Edit Estimates	S\$3,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	NANG KHAM, ID: G1461611Q, Tel: +6582647609, Email: richard20080126@gmail.com			
Main Claimant:	VU MEI I, ID: S2596783F			
Vehicle Reg. No.:	SFZ8892G	Date of Loss:	21/10/2019 10:00 - :59 [59 Months and 2 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / CMTD1904961	Policy/Cover Note No.:	D19MTPV01008145 (Comprehensive)	
Vehicle Reg. No. (Insured):	SLD424Y	Policy No. (Claimant):		
		Excess:		
Repairer:	Liu's Brother Auto Engineering Workshop (HQ) BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel:			
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by IRENE JAMES HENRY - 6322 4618]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 01/11/2019]			
Driver/Custodian (Insured):	NANG KHAM (33 / Female), NRIC: G1461611Q, Tel: +6582647609 Email: richard20080126@gmail.com			
Adj Asg. Remarks:	Susan Low-67411730			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SFZ8892G (CMTD1904961)**
[SLD424Y]

TP

VU MEI I

Oct 21 2019 10:00AM

[NANG KHAM]

Liu's Brother Auto Engineering Workshop

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/11/19 11:57	Adjuster Immediate Advice	 Load HTM	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/11/19 12:00	Odometer Reading	 Load JPG	☒
2	04/11/19 12:00	Chassis Number	 Load JPG	☒
3	04/11/19 12:00	General View	 Load JPG	☒
4	04/11/19 12:00	General View	 Load JPG	☒
5	04/11/19 12:00	General View	 Load JPG	☒
6	04/11/19 12:00	General View	 Load JPG	☒
7	04/11/19 12:00	General View	 Load JPG	☒
8	04/11/19 12:00	General View	 Load JPG	☒
9	04/11/19 12:00	General View	 Load JPG	☒
10	04/11/19 12:00	General View	 Load JPG	☒
11	04/11/19 12:00	General View	 Load JPG	☒
12	04/11/19 12:00	General View	 Load JPG	☒
13	04/11/19 12:00	General View	 Load JPG	☒
14	04/11/19 12:00	General View	 Load JPG	☒
15	04/11/19 12:00	General View	 Load JPG	☒
16	04/11/19 12:00	General View	 Load JPG	☒
17	04/11/19 12:00	General View	 Load JPG	☒
18	04/11/19 12:00	General View	 Load JPG	☒
19	04/11/19 12:00	General View	 Load JPG	☒
20	04/11/19 12:00	General View	 Load JPG	☒
21	04/11/19 12:00	General View	 Load JPG	☒
22	04/11/19 12:00	General View	 Load JPG	☒
23	04/11/19 12:00	General View	 Load JPG	☒
24	04/11/19 12:00	General View	 Load JPG	☒
25	04/11/19 12:00	General View	 Load JPG	☒
26	04/11/19 12:00	General View	 Load JPG	☒
27	04/11/19 12:00	General View	 Load JPG	☒
28	04/11/19 12:00	General View	 Load JPG	☒
29	04/11/19 12:00	General View	 Load JPG	☒
30	04/11/19 12:00	General View	 Load JPG	☒
31	04/11/19 12:00	General View	 Load JPG	☒
32	04/11/19 12:00	General View	 Load JPG	☒
33	04/11/19 12:00	General View	 Load JPG	☒
34	04/11/19 12:00	General View	 Load JPG	☒
35	04/11/19 12:00	General View	 Load JPG	☒
36	04/11/19 12:00	General View	 Load JPG	☒
37	04/11/19 12:00	General View	 Load JPG	☒

Assessment Reports			1 per page ▼	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	04/11/19 12:00	General View	 Load JPG	✓
39	04/11/19 12:00	General View	 Load JPG	✓
40	04/11/19 12:00	General View	 Load JPG	✓
41	04/11/19 12:00	General View	 Load JPG	✓
42	04/11/19 12:00	General View	 Load JPG	✓
43	04/11/19 12:00	General View	 Load JPG	✓
44	04/11/19 12:01	Reinspection Photo	 Load JPG	✓
45	04/11/19 12:01	Reinspection Photo	 Load JPG	✓
46	04/11/19 12:01	Reinspection Photo	 Load JPG	✓
47	04/11/19 12:01	Reinspection Photo	 Load JPG	✓
48	04/11/19 12:01	Reinspection Photo	 Load JPG	✓
49	04/11/19 12:01	Reinspection Photo	 Load JPG	✓
50	04/11/19 12:01	Reinspection Photo	 Load JPG	✓
51	04/11/19 12:01	Reinspection Photo	 Load JPG	✓
52	04/11/19 12:01	Reinspection Photo	 Load JPG	✓
53	06/11/19 17:20	After Repair Photo	 Load JPG	✓
54	06/11/19 17:20	After Repair Photo	 Load JPG	✓
55	06/11/19 17:20	After Repair Photo	 Load JPG	✓
56	06/11/19 17:20	After Repair Photo	 Load JPG	✓
57	06/11/19 17:20	After Repair Photo	 Load JPG	✓
58	06/11/19 17:20	After Repair Photo	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	22/10/19 18:40	Third Party E-filed GIA report	 Load PDF	
2	22/10/19 18:40	Pre-Repair Survey-LIU BROS ACK/AGREE LKK AUTO	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19018716/UQD3S2
Date: 07/11/2019

REFERENCE

Handling Insurer: Sompo Insurance Singapore Pte. Ltd. Policy No: D19MTPV01008145
Claimant Vehicle No : SFZ8892G **Insured Vehicle No :** SLD424Y
 Date of Loss: 21/10/2019 Nature of Claim: TP Claim No: CMTD1904961

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFZ8892G**
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 1ZRY113854
 Reg. Date: 19/11/2014 (Man. Year: 2014) Chassis No: MR053REH104518991
 Colour: White Odometer: 78383 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm
 Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,231.60	2,737.57	4,494.03	62.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,160.00	1,650.00	510.00	23.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,391.60	4,387.57	5,004.03	53.28
Approved Total (Overridden) (S\$)		3,500.00		
(S\$)	9,391.60	3,500.00	5,891.60	62.73
+ GST 7.00/7.00% (S\$)	657.41	245.00	412.41	62.73
Nett Amount (S\$)	10,049.01	3,745.00	6,304.01	62.73

INSPECTION

Date of Assignment: 22/10/2019
 Date Inspected: 22/10/2019 Inspected At: Liu's Brother Auto Engineering Workshop (HQ)
 BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @
 KAKI BUKIT
 Singapore 417883
 Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Nov 2019)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFZ8892G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Badly Dented	766.10 F	*766.10 FL
2	1		*FRONT FENDER VVTI EMBLEM	Necessary	48.20 F	*48.20 FL
3	1		*FRONT FENDER INNER SHIELD	Deformed / Torn	181.50 F	*181.50 FL
4	1		*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	50.00 F	*50.00 FL
5	1		*FRONT SPORT RIM	Cut / Bent	680.00 F	*680.00 FL
6	1		*FRONT KNUCKLE ARM	Serviceable	545.10 F	*- FL
7	1		*FRONT KNUCKLE ARM BEARING	Not Necessary	185.20 F	*- FL
8	1		*FRONT LOWER ARM	Serviceable	488.50 F	*- FL
9	1		*FRONT DOOR	Dented / Bent	1,099.10 F	*1,099.10 FL
10	1		*SET FRONT DOOR FRAME BLACK STICKER	Necessary	89.90 F	*89.90 FL
11	1		*FRONT DOOR INNER RUBBER	Necessary	209.20 F	*209.20 FL
12	1		*FRONT DOOR INNER LOCK	Serviceable	399.50 F	*- FL
13	1		*FRONT DOOR HINGES	Lower Bent	151.00 F	*75.50 FL
14	1		*FRONT DOOR CHECKER	Twisted	139.10 F	*139.10 FL
15	1		*FRONT DOOR MIRROR	Serviceable	866.50 F	*- FL
16	1		*FRONT DOOR GLASS REGULATOR	Bent / Jammed	311.50 F	*311.50 FL
17	1		*REAR DOOR	Repair	1,021.20 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	7,231.60	3,650.10
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	912.53
Total Parts (\$\$)	7,231.60	2,737.57

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION.	New	50.00	20.00
2	TO REMOVE, REPLACE AND TRANSFER DOOR PANEL FITTING AND MECHANISMS.	New	80.00	60.00
3	TO APPLY RUST PROOFING, RESEAL RUFF-COATING TREATMENT ON ACCIDENT AREA.	New	80.00	60.00
4	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	New	120.00	80.00
5	TO DISMANTLE & REPLACING UNDERCARRIAGE PARTS & COMPONENTS.	New	150.00	0.00
6	LABOR & PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS.	New	680.00	550.00
7	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED.	New	1,000.00	880.00
Gross Labour Cost (\$\$)			2,160.00	1,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >