

27/03/2002

ASS. REC. BY:

REF: CS/CT119618751 / Rlvf307 Special Instruction:

Surveyor: Rasul

ASSIGNMENT (Office)

From (Person): Chong Boon Sen of CTI

Date/Time: 23.10.19 9.48a.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBG 5699R Insured:

at Workshop m/s Triple - T Automobile Tel: 98535175

of BIK 6 DeFu Lane 10 #01-574

Policy No: DMCVSN3075531902 Claim No: SNM19D204998C01

Sum Insured: Excess: \$3000.00

Make of Veh: D.O.A. 18.10.19

(Client's Record) 2) 7.30 p.m

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 23.10.19 12.04pm Person Contacted: Irene Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate Inspection: 25 Kaki Bukit road 4 #08-43 synggy.
	GBG 5699R - CS/CT119618751 / Rlvf3 D.O.A - 18/10/2019
24/10/19	Revert via Merimen
25/10/19	Rece approved \$2900 from Boon Sen by merimen
25/10/19	Informed Irene c/A ex \$3000 by email
26/11/19	@530pm Irene said ok withdraw claim

ASS. REC. BY Kasaul

680H

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 @ / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: GBG 5699R
 at Workshop m/s TRIPLE - T
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: 3000
 (Client's Record)
 Make of Veh: _____

Veh No: GBG 5699R Yr Regn: 2017 / Aug
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: TOYOTA DYNA 150 MT c.c. 2982
 Colour: WHITE A/C: Insured / Std / NI / NA
 Sp. Reading: 85299 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JTFAT35470K 208481
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 195/75R15
 R: 155R12C

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front: R/Bal. 7 mm L/Bal. 7 mm D.O.A. 18/10/19
 Rear: R/Bal. 6/6 mm L/Bal. 6/6 mm D.O.I. 23/10/19 @ 7:30pm
 Survey held at TRIPLE - T
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
0/S FRNT
 The U/C / Chassis frame / Body Structure affected due to collision.

Bal. or Market Value: 51K
 IDAC Accident Rport: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction
<u>19/12/19</u>	<u>Submit preli report</u>
RECEIVED 19 DEC 2019	

Date/Time, File Pass to? Prel. Report
 Final Report
 1) _____
 Date/Time, File Return to?
 2) 19/12 - typist
 Report Format: _____
 Lump Sum / T.B. / L.S. _____

Days Of Repair: 4
 Resurvey No. of Trip: _____
 Add Fee: Site Insp (\$) Interview (\$) Tech. Invs (\$) Wheel end (\$)
 Survey Fee: 270
 Transportation: _____ \$ + RS _____ \$
 Photos: _____
 Other: _____
 TOTAL: 270

You are returning to a previous page. This page may be outdated.
Please click 'Refresh' to refresh the page.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Oct 2019		23 Oct 2019 09:36 Edit Adj Rpt				Pending for Survey Report Cancel Case

[Show All](#)

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]			
Insured:	GUAN LEE VEGETABLES & FRUITS PTE LTD, Co. Reg. No.: -		
Vehicle Reg. No.:	GBG5699R	Date of Loss:	18/10/2019 19:00 - :59
Claim Type:	OD / SNM19D204998C01	Policy/Cover Note No.:	DMCVSN3075531902 (Comprehensive)
		Excess:	S\$3,000.00
Repairer:	Triple- T Automobile (HQ) BLK 5 DEFU LANE 10, #01-574, 539186 Defu Lane - Tel: 68585011		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 04/11/2019]		
Driver/Custodian:	ROKIMIN BIN UDA DIN (38 / Male), NRIC: G2523728K, Tel: +6597339433 Email: NOEMAIL		
			View All Compose Case Mail

ASSOCIATED MAIL RECEIVED

- CHINA_TAIPING (23/10/2019): Cancellation of Assignment: GBG5699R

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 25 October 2019 12:34 PM
To: SUR; MOTOR@IACONSULTINGSG.COM
Subject: GBG 5699R-DOA: 18/10/2019 @ 19:30PM (CHINA TAIPING OD)

Dear Irene,

As instructed by our client , please proceed to repair the **insured vehicle GBG 5699R on Lump Sum Repair, (Excess S3000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***GBG5699R (SNM19D204998C01)**
OD
Oct 18 2019 7:00PM
[GUAN LEE VEGETABLES & FRUITS PTE LTD]
Triple- T Automobile

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 25/10/2019 10:59 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$2900.00) - GBG5699R - Claim Handler: Chong Boon Sen

Approved:2900.00.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd. 3 Anson Road #16-00 Springleaf Tower Singapore 079909	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Chong Boon Sen	Date: 24 Oct 2019
<u>Preliminary Advice</u>	

Vehicle No	: GBG5699R	Accident Date	: 18/10/2019
Make	: TOYOTA DYNA 1.5T	Policy No.	: DMCVSN3075531902
Assignment Date	: 23/10/2019	Excess	: S\$3,000.00
Date of Inspection	: 23/10/2019	Est. Duration of Repair	: 4
Inspection At	: TRIPLE-T AUTOMOBILE		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,954.23	
Revised Amount	:S\$	2,678.16	
Check Items (Estimated)	:S\$	945.07	
Total	:S\$	3,623.23	
Lump Sum Repair (Estimated)	:S\$	2,900.00	
Total Loss Consideration			
New for Old Value	:S\$		
Pre-Accident Value	:S\$	51,000.00	
COE / PARF Rebate	:S\$	23,888.00	
Salvage Value	:S\$		
Margin for Repair	:S\$	27,112.00	

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Wednesday, 23 October 2019 9:48 AM
To: assignments
Cc: Eddie Sim
Subject: RE: snm19d204998c01 / OD CLAIM / GBG5699R / DATE OF ACCIDENT 18.10.19

Dear LKK,

Pls note above is another accident reference.

Same as below handling method.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Chong Boon Sen

Sent: Wednesday, October 23, 2019 9:38 AM

To: assignments <assignments@lkkauto.com>

Cc: Eddie Sim <eddie.sim@sg.cntaiping.com>

Subject: SNM19D204997C01 / OD CLAIM / GBG5699R / DATE OF ACCIDENT 18.10.19

Importance: High

Dear LKK,

Refer to above matter assigned to you.

As there are 2 accidents in same date but different time which we will assign to you for OD as well, kindly assist to check consistency for 2 accidents.

Thank you very much.

Meanwhile, cost + 15%.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	860H
Vehicle Details	
Vehicle No.:	GBG5699R
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Oct 2019
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 5MT
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	1KD2731122
Chassis No.:	JTFAT35Y70K208481
Maximum Power Output:	-
Open Market Value:	\$26,436.00
Original Registration Date:	31 Aug 2017
First Registration Date:	31 Aug 2017
Transfer Count:	1
Actual ARF Paid:	\$1,322.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Aug 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$30,423.00
COE Rebate Amount:	\$23,888.00
Total Rebate Amount:	\$23,888.00

The information contained herein is correct as at 23 Oct 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	21/10/2019 15:47
Date Of Accident	18/10/2019 19:30
Exact Location Of Accident	KAKI BUKIT RD 3 TWDS KAKI BUKIT AVE 3
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	GBG5699R
Insured/Policyholder	
Name Of Registered Owner	GUAN LEE VEGETABLES & FRUITS PTE LTD
Co Reg No	-
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-97339433
Vehicle Particulars	
Manufacturer	TOYOTA
Model	DYNA
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN3075531902
Cover Note Number	
Driver	
Name of Driver	ROKIMIN BIN UDA DIN
Passport No/FIN	G2523728K
Date Of Birth	17/06/1981
Occupation	OUTDOOR
Date Of Driving Pass	11/07/2019
Driving Experience	0 YEAR AND 3 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-97339433
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address BLK 10 PASIR PANJANG WHOLESALE CENTRE #01-479
 Postcode 110010
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SGY800T
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **reassess policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIAs Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC / FIN No.:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On mentioned date & time, I was travelling along Kaki Bukit Road 3 towards Kaki Bukit Ave 3.

When I was turning right to Kaki Bukit Ave 3, suddenly hit onto the vehicle SGY800T right position.

That's all.

DECLARATION
I/we declare the foregoing particulars are true in every respect.

Policyholder's
Date & Time



Driver's Signature
(If driver is not the policyholder)
Date & Time

A handwritten signature in black ink, appearing to be 'W'.

Recording Centre Personnel's Signature
Name:
NRIC/FIN No:

A handwritten signature in black ink, appearing to be 'H'.

TRIPLE-T AUTOMOBILE

BLK 5 DEFU LANE 10 #01-574 SINGAPORE 539186

TEL: 6280 8927 FAX: 6280 4205

Vehicle No: GBG5699R
 Model No. Toyota Dyna
 Chassis no. *

Accident Date : 18/10/2019
 Owner : Guan Lee Vegetables & Fruits Pte Ltd
 Date of Estimate : 22/10/2019

Estimate for Accident Vehicle No. GBG5699R

<u>List Items:</u>	Qty	Unit Price	Total Amount
1 Front door rh <i>bt ✓</i>	1	\$658.90	\$658.90
2 Front door hinge rh <i>?</i>	1	\$64.20	\$64.20
3 Front door hinge lower rh <i>?</i>	1	\$64.20	\$64.20
4 Front door inner board rh <i>?</i>	1	\$358.90	\$358.90
5 Front door weatherstrip rh <i>re ✓</i>	1	\$114.50	\$114.50
6 Front door inner lock rh <i>jam ✓</i>	1	\$198.00	\$198.00
7 Front door lower rubber <i>re ✓</i>	1	\$85.00	\$85.00
8 Front door regulator gear rh <i>?</i>	1	\$144.50	\$144.50
9 Front door regulator motor rh <i>?</i>	1	\$190.00	\$190.00
10 Front door outer handle rh <i>Xsu</i>	1	\$98.00	\$98.00
11 Front door channel rh <i>Xsu</i>	1	\$132.00	\$132.00
12 Front wheel arch panel garnish rh <i>Xsu</i>	1	\$110.00	\$110.00
13 Front windscreen pillar A - repair	1	\$278.50	\$0.00
14 Front driver floor panel - repair	1	\$312.50	\$0.00
15 Front step garnish rh <i>ca ✓</i>	1	\$142.00	\$142.00
16 Cabin rear panel - repair	1	\$0.00	\$0.00
17 Rear platform frame rh - repair <i>✗</i>	1	\$0.00	\$0.00
		Bal c/d	\$2,360.20
		Add 15%	\$354.03
		Sub-Total	\$2,714.23

Special Nett Items

	Qty	Unit Price	Total Amount
1 Front door company address sticker rh <i>re ✓</i>	1	\$450.00	\$450.00 <i>Zero</i>
2 Front door LTA sticker rh <i>re ✓</i>	1	\$40.00	\$40.00
		Sub-Total =	\$490.00
		Total cost for parts =	\$490.00

Labour charges

- 1 Panel beating for replace and repair affected parts
- 2 Spray painting - cabin rear panel, front door rh
- 3 Apply putty and anti-corrosion to affected parts.
- 4 Wiring / bulb checking
- 5 Transfer door mechanisms rh

500 400	\$1,050.00
450	\$550.00
	\$20.00
	\$30.00
60	\$100.00
	\$1,750.00

Total parts	=	\$3,204.23
Total labour	=	\$1,750.00
Total Amount	=	\$4,954.23

[Handwritten Signature]
25/10/19

5673 88
Rasul
Hp 90010068

4 days

4s

23/10/19 @ 1110

EXCESS: 3000

REVERT

Reay after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Oct 2019		23 Oct 2019 09:36 Edit Adj Rpt	S\$2,678.16 Edit Estimates	S\$2,678.16 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	GUAN LEE VEGETABLES & FRUITS PTE LTD, Co. Reg. No.: -								
Vehicle Reg. No.:	GBG5699R	Date of Loss:	18/10/2019 19:00 - :59 [25 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / SNM19D204998C01	Policy/Cover Note No.:	DMCVSN3075531902 (Comprehensive)						
		Excess:	S\$3,000.00						
Repairer:	Triple- T Automobile (HQ) BLK 5 DEFU LANE 10, #01-574, 539186 Defu Lane - Tel: 68585011								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 04/11/2019]								
Driver/Custodian:	ROKIMIN BIN UDA DIN (38 / Male), NRIC: G2523728K, Tel: +6597339433 Email: NOEMAIL								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> CHINA_TAIPING (25/10/2019): Alert - Adj Mandate Approved (S\$2900.00) - GBG5699R - Claim Handler: Chong Boon ... CHINA_TAIPING (23/10/2019): Cancellation of Assignment: GBG5699R 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBG5699R (SNM19D204998C01)
 OD
 Oct 18 2019 7:00PM
 [GUAN LEE VEGETABLES & FRUITS PTE LTD]
 Triple- T Automobile

Upload Documents		Upload Photos		Compose New Letter		View	View in Browser
Assessment Reports						1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print		
1	24/10/19 10:38	LKK Auto Consultants Pte Ltd (HQ) Adjuster Immediate Advice			Load HTM		
Photos/Images						3 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print		
1	21/10/19 15:53	National Assessment Centre Services (Ubi) Accident Photo <small>[Linked Accident Report Documents]</small>			Load JPG	<input checked="" type="checkbox"/>	
2	21/10/19 15:53	Accident Photo <small>[Linked Accident Report Documents]</small>			Load JPG	<input checked="" type="checkbox"/>	
3	21/10/19 15:53	Accident Photo <small>[Linked Accident Report Documents]</small>			Load JPG	<input checked="" type="checkbox"/>	
4	21/10/19 15:53	Accident Photo <small>[Linked Accident Report Documents]</small>			Load JPG	<input checked="" type="checkbox"/>	
5	21/10/19 15:53	Accident Photo <small>[Linked Accident Report Documents]</small>			Load JPG	<input checked="" type="checkbox"/>	
6	21/10/19 15:53	Accident Photo <small>[Linked Accident Report Documents]</small>			Load JPG	<input checked="" type="checkbox"/>	
7	21/10/19 15:53	Accident Photo <small>[Linked Accident Report Documents]</small>			Load JPG	<input checked="" type="checkbox"/>	
8	21/10/19 15:53	Accident Photo <small>[Linked Accident Report Documents]</small>			Load JPG	<input checked="" type="checkbox"/>	
9	21/10/19 15:53	Accident Photo <small>[Linked Accident Report Documents]</small>			Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder			Thumbnail	Print		
1	24/10/19 10:28	LKK Auto Consultants Pte Ltd (HQ) General View			Load PDF		
Documentation						1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print		
1	23/10/19 09:55	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) od estimate			Load PDF		
No	Finalized On			Thumbnail	Print		
1	21/10/19 15:53	National Assessment Centre Services (Ubi) Accident Sketch Plan <small>[Linked Accident Report Documents]</small>			Load JPG	<input checked="" type="checkbox"/>	
2	21/10/19 15:53	Accident Sketch Plan <small>[Linked Accident Report Documents]</small>			Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder			Thumbnail	Print		
1	24/10/19 10:29	LKK Auto Consultants Pte Ltd (HQ) MARK ESTIMATE			Load PDF		

Linked Accident Report Documents

				View	View in Browser
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
1	06/12/19 19:08	National Assessment Centre Services (Ubi) Accident Statement			Load HTM
2	06/12/19 19:08	Accident Statement			Load HTM
3	06/12/19 19:11	Accident Statement			Load HTM
4	06/12/19 19:12	Accident Statement			Load HTM
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
1	21/10/19 15:53	National Assessment Centre Services (Ubi) Accident Photo			Load JPG <input checked="" type="checkbox"/>
2	21/10/19 15:53	Accident Photo			Load JPG <input checked="" type="checkbox"/>
3	21/10/19 15:53	Accident Photo			Load JPG <input checked="" type="checkbox"/>
4	21/10/19 15:53	Accident Photo			Load JPG <input checked="" type="checkbox"/>
5	21/10/19 15:53	Accident Photo			Load JPG <input checked="" type="checkbox"/>
6	21/10/19 15:53	Accident Photo			Load JPG <input checked="" type="checkbox"/>
7	21/10/19 15:53	Accident Photo			Load JPG <input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
8	21/10/19 15:53	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	21/10/19 15:53	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	21/10/19 15:53	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	21/10/19 15:53	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="text-align: right;"> ^ v </div>
<p>Show Remarks To: <input type="checkbox"/> Handling Insurer</p> <p><small>Note: Remarks are private unless you show it to other parties.</small></p>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI19018751/R1VF3E2

Date: 31/12/2019

REFERENCE

Insured/Claimant: GUAN LEE VEGETABLES &
FRUITS PTE LTD

Policy No: DMCVSN3075531902

Date of Loss: 18/10/2019

Nature of
Claim: OD

Claim
No: SNM19D204998C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBG5699R**

Make & Model: TOYOTA DYNA 1.5T, 3.0 (A)

Reg. Date: 31/08/2017 (Man. Year: 2017)

Colour: White

Engine Capacity: 2982 cc

Market Value/New Car
Price: S\$51,000.00

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 1KD2731122

Chassis No: JTFAT35Y70K208481

Odometer: 85299 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/75 R15

Rear Tyre Size: 155 R12C (D)

Front Left Side: Bridgestone 7 mm

Rear Left Side: Bridgestone 6/6 mm

Front Right Side: Bridgestone 7 mm

Rear Right Side: Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,883.88	1,618.16	2,265.72	58.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,750.00	1,060.00	690.00	39.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	5,633.88	2,678.16	2,955.72	52.46

INSPECTION

Date of Assignment: 23/10/2019

Date Inspected: 23/10/2019 Inspected At:

25 Kaki Bukit Road 4 #08-43 Synergy
Repairer : Triple- T Automobile (HQ)

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

EXCESS : \$3,000.00

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$945.07 NETT)

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 31 Dec 2019)	
Parts:	N/A	TOYOTA DYNA 1.5T 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG5699R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT DOOR RH (WCP)	Bent	658.90 F	*658.90 F
2	1	*FRONT DOOR HINGE RH (WCP)	* Check	64.20 F	*- F
3	1	*FRONT DOOR HINGE LOWER RH (WCP)	* Check	64.20 F	*- F
4	1	*FRONT DOOR INNER BOARD RH (WCP)	* Check	358.90 F	*- F
5	1	*FRONT DOOR WEATHERSTRIP RH (WCP)	Necessary	114.50 F	*114.50 F
6	1	*FRONT DOOR INNER LOCK RH (WCP)	Jammed	198.00 F	*198.00 F
7	1	*FRONT DOOR LOWER RUBBER (WCP)	Necessary	85.00 F	*85.00 F
8	1	*FRONT DOOR REGULATOR GEAR RH (WCP)	* Check	144.50 F	*- F
9	1	*FRONT DOOR REGULATOR MOTOR RH (WCP)	* Check	190.00 F	*- F
10	1	*FRONT DOOR OUTER HANDLE RH (WCP)	Serviceable	98.00 F	*- F
11	1	*FRONT DOOR CHANNEL RH (WCP)	Serviceable	132.00 F	*- F
12	1	*FRONT WHEEL ARCH PANEL GARNISH RH (WCP)	Serviceable	110.00 F	*- F
13	1	*FRONT WINDSCREEN PILLAR A (WCP)	Repair	278.50 F	*- F
14	1	*FRONT DRIVER FLOOR PANEL (WCP)	Repair	312.50 F	*- F
15	1	*FRONT STEP GARNISH RH (WCP)	Cracked	142.00 F	*142.00 F
16	1	*CABIN REAR PANEL (NPA)	Repair	0.00 F	*- F
17	1	*REAR PLATFORM FRAME RH (NPA)	Repair	0.00 F	*- F
18	1	*FRONT DOOR COMPANY ADDRESS STICKER RH	Necessary	450.00 FS	*200.00 FS
19	1	*FRONT DOOR LTA STICKER RH	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett.

Sub Total (S\$)	3,441.20	1,438.40
+ Margin on L,N Items 15.00/15.00% (S\$)	442.68	179.76
Total Parts (S\$)	3,883.88	1,618.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING FOR REPLACE AND REPAIR AFFECTED PARTS	New	1,050.00	500.00
2	SPRAY PAINTING - CABIN REAR PANEL, FRONT DOOR RH	New	550.00	450.00
3	APPLY PUTTY AND ANTI-CORROSION TO AFFECTED PARTS	New	20.00	20.00
4	WIRING / BULB CHECKING	New	30.00	30.00
5	TRANSFER DOOR MECHANISMS RH	New	100.00	60.00
Gross Labour Cost (S\$)			1,750.00	1,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >