

ASS. REC. BY:

REF

CS/CTI/9018756/Gsd301

Special Instruction:

Surveyor: WOOCHONG

ASSIGNMENT (Office)

From (Person): Chong Boonsen

of

CTI

Date/Time: 23/10/14 @ 11:20am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No:

SMK 8623M

Insured:

GBJ 5667S

at Workshop m/s

Performance Motor

Tel:

63190174

of

303 Alexandra Road

Policy No:

Claim No:

SNM19D204867

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 11/10/2014

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 12:10pm @ 23/10/14

Person Contacted:

Online

Vehicle IN/OUT

Date/Time	Action/Instruction
	<u>Johny</u>
	<u>SMK 8623M - X</u>
	<u>GBJ 5667S - X</u>

Surveyor

kel.

REF:

CTI

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Performance Motors

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMK8623M Yr Regn: 26 Apr 2019

Type: M.Cab / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW X1 c.c. 1499

Colour: Grey A/C: Insured / Std / NI / NA

Sp.Reading: 7800 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBAJG120803.977251

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / A/Rim or

Tyre Size: F: 225/55 R17

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal: 9 mm R/Bal: 9 mm

L/Bal: 9 mm L/Bal: 9 mm

D.O.A. _____ D.O.I. 23-10-19

Survey held at w/s 12:30

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

24/10/19 Pending GIA Report

X62 confirmed P/P \$ 7,910.70 @ 5 days with Sharon
(\$ 2,472.85 Red - 24%)

RECEIVED 28 DEC 2019

26/12/2019

Date/Time, File Pass to?

26/12/19

1) Typist

Date/Time/ File Return to?

2) _____

☐ : Preli. Report

☒ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee: 770

Transportation:

____ S + RS ____ SI

Photos

Others

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

TOTAL

770

Report Format :

Lump Sum N.B.1 (\$ 7,910.70 P/P)

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Wednesday, 23 October 2019 11:20 AM
To: PBSP
Cc: assignments
Subject: RE: CAR IN FOR SURVEY TODAY : OUR REF: SNM19D204867-GBJ5667S-CBS - REQUEST FOR DIRECT SETTLEMENT - SMK8623M & GBJ5667S ON 11/10/2019

WITHOUT PREJUDICE

Dear Sir

We will be assigning M/s LKK AUTO CONSULTANTS to survey your client's vehicle.

Aside to LKK AUTO CONSULTANTS,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]

Sent: Tuesday, October 22, 2019 3:01 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: Re: CAR IN FOR SURVEY TODAY : OUR REF: SNM19D204867-GBJ5667S-CBS - REQUEST FOR DIRECT SETTLEMENT - SMK8623M & GBJ5667S ON 11/10/2019

Dear Sirs

We are agreeable to use a common surveyor below as the SJE.

LKK

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Tuesday, 22 October 2019 12:59 PM
To: PBSP <pml-pbsp@simedarby.com.sg>
Cc: Yaguel Renan Joseph Estoria <yaguel.renan.joseph@simedarby.com.sg>
Subject: RE: CAR IN FOR SURVEY TODAY : OUR REF: SNM19D204867-GBJ5667S-CBS - REQUEST FOR DIRECT SETTLEMENT - SMK8623M & GBJ5667S ON 11/10/2019

Without prejudice
Dear Sir,
LKK
STA
LBS

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: PBSP [<mailto:pml-pbsp@simedarby.com.sg>]
Sent: Tuesday, October 22, 2019 10:36 AM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>
Cc: Yaguel Renan Joseph Estoria <yaguel.renan.joseph@simedarby.com.sg>
Subject: CAR IN FOR SURVEY TODAY : OUR REF: SNM19D204867-GBJ5667S-CBS - REQUEST FOR DIRECT SETTLEMENT - SMK8623M & GBJ5667S ON 11/10/2019

Dear Sirs

Please arrange survey ASAP. Vehicle is already in workshop.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Tuesday, 22 October 2019 10:15 AM
To: Yaguel Renan Joseph Estoria <yaguel.renan.joseph@simedarby.com.sg>
Subject: Fw: OUR REF: SNM19D204867-GBJ5667S-CBS - REQUEST FOR DIRECT SETTLEMENT - SMK8623M & GBJ5667S ON 11/10/2019

From: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Sent: Tuesday, 22 October 2019 10:09 AM

To: PBSP <pml-pbsp@sime-darby.com.sg>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>
Subject: OUR REF: SNM19D204867-GBJ5667S-CBS - REQUEST FOR DIRECT SETTLEMENT - SMK8623M & GBJ5667S
ON 11/10/2019

Dear Boon Sen,

Fya

Thank you

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Owner ID Type:	Singapore NRIC
Owner ID:	170G
Vehicle No.:	SMK8623M
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Oct 2019
Vehicle Make:	B.M.W.
Vehicle Model:	X1 SDRIVE18i LED NAV
Primary Colour:	Brown
Manufacturing Year:	2018
Engine No.:	31855543838B15A
Chassis No.:	WBAJG120803G77251
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$35,224.00
Original Registration Date:	26 Apr 2019
First Registration Date:	26 Apr 2019
Transfer Count:	0
Actual ARF Paid:	\$41,314.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Apr 2029
PARF Rebate Amount:	\$30,985.00
COE Expiry Date:	25 Apr 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$48,000.00
COE Rebate Amount:	\$45,626.00
Total Rebate Amount:	\$76,611.00

The information contained herein is correct as at 23 Oct 2019

OK

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Thursday, 26 December 2019 3:26 pm
To: Sharon Heng L K
Subject: RE: DIRECT SETTLEMENT FINAL REPORT - SMK8623M

Dear Sharon,

Confirmed final fig \$7,910.70 @ 5 days of repairs before GST.

Kindly expedite the discharge voucher and tax invoice to us for close case.

"Best Wishes for Merry Christmas & Happy New Year 2020"

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Sharon Heng L K <sharon.heng.leekun@simedarby.com.sg>

Sent: Monday, 23 December 2019 11:37 am

To: Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>

Subject: FW: DIRECT SETTLEMENT FINAL REPORT - SMK8623M

Dear Quo Qiang

Please find attach invoice provided by owner

Best Regards

Sharon Heng

Performance Motors Ltd

Body & Paint

DID : 63190123

Fax : 64743229

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 11/10/2019 15:15
 Date Of Accident 11/10/2019 11:30
 Exact Location Of Accident ANG MO KIO AVE 3
 Country/State Of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMK8623M
Insured/Policyholder
 Name Of Registered Owner CHEAH ENG HANG
 NRIC No S7861170G
 Email Address ANDYCHEAH898@YAHOO.COM.SG
 Mobile Phone No (LOCAL) +65-92369228
 Alternative Phone No OTHERS-92369228
Vehicle Particulars
 Manufacturer BMW
 Model X1-1.5 SDRIVE 18i (A)
 Exact Purpose for which vehicle was being used at time of accident PTE USE
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category PRIVATE CAR
Insurance Company
 Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number 5109123056 PREMIUM
 Cover Note Number 25/04/2019 - 25/04/2020
Driver
 Name of Driver CHEAH ENG HANG
 NRIC No S7861170G
 Date Of Birth 11/05/1978
 Occupation INDOOR
 Date Of Driving Pass 14/05/2003
 Driving Experience 16 YEARS AND 4 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-92369228
 Fax Number
 Contact Number OTHERS-92369228
 Email Address ANDYCHEAH898@YAHOO.COM.SG

Address	BLK 303B ANCHORVALE LINK #08-98
Postcode	542303
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : KOH PEY HWA
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBJ5667S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	NG CHIN GIAP
NRIC/Passport Number	S6841804F
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

VEHICLE NO.: SMK 8623M
INSURER: NAC
DATE & TIME: 11/10/2019 @ 11:30

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Jodynn (AMK)
NRIC/FIN No: 11/10/19

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Vehicle No: JMK 8623M (NTUC)
Date & Time: 11/10/2019 @ 11:30 (clear/dry)

GBJ5667S Hit onto my car back portion.

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: AWK
IDUC/FIN No: _____

() Claim Own Policy () Claim Third Party () Reporting Only
 (x) Claim OOTP at other workshop ()

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/10/2019 15:15
Date Of Accident	11/10/2019 11:30
Exact Location Of Accident	ANG MO KIO AVE 3
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMK8623M
Insured/Policyholder	
Name Of Registered Owner	CHEAH ENG HANG
NRIC No	S7861170G
Email Address	ANDYCHEAH898@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-92369228
Alternative Phone No	OTHERS-92369228

Vehicle Particulars

Manufacturer	BMW
Model	X1-1.5 SDRIVE 18i (A)
Exact Purpose for which vehicle was being used at time of accident	PTE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5109123056 PREMIUM
Cover Note Number	26/04/2019 - 25/04/2020

Driver

Name of Driver	CHEAH ENG HANG
NRIC No	S7861170G
Date Of Birth	11/05/1978
Occupation	INDOOR
Date Of Driving Pass	14/05/2003
Driving Experience	16 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92369228
Fax Number	
Contact Number	OTHERS-92369228
Email Address	ANDYCHEAH898@YAHOO.COM.SG

Address	BLK 303B ANCHORVALE LINK #08-98
Postcode	542303
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : KOH PEY HWA
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBJ5667S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	NG CHIN GIAP
NRIC/Passport Number	S6841804F
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN


VEHICLE NO.: SMK 8623M
INSURER: NTRC
DATE & TIME: 11/10/2019 @ 1130


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 11/10/2019


Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: Johlyn (AMK)
NRIC/FIN No.: 11/10/19

Sketch Plan #2

SKETCH PLAN

Aug 1000 Kilo Aug 3

↑ ↑ ↑

A
B

A: 500K 8623M
m 1 passenger
i) Kon Poy Hua

B: 58J 56675
Ng Chin Giap
56841204F

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Vehicle No: SMK 8623M (NTUC)
Date & Time: 11/10/2019 @ 1130 (clearing)

GBJ5667S Hit onto my car back portion.

Note: Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: AWK
NfA/C/FIN No.:

☐ Claim Own Policy ☐ Claim Third Party ☐ Reporting Only
☒ Claim ODTP at other workshop ()

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255289)

103, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

289, Rempang Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64786624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

19 OCT 2019

ESTIMATE

CAR-IN

Estimate No. : b1 53144
Date Estimated : 19/10/2019
Prepared By : Joseph Yaguel

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Cheah Eng Hang
303B Anchorvale Link
#08-98

Singapore 542303

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMK8623M	WBAJG120803G77251	26/04/2019	X1 sDrive18i	0

DESCRIPTION

Replacing bootlid, rear bumper panel and attachment

Spray rear bumper and bootlid

To replace rear windscreen glass.

To conduct water leak tests.

To supply and install front or rear windscreen solar film.

To carry out body cavity preservation.
(Per panel).To check electrical wiring systems and lightings at the
rear section for proper function.

Sundries

BODY STICKER - TBA
INVOICE WITH OWNER

VALUE

2,125.00

2,006.00

574.00

75.00

531.00

118.00

177.00

150.00

0.00

Total Labour 1: 5,756.00

DESCRIPTION

SCREW SELF TAPPING

BLIND RIVET NUT M6

BOOTLID

RR BUMPER LH CORNER MOUNTING

RR BUMPER RH CORNER MOUNTING

REAR BUMPER PANEL PRIMED

REAR BUMPER MIDDLE TRIM PANEL (PDC)

BUMP STOP

REAR WINDOW (ESG)

HOOK AND LOOP FASTENER

DECOUPING RING PDC TORQUE CONVERTER

QTY

PRIC

VALUE

4 1.20

4 2.70

1 1,230.50

1 141.90

1 141.90

1 903.40

1 265.65

10 3.70

1 846.75

10 2.85

4 5.05

4.80

10.80

1,230.50

141.90

141.90

903.40

265.65

37.00

846.75

28.50

20.20



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Raffles Road
East Coast Centre
Singapore 438180
Fax: 63448773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motocrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : **b1 53144**
Date Estimated : **19/10/2019**
Prepared By : **Joseph Yaguel**

Page No. : **2 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMK8623M	WBAJG120803G77251	26/04/2019	X1 sDrive18i	0

DESCRIPTION	QTY	PRIC	VALUE
(DG) CLEANER R1 (100ML)	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	263.10
(DG/SL) GLASS PRIMER 30ML (VP206)	1	27.85	27.85
Total Parts :			3,948.50

Handwritten: 24/10/19
5 Days.
before paint photos.

Handwritten: Guo Qiang - 82880282

Handwritten: 23/10/19

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Handwritten: 10,383.55



Labour 1	:	5,756.00
Parts	:	3,948.50
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	679.32
Grand Total	:	10,383.82

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 53144**
Date Estimated : **19/10/2019**
Prepared By : **Joseph Yaguel**

- ESTIMATE REPAIR FOR -

Cheah Eng Hang
303B Anchorvale Link
#08-98

Singapore 542303

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMK8623M	WBAJG120803G772	26/04/2019	X1 sDrive18i	0

DESCRIPTION	ACCOUNT:		DISC. %	NETT
	ORIGINAL PRICE			

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT	
# EXPANDING NUT	1.00	2	0	2.00	✓ REC A
# REAR BUMPER TRIM PANEL BOTTOM (BAS)	191.80	1	0	191.80	✓ Cut A
# BMW PLAQUE WITH ADHESIVE FILM	71.25	1	0	71.25	✓ REC A
# EXPANDING RIVET BLACK	1.40	10	0	14.00	✓ REC A

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	279.05
Total Labour & Parts :	279.05

WORKSHOP QUOTATION

GST REG NO : M3 - 0020001 - X

Vehicle No : SMK 8623M

Chassis No : _____

CSA Name : _____

Model Year : _____

Quotation No : 0000536610

Date : 30/10/2019

Time : 13:51:26

Page : 1

Partsman : p13tansb

Del Doc : 003834819

S/N	PART NUMBER	DESCRIPTION	STX	PDC	ISS.	SELLING	DIS	NET
			CT	AT	SOH	QTY	PRICE	
		WBAJG120803G77251						
1	51127332323	REAR BUMPER TRIM P	P			1	191.80	191.80

/cut. cut

Guo Guo.

kk.

CSA Signature : _____

Date : _____

Time : _____

Customer's Name
or Contact Person : _____

Parts Total : 191.80

Labour Charges :

Sub Total :

Add 7% GST :

TOTAL AMOUNT :

- Notes: (1) The above quotation is based on visual inspection only and may change based on further checks.
 (2) The validity of this quotation is 14 days from the above date.
 (3) Parts are subject to availability.
 (4) Any price change is without prior notice.

If the quotation is acceptable to you, please confirm your authorization for

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 53144**
Date Estimated : **19/10/2019**
Prepared By : **Joseph Yaguel**

- ESTIMATE REPAIR FOR -

Cheah Eng Hang
303B Anchorvale Link
#08-98

Singapore 542303

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMK8623M	WBAJG120803G772	26/04/2019	X1 sDrive18i	0
DESCRIPTION	ACCOUNT: ORIGINAL PRICE	DISC. %	NETT	
To replace rear boot lid, rear bumper and attachments etc including to remove and install body parts in order to carry out painting job.	1,700.00	0	1,700.00	
To respray rear bumper and rear boot lid.	1,805.00	0	1,805.00	
To remove and install rear windscreen glass to facilitate the repair job.	574.00	0	574.00	
To conduct water leak tests.	75.00	0	75.00	
To carry out body cavity preservation.	100.00	0	100.00	
To check electrical wiring systems and lightings at the rear section for proper function.	150.00	0	150.00	
Sundries	80.00	0	80.00	
To carry out Body Wrapworks(by owne)	400.00	0	400.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET NUT M6	2.70	2	0	5.40
BLIND RIVET NUT M6	2.70	2	0	5.40
BOOTLID	1,230.50	1	0	1,230.50
# EXPANDING NUT	1.00	2	0	2.00
# REAR BUMPER TRIM PANEL BOTTOM (BASI)	191.80	1	0	191.80
REAR BUMPER PANEL PRIMED	903.40	1	0	903.40
REAR BUMPER MIDDLE TRIM PANEL (PDC)	265.65	1	0	265.65
# BMW PLAQUE WITH ADHESIVE FILM	71.25	1	0	71.25
# EXPANDING RIVET BLACK	1.40	10	0	14.00
DECOUPING RING PDC TORQUE CONVERTER	5.05	4	0	20.20
(DG) CLEANER R1 (100ML)	26.15	1	0	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	131.55	2	0	263.10
(DG/SL) GLASS PRIMER 30ML (VP206)	27.85	1	0	27.85

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W; GST Reg. No. M2-0020081-X



Final Report

SUPPLEMENTARY ITEMS

FAX TO FAX NO		Gro Qiang LKK	24/11/19	5
FAX TO FAX NO				
FAX TO FAX NO				
COMPLAINT DATE				

Total Labour :	4,884.00
Total Parts :	3,026.70
Total Labour & Parts :	7,910.70
GST @7%:	553.75
Grand Total :	8,464.45

LOSS OF USE = \$60 X 5 DAYS.
GIA SEARCH FEE - \$2.00

Ang Mo Kio Autopoint
10 Ang Mo Kio Industrial Park 2A #05-03
Singapore 568047
Email: wrapworks@outlook.com
Tel: 9644 1894 / 8716 2120



INVOICE NO. : 1724

Sold To: _____

Tel: _____

92369228

Date: _____

2/11/19

Item	Services / Products Description	Qty	Amount
	SMK 8623 M	/	\$400
	BMW X1		
	3M SATIN DARK GREY WRAPPED		
	REAR BOOT & REAR BUMPER		

Deposits have a validity of 6 months and is only exchangeable for other service. Our Terms & Conditions incorporate the Terms & Regulations of Case Trust. Goods & Services are non-refundable after the stipulated period.

Cash / Nets / Others

Total	\$400
Deposit	
Balance	/

Issued by: _____

Received/Accepted by: _____

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Dec 2019		26 Dec 2019 09:17 Edit Adj Rpt	\$57,910.70 Edit Estimates	\$57,910.70 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	0, Co. Reg. No.: 0								
Main Claimant:	CHEAH ENG HANG, ID: S7861170G								
Vehicle Reg. No.:	SMK8623M	Date of Loss:	11/10/2019 11:00 - :59 [5 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D204867C02	Policy/Cover Note No.:	DMCVSN30404919000						
Vehicle Reg. No. (Insured):	GBJ5667S	Policy No. (Claimant):	5109123056 PREMIUM						
		Excess:	S\$0.00						
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 07/01/2020]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									














Claim Documents

*SMK8623M (SNM19D204867C02)
[GBJ5667S]
TP
CHEAH ENG HANG
Oct 11 2019 11:00AM
[0]
Performance Motors Limited

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail	Print
1	11/10/19 18:34	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
2	11/10/19 18:34	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
3	11/10/19 18:34	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
4	11/10/19 18:34	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
5	11/10/19 18:34	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
6	11/10/19 18:34	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
7	11/10/19 18:34	TP VEHICLE [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	26/12/19 09:32	General View		Load JPG	<input checked="" type="checkbox"/>
2	26/12/19 09:32	General View		Load JPG	<input checked="" type="checkbox"/>
3	26/12/19 09:32	General View		Load JPG	<input checked="" type="checkbox"/>
4	26/12/19 09:32	General View		Load JPG	<input checked="" type="checkbox"/>
5	26/12/19 09:32	General View		Load JPG	<input checked="" type="checkbox"/>
6	26/12/19 09:32	General View		Load JPG	<input checked="" type="checkbox"/>
7	26/12/19 09:32	General View		Load JPG	<input checked="" type="checkbox"/>
8	26/12/19 09:32	General View		Load JPG	<input checked="" type="checkbox"/>
9	26/12/19 09:32	General View		Load JPG	<input checked="" type="checkbox"/>
10	26/12/19 09:32	General View		Load JPG	<input checked="" type="checkbox"/>
11	26/12/19 09:32	General View		Load JPG	<input checked="" type="checkbox"/>
12	26/12/19 09:32	General View		Load JPG	<input checked="" type="checkbox"/>
13	26/12/19 09:33	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
14	26/12/19 09:33	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
15	26/12/19 09:33	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
16	26/12/19 09:33	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
17	26/12/19 09:33	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
18	26/12/19 09:33	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
19	26/12/19 09:33	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
20	26/12/19 09:33	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail	Print
1	11/10/19 18:31	Sketch Plan [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
2	11/10/19 18:31	Sketch Plan #2 [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	30/12/19 11:54	Invoice		Load PDF	
2	30/12/19 11:55	Supplementary		Load PDF	

Linked Accident Report Documents

View View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail	Print
1	06/12/19 18:41	Accident Statement		Load HTM	
2	06/12/19 18:44	Accident Statement		Load HTM	
3	06/12/19 18:44	Accident Statement		Load HTM	
4	06/12/19 18:54	Accident Statement		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail	Print
1	11/10/19 18:34	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	11/10/19 18:34	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	11/10/19 18:34	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	11/10/19 18:34	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	11/10/19 18:34	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	11/10/19 18:34	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	11/10/19 18:34	TP VEHICLE		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail	Print
1	11/10/19 18:31	Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
2	11/10/19 18:31	Sketch Plan #2		Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119018756/GSD3E2

Date: 30/12/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN30404919000

Claimant
Vehicle No : SMK8623MInsured
Vehicle No : GBJ5667S

Date of Loss: 11/10/2019

Nature of Claim: TP

Claim
No: SNM19D204867C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMK8623M

Make & Model: BMW X1, 1.5 SDRIVE 18i (A)

Engine No: 31855543B38B15A

Reg. Date: 26/04/2019 (Man. Year: 2018)

Chassis No: WBAJG120803G77251

Colour: Grey

Odometer: 7800 km

Engine Capacity: 1499 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17

Rear Tyre Size: 225/55 R17

Front Left Side: Bridgestone 9 mm

Rear Left Side: Bridgestone 9 mm

Front Right Side: Bridgestone 9 mm

Rear Right Side: Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,377.55	3,106.70	1,270.85	29.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,006.00	4,804.00	1,202.00	20.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,383.55	7,910.70	2,472.85	23.82
+ GST 7.00/7.00% (S\$)	726.85	553.75	173.10	23.82
Nett Amount (S\$)	11,110.40	8,464.45	2,645.95	23.82

INSPECTION

Date of Assignment: 26/12/2019

Date Inspected: 23/10/2019 Inspected At:

Performance Motors Limited
(Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Dec 2019)
Parts:	M1-SUV	BMW X1 1.5 SDRIVE 18i (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMK8623M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	4		*SCREW SELF TAPPING	Not Necessary	4.80 FS	*- FS
2	4		*BLIND RIVET NUT M6	Necessary	10.80 FS	*10.80 FS
3	1		*BOOTLID	Dented	1,230.50 FS	*1,230.50 FS
4	1		*RR BUMPER LH CORNER MOUNTING	Not Necessary	141.90 FS	*- FS
5	1		*RR BUMPER RH CORNER MOUNTING	Not Necessary	141.90 FS	*- FS
6	1		*REAR BUMPER PANEL PRIMED	Cut	903.40 FS	*903.40 FS
7	1		*REAR BUMPER MIDDLE TRIM PANEL (PDC)	Cut	265.65 FS	*265.65 FS
8	10		*BUMP STOP	Not Necessary	37.00 FS	*- FS
9	1		*REAR WINDOW (ESG)	Not Necessary	846.75 FS	*- FS
10	10		*HOOK AND LOOP FASTENER	Not Necessary	28.50 FS	*- FS
11	4		*DECOUPING RING PDC TORQUE CONVERTER	Necessary	20.20 FS	*20.20 FS
12	1		*(DG) CLEANER R1 (100ML)	Necessary	26.15 FS	*26.15 FS
13	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary	263.10 FS	*263.10 FS
14	1		*(DG/SL) GLASS PRIMER 30ML (VP206)	Necessary	27.85 FS	*27.85 FS
15	2		*EXPANDING NUT	Necessary	2.00 FS	*2.00 FS
16	1		*REAR BUMPER TRIM PANEL BOTTOM (BASI)	Cut	191.80 FS	*191.80 FS
17	1		*BMW PLAQUE WITH ADHESIVE FILM	Necessary	71.25 FS	*71.25 FS
18	10		*EXPANDING RIVET BLACK	Necessary	14.00 FS	*14.00 FS
19	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
Total Parts (S\$)					4,377.55	3,106.70

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACING BOOTLID,REAR BUMPER PANEL AND ATTACHMENT	New	2,125.00	1,700.00
2	SPRAY REAR BUMPER AND BOOTLID	New	2,006.00	1,805.00
3	TO REPLACE REAR WINDSCREEN GLASS	New	574.00	574.00
4	TO CONDUCT WATER LEAK TESTS	New	75.00	75.00
5	TO SUPPLY AND INSTALL FRONT OR REAR WINDSCREEN SOLAR FILM	New	531.00	0.00
6	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
7	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
8	BODY STICKER-INVOICE WITH OWNER	New	400.00	400.00
Gross Labour Cost (S\$)			6,006.00	4,804.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >