

22000000

A.S. REC. BY:

REF: CS/CT19018760/KSD3n2

Special Instructions:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Chung Boon Sen

of CRF

Date/Time: 5:28pm @ 22/10/19

Estimated Cost:

Bill to:

OD/TP WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKD 6043K

Insured:

SKL 888L

at Workshop m/s

76B Motor

Tel:

6458 0296

of

160 Sin Ming Drive #08-03

Policy No:

Claim No:

SNM19D204990

Sum Insured:

Excess:

Make of Veh:

D.O.A.

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:11am @ 23/10/19

Person Contacted:

Judy

Vehicle IN/OUT

Date/Time

Action/Instruction

Estimate 1/1

SKD 6043K - NBR/INCL 4069965 / 34

Date: 28/5/2019

20/12 1/1 Lm @ 14, 100% email & confirm
(\$ 14,689.55 Red - 51%)

ASS. REC. BY:

CTI

ASSIGNMENT

From:

Date:

23/10/2019

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SKD 6043K

at Workshop m/s

T&B Motor

of

160 Sin Ming Drive #08-03

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

81000

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

07

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

(up)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKD 6043K

Yr Regn:

12 / 11

Type: ☒ M.Car / ☐ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A8L

CC

4163

Colour

White

A/C:

Insured / Std / NI / NA

Sp. Reading

84186

T/Radio:

Insured / Std / NI / NA

Eng/No:

WAU 888410B2017899

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

Dun

R:

275/35R20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

6

mm

L/Bal.

5

mm

L/Bal.

6

mm

D.O.A.

16/10/19

D.O.I.

23/10/19

Survey held at

✓

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 23 DEC 2019

Date/Time, File Pass In?

23/12/19

1)

Type

Date/Time, File Return In?

2)



: Prel. Report



: Final Report

Days Of Repair:

7

Resurvey No. of Trip:

1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Insp (\$



: Weekend (\$

Survey Fee:

Transportation:

S + R + G

Photo:

Other:

TOTAL:

220

Report Format:

Lump Sum / L&I: (\$

\$14,100/- 45

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Tuesday, 22 October 2019 5:28 PM
To: Sally
Cc: assignments
Subject: RE: OUR REF; SNM19D204990-SKL888L-CBS - YOUR REFA: SKL 888L OUR REF: CL/191032/T/TNB

WITHOUT PREJUDICE

Dear Sir

We will be assigning M/s LKK AUTO CONSULTANTS to survey your client's vehicle.

Aside to LKK AUTO CONSULTANTS,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Sally [mailto:info@catherinelimllc.com]
Sent: Tuesday, October 22, 2019 10:12 AM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: FW: OUR REF; SNM19D204990-SKL888L-CBS - YOUR REFA: SKL 888L OUR REF: CL/191032/T/TNB
Importance: High

Dear Sir (Without Prejudice)

Our email appended below. Please arrange. Thank you.

Regards
Sally Goh
Catherine Lim LLC
20 Havelock Road #03-01
Central Square
Singapore 059765
Email: info@catherinelimllc.com

From: Sally [<mailto:info@catherinelimllc.com>]
Sent: Monday, October 21, 2019 5:10 PM
To: 'Chong Boon Sen'
Subject: RE: OUR REF; SNM19D204990-SKL888L-CBS - YOUR REFA: SKL 888L OUR REF: CL/191032/T/TNB

Dear Sir (Without Prejudice)

Our client is agreeable to LKK: Kenneth Kong. Please arrange.

Regards
Sally Goh
Catherine Lim LLC
20 Havelock Road #03-01
Central Square
Singapore 059765
Email: info@catherinelimllc.com

From: Chong Boon Sen [<mailto:boonsen.chong@sg.cntaiping.com>]
Sent: Monday, October 21, 2019 4:14 PM
To: info@catherinelimllc.com
Subject: RE: OUR REF; SNM19D204990-SKL888L-CBS - YOUR REFA: SKL 888L OUR REF: CL/191032/T/TNB

Without prejudice
Dear Sir,
LKK
STA
LBS

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI
Sent: Monday, October 21, 2019 4:13 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Chee So Chow
<sochow.chee@sg.cntaiping.com>; info@catherinelimllc.com
Subject: OUR REF; SNM19D204990-SKL888L-CBS - YOUR REFA: SKL 888L OUR REF:
CL/191032/T/TNB

Dear boon Sen,

Please conduct PRS for SKD6043K.

Note : officer in charge – Boon Sen 63896171.

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Sally [<mailto:info@catherinelimllc.com>]

Sent: Monday, 21 October, 2019 10:11 AM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: YOUR REFA: SKL 888L OUR REF: CL/191032/T/TNB

Dear Sir

Please find attached, PRI notice for your attention.

Regards

Sally Goh

Catherine Lim LLC

20 Havelock Road #03-01

Central Square

Singapore 059765

Email: info@catherinelimllc.com

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



INSEAD Business School
Leading in Asia & Beyond

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

2008 3.5 Acura Integra Moonroof



100 Sportline Superheats, 19"
Rims, PS4 Transmission, Side And
Rear Drains.
Direct Owner - Smoke

Lake View Credit Pte Ltd view our cars

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable


Browse by Category ▾

Sort by Date Posted ▾ 20 results/page ▾

1 vehicles

Audi A8L

Advanced Search 🔍

Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection Audi A8L	Any	Any	2011	Any	Any	Any	Available
 Audi A8L 4.2A FSI Quattro	\$109,800	\$26,880 /yr	20-Dec-2011	4,163 cc	88,000 km	Luxury	Available
High Spec Ultra Luxurious A8 Long Wheelbase, Classy Wood And Leather Finishing, Nappa/Alcantara Leather Lining, Accident Free, Well Kept In Original Beautiful White Paint. Brown Leather Interior, Audi MMI, Rear Entertainment, Call For Viewing Appointment							
Posted: 29-Aug-2019 Tags: 2011 Audi A8L, 2011 audi a8l, Audi A8L, audi a8l, Audi, A8L, a8l, Used Audi							

Save this search criteria, to get email alerts whenever a match is found.

Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view Expired ads

20 ▾ results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or station wagons, SUV, MPV, hatchback, to COE cars & CPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Audi A8L, Audi A8L Singapore, used Audi A8L Singapore, used Audi A8L, used vehicles Singapore or even buy used Audi A8L Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, movie, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 853A

Vehicle Details

Vehicle No.: SKD6043K

Vehicle to be Exported: No

Intended Deregistration Date: 24 Oct 2019

Vehicle Make: AUDI

Vehicle Model: ABL 4.2 FSI QU (PSR+LED)

Primary Colour: White

Manufacturing Year: 2011

Engine No.: CDR009367

Chassis No.: WAUZZZ4H0BN017899

Maximum Power Output: 273.0 kW (366 bhp)

Open Market Value: \$103,664.00

Original Registration Date: 20 Dec 2011

First Registration Date: 20 Dec 2011

Transfer Count: 0

Actual ARF Paid: \$103,664.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 19 Dec 2021

PARF Rebate Amount: \$62,198.00

Intended COE Rebate Details

COE Expiry Date: 19 Dec 2021

COE Category: B - Car (1601cc & above)

COE Period(Years): 10

QP Paid: \$72,350.00

COE Rebate Amount: \$15,563.00

Total Rebate Amount: \$77,761.00

The information contained herein is correct as at 24 Oct 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/10/2019 18:18
Date Of Accident	16/10/2019 02:20
Exact Location Of Accident	JALAN LINGKARAN DALAM TURNING TO TEBRAU HIGHWAY
Country/State of Loss	MALAYSIA/JOHOR DARUL TAKZIM

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKD6043K
Insured/Policyholder	
Name Of Registered Owner	ROMAN CHAYKUN
NRIC No	S7964853A
Email Address	ROMANDX@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91733473
Alternative Phone No	OFFICE-91733473

Vehicle Particulars

Manufacturer	AUDI
Model	A8L-4.2 FSI QU (PSR+LED) (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA312559
Cover Note Number	

Driver

Name of Driver	TAN ZI CONG
NRIC No	S8542303G
Date Of Birth	29/12/1985
Occupation	INDOOR
Date Of Driving Pass	24/06/2004
Driving Experience	15 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83999599
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	3 PAVILION GROVE
Postcode	658595
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	FRIEND
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : FERRIS LAM GENDER: : MALE
Passenger 2	NAME: : JOEY TAN GENDER: : FEMALE
Passenger 3	NAME: : VENISE LAM GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT BATOK NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 21 BUKIT BATOK EAST AVE 4 , POSTCODE: 659840 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-6659999 - FAX NO: 66655793
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN & POLICE REPORT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKL888L
Vehicle Make/Model/Colour	LEXUS
Details Of Properties	

Vehicle Category	PRIVATE CAR
Name of Driver	ONG YUN HAN
NRIC/Passport Number	S7928490D
Contact Number	94888998
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	TAN ZI CONG
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SKD6043K
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

DETAILS OF INJURED PERSON 2

Name	FERRIS LAM
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SKD6043K
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

DETAILS OF INJURED PERSON 3

Name	JOEY TAN
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SKD6043K
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

18/10/11 @ 5.15pm

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SKETCH PLAN



SKD6043K - A

SKL888L - B

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report No. J/2091018/2060

- * Third Party claim other workshop - T & B

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____

Date & Time:

Company Chop (if applicable)

Driver's Signature _____

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

the same person.

NRIC/FIN No.:





**SINGAPORE
POLICE FORCE**



J/20191018/2060

1 of 2

POLICE REPORT (NP299)

Report No. J/20191018/2060

Police Station Of Origin
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

Date/Time Report Made 18/10/2019 13:48	Vide Report No.	Station Diary No. 58
Name Of Informant TAN ZI CONG	Address 3 PAVILION GROVE SINGAPORE 658595	
ID Type / ID No. NRIC NO / S8542303G	Contact No. Home/Office	Mobile 83999599
Nationality SINGAPORE CITIZEN	Email Address	
Occupation Director	Sex Male	Age 33
Institution/School Name	Date of Birth 29/12/1985	Race Chinese
Date/Time Of Incident 16/10/2019 02:20	Location Of Incident Jalan Lingkar Dalam turning to Tebrau Highway MALAYSIA	

Brief details.

On 16.10.2019 at about 0220hrs, I drove a car, SKD6043K along Jalan Lingkar Dalam with 3 passengers and thus stopped at the traffic light junction before turning to Tebrau Highway. When the traffic light turned green, I started to drive my car forward towards Tebrau Highway. After which I heard a loud skidding sound of vehicle from behind and shortly after my car was banged at the back by a Singapore car, SKL888L. The driver of the said car is one namely Ong Yun Han of S7928490D admitted that he had lost control of his car due to another car overtook his car. However two of my three passengers sustained some injury on their neck and knee and one of the injured passenger is one

Signature Of Officer Recording The Report:

J / Sr Staff Sgt ABDUL RAHMAN BIN ABDUL MAZIK

Signature Of Informant:

Signature Of Interpreter:
Not applicableDate/Time:
18/10/2019 13:48

Officer In-Charge Of Case:
J / Jurong Police Divisional Investigation Branch /
Sr Staff Sgt MUHAMMAD FAZLI BIN MOHAMED
KEFLI
Contact No.: 67910000

Classification Of Case:

Authentication Stamp





**SINGAPORE
POLICE FORCE**



J/20191018/2060

2 of 2

POLICE REPORT (NP299)


CONTINUATION OF REPORT

Report No. J/20191018/2060

namely Ferris Lam and the other two passengers are his wife and daughter. The other injured passenger is his wife whilst his 2 years old daughter did not sustain any injury. The impact caused pain on my neck, right upper arm and right knee and I thus went to Mount Elizabeth (Orchard) Hospital for treatment on 18.10.2019 afternoon. Hence I was hospitalized for 2 days and thereafter received 14 days medical leaves. My car was badly damaged at the rear. I am making this report for the purpose of insurance claim.

Signature Of Officer Recording The Report: J / Sr Staff Sgt ABDUL RAHMAN BIN ABDUL MATIK	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 18/10/2019 13:48
Officer In-Charge Of Case: J / Jurong Police Divisional Investigation Branch / Sr Staff Sgt MUHAMMAD FAZLI BIN MOHAMED KEFLI Contact No.: 67910000	Classification Of Case:
Authentication Stamp 	





Accident Photo



T & B MOTOR REPAIRS SERVICES PTE LTD

Page 1 / 2

160 SIN MING DRIVE #08-03 SIN MING AUTOCITY SINGAPORE 575722

Tel No. : 6458 0296 / 6454 8007 Fax No. : 6554 2640

E-Mail : tbmotor@hotmail.sg

Buss. Reg. No. : 199001597D

WITHOUT PREJUDICE

ROMAN CHAYKUN

46 KEPPEL DRIVE #05-129 CARRIBEAN @KEPPEL BAY

Estimate : ES003374

Date : 15/10/2019

Vehicle Num. : SKD6043K

Make/Model : AUDI A8L

Chassis/Eng# :

Accident Date : 16/10/2019

Claim No. :

Reference :

Policy No. : GA312559

Attention : Motor Claim Department

Not Withheld
C/Pg 8?
Penny After Paint

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR BOOT COVER <i>RD</i>		
2.	1	REAR BOOT COVER INNER LOCK <i>Rx</i>		
3.	1	REAR BOOT COVER LOGO <i>RD</i>		
4.	1	REAR LAMP LH <i>RD</i>		
5.	1	REAR LAMP SIDE GARNISH LH <i>RD</i>		
6.	1	REAR LAMP WEATHERSTRIP LH <i>RD</i>		
7.	1	REAR BUMPER TOP <i>RD</i>		
8.	1	REAR BUMPER TOP SIDE RETAINER RH <i>RD</i>		
9.	1	REAR BUMPER TOP SIDE RETAINER LH <i>RD</i>		
10.	1	REAR BUMPER CENTER MOULDING <i>RD</i>		
11.	1	REAR BUMPER LOWER <i>RD</i>		
12.	1	REAR BOOT WEATHERSTRIP <i>RD</i>		
13.	1 SET	REAR BOOT INNER GARNISH CLIPS <i>RD</i>		
14.	1	REAR END PANEL <i>RD</i>		
15.	1	REAR FLOOR BOARD PANEL <i>Rx</i>		
16.	1	REAR FLOOR BOARD OUTER LOWER COVER <i>RD</i>		
17.	1	REAR BUMPER REINFORCEMENT <i>RD</i>		
18.	1	REAR BUMPER REINFORCEMENT BRACKET RH <i>RD</i>		
19.	1	REAR BUMPER REINFORCEMENT BRACKET LH <i>RD</i>		
20.	1	REAR BUMPER SPONGE <i>RD</i>		
21.	1 SET	REAR EXHAUST SILENCER BOX <i>RD</i>		
22.	1 (R/H)	REAR EXHAUST SILENCER BOX MOUNTING <i>RD</i>		
23.	1	REAR EXHAUST SILENCER BOX MOUNTING BRACKET RH <i>Rx</i>		
24.	1 (L/H)	REAR EXHAUST SILENCER BOX MOUNTING <i>RD</i>		
25.	1	REAR EXHAUST SILENCER BOX MOUNTING BRACKET LH <i>RD</i>		
26.	1	REAR EXHAUST SILENCER BOX FRONT MOUNTING <i>RD</i>		
27.	1 (R/H)	FRONT EXHAUST PIPE <i>RD</i>		
28.	1	FRONT EXHAUST PIPE MOUNTING RH <i>RD</i>		
29.	1 (L/H)	FRONT EXHAUST PIPE <i>RD</i>		

LEK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

CONTINUE / ...

T & B MOTOR REPAIRS SERVICES PTE LTD

Page 2 / 2

160 SIN MING DRIVE #08-03 SIN MING AUTOCITY SINGAPORE 575722

Tel No. : 6458 0296 / 6454 8007 Fax No. : 6554 2640

E-Mail : tbmotor@hotmail.sg

Buss. Reg. No. : 199001597D

WITHOUT PREJUDICE

ROMAN CHAYKUN

46 KEPPEL DRIVE #05-129 CARRIBEAN @KEPPEL BAY

Attention : Motor Claim Department

Estimate : ES003374

Date : 15/10/2019

Vehicle Num. : SKD6043K

Make/Model : AUDI A8L

Chassis/Eng# :

Accident Date : 16/10/2019

Claim No. :

Reference :

Policy No. : GA312559

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

30.	1	FRONT EXHAUST PIPE MOUNTING LH		
31.	1	REAR EXHAUST SILENCER BOX PIPE CHROME LH		

List Total S\$:

10.00% Discount S\$:

1.	1	SPECIAL NETT ITEMS :		
2.	2 SET	EXHAUST CENTER PIPE, HEATER LOWER		
		EXHAUST BOLT & NUT		

Special Nett Total S\$:

LABOUR :

1. REMOVE & REFIX REAR BUMPER REVERSE SENSOR	250.00	800
2. SPRAY PAINT ANTI-RUST COATING	180.00	?
3. SPECIAL SUPPLY BOOT LIT SEALANT & END PANEL WELDING PARTS SEALANT	250.00	x
4. REMOVE & REFIX REAR BOOT COMPARTMENT INNER GARNISH	250.00	?
5. CHECK REAR LIGHT WIRING AND REPAIR REAR BOOT WIRING, REAR CAMERA & COMPUTER CHECK, RESET & CALIBRATION	550.00	?
6. REMOVE & REFIX FRONT, CENTER & REAR EXHAUST PIPE, SILENCER AND CATALISY CONVERTER	800.00	2000
7. SPRAY PAINTING REAR BOOT COVER, REAR END PANEL, REAR FENDER, REAR LAMP PENAL, FLOORBOARD PANEL AND REAR BUMPER LOWER	2,300.00	1000
8. LABOUR TO DO PANEL BEATING, WELDING AND REPAIR AND REPLACE DAMAGED PARTS, STRAIGHTEN CHASSIS AND ADJUST ALIGNMENT, AND TEST WATER LEAK	2,800.00	?

Labour Total S\$:

7,380.00

SingDollars : Seven Thousand Three Hundred Eighty Only

E. & O.E.

Total S\$: 7,380.00

for T & B MOTOR REPAIRS SERVICES PTE LTD

T & B MOTOR REPAIRS SERVICES PTE LTD

Page 1 / 2

160 SIN MING DRIVE #08-03 SIN MING AUTOCITY SINGAPORE 575722

Tel No. : 6458 0296 / 6454 8007 Fax No. : 6554 2640

E-Mail : tbmotor@hotmail.sg

Buss. Reg. No. : 199001597D

WITHOUT PREJUDICE

ROMAN CHAYKUN

46 KEPPEL DRIVE #05-129 CARRIBEAN @KEPPEL BAY

Estimate : ES003374

Attention : Motor Claim Department

Not Notified
1/10/2019
Resurvey After Painting

Date : 15/10/2019
Vehicle Num. : SKD6043K
Make/Model : AUDI A8L
Chassis/Eng# :
Accident Date : 16/10/2019
Claim No. :
Reference :
Policy No. : GA312559

S/N Quantity Particular Unit Price Amount S\$

LIST ITEMS :		
1.	1	REAR BOOT COVER 385P.u
2.	1	REAR BOOT COVER INNER LOCK
3.	1	REAR BOOT COVER LOGO
4.	1	REAR LAMP LH 767
5.	1	REAR LAMP SIDE GARNISH LH
6.	1	REAR BUMPER TOP 2838.u
7.	1	REAR BUMPER TOP SIDE RETAINER RH
8.	1	REAR BUMPER TOP SIDE RETAINER LH
9.	1	REAR BUMPER CENTER MOULDING
10.	1	REAR BUMPER LOWER
11.	1	REAR BOOT WEATHERSTRIP
12.	12	REAR BOOT INNER GARNISH CLIPS
13.	1	REAR END PANEL
14.	1	REAR FLOOR BOARD PANEL
15.	1	REAR FLOOR BOARD OUTER LOWER COVER
16.	1	REAR BUMPER REINFORCEMENT
17.	1	REAR EXHAUST SILENCER BOX ASSY 3354.u
18.	1 (R/H)	REAR EXHAUST SILENCER BOX MOUNTING
19.	1	REAR EXHAUST SILENCER BOX MOUNTING BRACKET RH
20.	1 (L/H)	REAR EXHAUST SILENCER BOX MOUNTING
21.	1	REAR EXHAUST SILENCER BOX MOUNTING BRACKET LH
22.	1	REAR EXHAUST SILENCER BOX FRONT MOUNTING
23.	1	REAR BUMPER TOWING HOOK COVER
24.	1 (R/H)	FRONT EXHAUST PIPE
25.	1	FRONT EXHAUST PIPE MOUNTING RH
26.	1 (L/H)	FRONT EXHAUST PIPE
27.	1	FRONT EXHAUST PIPE MOUNTING LH
28.	1	REAR EXHAUST SILENCER BOX PIPE CHROME LH 415.u

List Total S\$:

10.00% Discount S\$:

Net	3,950.80	✓
R	179.08	X
mg.m	113.13	✓
mg.m	1,419.33	✓
Di	48.60	✓
Bu	3,368.90	✓
Di	44.10	X
Di	44.10	X
CM	606.32	✓
CM	618.35	✓
Di	374.18	50% ✓
10.00	120.00	X
R	462.15	X
R	1,876.35	X
Net	226.85	✓
Di	1,380.63	X
R	3,769.50	✓
CM	73.10	✓
R	73.10	X
CM	73.10	✓
R	73.10	✓
R	73.10	✓
Di	58.00	✓
R	1,469.63	✓
Di	83.15	✓
R	1,469.63	✓
Di	83.15	✓
Net	521.85	✓
22,653.28		
2,265.33		
20,387.95		

LIK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CONTINUE / ...

T & B MOTOR REPAIRS SERVICES PTE LTD

Page 2 / 2

160 SIN MING DRIVE #08-03 SIN MING AUTOCITY SINGAPORE 575722

Tel No. : 6458 0296 / 6454 8007 Fax No. : 6554 2640

E-Mail : tbmotor@hotmail.sg

Buss. Reg. No. : 199001597D

WITHOUT PREJUDICE

ROMAN CHAYKUN

46 KEPPEL DRIVE #05-129 CARRIBEAN @KEPPEL BAY

Attention : Motor Claim Department

Estimate : ES003374

Date : 15/10/2019

Vehicle Num. : SKD6043K

Make/Model : AUDI A8L

Chassis/Eng# :

Accident Date : 16/10/2019

Claim No. :

Reference :

Policy No. : GA312559

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | | | |
|----|--------|--|--|--|
| 1. | 2 SET | SPECIAL NETT ITEMS : | | |
| 2. | 2 # kg | EXHAUST BULT & NUT | | |
| 3. | 1 | REAR BUMPER REVERSE SENSOR | | |
| | | REAR CENTER EXHAUST CENTER PIPE HEATER COVER | | |

Special Nett Total S\$:

LABOUR :

- | | | |
|---|----------|-------|
| 1. REMOVE & REFIX REAR BUMPER REVERSE SENSOR | 250.00 | 801 |
| 2. SPRAY PAINT ANTI-RUST COATING | 180.00 | 301 |
| 3. SPECIAL SUPPLY BOOT LIT SEALANT & END PANEL WELDING PARTS SEALANT | 250.00 | 1 |
| 4. REMOVE & REFIX REAR BOOT COMPARTMENT INNER GARNISH | 250.00 | 601 |
| 5. CHECK REAR LIGHT WIRING AND REPAIR REAR BOOT WIRING, REAR CAMERA & COMPUTER CHECK, RESET & CALIBRATION | 550.00 | 1801 |
| 6. REMOVE & REFIX FRONT, CENTER & REAR EXHAUST PIPE, SILENTER AND CATALISY CONVERTER | 800.00 | 2001 |
| 7. SPRAY PAINTING REAR BOOT COVER, REAR END PANEL, REAR FENDER, REAR LAMP PENAL, FLOORBOARD PANEL AND REAR BUMPER LOWER | 2,300.00 | 10001 |
| 8. LABOUR TO DO PANEL BEATING, WELDING AND REPAIR AND REPLACE DAMAGED PARTS, STRAIGHTEN CHASSIS AND ADJUST ALIGNMENT, AND TEST WATER LEAK | 2,800.00 | 6001 |

Labour Total S\$:

SingDollars : Twenty-Eight Thousand Seven Hundred Eighty-Nine & Cents Fifty-Five Only

E. & O.E.

Total S\$: 28,789.55

for T & B MOTOR REPAIRS SERVICES PTE LTD

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT19018760/KSD3N2
Date: 30/12/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN30757719000
Claimant Vehicle No: SKD6043K Insured Vehicle No: SKL888L
Date of Loss: 16/10/2019 Nature of Claim: TP Claim No: SNM19D204990C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKD6043K
Make & Model: AUDI A8L, 4.2 FSI QU (PSR+LED) (A) Engine No: CDR009367
Reg. Date: 20/12/2011 (Man. Year: 2011) Chassis No: WAUZZZ4H0BN017899
Colour: White Odometer: 84186 km
Engine Capacity: 4163 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/35R20 Rear Tyre Size: 275/35R20
Front Left Side: Dunlop 5 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Dunlop 5 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,409.55	15,474.68	5,934.87	27.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,380.00	2,150.00	5,230.00	70.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,789.55	17,624.68	11,164.87	38.78
Approved Total (Overridden) (S\$)		14,100.00		
Nett Amount (S\$)	28,789.55	14,100.00	14,689.55	51.02

INSPECTION

Date of Assignment: 20/12/2019
Date Inspected: 23/10/2019 Inspected At: T & B Motor Repairs Services Pte Ltd
Blk 160 Sin Ming Drive #08-03, Sin Ming Auto City
Singapore 575722
Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Dec 2019)

Parts: 143 AUDI A8L 4.2 FSI QU (PSR+LED) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKD6043K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BOOT COVER	Dented	3,950.80 FL	*3,859.00 FL
2	1	*REAR BOOT COVER INNER LOCK	Repair	179.08 FL	*- FL
3	1	*REAR BOOT COVER LOGO	Necessary	113.13 FL	*113.13 FL
4	1	*REAR LAMP LH	Mtg Cracked	1,419.33 FL	*767.00 FL
5	1	*REAR LAMP SIDE GARNISH LH	Distorted	48.60 FL	*48.60 FL
6	1	*REAR BUMPER TOP	Buckled	3,368.90 FL	*2,838.00 FL
7	1	*REAR BUMPER TOP SIDE RETAINER RH	Serviceable	44.10 FL	*- FL
8	1	*REAR BUMPER TOP SIDE RETAINER LH	Serviceable	44.10 FL	*- FL
9	1	*REAR BUMPER CENTER MOULDING	Cracked	606.32 FL	*606.32 FL
10	1	*REAR BUMPER LOWER	Cracked	618.35 FL	*618.35 FL
11	12	*REAR BOOT INNER GARNISH CLIPS	Not Necessary	120.00 FL	*- FL
12	1	*REAR END PANEL	Repair	462.15 FL	*- FL
13	1	*REAR FLOOR BOARD PANEL	Repair	1,876.35 FL	*- FL
14	1	*REAR FLOOR BOARD OUTER LOWER COVER	Deformed	226.85 FL	*226.85 FL
15	1	*REAR BUMPER REINFORCEMENT	No such part	1,380.63 FL	*- FL
16	1	*REAR EXHAUST SILENCER BOX ASSY	Bent	3,769.50 FL	*3,354.00 FL
17	1	*REAR EXHAUST SILENCER BOX MOUNTING R/H	Cracked	73.10 FL	*73.10 FL
18	1	*REAR EXHAUST SILENCER BOX MOUNTING BRACKET R/H	Repair	73.10 FL	*- FL
19	1	*REAR EXHAUST SILENCER BOX MOUNTING L/H	Cracked	73.10 FL	*73.10 FL
20	1	*REAR EXHAUST SILENCER BOX MOUNTING BRACKET LH	Bent	73.10 FL	*73.10 FL
21	1	*REAR EXHAUST SILENCER BOX FRONT MOUNTING	Bent	73.10 FL	*73.10 FL
22	1	*REAR BUMPER TOWING HOOK COVER	Distorted	58.00 FL	*58.00 FL
23	1	*FRONT EXHAUST PIPE R/H	Bent	1,469.63 FL	*1,469.63 FL
24	1	*FRONT EXHAUST PIPE MOUNTING RH	Distorted	83.15 FL	*83.15 FL
25	1	*FRONT EXHAUST PIPE L/H	Bent	1,469.63 FL	*1,469.63 FL
26	1	*FRONT EXHAUST PIPE MOUNTING LH	Distorted	83.15 FL	*83.15 FL
27	1	*REAR EXHAUST SILENCER BOX PIPE CHROME LH	Dented	521.85 FL	*415.00 FL
28	2	*SET EXHAUST BULT & NUT	Necessary	13.60 FS	*13.60 FS
29	1	*REAR BUMPER REVERSE SENSOR (4 Pcs)	Shorted (2 Pcs ony)	812.00 FS	*406.00 FS
30	1	*REAR CENTER EXHAUST CENTER PIPE HEATER COVER	Bent	196.00 FS	*196.00 FS
31	1	*REAR BOOT WEATHERSTRIP (50%)	Dented/Distorted	374.18 FN	*187.09 F

F=Franchise part, S=SpcNett, L=ListItemDisc, N=NettItemDisc.

Sub Total (S\$)	23,674.88	17,104.90
- List Item Discount on L Items 10.00/10.00% (S\$)	2,227.91	1,630.22
- Nett Item Discount on N Items 10.00/0.00% (S\$)	37.42	0.00
Total Parts (S\$)	21,409.55	15,474.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX REAR BUMPER REVERSE SENSOR	New	250.00	80.00
2	SPRAY PAINT ANTI-RUST COATING	New	180.00	30.00
3	SPECIAL SUPPLY BOOT LIT SEALANT & END PANEL WELDING PARTS SEALANT	New	250.00	0.00
4	REMOVE & REFIX REAR BOOT COMPARTMENT INNER GARNISH	New	250.00	60.00
5	CHECK REAR LIGHT WIRING AND REPAIR REAR BOOT WIRING,REAR CAMERA & COMPUTER CHECK,RESET & CALIBRATION	New	550.00	180.00
6	REMOVE & REFIX FRONT,CENTER & REAR EXHAUST PIPE,SILENCER AND CATALISY CONVERTER	New	800.00	200.00
7	SPRAY PAINTING REAR BOOT COVER,REAR END PANEL,REAR FENDER,REAR LAMP PANEL,FLOORBOARD PANEL AND REAR BUMPER LOWER	New	2,300.00	1,000.00
8	LABOUR TO DO PANEL BEATING,WELDING AND REPAIR AND REPLACE DAMAGED PARTS,STRAIGHTEN CHASSIS AND ADJUST ALIGNMENT,AND TEST WATER LEAK	New	2,800.00	600.00
Gross Labour Cost (S\$)			7,380.00	2,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >