

11/17/2019

ASS. REC. BY:

REF:

9/TPD19018770/Pg
ASSIGNMENT (Office)

Special Instruction:

Surveyor:

From (Person): Kamaliah Kamie

of

SPF

Date/Time: 23/10/2019

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: VR3460

Insured:

at Workshop m/s

Tel:

of

Policy No:

MHASPF06000026802/1

Claim No:

TP/1P/60999/2019

Sum Insured:

Excess:

D.O.A.

27/9/2019

Make of Veh:

(Client's Record)

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Date/Time:

Person Contacted:

Vehicle IN/OUT

| Date/Time | Action/Instruction () Estimate |
|-----------|---------------------------------|
| | VR3460-X |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

Outside pound
NIK D3M
revised.

Sherwin Beh (LKK Auto)

From: Kamaliah KAMIS (SPF) <Kamaliah_KAMIS@spf.gov.sg>
Sent: Wednesday, 23 October, 2019 8:25 AM
To: Sherwin Beh (LKK Auto); Naz (LKKAuto)
Cc: Bryan Ang (LKKAuto); SPF-TP FAIT; Nor Hidayu ABDUL SAMAD (SPF)
Subject: Mechanical Inspection Report Request

Dear Sirs,

May I seek your assistance to perform a detailed mechanical inspection of the **9 vehicles** below: [The ones marked in RED are deemed to be URGENT hence please EXPEDITE ON THESE REQUESTS]

- a) Case IAFP-IB-20191022 - Mechanical Inspection of Motorcycle, JSG3986 (TP/IP/60999/2019)
- b) Case IAFP-IB-20191022 - Mechanical Inspection of Motor Trailer, VR3460 (TP/IP/60999/2019)

On 27 September 2019 (Friday) at about 4.31 pm, the rider of motorcycle JSG3986 was travelling along AYE towards Tuas when the motorcycle skidded and fell onto the path of the trailer VR3460 where the said trailer ran over the deceased. The deceased was pronounced dead at the scene.

Vehicles to be inspected: JSG3986 - Rider (Deceased)
VR3460 - Driver (Involved Party)

IO In-Charge: SIO Yazid

- c) Case IAFP-IB-20191022 - Mechanical Inspection of Motorcycle, VAL1344 (TP/IP/33001/2019)

On 25 May 2019 (Saturday) at about 3.27 a.m., B1 (VAL1344) was riding his motorcycle along Bartley Road East towards Bartley Road when he veered to the right hit onto the centre divider and skidded for unknown reason. The Deceased was conveyed to TTSH by ambulance. On the same day, B1 succumbed to his injuries and was pronounced dead at TTSH.

Vehicles to be inspected: VAL1344 - Rider (Deceased)

IO In-Charge: SIO Dzul Hairie

- d) Case IAFP-IB-20191022 - Mechanical Inspection of Motor Bus, NCK9059 (TP/IP/32037/2019)

On 20 May 2019 (Monday) at about 11.40 p.m., A1 (NCK9059) was driving off from bus bay located at Woodlands Checkpoint. When he was driving off, a deceased (pedestrian) ran to catch the bus when the deceased tried to step on the front door of the bus while the bus was in motion. The deceased lose balance and fell. As result of the fell, the deceased went underneath the bus and ran over by the front left tyre of the said bus.

Vehicles to be inspected: NCK9059 - Driver (Involved Party)

IO In-Charge: SIO Dzul Hairie

- e) Case IAFP-IB-20191022 - Mechanical Inspection of Motor Lorry, GZ8811D (TP/IP/65207/2019)
- f) Case IAFP-IB-20191022 - Mechanical Inspection of Bicycle (TP/IP/65207/2019)