

ASS. REC. BY:

REF: CS3 / MSG M018773 / Pgs 322

Special Instruction:

SUNVAJOY ROM

ASSIGNMENT (Office)

From (Person): Jasmine Lok Chung Kwai of MS19 Date/Time: 23.10.19 8.44A.m

Estimated Cost: Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMK 6282B Insured: FBG 33041

at Workshop m/s Apex motoring Tel: 91690825

of 25 Kaki Bukit Road 4 #01-55

Policy No: MSD / VMT / 19-999106 Claim No: MSC / V / 19-001274

Sum Insured: Excess:

Make of Veh: D.O.A. 17.10.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 23.10.19 9.44A.m Person Contacted: ms Lim Vehicle: IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SMK 6282B - NA / MSG M018474 / h4 DOA - 17/10/2019
	FBG 33041 - NA / MSG M018474 / h4 DOA - 17/10/2019
	Disassemble: 23/10/19
	After paint: 25/10/19
06/11/19	Submit PRS.

ASS. REC. BY:

REF:

MSLG

PRS

ASSIGNMENT

From:

Date:

23.10.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMK 6282B

at Workshop m/s Apex Motoring

of 25 kaki Bukit Road 4 #101-55

Insured:

Policy No.:

Claims No.:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

my

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMK 6282B

Yr Regn:

Apr / 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Freed Hybrid c.c 1496

Colour:

Silver Grey

A/C: Insured / Std / NI / NA

Sp. Reading

51644

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

GB7-1092021

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 185/65R15

R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Yokohama

Front

Rear

R/Bal.

5 mm

R/Bal.

5 mm

L/Bal.

5 mm

L/Bal.

5 mm

D.O.A.

17/10/19

D.O.I.

23/10/19

Survey held at

Apex Motoring

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range: \$3000-54000

24/10/2019

MV: \$97563

PV: \$54795

NV: \$42768

RECEIVED 06 NOV 2019

Date/Time, File Pass to?

☐

: Preli. Report

1) 06/11/2019

☐

: Final Report

Date/Time, File Return to?

2)

Rep. Format:

PRS

Lump Sum / T.B. / C

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

120

11

131

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Oct 2019		23 Oct 2019 08:44 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	TAN NIAN CAI, ID: S9522661B		
Main Claimant:	ASIA EXPRESS CAR RENTAL, Co. Reg. No.: 201116882D		
Vehicle Reg. No.:	SMK6282B	Date of Loss:	17/10/2019 16:00 - :59 [6 Months From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	MSD/VMT/19-999108 (Third Party Only) Coverage: 11/01/2019 - 10/01/2020
Vehicle Reg. No. (Insured):	FBG3304T	Policy No. (Claimant):	
		Excess:	
Repairer:	Apex Motoring () 25 Kaki Bukit Road 4, #01-55 Synergy @ KB, 417800 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 24/10/2019]		
Driver/Custodian (Insured):	TAN NIAN CAI (24 / Male), NRIC: S9522661B Email:		
Adj Asg. Remarks:	on WP. Manual assigned to LKK via email on 22/10/19. (Manual Assign). Liab: clear. Disagree on SJE. Contact: Ms Lim @ 9169 0825.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.



ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

quire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 882D

Vehicle Details

Vehicle No.: SMK6282B
Vehicle to be Exported: No
Intended Deregistration Date: 24 Oct 2019
Vehicle Make: HONDA
Vehicle Model: FREED HYBRID 1.5G AUTO
Primary Colour: Grey
Manufacturing Year: 2018
Engine No.: LEB5630958
Chassis No.: GB71092021
Maximum Power Output: 101.0 kW (135 bhp)
Open Market Value: \$26,129.00
Original Registration Date: 17 Apr 2019
First Registration Date: 17 Apr 2019
Transfer Count: 0
Actual ARF Paid: \$18,581.00 x 50% = \$9290.5

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 16 Apr 2029
PARF Rebate Amount: \$13,935.00

Intended COE Rebate Details

COE Expiry Date: 16 Apr 2029
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$43,102.00
COE Rebate Amount: \$40,860.00
Total Rebate Amount: \$54,795.00

he information contained herein is correct as at 24 Oct 2019

Remaining: 9 years 5 months ³⁰ ~~29~~ days (113.9) OK

Depn: \$9300/yearly \$775/monthly

$$113.9 \times \$775 = \$88272.5$$

$$\$88272.5 + \$9290.5$$

$$= \$97563$$

New Car \$113,000

M.V. - \$96,000

The Manulife Vault guaranteed retirement plan worth apply.

2.88% P.A. \$0 Down, \$0 Admin.
Monthly From \$438, 2 Year
Warranty Engine/Gearbox.
GV Credit Pte Ltd StarAd

[view our cars](#)

Ways of Selling

20 results/page

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Available

Available

AUCTION VER

Available

Available

100

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/10/2019 14:21
Date Of Accident	17/10/2019 16:15
Exact Location Of Accident	ANG MO KIO AVE 03
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMK6282B
Insured/Policyholder	
Name Of Registered Owner	ASIA EXPRESS CAR RENTAL
Co Reg No	201116882D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91998131
Alternative Phone No	OFFICE-68424992

Vehicle Particulars

Manufacturer	HONDA
Model	FREED HYBRID 1.5G AUTO
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B 29120056 MCX
Cover Note Number	

Driver

Name of Driver	BEH YU LING
NRIC No	S73723011
Date Of Birth	01/06/1973
Occupation	OUTDOOR
Date Of Driving Pass	17/07/1997
Driving Experience	22 YEARS AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-84682187
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 184 WESTWOOD AVENUE #03-11
Postcode	046147
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : GRAB PASSENGER GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	NANYANG N.P.C
Police Station Name	ROAD: 2 JURONG WEST AVE 5 , POSTCODE: 649482 , COUNTRY: SINGAPORE
Police Station Address	TEL NO: 1800-7929999 - FAX NO:
Police Station Contact	NO
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER POLICE REPORT No.T/20191018/2226;

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH OWNER/DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBG3304T
Vehicle Make/Model/Colour	SYM / MAXSYM 400I CVT
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	TAN NIAN CAI
NRIC/Passport Number	S9522661B
Contact Number	

Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	BEH YU LING
Approximate Age	46
Injuries Sustain	
Injured person in which vehicle?	SMK6282B
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	
Address	BLK 184 WESTWOOD AVENUE #03-11
Postcode	046147

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time: 18/10/19
3:25pm

Driver's Signature

(If driver is not the policyholder)

Date & Time: 18/10/19
3:25pm

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4 #02-02
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vackb@vicom.com.sg

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN

A Smk 6730B
B FBG 3324U

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report



DECLARATION

We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 18/10/19
3:25pm

Driver's Signature
(If driver is not the policyholder)

Date & Time: 18/10/19
3:25pm

IDAC KAKI BUKIT (VAG)
23 Kaki Bukit Ave 4 #02-02
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vackb@vicom.com.sg

Reporting Centre Personnel's Signature

Name:
NRIC/FIN No.:

Accident Sketch Plan



**SINGAPORE
POLICE FORCE**



T/20191018/2226

1 of 3

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

Report No. T/20191018/2226

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 18/10/2019 21:59		Vide Report No.:		Station Diary No.: 458	
Informant's Particulars					
Name of Informant: BEH YU LING			Address: APT BLK 184 WESTWOOD AVENUE #03-11 SINGAPORE 648147		
ID Type / ID No.: NRIC NO / S73723011			Contact No.:		Mobile:
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 46	Date of Birth: 01/06/1973	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: GRAB DRIVER			Driving Licence Information: Class:		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 17/10/2019 16:20	Type of Location: Straight Road
Location: Along Road 1 ANG MO KIO AVENUE 3				
TOWARDS ANG MO KIO HUB DIRECTION				
Weather: Clear		Road Surface: Wet	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control:	Traffic Volume:	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
FBG3304T	Motorcycle				Slightly Damaged	0
SMK6282B	Car				Slightly Damaged	1

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Accident Sketch Plan



**SINGAPORE
POLICE FORCE**



T/20191018/2226

2 of 3

Report No. T/20191018/2226

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

CONTINUATION OF REPORT

Driver			
Name	BEH YU LING	ID No.	S73723011
Related Vehicle	SMK6282B (Car)	Contact No.	84682187
Hospital/Clinic	CLOVER MEDICAL CLINIC PTE LTD	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	18/10/2019	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

On 17/10/2019 at about 1620hrs, while I was driving my vehicle bearing the registration SMK6282B along Ang Mo Kio Ave 3 towards Ang Mo Kio Hub. I was travelling on the 3rd lane, suddenly I felt that there was a impact from the rear of the vehicle. I stopped at the side of the road and notice that it was a motorbike bearing the registration number FBG3304T that had collided with my vehicle. I spoke to the rider namely Tan Nian Cai, S9522661B who seems injured but refused to be conveyed to hospital.

There was dent at the rear of my vehicle, I was given 3 days MC by Clover Medical Clinic Pte Ltd. MC 12201. There was camera installed in my vehicle. The vehicle that I was driving was rented and they instructed me to lodge a report for insurance claimed.

Accident Sketch Plan



**SINGAPORE
POLICE FORCE**



T/20191018/2226

3 of 3

Report No. T/20191018/2226

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

Sgt 2 SOH XUAN YI

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

18/10/2019 21:59

Officer In Charge Of Case:

TP / AEIT /

SI ANG YI TING, STEPHANIE

Contact No.: 65476414

Classification Of Case:

Authentication Stamp
NP168



SIGNATURE

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Oct 2019		23 Oct 2019 08:44 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case




































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TAN NIAN CAI, ID: S9522661B								
Main Claimant:	ASIA EXPRESS CAR RENTAL, Co. Reg. No.: 201116882D								
Vehicle Reg. No.:	SMK6282B	Date of Loss:	17/10/2019 16:00 - :59 [6 Months From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MSC/V/19-001274	Policy/Cover Note No.:	MSD/VMT/19-999108 (Third Party Only) Coverage: 11/01/2019 - 10/01/2020						
Vehicle Reg. No. (Insured):	FBG3304T	Policy No. (Claimant):							
		Excess:							
Repairer:	Apex Motoring () 25 Kaki Bukit Road 4, #01-55 Synergy @ KB, 417800 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Imm.Advice due 24/10/2019]								
Driver/Custodian (Insured):	TAN NIAN CAI (24 / Male) , NRIC: S9522661B Email:								
Adj Asg. Remarks:	on WP. Manual assigned to LKK via email on 22/10/19. (Manual Assign). Liab: clear. Disagree on SJE. Contact: Ms Lim @ 9169 0825.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									


















Claim Documents

*SMK6282B (MSC/V/19-001274)
[FBG3304T]
TP
ASIA EXPRESS CAR RENTAL
Oct 17 2019 4:00PM
[TAN NIAN CAI]
Apex Motoring

Upload Documents | Upload Photos | Compose New Letter

View View in Browser v

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/10/19 11:23	General View	 Load JPG	<input checked="" type="checkbox"/>
2	24/10/19 11:23	General View	 Load JPG	<input checked="" type="checkbox"/>
3	24/10/19 11:23	General View	 Load JPG	<input checked="" type="checkbox"/>
4	24/10/19 11:23	General View	 Load JPG	<input checked="" type="checkbox"/>
5	24/10/19 11:23	General View	 Load JPG	<input checked="" type="checkbox"/>
6	24/10/19 11:23	General View	 Load JPG	<input checked="" type="checkbox"/>
7	24/10/19 11:23	General View	 Load JPG	<input checked="" type="checkbox"/>
8	24/10/19 11:23	General View	 Load JPG	<input checked="" type="checkbox"/>
9	24/10/19 11:23	General View	 Load JPG	<input checked="" type="checkbox"/>
10	24/10/19 11:23	General View	 Load JPG	<input checked="" type="checkbox"/>
11	24/10/19 11:23	General View	 Load JPG	<input checked="" type="checkbox"/>
12	24/10/19 11:23	General View	 Load JPG	<input checked="" type="checkbox"/>
13	24/10/19 11:23	General View	 Load JPG	<input checked="" type="checkbox"/>
14	24/10/19 11:23	General View	 Load JPG	<input checked="" type="checkbox"/>
15	24/10/19 11:23	General View	 Load JPG	<input checked="" type="checkbox"/>
16	24/10/19 11:23	General View	 Load JPG	<input checked="" type="checkbox"/>
17	24/10/19 11:23	General View	 Load JPG	<input checked="" type="checkbox"/>
18	24/10/19 11:23	General View	 Load JPG	<input checked="" type="checkbox"/>
19	24/10/19 11:23	General View	 Load JPG	<input checked="" type="checkbox"/>
20	24/10/19 11:23	General View	 Load JPG	<input checked="" type="checkbox"/>
21	24/10/19 11:23	General View	 Load JPG	<input checked="" type="checkbox"/>
22	24/10/19 11:23	General View	 Load JPG	<input checked="" type="checkbox"/>
23	24/10/19 11:23	General View	 Load JPG	<input checked="" type="checkbox"/>
24	24/10/19 11:23	General View	 Load JPG	<input checked="" type="checkbox"/>
25	24/10/19 11:23	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
26	24/10/19 11:23	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
27	24/10/19 11:23	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
28	24/10/19 11:23	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
29	24/10/19 11:23	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
30	24/10/19 11:23	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
31	24/10/19 11:23	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
32	24/10/19 11:23	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
33	24/10/19 11:23	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
34	24/10/19 11:23	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
35	24/10/19 11:23	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
36	24/10/19 11:23	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
37	24/10/19 11:23	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
38	24/10/19 11:23	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
39	24/10/19 11:23	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
40	24/10/19 11:23	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
41	24/10/19 11:23	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
42	24/10/19 11:23	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
43	24/10/19 11:23	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	24/10/19 11:23	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
45	24/10/19 11:23	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
46	24/10/19 11:23	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
47	24/10/19 11:23	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
48	24/10/19 11:23	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
49	24/10/19 11:23	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
50	24/10/19 11:23	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
51	24/10/19 11:23	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
52	25/10/19 18:57	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
53	25/10/19 18:57	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
54	25/10/19 18:57	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
55	25/10/19 18:57	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
56	25/10/19 18:57	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	22/10/19 17:18	PRI	 Load PDF	
2	22/10/19 17:18	OI Accident Report	 Load PDF	
3	22/10/19 17:18	TP SMK6282B E-REPORT	 Load PDF	
4	22/10/19 17:22	Disagree on SJE	 Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	23/10/19 08:42	Survey Request - Manual Assigned	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19018773/FCF3E2

Date: 08/11/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/MT/19-999108
Claimant Vehicle No :	SMK6282B	Insured Vehicle No :	FBG3304T
Date of Loss:	17/10/2019	Nature of Claim:	TP
		Claim No:	MSCV/19-001274

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK6282B	Engine No:	LEB5630958
Make & Model:	HONDA FREED HYBRID, 1.5 G (A)	Chassis No:	GB71092021
Reg. Date:	17/04/2019 (Man. Year: 2018)	Odometer:	51644 km
Colour:	Grey/Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	23/10/2019	
Date Inspected:	23/10/2019 Inspected At:	Apex Motoring 25 Kaki Bukit Road 4, #01-55 Synergy @ KB Singapore 417800
Estimated Period of Repair:	4.0 days	

Adjuster: PARASURAM SHANMUGAM

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$4,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Nov 2019)

Parts: M1-MPV HONDA FREED HYBRID 1.5 G (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMK6282B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >