

ASS. REC. BY:

REF: CS/PCI K1018783/R15f3⁵² Special Instruction:

Simulator Rasul

ASSIGNMENT (Office)

From (Person): May Chua

of FC1

Date/Time: 23.10.19 12.54p.m

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: FB P 1973C

Insured:

SHD 6730X

at Workshop m/s HK L Lim Team

Tel:

62756656

of BIK 1008 # 01-24 Subst mrah Lem 3

Policy No:

Claim No: D19006637MFS4

Sum Insured:

Excess:

D.O.A. 15.10.2019

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS

myr'

H.O.D. Endorsement:

Date/Time: 23.10.19 116p.m

Person Contacted:

James

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	FBP 1973C - NBA / INC 19018416/F D.O.A. 15/10/2019
	SHD 6730X - NBA / INC 19018416/F D.O.A. 15/10/2019
25/10/19	@ 14:21 pm revised PA to May via email.

ASS. REC. BY:

Rasul

REF: FC1

768H

ASSIGNMENT

From:

Date: 24.10.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBP 1973C

at Workshop m/s HKL Lim Tram

of BILION 3 #01-24 Bukit merah Lane 3

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh: morning

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

mp

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: FBP 1973C

Yr Regn: 2019 / PGB

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: YAMAHA AEROX GARISSA c.c 155

Colour: Multi Black. A/C: Insured / Std / NI / NA

Sp.Reading: 22049 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MH3SG4640JJ047416

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120/70-14

R: 180/70-14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 4 mm R/Bal. 4 mm

L/Bal. mm L/Bal. mm

D.O.A. 15/10/19 D.O.I. 24/10/19

Survey held at HKL LIM TEAM

Des. of Damages: Fit / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Rasul

RECEIVED 13 NOV 2019

Pls check repair limit & see my remarks.

13/11/19 Confirmed P/P \$ 5,300/- @ 5 days with Rasul
(S 3,460.00 Red - 40%)
MV - \$ 9,000/- } Net = \$ 5,570/-
LTA - \$ 3,430/-

Date/Time, File Pass to?

1) 13/11/19

2) Typ. 4

Date/Time, File Return to?

2)

Report Format:

Lump Sum P.P.:

☐ : Preli. Report

☒ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Week end (\$

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

160

50

50

135

395

MOTOR SURVEY ASSIGNMENT

Date	17-10-2019	Our Ref No. D19006637MFSH
Accident Date	15-10-2019	Claim Type. Third Party
Insured Vehicle	SHD6730X	Third Party Vehicle. FBP1973C
Survey Location	BLK 1008 #01-24 BUKIT MERAH LANE 3	
Contact Person.	JAMES LIM (KEONG)	
Contact No.	62756656/ 62756566	Fax No. 62729291
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	HKL LIM TEAM MOTORSPORT	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Friday, 25 October 2019 2:21 pm
To: 'May Chua'; 'CWS Motor Claims'
Cc: assignments; Admin-D (LKKAuto); SUR
Subject: RE: SURVEY ASSESSMENT - D19006637MFSH/1
Attachments: PRELI ADVISE - FBP 1973C.pdf

Dear May,

Enclosed preliminary revised of vehicle FBP 1973C.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Wednesday, 23 October 2019 1:19 pm
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'May Chua' <maychua@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19006637MFSH/1

Dear Sir/Madam,

Thank you for your assignment.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Sent: Wednesday, 23 October, 2019 12:54 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; May Chua <maychua@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19006637MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Shirley Hiew (LKK Auto)

From: HKL Lim Team Motorsport <hkllimteam@gmail.com>
Sent: Tuesday, 12 November 2019 6:08 pm
To: Rasul (LKKAuto)
Cc: Shirley Hiew (LKK Auto)
Subject: Re: FBP1973C Finalize

Hi Rasul

\$5300 agree

On Tue, Nov 12, 2019 at 6:05 PM Rasul (LKKAuto) <Rasul@lkkauto.com> wrote:

Hi James,

As spoken, repair limit for this case \$ 5300 / 5 days part by part is confirmed

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK Auto Consultants Pte Ltd *Save the Earth. Print only when necessary.*

From: HKL Lim Team Motorsport [<mailto:hkllimteam@gmail.com>]
Sent: Thursday, 7 November, 2019 1:21 PM
To: Admin-D (LKKAuto)
Cc: Rasul (LKKAuto)
Subject: FBP1973C Finalize



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL.: (065) 62563561 FAX : (065) 62564315

Your Ref: D19006637MFSH

Date: 25 October 2019

Our Ref: CS/FCI19018783/R1sf3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. FBP 1973C .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 24/10/2019 at the premises of M/s HKL Lim Team Motorsport and have the following to report:-

Workshop Estimate Amount	: S\$ <u>8,425.00</u> .
Revised Estimate Amount	: S\$ <u>3,765.00</u> .
"Check" Items Amount	: S\$ <u>2,450.00</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the front & front n/s portion, o/s body



Comments/ Present Status:

Damages Consistent.

Repair days: 5 days

Yours faithfully

Mohammed Rasul
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/10/2019 12:44
Date Of Accident	15/10/2019 17:40
Exact Location Of Accident	JUNCTION OF SEMBAWANG ROAD ALONG YISHUN AVE 5
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBP1973C
Insured/Policyholder	
Name Of Registered Owner	AHMAD SYUKRI BIN KHALIL
NRIC No	S9434768H
Email Address	AHMADSYUKRIZ4@GMAIL.COM
Mobile Phone No	(LOCAL) +65-92966954
Alternative Phone No	OFFICE-92966954

Vehicle Particulars

Manufacturer	YAMAHA
Model	AEROX
Exact Purpose for which vehicle was being used at time of accident	PERSONAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5107816996
Cover Note Number	

Driver

Name of Driver	AHMAD SYUKRI BIN KHALIL
NRIC No	S9434768H
Date Of Birth	24/09/1994
Occupation	OUTDOOR
Date Of Driving Pass	25/02/2015
Driving Experience	4 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92966954
Fax Number	
Contact Number	OFFICE-92966954
Email Address	AHMADSYUKRIZ4@GMAIL.COM

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

AHMAD SYUKRI BIN KHALIL

Approximate Age

Injuries Sustain

Injured person in which vehicle?

FBP1973C

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode


SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 17/01/14

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/EIN No.:



SINGAPORE POLICE FORCE



T/20191017/2079

1 of 3

Report No. T/20191017/2079

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 17/10/2019 13:25	Vide Report No.:	Station Diary No.:
--	------------------	--------------------

Informant's Particulars

Name of Informant: AHMAD SYUKRI BIN KHALIL			Address: APT BLK 492 ADMIRALTY LINK #03-185 SINGAPORE 750492		
ID Type / ID No.: NRIC NO / S9434768H			Contact No.: Home/Office: Mobile: 92966954		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 25	Date of Birth: 24/09/1994	Type of Informant: Rider		
Race: Javanese			Language:		Institution / School Name:
Occupation: OTHERS			Driving Licence Information: Class: 2B,3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 15/10/2019 17:40	Type of Location:
Location: Along Road 1 SEMBAWANG ROAD YISHUN AVENUE 5 JUNCTION OF SEMBWANG ROAD ALONG YISHUN AVE 5				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume: Light
Type of Collision:				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBP1973C	Motorcycle	YAMAHA	AEROX GDR155A CVT	Black		0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBP1973C	NTUC Income Insurance Co-Operative Limited	5107816996	26/02/2019	25/02/2020



**SINGAPORE
POLICE FORCE**



T/20191017/2079

2 of 3

Report No. T/20191017/2079

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	AHMAD SYUKRI BIN KHALIL	ID No.	S9434768H
Related Vehicle	FBP1973C (Motorcycle)	Contact No.	92966954
Hospital/Clinic	KHOO TECK PUAT HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	15/10/2019	Date Discharge	15/10/2019
No. of Days granted Medical Leave	05	Degree of Injury	Serious

Brief Details.

AT THE ABOVEMENTIONED DATE AND TIME,

I WAS RIDING ALONG THE FIRST LANE WHEN THE TAXI CUT INTO MY LANE AND I HIT THE TAXI.
AFTER WHICH I FELL DOWN.

THAT IS ALL.



Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20191017/2079

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:
TP /
LEE CHEN EN

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIT /

Contact No.:

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:
17/10/2019 13:25

Classification Of Case:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	768H
Vehicle Details	
Vehicle No.:	FBP1973C
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Nov 2019
Vehicle Make:	YAMAHA
Vehicle Model:	AEROX GDR155A CVT
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	G3J8E0083505
Chassis No.:	MH3SG4640JJ047411
Maximum Power Output:	-
Open Market Value:	\$2,280.00
Original Registration Date:	25 Feb 2019
First Registration Date:	25 Feb 2019
Transfer Count:	1
Actual ARF Paid:	\$342.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	24 Feb 2029
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$3,689.00
COE Rebate Amount:	\$3,430.00
Total Rebate Amount:	\$3,430.00

The information contained herein is correct as at 07 Nov 2019

OK

9000
3430

5570

Repair limit after
5300



HKL LIM TEAM MOTORSPORT

Bik 1008 #01-24 Bukit Merah Lane 3, Singapore 160722 Tel: 6276 8988, 6273 8588, 62777297 Fax: 6272 0201
Email: support@hklmotorsport.com.sg Website: www.hklmotorsport.com.sg

FBP1973C

1 LAMP STAY	\$ 80.00
2 METER ASSY	\$ 350.00 X
3 FRONT FORK ASSY LH/RH	\$ 500.00
4 FRONT FORK UNDER BRACKET	\$ 180.00
5 STEERING CONE BEARING	\$ 90.00
6 BODY FRAME ALIGNMENT	\$ 700.00 L=
7 FRONT WHEEL RIM	\$ 380.00
8 FRONT WHEEL SHALE	\$ 35.00
9 FRONT WHEEL BEARING 2PCS	\$ 30.00
10 FRONT WHEEL BEARING OIL SEAL	\$ 20.00
11 FRONT BRAKE DISC	\$ 150.00
12 FRONT BRAKE CALIPER	\$ 220.00
13 HEAD COWLING LH/RH	\$ 300.00
14 HEAD COWLING IN PANEL LH/RH	\$ 160.00
15 FRONT SIGNALS LH/RH	\$ 160.00 80
16 IU UNIT	\$ 180.00 X
17 HANDLE BAR	\$ 120.00
18 HANDLE BAR GRIP	\$ 20.00 X
19 HANDLE BAR BALANCER + MIRROR	\$ 120.00
20 HANDLE BAR FRONT COVER	\$ 70.00
21 HANDLE BAR REAR COVER	\$ 60.00
22 WINDSHIELD	\$ 45.00
23 FRONT NO PLATE	\$ 10.00
24 BRAKE LEVER LH/RH	\$ 120.00
25 HEAD LIGHT	\$ 380.00
26 HEAD LIGHT PANEL	\$ 45.00
27 FRONT HEAD COVER (CORBON)	\$ 80.00 X
28 FRONT TOP COVER (CORBON)	\$ 80.00 X
29 FRONT FENDER	\$ 80.00
30 FRONT FENDER PANEL	\$ 60.00
31 FOOT REST LH/RH PANEL	\$ 160.00
32 EXHAUST PIPE	\$ 450.00 X
33 EXHAUST MUFFLER COVER	\$ 90.00
34 REAR SIGNAL LH/RH	\$ 100.00 X
35 TAIL BOARD LH/RH	\$ 240.00 120
36 SIDE COVER LH/RH	\$ 160.00
37 SIDE STAND	\$ 45.00 XR
38 MAIN STAND	\$ 90.00 XR
39 AIR BOX COVER	\$ 80.00 X
40 IN PANEL LH/RH	\$ 140.00
41 LOWER CENTER PANEL	\$ 80.00
42 LOWER PANEL LH/RH	\$ 160.00
43 CENTER PANEL	\$ 80.00
44 FOOT PANEL PLATE SET	\$ 150.00
45 COMPARTMENT	\$ 150.00
46 COMPARTMENT COVER	\$ 60.00
47 FUEL TANK COVER (CORBON)	\$ 80.00 X
48 SEAT	\$ 350.00
49 PHONE HOLDER	\$ 45.00 X
50 TOWING	\$ 40.00
51 LABOUR	\$ 850.00
TOTAL	\$ 8,425.00

Rasul

Hp 90010068

5 days

P/P

24/10/19 @1145

Reserving before paint

RESERVED
Rosh

06/11/2019
1645 HRS

Tr type ^{Pirelli Rosso Scooter} Rosso Scooter. \$1900
Helmet Compartment \$120
Tr brake pad - \$25 cut
Tr brake Caliper. \$220 (item no. 12)

Suppl - 10%
301150



HKL LIM
TEAM MOTORSPORT

Blk 100B #01-24, Bukit Merah Lane 3, Singapore 150722 Tel: 6275 8650, 6275 8585, 62727292 Fax: 6272 9291
Email: support@hklmotorsport.com.sg Website: www.hklmotorsport.com.sg

FBP1973C

1 LAMP STAY ? cr	\$ 80.00
2 METER ASSY X su	\$ 350.00 X
3 FRONT FORK ASSY LH/RH 7 bt	\$ 500.00
4 FRONT FORK UNDER BRACKET 7 bt	\$ 180.00
5 STEERING CONE BEARING 7 bt	\$ 90.00
6 BODY FRAME ALIGNMENT X su	\$ 700.00 X
7 FRONT WHEEL RIM 7 cut	\$ 380.00
8 FRONT WHEEL SHALF 7 bt	\$ 35.00
9 FRONT WHEEL BEARING 2PCS X ? ne	\$ 30.00
10 FRONT WHEEL BEARING OIL SEAL X ? ne	\$ 20.00
11 FRONT BRAKE DISC X 7 bt	\$ 150.00
12 FRONT BRAKE CALIPER cut	\$ 220.00 X
13 HEAD COWLING LH/RH cr	\$ 300.00
14 HEAD COWLING IN PANEL LH/RH Mis	\$ 160.00
15 FRONT SIGNALS LH/RH Ose / (1pc)	\$ 160.00 80
16 IU UNIT X su	\$ 180.00 X
17 HANDLE BAR 7 bt	\$ 120.00
18 HANDLE BAR GRIP X su	\$ 20.00 X
19 HANDLE BAR BALANCER + MIRROR su	\$ 120.00
20 HANDLE BAR FRONT COVER su	\$ 70.00
21 HANDLE BAR REAR COVER ? cr	\$ 60.00
22 WINDSHIELD cr	\$ 45.00
23 FRONT NO PLATE ne	\$ 10.00
24 BRAKE LEVER LH/RH su	\$ 120.00
25 HEAD LIGHT ? cr	\$ 380.00
26 HEAD LIGHT PANEL ? cr	\$ 45.00
27 FRONT HEAD COVER (CORBON) X su	\$ 80.00 X
28 FRONT TOP COVER (CORBON) X su	\$ 80.00 X
29 FRONT FENDER su	\$ 80.00
30 FRONT FENDER PANEL X cr	\$ 60.00
31 FOOT REST LH/ RH PANEL su	\$ 160.00
32 EXHAUST PIPE X su	\$ 450.00 X
33 EXHAUST MUFFLER COVER su	\$ 90.00
34 REAR SIGNAL LH/RH X su	\$ 100.00 X
35 TAIL BOARD LH/RH X su (1pc)	\$ 240.00 120
36 SIDE COVER LH/RH su (1pc) cr / LH / RH - 7 su	\$ 160.00
37 SIDE STAND X repair	\$ 45.00 X
38 MAIN STAND X repair	\$ 90.00 X
39 AIR BOX COVER X su	\$ 80.00 X
40 IN PANEL LH/RH ? cr	\$ 140.00
41 LOWER CENTER PANEL su	\$ 80.00
42 LOWER PANEL LH/RH de	\$ 160.00
43 CENTER PANEL cr	\$ 80.00
44 FOOT PANEL PLATE SET cr	\$ 150.00
45 COMPARTMENT E. cut	\$ 150.00
46 COMPARTMENT COVER cr	\$ 60.00
47 FUEL TANK COVER (CORBON) X su	\$ 80.00
48 SEAT Tube	\$ 350.00
49 PHONE HOLDER X su	\$ 45.00 X
50 TOWING	\$ 40.00
51 LABOUR	\$ 850.00

TOTAL

\$ 8,425.00

8760*

Labour & part?

Rasu

Hp 90010068

5035

5 days

10%

P/P

45,315.50

24/10/19 @ 1145

Resurvey before paint

LKK/Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to negotiation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications to be made
- Supplementary repair work, parts and material is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P - 4531.50

Supp/p - 301.50

L - 540.00

T - 5373

P/P

Repair limit 5300
5 days




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19018783/R1sf3s2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 20-11-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 6730X	Veh. Inspected	FBP 1973C
Policy No.		Coverage (\$)	0.00
Claim No.	D19006637MFSH	Excess (\$)	0.00
Assign From	MAY CHUA	Assign Date	23/10/2019
2. Vehicle Particulars & Condition			
Make & Model	YAMAHA AEROX GDR155A	c.c	155
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	MH3SG4640JJ047411	Colour	BLACK
Odometer	22049	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	120/70-14	PIRELLI	4 mm
L/H Front Tyre			mm
R/H Rear Tyre	150/70-14	PIRELLI	4 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION, O/S AND N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	15/10/2019	Inspection Date	24/10/2019
Survey held at	HKL LIM TEAM MOTORSPORT BLK 1008 #01-24 BUKIT MERAH LANE 3 SINGAPORE 159722.		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBP 1973C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	LAMP STAY	CRACKED	80.00	80.00
1	METER ASSY	SERVICEABLE	350.00	-
2	FRONT FORK ASSY LH/RH	BENT	500.00	500.00
1	FRONT FORK UNDER BRACKET	BENT	180.00	180.00
1	STEERING CONE BEARING	BENT	90.00	90.00
1	FRONT WHEEL RIM	CUT	380.00	380.00
1	FRONT WHEEL SHALF	BENT	35.00	35.00
2	FRONT WHEEL BEARING	NECESSARY	30.00	30.00
1	FRONT WHEEL BEARING OIL SEAL	NECESSARY	20.00	20.00
1	FRONT BRAKE DISC	BENT	150.00	150.00
1	FRONT BRAKE CALIPER	CUT	220.00	220.00
2	HEAD COWLING LH/RH	CRACKED	300.00	300.00
2	HEAD COWLING IN PANEL LH/RH	MISSING	160.00	160.00
2	FRONT SIGNALS LH/RH	O/S SCRATCHED	160.00	80.00
1	IU UNIT	SERVICEABLE	180.00	-
1	HANDLE BAR	BENT	120.00	120.00
1	HANDLE BAR GRIP	SERVICEABLE	20.00	-
1	HANDLE BAR BALANCER + MIRROR	SCRATCHED	120.00	120.00
1	HANDLE BAR FRONT COVER	SCRATCHED	70.00	70.00
1	HANDLE BAR REAR COVER	CRACKED	60.00	60.00
1	WINDSHIELD	CRACKED	45.00	45.00
1	FRONT NO PLATE	NECESSARY	10.00	10.00
2	BRAKE LEVER LH/RH	SCRATCHED	120.00	120.00
1	HEAD LIGHT	CRACKED	380.00	380.00
1	HEAD LIGHT PANEL	CRACKED	45.00	45.00
1	FRONT HEAD COVER (CORBON)	SERVICEABLE	80.00	-
1	FRONT TOP COVER (CORBON)	SERVICEABLE	80.00	-
1	FRONT FENDER	SCRATCHED	80.00	80.00
1	FRONT FENDER PANEL	CRACKED	60.00	60.00
2	FOOT REST LH/RH PANEL	SCRATCHED	160.00	160.00
1	EXHAUST PIPE	SERVICEABLE	450.00	-

Report Ref No. CS/FCI19018783/R1sf3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	EXHAUST MUFFLER COVER	SCRATCHED	90.00	90.00
2	REAR SIGNAL LH/RH	SERVICEABLE	100.00	-
2	TAIL BOARD LH/RH	O/S SCRATCHED	240.00	120.00
2	SIDE COVER LH/RH	CRACKED	160.00	160.00
1	SIDE STAND	TO REPAIR SEE LABOUR	45.00	-
1	MAIN STAND	TO REPAIR SEE LABOUR	90.00	-
1	AIR BOX COVER	SERVICEABLE	80.00	-
2	IN PANEL LH/RH	CRACKED	140.00	140.00
1	LOWER CENTRE PANEL	SCRATCHED	80.00	80.00
2	LOWER PANEL LH/RH	DEFORMED	160.00	160.00
1	CENTRE PANEL	CRACKED	80.00	80.00
1	SET FOOT PANEL PLATE	CRACKED	150.00	150.00
1	COMPARTMENT	CUT	150.00	150.00
1	COMPARTMENT COVER	CRACKED	60.00	60.00
1	FUEL TANK COVER (CORBON)	SERVICEABLE	80.00	-
1	SEAT	TORN	350.00	350.00
1	PHONE HOLDER	SERVICEABLE	45.00	-
1	FRT TYRE PIRELLI ROSSO SCOOTER	CUT	190.00	190.00
1	HELMET COMPARTMENT	CRACKED	120.00	120.00
1	FR BRAKE PAD	CUT	25.00	25.00
	LESS 10% DISCOUNT		-	-537.00
			7,170.00	4,833.00
	LABOUR			
	BODY FRAME ALIGNMENT.	NOT NECESSARY	700.00	-
	TOWING.		40.00	40.00
	LABOUR. INCLUSIVE OF THE REPAIR OF SIDE STAND AND MAIN STAND.		850.00	500.00
			-	-
			-	-
			-	-
			1,590.00	540.00

Report Ref No. CS/FCI19018783/R1sf3s2



GRAND TOTAL		8,760.00	5,373.00
RECOMMENDED COST OF REPAIR LIMIT			5,300.00

Report Ref No. CS/FCI19018783/R1sf3s2

MARKET VALUE: \$9,000.00-LTA REIMBURSEMENT VALUE: \$3,430=NETT VALUE: \$5,570.00

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.