

22/03/2002

ASS. REC. BY:

REF: CS

PWD19018792 / Kqd3⁸²

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (PERSON):

Venessa Chen

of

PUB

Date/Time:

23/10/19 @ 9:35am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SLS 7876B

Insured:

8KB 51512

at Workshop m/s

Lyc Design

Tel:

64833353

of

10 Amk Ind. Park 2A #04-04

Policy No:

PNPV 2018 - 00005666-01

Claim No:

1201900031803

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22/10/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11am @ 23/10/19

Person Contacted:

Siew Hoon

Vehicle IN/OUT

Date/Time

Action/Instruction

Johnnie

SLS 7876B -X

8KB 51512 -X

23/10/19 @ 2:11pm Siew Hoon informed conduct this case as 'WP'.

24/10/19 @ 2:20pm Informed Venessa Chan, we are pending estimate from repairer.

23/10/19 @ 11:57pm ULVISED to Venessa Chen via Mennmen.