

ASS. REC. BY:

REF: CS/AIG 19018794 / Ut f3

Special Instruction:

Surveyor:

MARCUS

ASSIGNMENT (Office)

From (Person):

Hor Yia nu I

of

AIG

Date/Time:

23.10.19 2.51 p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

PA 7251B

Insured:

GT 4998G

at Workshop n/s

Trek Hai Motor

Tel:

68429089

of

Block 1 Kati Bukit Ave 6 #01-54

Policy No:

0999994063

Claim No:

2685441659SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21.10.2019

CA / REV / REP. / REV 24 HRS

Date/Time:

23.10.19 2.59

Person Contacted:

Connie

Vehicle IN/OUT

H.O.D. Endorsement:

Date/Time

Action/Instruction

(✓)

Estimate

PA 7251B - CS / SMO 18 006179 / G162

1104 - 01/04/2018

GT 4998G - CC4 / AG / 5019172 / A2222

R01 - 21/11/2018

ASSIGNED BY:

Rpt:

A164

M/CWJ

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

PA 72513

at Workshop m/s

Tuck h.

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

40k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

LTA 26468

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

PA 72513

Yr Regn:

10, 07

Type: M. Car / M. Cycle / ~~Bus~~ Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Toyota Hiace

cc

2494

Colour

multi color

A/C:

Insured / Std / NI / NA

Sp. Reading

£4820

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KPH2220037252

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brakes: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195 R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Gardor

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

21/10/19

D.O.I.

24/10/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rt o/s &amp; als LHS

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

See 31-7-2027 - 7 yrs. 9 m.

have accident scene photo. MTH 13532

8/11/19 4/5 £5900 contact with Robert.

RECEIVED 11 NOV 2019

Date/Time, File Pass to?



Preli. Report



Final Report

11/11/19 Typist

Date/Time, File Return to?

21

Days Of Repair:

6

Resurvey No. of Trip:

1

Add Fee:



Site Insp. (\$



Interview (\$



Tech. Invs (\$



Wash and

Survey Fee:

Transportation:

B = RS. \$1

Photos

Cables

TOTAL

250

11

261

Report Format:

TP

Ramp Pump / L.P.J.:

5900

## PRE-REPAIR INSPECTION REQUEST – PA7251B vs GT4998G (OI) on D.O.A.: 21/10/2019

From: Hor, Yinnul  
 To: 'assignments@ikauto.com'; Admin A (admin-a@ikauto.com)  
 Cc: Fong, Andy-SY; Fan, Winnie-LW; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divyashni  
 Sent: Wednesday, 23 October, 2019 2:51:04 PM  
 Attachments:  23102019120208.pdf

Hi,

Please refer to the enclosed request from ARIDAS & ASSOCIATES.

Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Kindly assist to assign Marcus Chua as Single Joint Expert as requested.

Thanks & Regards,

Hor Yin Rul (Viviane)  
 AIG  
 PNO, 4000000  
 Singapore PNO, Claims Operations – Auto

Tel: 9007200896 | Ext: 1002208  
 Email: [Yinnul.Hor@aig.com](mailto:Yinnul.Hor@aig.com) | [www.aig.sg](http://www.aig.sg)

From: aridasv@singnet.com.sg [mailto:aridasv@singnet.com.sg]

Sent: Wednesday, October 23, 2019 2:46 PM

To: Hor, Yinnul

Cc: Fong, Andy-SY; Fan, Winnie-LW; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divyashni; aridasv@singnet.com.sg

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GT4998G AND PA7251B ON 21/10/2019

Dear Sir,

Our client has selected Marcus Chua -LKK. Please liaise with Connie directly 68429089.

Thank you.

Regards,

ARIDAS & ASSOCIATES

From: Hor, Yinnul

Sent: Wed, 23 Oct 2019 04:12:47 +0000

To: aridasv@singnet.com.sg

Cc: Fong, Andy-SY; Fan, Winnie-LW; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divyashni

Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GT4998G AND PA7251B ON 21/10/2019

Without Prejudice

Your Reference : AA.21600.19.159

Our Reference : GT4998G

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client's/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pung Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon Han Xin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufik	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Raul	LKK Auto Consultants Pte Ltd

Kenneth Kong	LKK Auto Consultants Pte Ltd
--------------	------------------------------

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rul (Viviane)  
AIG  
FNOL Adjuster I  
Singapore FNOL / Claims Operations – Auto

Tel: 8001208888 / Ext: 1002208  
YinRul.Hor@aig.com / [www.aig.sg](http://www.aig.sg)

---

**From:** Aridas @ Associates [mailto:[aridasv@singnet.com.sg](mailto:aridasv@singnet.com.sg)]  
**Sent:** Wednesday, October 23, 2019 12:06 PM  
**To:** ClaimsDocManagement  
**Subject:** [EXTERNAL] GT 4998G/PA 7251B

This message is from an external sender; be cautious with links and attachments.

Dear Sir,

Please arrange for Pre Repair Survey. Thank you.

Regards,  
**ARIDAS & ASSOCIATES**  
IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:  
The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

# ARIDAS & ASSOCIATES

ACRA REG. NO : 53131060D

NOTARY PUBLIC

ADVOCATES & SOLICITORS

COMMISSIONER FOR OATHS

NO. 75 BUKIT TIMAH ROAD, #03-13, BOON SIEW BUILDING, SINGAPORE 229833

TEL : 6 337 6359 (3 LINES) FAX : 6 338 2713

E-mail : aridasv @ singnet.com.sg

## VYILINGAM ARIDAS

LLB (Hons) Lond. M.A.  
Barrister, (Lincoln's Inn)

*Service of Court Documents  
By Fax  
Is Not Acceptable*

Our Ref : AA.21600.19.159

Your Ref : Please advise

23 OCTOBER 2019

Dear Sirs,

**ACCIDENT INVOLVING MOTOR VEHICLES PA 7251B AND GT 4998G AT CHAMPIONS WAY CARPARK LOT 48/47 ON 21 OCTOBER 2019 AT 01:20.**

We are instructed by **AURORA WORLD PTE LTD** to notify you of a road traffic accident on 2/4/19 at 15:45 involving our client's vehicle registration number **PA 7251B** and vehicle registration number **GT 4998G** driven by your insured at the material time.

Copies of the Singapore Accident Statement filed and LTA search particulars are enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damage vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Our client's motor vehicle **PA 7251B** can be inspected at

**Please contact Ms Connie at office number: 6842 9089.**

**M/s Tick Hai Motor & Welding Services,  
Block 1 Kaki Bukit Avenue 6,  
#01-54 Auto @ Kaki Bukit, Singapore 417883.**

Yours faithfully,  
**ARIDAS & ASSOCIATES**

SGCARMART.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

B

Imperial College Business School

Future you has a Full-Time MBA from Imperial College London

Find out more »

Post an Advertisement

Sell it yourself! Advertise it at just \$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Porsche 911 Carrera 997.2 Manual, COE Till 05/2020.



Rare Manual 997.2 C2 For Sale.





COE Recently Renewed.

Direct Owner - StarAd.

AutoInn

No Implications For Car Buyers

click here to view our PRISTINE USED CARS at GREAT PRICES

Browse by Category		Sort by Date Posted		20 results/page														
10 vehicles		Hiace Commuter		Advanced Search Submit														
Search Selection		Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status								
		Hiace Commuter		Any	Any	> 10 year(s) old	Any	Any	Any	Available								
	Toyota Hiace Commuter 3.0A (COE till 10/2023)		\$32,800	\$8,160 /yr	21-Jan-2009	2,982 cc	223,473 km	Bus	Available									
	Fuel Type: Diesel		Think One Automobile & Trading															
		Posted: 21-Oct-2019 Tags: 2009 Toyota Hiace, 2009 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota																
	Toyota Hiace Commuter 3.0A (COE till 07/2027)		\$45,800	\$5,890 /yr	07-Oct-2008	2,982 cc	-	Bus	Available									
	Fuel Type: Diesel		Cheapest In Market! GL Model With Auto Sliding Door! 13 Passengers! Fussy Owner, Mint Condition, Well Maintained And Serviced Regul...															
		Posted: 19-Oct-2019 Tags: 2008 Toyota Hiace, 2008 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota																
	Toyota Hiace Commuter 3.0M (COE till 06/2028)		\$55,800	\$6,440 /yr	20-Jun-2008	2,982 cc	-	Bus	Available									
	Fuel Type: Diesel		View To Offer. Driven By A Careful Driver. Regular Maintenance Done. Vehicle Is In Fantastic Condition.															
		Posted: 16-Oct-2019 Tags: 2008 Toyota Hiace, 2008 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota																
	Toyota Hiace Commuter 3.0A (COE till 05/2028)		\$48,800	\$5,700 /yr	15-May-2008	2,982 cc	348,835 km	Bus	Available									
	Fuel Type: Diesel		Think One Automobile & Trading															
		Posted: 13-Oct-2019 Tags: 2008 Toyota Hiace, 2008 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota																
		Is your COE expiring? Let us help you renew it!																
		Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.																
	Toyota Hiace Commuter 3.0A GL (COE till 03/2024)		\$36,800	\$8,320 /yr	26-Mar-2009	2,982 cc	-	Bus	Available									
	Fuel Type: Diesel		High Roof Commuter Bus, Auto Gear, Auto Sliding Door, Comfortable And Spacious Seats, New Paintwork, Excellent Condition, High Loa...															
		Bell Auto Pte Ltd																
		Posted: 07-Oct-2019 Tags: 2009 Toyota Hiace, 2009 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota																
	Toyota Hiace Commuter 3.0M (New 5-yr COE)		\$31,800	\$6,350 /yr	07-Oct-2009	2,982 cc	-	Bus	Available									
	Fuel Type: Diesel		Selling With Warranty, Engine And Gearbox In Excellent Condition! Interior In Excellent Condition, Leather Seats. 11 Seater Bus. Paint In...															
		KSL Automotive Pte Ltd																

https://www.sgcarmart.com/used\_cars/listing.php?RGD=10&MOD=Hiace Commuter&RPG=20&VEH...

24-Oct-19

Get More Cash for Your Car, Post an Ad Today

Receive a higher selling price by selling your car yourself.  
Advertise it for sale at just \$58, list till sold.

Hiace Commuter

Price Range

Depreciation

> 10 year

Vehicle Type

 Submit

Advanced Search

Home > Used Cars > Think One Automobile & Trading > Toyota Hiace Commuter 3.0A (COE till 05/2028)

Toyota Hiace Commuter 3.0A (COE till 05/2028)

[Overview](#) [Financial](#) [Accessories](#) [Similar](#) [Research](#) [Photos](#) [Map](#)

 **Think One Automobile**  

Price	\$48,800	Lifespan	14-May-2028
Depreciation	\$5,700 /yr	Reg Date	15-May-2008 (8yrs 6mths 20days COE left)
Mileage	348,835 km (30.5k /yr)	Manufactured	2008
Road Tax	N.A.	Transmission	Auto
Dereg Value	\$30,590 as of today (change)	OMV	\$41,160
COE	\$35,729	ARF	\$2,058
Engine Cap	2,982 cc	No. of Owners	3
Curb Weight	2,180 kg		
Type of Vehicle	Bus/Mini Bus		

**Features**  
View specs of the Toyota Hiace High Roof (2005)

**Category**  
COE Car

**Status**  
Available

Resources

 **Vehicle Evaluation**  
Afraid of lemons? Request to have this car evaluated professionally. Find out more

 **Car Valuation - Free**  
Find out the market value of your existing car for free. Get started



[Shortlist](#) [Compare](#) [Add note](#)

[Report Error](#) [More Actions](#)

Seller Information

Company	Think One Automobile & Trading <ul style="list-style-type: none"><li>• dealer's pricelist</li><li>• 51 vehs sold   107 vehs available</li></ul>	
Address	20 Ubi Road 4 <a href="#">Search cars nearby this location</a>	
Location	Think One Building	
Office No	65553300	
Contact Person (s)	Sheila Wong Eric	93911969 96884305 91638879

Posted on: 13-Oct-2019 | Last Updated on: 13-Oct-2019

Upfront Payment		<a href="#">+ more Financial info</a>
Transfer Fee	\$25	
Down Payment	\$4,880 (change)	Maximum 90% Loan
1st Instalment	\$1,080	Based on 4.5% interest rate
<a href="#">Compare</a>		

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	992D

### Vehicle Details

Vehicle No.:	PA7251B
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Oct 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE 2.5 A
Primary Colour:	Silver
Manufacturing Year:	2007
Engine No.:	2KD1681187
Chassis No.:	KDH2220037252
Maximum Power Output:	-
Open Market Value:	\$27,544.00
Original Registration Date:	23 Oct 2007
First Registration Date:	23 Oct 2007
Transfer Count:	5
Actual ARF Paid:	\$0.00

### Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

### Intended COE Rebate Details

COE Expiry Date:	31 Jul 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$34,070.00
COE Rebate Amount:	\$26,468.00
<b>Total Rebate Amount:</b>	<b>\$26,468.00</b>

The information contained herein is correct as at 24 Oct 2019

OK



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

15A Tick Hai Motor

ACCIDENT STATEMENT

Date Of Report 22/10/2019 16:42  
Date Of Accident 21/10/2019 01:20  
Exact Location Of Accident CHAMPIONS WAY CARPARK LOT 48/47  
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number PA7251B  
**Insured/Policyholder**  
Name Of Registered Owner AURORA WORLD PTE LTD  
Co Reg No 201002992D  
Email Address NOEMAIL  
Mobile Phone No  
Alternative Phone No OFFICE-91168517

Vehicle Particulars

Manufacturer TOYOTA  
Model HIACE  
Exact Purpose for which vehicle was being used at time of accident  
Are you claiming under your own insurance policy for repair to your vehicle? NO  
If No, Please state action to be taken THIRD PARTY  
Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company SOMPO INSURANCE SINGAPORE PTE. LTD.  
Type Of Coverage THIRD PARTY FIRE AND/OR THEFT  
Fleet Policy NO  
Policy Number D18MTSCBU000684  
Cover Note Number

Driver

Name of Driver MOHAMAD ROZMAN BIN AHMAD  
NRIC No S1616461E  
Date Of Birth 17/01/1963  
Occupation OUTDOOR  
Date Of Driving Pass 13/04/2000  
Driving Experience 19 YEARS AND 6 MONTHS  
Gender MALE  
Mobile Number (LOCAL) +65-90619444  
Fax Number  
Contact Number  
Email Address NOEMAIL

Address : BLK 515 WOODLANDS DRIVE 14 #02-147  
 Postcode 730515  
 Was driver an employee of the Insured's Company YES  
 If No, Relationship of the Driver with the Insured  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

#### General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED  
 Weather Conditions CLEAR  
 Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 2  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 Police Station Name WOODLANDS EAST N.P.C  
 Police Station Address ROAD: 3 WOODLANDS DRIVE 63 , POSTCODE: 737890 , COUNTRY: SINGAPORE  
 Police Station Contact TEL NO: - FAX NO:  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

REFER TO POLICE REPORT: T/20191021/2026.

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

#### Details of Witness 1

Name KC  
 Phone Number 98647659  
 Email Address

#### Details of Witness 2

Name BLACK  
 Phone Number 87483921  
 Email Address

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GT4998G  
 Vehicle Make/Model/Colour

Details Of Properties	VEHICLE B
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number	GBC7079M
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE C
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Sketch Plan Pg. 1

## SKETCH PLAN

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reassess policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Sketch Plan #2 Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:


- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Sketch Plan #3 Pg. 1

Describe Circumstances of the Accident

Refer to police report

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time



Driver's Signature (if driver is not the policyholder) / Date & Time

*N. R...*

Witnessed by Reporting Centre Personnel

Insurance Co. Sompo

Vehicle NO. PA72518 Date Of Accident 21, 10, 19

☐ Reporting Only

☐ Own Damage Claim

☒ Third Party Claim TICK HERE

## Sketch Plan #4 Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20191021/2026

Police Station Of Origin:  
Woodlands East N.P.C.  
3 Woodlands Drive 63 SINGAPORE 737690  
Tel No: 1800-7679999

1 of 3

Report No. T/20191021/2026

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 21/10/2019 11:09		Vide Report No.: L/20191021/0032		Station Diary No.: 104	
<b>Informant's Particulars</b>					
Name of Informant: MOHAMAD ROZMAN BIN AHMAD			Address: APT BLK 515 WOODLANDS DRIVE 14 #02-147 SINGAPORE 730515		
ID Type / ID No.: NRIC NO / S1816461E			Contact No : Home/Office: Mobile: 90619444		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 56	Date of Birth: 17/01/1963	Type of Informant: Van Owner		
Race: Bugis			Language:		Institution / School Name:
Occupation: GRAB			Driving Licence Information Class: 3,4		Date of Expiry:

<b>General Information of the Accident</b>				
Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 21/10/2019 01:20	Type of Location: Car Park
Location: Along Road 1 CHAMPIONS WAY				
Carpark:				
Weather:		Road Surface:	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision:			Anyone conveyed by ambulance: No	

<b>Details of Vehicle Involved</b>						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
PA7251B	Van				Seriously Damaged	0

## Sketch Plan #5 Pg. 1

**SINGAPORE  
POLICE FORCE**

T/20191021/2026

Police Station Of Origin:  
Woodlands East N.P.C.  
3 Woodlands Drive 63 SINGAPORE 737690  
Tel No: 1800-7679999

2 of 3

Report No: T/20191021/2026

## CONTINUATION OF REPORT

Brief Details.

On the 20/10/2019 at about 2120 hr I parked my Van (PA7251B) at the carpark of Champions way, everything was intact nothing was amiss.

On the 21/10/2019 at about 0520 hrs I went down back to my van and discovered it to be damaged with another lorry beside. I then called for traffic police and they came down.

There was a slip of paper on my vehicle stating that they are witnesses, KC 98647659 and Black 87483921, they informed me last night someone drove and bang into my van.



Sketch Plan #6 Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20191021/2028

Police Station Of Origin:  
Woodlands East N.P.C.  
3 Woodlands Drive 63 SINGAPORE 737890  
Tel No: 1800-7679999

3 of 3

Report No. T/20191021/2028

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:  
L/  
Sgt 3 JONATHAN LOW JIN HUA

Signature Of Informant:

Signature Of Interpreter:  
Not applicable

Date/Time:  
21/10/2019 11:09

SN 130	
Officer In Charge Of Case: TP/ GHT/	Signature:
Contact No.:	
Singapore Police Force	
Authentication Stamp	

Classification Of Case:



159 TICK HAI MOTOR  
1 KAKI BUKTI AVE 6 #01-20 SINGAPORE 417883  
TEL: 6842 9089 FAX: 6841 2869  
REG NO : 53033608A

Vehicle Number: PA7251B  
Vehicle Model : Toyota Hiace 2.5 A  
Manufacturing Year : 2007  
Chassis No. KDH2220037252

not Affected  
Mark  
narcus  
24/10/19  
2/5 \* 5900/  
The photo of the 1st spec  
6 day.

S/N.	Item Description	Amount (\$)
1	Front Bumper <i>Dis</i>	\$ 575.52
2	Front Bumper Side Retainer x 2 pcs <i>one</i>	\$ 397.54
3	Front Bumper Clip x 6 pcs <i>new</i>	\$ 13.60
4	Front Bumper Reinforcement (top) <i>Bent</i>	\$ 167.60
5	Front Bumper Reinforcement (top) holder x 2 pcs <i>all</i>	\$ 95.60
6	Front Bumper Reinforcement (bottom) <i>Bent</i>	\$ 380.40
7	Foglamp Cover x 2 pcs <i>11</i>	\$ 64.20
8	Front Grille <i>one</i>	\$ 567.60
9	Front Bonnet <i>1</i>	\$ 976.03
10	Front Bonnet Hinge x 2 pcs <i>11</i>	\$ 124.52
11	Front Bonnet Lock <i>one</i>	\$ 57.78
12	Toyote Centre Logo <i>new</i>	\$ 56.10
13	Headlamp x 2 pcs <i>one</i>	\$ 1,401.18
14	Front Support Panel <i>Bent/11</i>	\$ 492.60
15	Radiator <i>Bent/11</i>	\$ 1,560.20
16	Spare Tank <i>11</i>	\$ 120.38
17	Small Radiator <i>1255/10 Bent/11</i>	\$ 1,263.70
18	Small Radiator Fan Motor <i>one</i>	\$ 578.90
19	Front Corner Panel (LH) <i>11</i>	\$ 246.23
20	Side Mirror Assy (LH) <i>1</i>	\$ 441.38
21	Step Garnish <i>115</i> <i>10/11</i>	\$ 160.50
Total :		\$ 9,441.56
Less 25% :		\$ 2,360.39
Amount :		\$ 7,081.17

1-28307  
25%  
5889.80

S/N	Special Nett Item	Amount (\$)
1	Front Bumper Lower Spoiler <i>11</i>	\$ 280.00
2	Front Number Plate <i>11</i>	\$ 30.00
3	Radiator Coolant <i>new</i>	\$ 100.00
4	Headlamp Cover x 2 pcs <i>1</i>	\$ 160.00

X  
X  
30 S.N  
X

	Total :	\$ 570.00

Labour	Amount (\$)
To check front electrical wiring system and focus headlamps	\$ 50.00
To remove & reinstall 2 radiators	\$ 180.00
To remove, replace above listed parts and panel, to panel beat accident affected parts	\$ 1,800.00
To spray painting on affected area	\$ 1,500.00
Labour Total :	\$ 3,530.00
Total (Parts & Labour)	\$ 11,181.17

11406.17

P-589.80

S.N-30-00

L-1520.00

- 743980

252

5900

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No ~~allow~~ modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

### Synonyms:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG19018794/UTF3N2

Date: 15/11/2019

**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	09999994063
Claimant Vehicle No :	PA7251B	Insured Vehicle No :	GT4998G
Date of Loss:	21/10/2019	Nature of Claim:	TP
		Claim No:	2685441659SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	PA7251B	Engine No:	2KD1681187
Make & Model:	TOYOTA HIACE, 2.0 (M)	Chassis No:	KDH2220037252
Reg. Date:	23/10/2007 (Man. Year: 2007)	Odometer:	548020 km
Colour:	Multi-colour		
Engine Capacity:	2494 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195R15	Rear Tyre Size:	195R15
Front Left Side:	Condor 6 mm	Rear Left Side:	Condor 6 mm
Front Right Side:	Condor 6 mm	Rear Right Side:	Condor 6 mm

The above values represent the remaining tyre treads depth

**COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	7,876.17	5,919.80	1,956.37	24.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,530.00	1,520.00	2,010.00	56.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,406.17</b>	<b>7,439.80</b>	<b>3,966.37</b>	<b>34.77</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,900.00</b>		
<b>Nett Amount (S\$)</b>	<b>11,406.17</b>	<b>5,900.00</b>	<b>5,506.17</b>	<b>48.27</b>

**INSPECTION**

Date of Assignment:	23/10/2019	Inspected At:	Tick Hai Motor
Date Inspected:	24/10/2019		Blk 1 Kaki Bukit Avenue 6,
			#01-54
			Singapore 417883
Estimated Period of Repair:	6.0 days		

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Distorted	575.52 FL	*575.52 FL
2	2	*FRONT BUMPER SIDE RETAINER	Cracked	397.54 FL	*397.54 FL
3	1	*FRONT BUMPER CLIP (6 Pcs)	Necessary	13.60 FL	*13.60 FL
4	1	*FRONT BUMPER REINFORCEMENT (TOP)	Bent	167.60 FL	*167.60 FL
5	2	*FRONT BUMPER REINFORCEMENT (TOP) HOLDER	Not Necessary	95.60 FL	*- FL
6	1	*FRONT BUMPER REINFORCEMENT (BOTTOM)	Bent	380.40 FL	*380.40 FL
7	2	*FOGLAMP COVER	Not Necessary	64.20 FL	*- FL
8	1	*FRONT GRILLE	Cracked	567.60 FL	*567.60 FL
9	1	*FRONT BONNET	Repair	976.03 FL	*- FL
10	2	*FRONT BONNET HINGE	Not Necessary	124.52 FL	*- FL
11	1	*FRONT BONNET LOCK	Serviceable	57.78 FL	*- FL
12	1	*TOYOTA CENTRE LOGO	Necessary	56.10 FL	*56.10 FL
13	2	*HEADLAMP	Cracked	1,401.18 FL	*1,401.18 FL
14	1	*FRONT SUPPORT PANEL	Bent/Twisted	492.60 FL	*492.60 FL
15	1	*RADIATOR	Bent/Punctured	1,560.20 FL	*1,560.20 FL
16	1	*SPARE TANK	Not Necessary	120.38 FL	*- FL
17	1	*SMALL RADIATOR	Bent/Punctured	1,263.70 FL	*1,255.10 FL
18	1	*SMALL RADIATOR FAN MOTOR	Cracked	578.90 FL	*578.90 FL
19	1	*FRONT CORNER PANEL (LH)	Dented	246.23 FL	*246.23 FL
20	1	*SIDE MIRROR ASSY (LH)	Repair	441.38 FL	*- FL
21	1	*STEP GARNISH N/S	Torn	160.50 FL	*160.50 FL
22	1	*FRONT BUMPER LOWER SPOILER	Not Necessary	280.00 FS	*- FS
23	1	*FRONT NUMBER PLATE	Not Necessary	30.00 FS	*- FS
24	1	*RADIATOR COOLANT	Necessary	100.00 FS	*30.00 FS
25	2	*HEADLAMP COVER	Repair	160.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 10,311.56 7,883.07  
 - List Item Discount on L Items 25.00/25.00% (\$\$) 2,435.39 1,963.27

Total Parts (\$\$) 7,876.17 5,919.80

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK FRONT ELECTRICAL WIRING SYSTEM AND FOCUS HEADLAMPS	New	50.00	20.00
2	TO REMOVE & REINSTALL 2 RADIATORS	New	180.00	0.00
3	TO REMOVE,REPLACE ABOVE LISTED PARTS AND PANEL,TO PANEL BEAT ACCIDENT AFFECTED PARTS	New	1,800.00	700.00
4	TO SPRAY PAINTING ON AFFECTED AREA	New	1,500.00	800.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,530.00</b>	<b>1,520.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >