

ASS. REC. BY:

REF:

CS3/II 19018 746/ fcd321

Special Instruction:

Supervisor:

RAM

ASSIGNMENT (Office)

From (Person): Gabriel wee

of

III

Date/Time: 22/10/2019 @ 4:13pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMN 4717L

Insured:

SHD 3134L

at Workshop in/s

ECO Automobile

Tel:

9176 5733

of

13 Kaki Bukit Road 4 #03-29

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21/10/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9:50am @ 23/10/19

Person Contacted:

Alfie

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction

Estimate (X)

SMN 4717L - X

SHD 3134L - NS/INC/9007643/k/sd382

D.O.A: 26/4/2019

Disassemble - 23/10/19 03:40PM

After - 04/11/19 01:17PM

08/11/19

Submit PRS.

ASS. REC. BY:

REF: III

PRS

ASSIGNMENT

From:

Date:

23/10/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMN 4717L

at Workshop m/s

ECO Automobile

of 13 kaki Bukit Road 4 # 03-29

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
xx	

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SMN4717L

Yr Regn:

AUG / 2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota vellfire

c.c 2493

Colour

black

A/C:

Insured / Std / NI / NA

Sp. Reading

13557

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

AH300239668

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 235/50 R18

R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 4 mm

R/Bal. 5 mm

L/Bal. 4 mm

L/Bal. 5 mm

D.O.A. 21/10/19

D.O.I. 23/10/19 1021AM

Survey held at ECO Automotive

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Repair days: 6 days
	Range: \$4,000 - \$11,000 \$7,000 - \$8,000
	MV: \$168599.44
	PV: \$74091
	NV: \$94508.44

Date/Time, File Pass to?

☐

Prel. Report

1) 08/11 11:15 AM

☐

Final Report

Date/Time, File Return to?

2)

Report Format:

PRS.

Lump Sum / LB: C

Days Of Repair: 6

Resurvey No. of Trip: 2

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

S + RS: \$

Photos

Others

TOTAL

120

11

131

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Tuesday, 22 October 2019 4:13 PM
To: Weng Kit; 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: 'Jerone'; Pooi Chin Han Daniel
Subject: RE: Our Ref: SMN 4717L (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING SMN 4717L & SHD 3134L ALONG PIE ON 21 OCTOBER 2019
Attachments: 20191022142852780.pdf

Dear Sir / Mdm

This Pre-Repair Survey is on Without Prejudice Basis.

THIRD PARTY VEHICLE NO. : SMN4717L
III INSURED VEHICLE NO. : SHD3134L
DATE OF LOSS : 21.10.19

We acknowledge receipt of your email.

In compliance to Pre-Action Protocol for NIMA cases, we note that

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK AUTO CONSULTANT to conduct the pre-repair survey.

This claim is handled by Daniel.

Please let us have your client's accident report and repair estimate for our appointed surveyor to conclude his report.

****We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**

****Surveyor kindly upload this assignment to Merimen.**

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext – 248

From: Weng Kit [mailto:wengkit@chiaarul.com]
Sent: 22 October, 2019 3:02 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: 'Jerone' <jerone@chiaarul.com>
Subject: RE: Our Ref: SMN 4717L (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING SMN 4717L & SHD 3134L ALONG PIE ON 21 OCTOBER 2019

Dear Sirs,

We refer to your email below.

Our client is not agreeable to your list of motor surveyors.

We are instructed by our client to propose the list of their surveyor as the mutual surveyor / single joint expert for your consideration as follows:

Surveyor	Surveyor Firm
S. Kumanan	SK Auto Consultants

Best Regards,

Weng Kit (Mr.)

Paralegal

M/s Chia S Arul LLC

151 Chin Swee Road

#03-09 Manhattan House

Singapore 169876

Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and /or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at info@chiaarul.com. Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

From: Motor Claim - III [<mailto:motorclaim@iii.com.sg>]

Sent: Tuesday, October 22, 2019 2:48 PM

To: Weng Kit

Cc: 'Jerone'

Subject: RE: Our Ref: SMN 4717L (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING SMN 4717L & SHD 3134L ALONG PIE ON 21 OCTOBER 2019

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext – 248

From: Weng Kit [<mailto:wengkit@chiaarul.com>]

Sent: 22 October, 2019 2:29 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Cc: 'Jerone' <jerone@chiaarul.com>

Subject: Our Ref: SMN 4717L (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING SMN 4717L & SHD 3134L
ALONG PIE ON 21 OCTOBER 2019

Dear Sirs,

We refer to the above matter.

Attached is a copy of our pre-repair survey notice dated 22 October 2019 for your attention.

Best Regards,

Weng Kit (Mr.)

Paralegal

M/s Chia S Arul LLC

151 Chin Swee Road

#03-09 Manhattan House

Singapore 169876

Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and /or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at info@chiaarul.com. Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be

intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Require PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	107N
Vehicle Details	
Vehicle No.:	SMN4717L
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Oct 2019
Vehicle Make:	TOYOTA
Vehicle Model:	VELLFIRE 8-SEATER 2.5X CVT
Primary Colour:	Black
Manufacturing Year:	2019
Engine No.:	2ARJ258668
Chassis No.:	AGH300239668
Maximum Power Output:	134.0 kW (179 bhp)
Open Market Value:	\$39,195.00
Original Registration Date:	13 Aug 2019
First Registration Date:	13 Aug 2019
Transfer Count:	0
Actual ARF Paid:	\$46,873.00 $\leftarrow 90\%$
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Aug 2029
PARF Rebate Amount:	\$35,154.00
Intended COE Rebate Details	
COE Expiry Date:	12 Aug 2029
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$42,002.00
COE Rebate Amount:	\$38,937.00
Total Rebate Amount:	\$74,091.00

e information contained herein is correct as at 24 Oct 2019

Remaining: 9 years 9 months 23dys (117.7) OK

Depn: \$14,800/yearly \$1233.33/monthly

$117.7 \times \$1233.33 = \145162.94

$\$145162.94 + \$23436.90 = \underline{\underline{\$168599.84}}$

New Car \$179,000

M.V - \$150,000

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/10/2019 10:26
Date Of Accident	21/10/2019 06:20
Exact Location Of Accident	[PIE TWRDS CHANGI]
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMN4717L
Insured/Policyholder	
Name Of Registered Owner	JUBSTAR PTE LTD
Co Reg No	201808107N
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-90298853

Vehicle Particulars

Manufacturer	TOYOTA
Model	VELLFIRE 8-SEATER 2.5X CVT
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5108220109
Cover Note Number	

Driver

Name of Driver	LIM YEW KENG EDMUND
NRIC No	
Date Of Birth	
Occupation	
Date Of Driving Pass	06/01/1997
Driving Experience	22 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92389387
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - HIRER

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN;

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHD3134L

Vehicle Make/Model/Colour HYUNDAI / I40 1.7 CRDI F/L AT ABS AIRBAG 4DR

Details Of Properties

Vehicle Category TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4 #02-02
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vackb@vicom.com.sg

Reporting Centre Personnel's Signature


Name:

NRIC/FIN No.:

22 OCT 2019

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 21/10/2019 @ 06:18am, I was travelling straight at PE towards Changi Airport. In front of my car slows down and stops. I also slow down and stop. Suddenly car B (SHD3134L) couldn't stop in time and bang onto my rear portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

IDAG-KAKI BUKIT (VAG)
23 Kaki Bukit Ave 4 #02-02
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vackb@vicom.com.sg

Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

22 OCT 2019

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Nov 2019 10:18 Edit Reg		22 Oct 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	-		
Vehicle Reg. No.:	SMN4717L	Date of Loss:	21/10/2019 00:00 - :59 [2 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	SHD3134L	Policy No. (Claimant):	
		Excess:	
Repairer:	Eco Automobile Claims And Repair Pte Ltd (HQ) 13 KAKI BUKIT ROAD 4, #03-29, 417807 Kaki Bukit - Tel:		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Pooi Chin Han Daniel]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 04/11/2019]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMN4717L
[SHD3134L]

TP























































-



Oct 21 2019 12:00AM

[-]

Eco Automobile Claims And Repair Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	24/10/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
2	24/10/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
3	24/10/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
4	24/10/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
5	24/10/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
6	24/10/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
7	24/10/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
8	24/10/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
9	24/10/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
10	24/10/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
11	24/10/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
12	24/10/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
13	24/10/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
14	24/10/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
15	24/10/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
16	24/10/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
17	24/10/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
18	24/10/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
19	24/10/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
20	24/10/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
21	24/10/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
22	24/10/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
23	24/10/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
24	24/10/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
25	24/10/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
26	24/10/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
27	24/10/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
28	24/10/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
29	24/10/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
30	24/10/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
31	24/10/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
32	24/10/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
33	24/10/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
34	24/10/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
35	24/10/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
36	24/10/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
37	24/10/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
38	24/10/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
39	24/10/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
40	24/10/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
41	24/10/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
42	24/10/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>
43	24/10/19 11:24	General View		Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	24/10/19 11:24	General View	 Load JPG	<input checked="" type="checkbox"/>
45	24/10/19 11:24	General View	 Load JPG	<input checked="" type="checkbox"/>
46	24/10/19 11:24	General View	 Load JPG	<input checked="" type="checkbox"/>
47	24/10/19 11:24	General View	 Load JPG	<input checked="" type="checkbox"/>
48	24/10/19 11:24	General View	 Load JPG	<input checked="" type="checkbox"/>
49	24/10/19 11:24	General View	 Load JPG	<input checked="" type="checkbox"/>
50	24/10/19 11:25	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
51	24/10/19 11:25	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
52	24/10/19 11:25	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
53	24/10/19 11:25	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
54	24/10/19 11:25	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
55	24/10/19 11:25	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
56	24/10/19 11:25	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
57	24/10/19 11:25	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
58	24/10/19 11:25	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
59	24/10/19 11:25	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
60	24/10/19 11:25	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
61	24/10/19 11:25	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
62	24/10/19 11:25	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
63	24/10/19 11:25	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
64	24/10/19 11:25	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
65	24/10/19 11:25	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
66	24/10/19 11:25	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
67	24/10/19 11:25	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
68	24/10/19 11:25	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
69	24/10/19 11:25	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
70	24/10/19 11:25	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
71	24/10/19 11:25	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
72	24/10/19 11:25	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
73	24/10/19 11:25	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
74	24/10/19 11:25	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
75	24/10/19 11:25	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
76	24/10/19 11:25	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
77	24/10/19 11:25	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
78	24/10/19 11:25	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
79	24/10/19 11:25	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
80	24/10/19 11:25	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
81	24/10/19 11:25	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
82	24/10/19 11:25	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
83	24/10/19 11:25	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
84	24/10/19 11:25	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
85	24/10/19 11:25	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
86	24/10/19 11:25	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
87	24/10/19 11:25	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
88	24/10/19 11:25	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
89	24/10/19 11:25	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
90	24/10/19 11:25	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
91	24/10/19 11:25	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
92	24/10/19 11:25	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
93	24/10/19 11:25	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
94	24/10/19 11:25	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
95	24/10/19 11:25	Photographs of Damaged Items	 Load JPG	<input checked="" type="checkbox"/>
96	13/11/19 10:25	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
97	13/11/19 10:25	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
98	13/11/19 10:25	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
99	13/11/19 10:25	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
100	13/11/19 10:25	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
101	13/11/19 10:25	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
102	13/11/19 10:25	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
103	13/11/19 10:25	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
104	13/11/19 10:25	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
105	13/11/19 10:25	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
106	13/11/19 10:25	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
107	13/11/19 10:25	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
108	13/11/19 10:25	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
109	13/11/19 10:25	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
110	13/11/19 10:25	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
111	13/11/19 10:25	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
112	13/11/19 10:25	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
113	13/11/19 10:25	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
114	13/11/19 10:25	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
115	13/11/19 10:25	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	24/10/19 09:19	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III19018796/FCD3E2

Date: 13/11/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant SMN4717L

Insured Vehicle No : SHD3134L

Vehicle No : SMN4717L

Nature of Claim:

TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMN4717L

Make & Model: TOYOTA VELLFIRE, 2.5 (A)

Engine No: 2ARJ258668

Reg. Date: 13/08/2019 (Man. Year: 2019)

Chassis No: AGH300239668

Colour: Black

Odometer: 13557 km

Engine Capacity: 2493 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50 R18

Rear Tyre Size:

235/50 R18

Front Left Side: Dunlop 4 mm

Rear Left Side:

Dunlop 5 mm

Front Right Side: Dunlop 4 mm

Rear Right Side:

Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 22/10/2019

Date Inspected: 23/10/2019 Inspected At:

Eco Automobile Claims And Repair
Pte Ltd (HQ)
13 KAKI BUKIT ROAD 4, #03-29
Singapore 417807

Estimated Period of Repair: 0.0 days

Adjuster: PARASURAM SHANMUGAM

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Nov 2019)
Parts:	M1-MPV	TOYOTA VELLFIRE 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMN4717L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >