

ASS. REC. BY:

REF: S/CT1 M018803/Kt f39

Special Instruction:

Written

SURVEYOR: Kamuth

ASSIGNMENT (Office)

From (Person): Tan Kah Leong

of CT2

Date/Time: 22.10.19 15.21 p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJT 6891G

Insured: SLL 1510H

at Workshop m/s Ah Lim Motor

Tel: 64631242

of 10 Amk Industrial Park 2A #01-09

Policy No: DMRESV 30331119022

Claim No: SNM 19D 20499507

Sum Insured:

Excess:

Make of Vch:
(Client's Record)

D.O.A. 19.10.2019

CA / REV / REP. / REV 24 HRS

imp

H.O.D. Endorsement:

Date/Time: 22.10.19 3.30 p.m

Person Contacted: wei jte

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SJT 6891G - ✓
	SLL 1510H - x
31/12	61 Smp @ 3600 confirmed (Red: 6342.60:63%)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Oct 2019		23 Oct 2019 15:21 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:									
Main Claimant:		ONG POO CHEW, ID: S13917461							
Vehicle Reg. No.:		SJT6891G	Date of Loss:	19/10/2019 23:00 - :59					
Claim Type:		TP / SNM19D20499502	Policy/Cover Note No.:	DMPCSN30331119022					
Vehicle Reg. No. (Insured):		SLL1510H	Policy No. (Claimant):	S111188594					
			Excess:	S\$750.00					
Repairer:		Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6483 1244							
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]							
Claimant's Insurer:		NTUC Income Insurance Co-operative Ltd (HQ) - Tel:							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 04/11/2019]							
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Summer Lee (LKK Auto)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Wednesday, 23 October, 2019 3:16 PM
To: Zila @ Ah Lim Motor Company; assignments
Subject: RE: OUR REF: SNM19D204995-SLL1510H-TKL- TP CASE / SJT6891G & SLL1510H

WITHOUT PREJUDICE

Dear Zila,

We refer to your email dated 23.10.2019.

We will be assigning M/s LKK Auto Consultants to survey your client's vehicle on a without prejudice basis.

Aside to LKK,

Please refer to the email below & proceed to survey the third party vehicle.

Thank you.

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Zila @ Ah Lim Motor Company [mailto:zila@ahlimmotor.com.sg]
Sent: Wednesday, October 23, 2019 3:10 PM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Subject: Re: OUR REF: SNM19D204995-SLL1510H-TKL- TP CASE / SJT6891G & SLL1510H

Hi,

We choose Kenneth Kong to be the surveyor.

Thanks.

Regards,
Zila
Ah Lim Motor (AMK)
10 Ang Mo Kio Ind Pk 2A
#01-09 AMK AUTOPOINT
S568047

Tel: 64831244 Fax: 64836170

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Wednesday, 23 October 2019 3:06 PM
To: Zila @ Ah Lim Motor Company <zila@ahlimmotor.com.sg>
Subject: RE: OUR REF: SNM19D204995-SLL1510H-TKL- TP CASE / SJT6891G & SLL1510H

Without Prejudice

Dear Zila,

Please see attached and let us know if you agree with SJE.

Thank you.

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI
Sent: Wednesday, October 23, 2019 2:58 PM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>;
zila@ahlimmotor.com.sg
Subject: OUR REF: SNM19D204995-SLL1510H-TKL- TP CASE / SJT6891G & SLL1510H

Dear Kah Leong,

Please conduct PRS for SJT6891G.

Note : officer in charge – Kah Leong 63896193.

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Zila @ Ah Lim Motor Company [<mailto:zila@ahlimmotor.com.sg>]
Sent: Wednesday, 23 October, 2019 2:28 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: TP CASE / SJT6891G & SLL1510H

Hi Claims Dept,

Kindly arrange for the vehicle to be survey.

Note: Vehicle is not in - To be arrange.

Thanks.

Regards,

Zila

Ah Lim Motor (AMK)

10 Ang Mo Kio Ind Pk 2A

#01-09 AMK AUTOPOINT

S568047

Tel: 64831244 Fax: 64836170

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 746I

Vehicle Details

Vehicle No.: SJT6891G
Vehicle to be Exported: No
Intended Deregistration Date: 23 Oct 2019
Vehicle Make: SUZUKI
Vehicle Model: SX4 HATCHBACK 1.6 AT
Primary Colour: Silver
Manufacturing Year: 2009
Engine No.: M16A1484737
Chassis No.: JSAGYA21500312481
Maximum Power Output: 82.0 kW (109 bhp)
Open Market Value: \$15,951.00
Original Registration Date: 27 Oct 2009
First Registration Date: 27 Oct 2009
Transfer Count: 3
Actual ARF Paid: \$15,951.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 26 Oct 2019
PARF Rebate Amount: \$7,975.00

Intended COE Rebate Details

COE Expiry Date: 26 Oct 2024
COE Category: A - Car (1600cc & below)
COE Period(Years): 5
PQP Paid: \$15,287.00
COE Rebate Amount: \$11.00
Total Rebate Amount: \$7,986.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 23 Oct 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/10/2019 14:57
Date Of Accident	19/10/2019 23:30
Exact Location Of Accident	CAUSEWAY FROM WOODLANDS CHECKPOINT (TWDS MSIA)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJT6891G
Insured/Policyholder	
Name Of Registered Owner	ONG POO CHEW
NRIC No	S1391746I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90669239
Alternative Phone No	OTHERS-97636435

Vehicle Particulars

Manufacturer	SUZUKI
Model	SX4 HATCHBACK 1.6 AT
Exact Purpose for which vehicle was being used at time of accident	PTE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5111188594
Cover Note Number	18/07/2019 - 17/07/2020

Driver

Name of Driver	ONG GUANG YANG
NRIC No	S9615445C
Date Of Birth	01/05/1996
Occupation	INDOOR
Date Of Driving Pass	07/08/2019
Driving Experience	0 YEAR AND 2 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-97636435
Fax Number	
Contact Number	
EMail Address	GUANGYANG5550@GMAIL.COM

Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number JQQ1031
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name ONG GUANG YANG
Approximate Age
Injuries Sustain
Injured person in which vehicle? SJT6891G
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address
Postcode

DETAILS OF INJURED PERSON 2

Name SHANICE BEK YEN YI
Approximate Age
Injuries Sustain
Injured person in which vehicle? SJT6891G
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address
Postcode

POLICE REPORT PG 1



**SINGAPORE
POLICE FORCE**



T/20191020/2078

1 of 3

Police Station Of Origin:
Kebun Baru NPP
111 Ang Mo Kio Avenue 4 SINGAPORE
560111
Tel No: 1800-4589999

Report No. T/20191020/2078

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 20/10/2019 18:53		Vide Report No.:		Station Diary No. 19	
Informant's Particulars					
Name of Informant: ONG GUANG YANG			Address: APT BLK 105 ANG MO KIO AVENUE 4 #10-204 SINGAPORE 560105		
ID Type / ID No.: NRIC NO / S9615445C			Contact No.: Home/Office: Mobile: 97636435		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 23	Date of Birth: 01/05/1996	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: TECHNICIAN			Driving Licence Information: Class: 3A		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 19/10/2019 23:30	Type of Location:
Location: Along Road 1 CAUSEWAY Along the causeway from Woodlands checkpoint, near to Malaysia Checkpoint				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJT6891G	Car				Slightly Damaged	1
SLL1510H	Car				Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20191020/2078

Police Station Of Origin:
Kebun Baru NPP
111 Ang Mo Kio Avenue 4 SINGAPORE
560111
Tel No: 1800-4589999

3 of 3


Report No. T/20191020/2078

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: F / Sgt 2 KOH JIA JUN 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 20/10/2019 18:53
Officer In Charge Of Case: TP / AEIT / Sgt 2 SHARIFAH NOR FARIZAN BINTE SYED MOHD SAID Contact No.: 65476172	Classification Of Case:
Authentication Stamp NP168 	 

2ND POLICE REPORT PG 2



**SINGAPORE
POLICE FORCE**



T/20191021/2074

Police Station Of Origin:
Kebun Baru NPP
111 Ang Mo Kio Avenue 4 SINGAPORE
560111
Tel No: 1800-4589999

2 of 3

Report No. T/20191021/2074

CONTINUATION OF REPORT

Driver			
Name	ONG GUANG YANG		ID No. S9615445C
Related Vehicle	NIL		Contact No. 97638435
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 3A Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

Reference to the earlier report that I lodged, (T/20191020/2078), there is an additional car involved in the accident. During the accident, the impact of the collision from the car behind mine caused my car to hit onto the front car, JQQ1031.

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5111188594	Cover : Third Party
1. Index mark and Registration Number of Vehicle	: SJT6891G
Chassis Number	: JSAGYA21S00312481
2. Name of Policyholder	: ONG POO CHEW
3. Effective Date of Insurance	: 18 Jul 2019
4. Expiry Date of Insurance	: 17 Jul 2020
5. Persons or Classes of Persons entitled to drive#	
(a) The Policyholder.	
(b) Any other person who is driving on the Policyholder's order or with his/her permission.	
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.	
6. Limitations as to Use#	
(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.	

This Policy does not cover

- (a) Use for hire or reward.
- (b) Use for racing, pace-making, reliability trial or speed-testing.
- (c) Use for the carriage of goods (other than samples) in connection with any trade or business.
- (d) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: N/A
EXCESS (SECTION 2)	: N/A
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: N/A
REPAIR AT OWNER'S PREFERRED WORKSHOP	: NO
INSURE WITH COE	: N/A
NCD PROTECTION	: NO
PRIMARY DRIVER	: ONG POO CHEW
NAMED DRIVER (1)	: N/A
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: N/A

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : ONE STOP INSURANCE AGENCY (00000571115)
Date of Issue : 18 Jul 2019 13:27 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

Authorised Officer



Chief Executive

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST-M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : ONG POO CHEW
 105 ANG MO KIO AVE 4
 #10-204
 SINGAPORE 560105
 TEL: 97636435
 ATTN:

Estimate No: MC1900774
 Date: 23 Oct 2019
 Policy No: 51111788594
 Veh Reg No: SJT6891G
 Make/Model: SUZUKI SX4
 HATCHBACK 1.6 AT

Your Ref No: SJT6891G
 Claim Type: Third Party
 Accident Date: 19/10/2019
 TP Veh Reg No: SLL1510H

*UIC
 1030am*

*Not withash
 UIC B?
 Missing After Paint 6-7 days*

Estimate Repair Cost to Vehicle No :SJT6891G

Description	Quantity	List Price	Amount
		SS	SS
SPARE PARTS			
1 FRONT BONNET	1 PC	481.60	✓
2 FRONT BONNET INNER LOCK	1 PC	56.55	X
3 HEADLAMP LH & RH	2 PC	738.10	2X 369.05
4 FRONT GRILLE	1 PC	117.30	X
5 FRONT GRILLE EMBLEM	1 PC	30.00	X
6 FRONT GRILLE CLIPS	8 PC	24.00	X
7 FRONT BUMPER	1 PC	790.45	✓
8 FRONT BUMPER SIDE RETAINER LH & RH	1 PC	18.45	✓
9 FRONT BUMPER CLIPS	15 PC	45.00	✓
10 FRONT BUMPER LOWER GARNISH	1 PC	167.00	X
11 FRONT BUMPER REINFORCEMENT	1 PC	345.10	X
12 FRONT FENDER LH	1 PC	272.20	X
13 FRONT FENDER COWLING LH	1 PC	60.00	X
14 FRONT FENDER CLIPS	8 PC	24.00	X
15 RADIATOR SUPPORT PANEL	1 PC	1,074.30	X
16 AIR CON CONDENSER	1 PC	586.30	X
17 RADIATOR ASSY	1 PC	806.20	X
18 ENGINE MOUNTING FRONT	1 PC	80.00	X
19 ENGINE MOUNTING RH	1 PC	140.10	X
20 ENGINE MOUNTING REAR	1 PC	75.00	X
21 GEARBOX MOUNTING LH	1 PC	73.00	X
22 REAR BUMPER	1 PC	549.00	✓
23 REAR BUMPER SIDE RETAINERS LH & RH	2 PC	44.00	✓
24 REAR BUMPER CLIPS	15 PC	45.00	✓
25 REAR BUMPER LOWER GARNISH CTR (BLACK)	1 PC	160.00	✓
26 REAR BUMPER LOWER GARNISH SIDE LH & RH	2 PC	240.00	X
27 REAR BUMPER REINFORCEMENT	1 PC	230.00	X
28 REAR END PANEL	1 PC	316.00	X
29 REAR END PANEL TOP GARNISH	1 PC	85.00	X
		7,673.65	
	Less 15%	1,151.05	6,522.60
LABOUR			
30 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	✓ 200
31 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	X



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : ONG POO CHEW
 105 ANG MO KIO AVE 4
 #10-204
 SINGAPORE 560105
 TEL: 97636435
 ATTN:

Estimate No: MC1900774
 Date: 23 Oct 2019
 Policy No: 51111788594
 Veh Reg No: SJT6891G
 Make/Model: SUZUKI SX4
 HATCHBACK 1.6 AT

Your Ref No: SJT6891G
 Claim Type: Third Party
 Accident Date: 19/10/2019
 TP Veh Reg No: SLL1510H

Estimate Repair Cost to Vehicle No :SJT6891G

Description	Quantity	List Price	Amount
32 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD RADIATOR SUPPORT PANEL TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	800.00	400.00
33 TO SPRAY FRONT BONNET,FRONT BUMPER,FRONT FENDER LH,RADIATOR SUPPORT PANEL.	1 PC	800.00	550.00
34 TO DISCONNECT AND CHECK ELECTRICAL WIRING. WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS. TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	20.00
35 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	80.00	50.00
36 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD END PANEL.TO KNOCK & REPAIR SPARE TYRE PANEL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	800.00	550.00
37 TO SPRAY TAILGATE,REAR BUMPER,END PANEL,SPARE TYRE PANEL.	1 PC	800.00	600.00
		3,420.00	3,420.00
		Total	S\$ 9,942.60
		Add GST @ 7%	695.98
		Total Amount Payable	S\$ 10,638.58

TOTAL: SINGAPORE DOLLAR TEN THOUSAND SIX HUNDRED THIRTY EIGHT AND CENTS FIFTY EIGHT ONLY

Please arrange this vehicle to be surveyed soonest possible.
 Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

LKK Auto Consultants hereby notify the Repairer of the following:

- To survey before/after some painting
- To display damaged parts only repaired
- Parts prices are subject to confirmation
- Third party survey is on "Who is available" basis
- No illegal modification is allowed
- Supplies and services are subject to availability and price change

Accepted: _____
 Signature: _____
 Date: _____

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Oct 2019		23 Oct 2019 15:21 Edit Adj Rpt	S\$3,600.00 Edit Estimates	S\$3,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: - ID: -									
Main Claimant: ONG POO CHEW , ID: S13917461									
Vehicle Reg. No.: SJT6891G		Date of Loss: 19/10/2019 23:00 - :59 [119 Months and 22 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM19D20499502		Policy/Cover Note No.: DMPCSN30331119022							
Vehicle Reg. No. (Insured): SLL1510H		Policy No. (Claimant): 5111188594							
		Excess: S\$750.00							
Repairer: Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6483 1244									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 04/11/2019]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJT6891G (SNM19D20499502)
[SLL1510H]
TP
ONG POO CHEW
Oct 19 2019 11:00PM
[-]
Ah Lim Motor Company

Upload Documents Upload Photos Compose New Letter			View View in Browser v
Photos/Images			3 per page v <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail <input type="checkbox"/>
1	06/01/20 17:26	General View	<input checked="" type="checkbox"/>
2	06/01/20 17:26	General View	<input checked="" type="checkbox"/>
3	06/01/20 17:26	General View	<input checked="" type="checkbox"/>
4	06/01/20 17:26	General View	<input checked="" type="checkbox"/>
5	06/01/20 17:26	General View	<input checked="" type="checkbox"/>
6	06/01/20 17:26	General View	<input checked="" type="checkbox"/>
7	06/01/20 17:26	General View	<input checked="" type="checkbox"/>
8	06/01/20 17:26	General View	<input checked="" type="checkbox"/>
9	06/01/20 17:26	General View	<input checked="" type="checkbox"/>
10	06/01/20 17:26	General View	<input checked="" type="checkbox"/>
11	06/01/20 17:26	General View	<input checked="" type="checkbox"/>
12	06/01/20 17:26	General View	<input checked="" type="checkbox"/>
13	06/01/20 17:26	General View	<input checked="" type="checkbox"/>
14	06/01/20 17:26	General View	<input checked="" type="checkbox"/>
15	06/01/20 17:26	General View	<input checked="" type="checkbox"/>
16	06/01/20 17:26	General View	<input checked="" type="checkbox"/>
17	06/01/20 17:26	General View	<input checked="" type="checkbox"/>
18	06/01/20 17:26	General View	<input checked="" type="checkbox"/>
19	06/01/20 17:26	General View	<input checked="" type="checkbox"/>
20	06/01/20 17:26	General View	<input checked="" type="checkbox"/>
21	06/01/20 17:26	General View	<input checked="" type="checkbox"/>
22	06/01/20 17:26	General View	<input checked="" type="checkbox"/>
23	06/01/20 17:26	General View	<input checked="" type="checkbox"/>
24	06/01/20 17:26	General View	<input checked="" type="checkbox"/>
25	06/01/20 17:26	General View	<input checked="" type="checkbox"/>
26	06/01/20 17:28	Reinspection Photo	<input checked="" type="checkbox"/>
27	06/01/20 17:28	Reinspection Photo	<input checked="" type="checkbox"/>
28	06/01/20 17:28	Reinspection Photo	<input checked="" type="checkbox"/>
29	06/01/20 17:28	Reinspection Photo	<input checked="" type="checkbox"/>
30	06/01/20 17:28	Reinspection Photo	<input checked="" type="checkbox"/>
31	06/01/20 17:28	Reinspection Photo	<input checked="" type="checkbox"/>
32	06/01/20 17:28	Reinspection Photo	<input checked="" type="checkbox"/>

Linked Accident Report Documents

Assessment Reports			View View in Browser v
			1 per page v <input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail <input type="checkbox"/>
1	06/12/19 19:10	Accident Statement	<input checked="" type="checkbox"/>
2	06/12/19 19:15	Accident Statement	<input checked="" type="checkbox"/>
3	06/12/19 19:20	Accident Statement	<input checked="" type="checkbox"/>
4	06/12/19 19:20	Accident Statement	<input checked="" type="checkbox"/>
Photos/Images			

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	21/10/19 16:12	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	21/10/19 16:12	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	21/10/19 16:12	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	21/10/19 16:12	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	21/10/19 16:12	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	21/10/19 16:12	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	21/10/19 16:12	SCENE PHOTO	Load JPG	<input checked="" type="checkbox"/>
8	21/10/19 16:12	SCENE PHOTO	Load JPG	<input checked="" type="checkbox"/>
9	21/10/19 16:12	SCENE PHOTO	Load JPG	<input checked="" type="checkbox"/>
10	21/10/19 16:12	SCENE PHOTO	Load JPG	<input checked="" type="checkbox"/>
11	21/10/19 16:12	SCENE PHOTO	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	21/10/19 16:09	Sketch Plan	Load JPG	<input checked="" type="checkbox"/>
2	21/10/19 16:09	Sketch Plan #2	Load JPG	<input checked="" type="checkbox"/>
3	21/10/19 16:09	Sketch Plan #3	Load JPG	<input checked="" type="checkbox"/>
4	21/10/19 16:11	POLICE REPORT PG 1	Load JPG	<input checked="" type="checkbox"/>
5	21/10/19 16:11	POLICE REPORT PG 2	Load JPG	<input checked="" type="checkbox"/>
6	21/10/19 16:11	POLICE REPORT PG 3	Load JPG	<input checked="" type="checkbox"/>
7	21/10/19 16:11	2ND POLICE REPORT PG 1	Load JPG	<input checked="" type="checkbox"/>
8	21/10/19 16:11	2ND POLICE REPORT PG 2	Load JPG	<input checked="" type="checkbox"/>
9	21/10/19 16:11	2ND POLICE REPORT PG 3	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<p>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</p> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
<p>Show Remarks To: <input type="checkbox"/> Handling Insurer</p> <p><small>Note: Remarks are private unless you show it to other parties.</small></p>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19018803/KTF3Q2

Date: 10/01/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN30331119022
 Claimant Vehicle No: SJT6891G Insured Vehicle No: SLL1510H
 Date of Loss: 19/10/2019 Nature of Claim: TP Claim No: SNM19D20499502

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJT6891G
 Make & Model: SUZUKI SX4, 1.6 HB (A) Engine No: M16A1484737
 Reg. Date: 27/10/2009 (Man. Year: 2009) Chassis No: JSAGYA21S00312481
 Colour: Metallic Silver Odometer: 236953 km
 Engine Capacity: 1586 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
 Front Left Side: Bridgestone 7 mm Rear Left Side: Bridgestone 7 mm
 Front Right Side: Bridgestone 7 mm Rear Right Side: Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,522.60	2,322.67	4,199.93	64.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,420.00	2,190.00	1,230.00	35.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,942.60	4,512.67	5,429.93	54.61
Approved Total (Overridden) (S\$)		3,600.00		
(S\$)	9,942.60	3,600.00	6,342.60	63.79
+ GST 7.00/7.00% (S\$)	695.98	252.00	443.98	63.79
Nett Amount (S\$)	10,638.58	3,852.00	6,786.58	63.79

INSPECTION

Date of Assignment: 23/10/2019
 Date Inspected: 25/10/2019 Inspected At: Ah Lim Motor Company (AMK)
 10 Ang Mo Kio Industrial Park 2A,
 #01-09 AMK Autopoint
 Singapore 568047
 Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 09 Jan 2020)
Parts: 144	SUZUKI SX4 1.6 HB (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJT6891G)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Bent	481.60 FL	*481.60 FL
2	1		*FRONT BONNET INNER LOCK	Repair	56.55 FL	*- FL
3	1		*HEADLAMP LH & RH	N/S Mtg Cracked/O/SServiceable	738.10 FL	*369.05 FL
4	1		*FRONT GRILLE	Serviceable	117.30 FL	*- FL
5	1		*FRONT GRILLE EMBLEM	Serviceable	30.00 FL	*- FL
6	8		*FRONT GRILLE CLIPS	Not Necessary	24.00 FL	*- FL
7	1		*FRONT BUMPER	Buckled	790.45 FL	*790.45 FL
8	1		*FRONT BUMPER SIDE RETAINER LH & RH (2 PCS)	Distorted	18.45 FL	*18.45 FL
9	15		*FRONT BUMPER CLIPS	Necessary	45.00 FL	*45.00 FL
10	1		*FRONT BUMPER LOWER GARNISH	Serviceable	167.00 FL	*- FL
11	1		*FRONT BUMPER REINFORCEMENT	Repair	345.10 FL	*- FL
12	1		*FRONT FENDER LH	Repair	272.20 FL	*- FL
13	1		*FRONT FENDER COWLING LH	Serviceable	60.00 FL	*- FL
14	8		*FRONT FENDER CLIPS	Not Necessary	24.00 FL	*- FL
15	1		*RADIATOR SUPPORT PANEL	Repair	1,074.30 FL	*- FL
16	1		*AIR CON CONDENSER	Serviceable	586.30 FL	*- FL
17	1		*RADIATOR ASSY	Serviceable	806.20 FL	*- FL
18	1		*ENGINE MOUNTING FRONT	Serviceable	80.00 FL	*- FL
19	1		*ENGINE MOUNTING RH	Serviceable	140.10 FL	*- FL
20	1		*ENGINE MOUNTING REAR	Serviceable	75.00 FL	*- FL
21	1		*GEARBOX MOUNTING LH	Serviceable	73.00 FL	*- FL
22	1		*REAR BUMPER	Cracked	549.00 FL	*549.00 FL
23	2		*REAR BUMPER SIDE RETAINER LH & RH	Distorted	44.00 FL	*44.00 FL
24	15		*REAR BUMPER CLIPS	Necessary	45.00 FL	*45.00 FL
25	1		*REAR BUMPER LOWER GARNISH CTR (BLACK)	Dented / Cut	160.00 FL	*160.00 FL
26	2		*REAR BUMPER LOWER GARNISH SIDE LH & RH	Serviceable	240.00 FL	*- FL
27	1		*REAR BUMPER REINFORCEMENT	Bent	230.00 FL	*230.00 FL
28	1		*REAR END PANEL	Repair	316.00 FL	*- FL
29	1		*REAR END PANEL TOP GARNISH	Serviceable	85.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	7,673.65	2,732.55
- List Item Discount on L Items 15.00/15.00% (S\$)	1,151.05	409.88
Total Parts (S\$)	6,522.60	2,322.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING ,WIRE SOCKETS AND ETC.TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS ,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	20.00
2	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	60.00	0.00
3	TO DISMANTLE ALL DAMAGED PARTS .TO CUT & WELD RADIATOR SUPPORT PANEL TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS .TO REFIT LISTED PARTS BACK SAME	New	800.00	400.00
4	TO SPRAY FRONT BONNET ,FRONT BUMPER ,FRONT FENDER LH ,RADIATOR SUPPORT PANEL	New	800.00	550.00
5	TO DISCONNECT AND CHECK ELECTRICAL WIRING ,WIRE SOCKETS AND ETC .TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS ,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	20.00
6	TO REMOVE AND REINSTALL /REPLACE FRONT /REAR BUMPER SENSORS	New	80.00	50.00
7	TO DISMANTLE ALL DAMAGED PARTS .TO CUT & WELD END PANEL.TO KNOCK & REPAIR SPARE TYRE PANEL INNER PANELS AND AFFECTED AREAS .TO REFIT LISTED PARTS BACK SAME	New	800.00	550.00
8	TO SPRAY TAILGATE ,REAR BUMPER ,END PANEL ,SPARE TYRE PANEL	New	800.00	600.00
Gross Labour Cost (\$\$)			3,420.00	2,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >