SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

| aforesaid. | |
|--|--------------------------------------|
| | ACCIDENT STATEMENT |
| Date Of Report | 24/10/2019 09:17 |
| Date Of Accident | 06/05/2019 11:50 |
| Exact Location Of Accident | JALAN TAN TOCK SENG BASEMENT CARPARK |
| Country/State of Loss | SINGAPORE |
| D | ETAILS OF OWN VEHICLE |
| Vehicle Registration Number | SGV737J |
| Insured/Policyholder | |
| Name Of Registered Owner | TAN SIA HWEE ALEX |
| NRIC No | S8137352C |
| Email Address | NOEMAIL |
| Mobile Phone No | (LOCAL) +65-98793227 |
| Alternative Phone No | OFFICE-98793227 |
| Vehicle Particulars | |
| Manufacturer | NISSAN |
| Model | X-TRAIL 2.0 CVT ABS 4WD S/R 7-STR |
| Exact Purpose for which vehicle was being used at time of accident | PRIVATE USE |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE CAR |
| Insurance Company | |
| Name of Insurance Company | FWD SINGAPORE PTE. LTD. |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | PNPV2018-00003657-01 |
| Cover Note Number | |
| Driver | |

TAN SIA HWEE, ALEX (CHEN SHEHUI, ALEX) Name of Driver

NRIC No S8137352C 20/11/1981 Date Of Birth Occupation **INDOOR Date Of Driving Pass** 18/10/2002

Driving Experience 16 YEARS AND 6 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-98793227

Fax Number

Contact Number OFFICE-98793227

EMail Address NOEMAIL

17 FERNVALE CLOSE Address

#12-29

Postcode 797478

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured **OWNER**

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED Type Of Accident

Weather Conditions **CLEAR** Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

involved in the accident

2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by

ambulance?

YES

Was any other material or property damaged? I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO 0

Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name TRAFFIC POLICE DIVISION HQ - SINGAPORE CITY

NO

ROAD: 10 UBI AVENUE 3, POSTCODE: 408865, COUNTRY:

Police Station Address SINGAPORE

Police Station Contact TEL NO: 65470000 - FAX NO:

Was notice of intended Prosecution given?

If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT - T/20190508/7001.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

VIDEO FOOTAGE WITH DRIVER

NO Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SDD1188S Vehicle Make/Model/Colour **TOYOTA**

Details Of Properties

PRIVATE CAR Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4: The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- 5. Any false reporting may be referred to the Police for investigation.
- 5. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association
- of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

l'understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date &

Sketch Plan

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reg

Tan Tock Seng Hospital BI Carpark.

rting Centre

One Way traffic

SGY737J

SDD 1188 S

Accident Sketch Plan

| Pala Ta Pa | Tine Roport | NO: 7/2019050 | 1001/8 |
|------------------------------|--------------------------------|--------------------------------------|--|
| Kefer 10 10 | 11a Age | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| 1 | , | | |
| | | | \ \ |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | - | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| aration | | | |
| | | | |
| ectare the foregoing partici | ulars are true in every respec | A. | |
| 0 | 2 | | -1 |
| LOWATN. | aguiatra | | |
| July 1 | * Salled | | VMA |
| holder's Signature / Date & | Driver's Signature (# dri | iver is not the policyholder) / Date | Witnessed by Reporting Centre Personnel |
| | 8. Time | | revsonner |
| | | | |
| | | | |

Police Report



T/20190508/7001

Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

1 of 3 Report No. T/20190508/7001

REPORT OF A TRAFFIC ACCIDENT

| | ate/Time Report Made: 8/05/2019 01:24 | | Vide Report No.: | Station Diary No. | | |
|--|--|---------------------------|--|----------------------------|--|--|
| Informa | nt's Partic | ulars | La Manual State Control | | | |
| Name of Informant: TAN SIA HWEE, ALEX | | | Address: 17 FERNVALE CLOSE #12-29 SINGAPORE 797478 | | | |
| ID Type NRIC N | / ID No.: D / S81373 | 52C | Contact No.: Home/Office: | Mobile: 98793227 | | |
| Nationality: SINGAPORE CITIZEN | | EN | Email: alextan737@yahoo.com.sg | | | |
| Sex: Male | Age: 37 | Date of Birth: 20/11/1981 | Type of Informant: Driver | | | |
| Race: Chinese | | | Language: English | Institution / School Name: | | |
| Occupation: Project Manager | | | Driving Licence Information: Class: Date of Expiry: | | | |

| Type of Accident: | Non-Injury Hit and Run | Drink Drive: No | Date/Time of Accident: 06/05/2019 11:50 | Type of Location Car Park |
|-----------------------------------|---------------------------|------------------------------------|---|------------------------------|
| Location: JALAN TAN 1 | OCK SENG | Road Surface: | | toad Speed Limit: |
| Clear | | | | U Nm/n |
| Clear Traffic Flow: One Way | | Traffic Control: Not Controlled | Т | raffic Volume: |

| Details of V | ehicle Invo | lved | The state of the s | SELECTION | SALIS VALUE OF SALIS | DEPT- PERSON I |
|--------------|-------------|--------|--|-----------|----------------------|----------------|
| Vehicle No. | Туре | Make | Model | Color | Condition | No of Passenge |
| SDD1188S | Car | ТОУОТА | ТОУОТА | Grey | Slightly Damaged | 0 |
| SGV737J | Car | NISSAN | X-TRAIL 2.0 CVT ABS 4WD S/R 7- STR | White | | 0 |

| Details of Vehicle Insurance | | | | | |
|------------------------------|------------------------|--------------------------|------------|-------------|--|
| Vehicle No. | Insurance Company | Insurance No | Effective | Expiry Date | |
| SGV737J | FWD Singapore Pte. Ltd | PNPV2018- 00003657-01 | 29/03/2019 | 28/03/2020 | |

Police Report





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

2 of 3 Report No. T/20190508/7001

CONTINUATION OF REPORT

| Details of Perso | n Involved | SECOND! | | 0100 100 | 19016 | |
|-------------------|-------------------|---------|-----------|------------------------------------|----------|-----------------------------------|
| Any Pedestrian I | nvolved: No | | | | | |
| No. of Pedestrian | ns Injured: NIL | | Use of Pe | destriar | Cross | ing: NA |
| Driver | | 1300000 | | E-0.04 | | ang. Tex |
| Name | TAN SIA HWEE, AI | LEX | | ID No | ١, | S8137352C |
| Related Vehicle | SGV737J (Car) | | Conta | ct No. | 98793227 | |
| Hospital/Clinic | NIL | | | Class Drivin Licen Expiry | g | Class: NIL Date of Expiry: NIL |
| Date Treatment | NIL | | Date Disc | harge | NIL | |
| No. of Days gran | ted Medical Leave | NIL | Degree o | | NIL | |

Brief Details.

ON 6 MAY 2019, AT ABOUT 1145HRS, I PARKED MY VEHICLE BEARING SGV737J, WHITE NISSAN X-TRAIL, AT TTSH B3 CARPARK, NEAR PILLAR "S12", UNKNOWN LOT NUMBER.

ON 7 MAY 2018, UPON CHECKING MY VEHICLE, I NOTICED THERE WERE SOME SCRATCHED ON MY FRONT RIGHT BUMPER. I IMMEDIATELY REVIEW MY FRONT CAR CAM FOOTAGE RECORDINGS AND DISCOVERED THE FOLLOWING.

THE FOOTAGE REVEALS THAT ON 6 MAY 2019 AT 1153HRS, A GREY TOYOTA MPV CAR, BEARING SDD1188S, HAD KNOCKED ONTO MY FRONT BUMPER WHILE MAKING A TURN AGAINST THE FLOW, WHILE EXITING ITS PARKING LOT. MY VEHICLE WAS OBSERVED TO BE SHAKING DUE TO THE IMPACT. THE CARPARK IS A ONE-WAY TRAFFIC. THERE WASN'T ANY NOTE LEFT ON MY VEHICLE AND THE SAID VEHICLE LEFT SCENE. I ONLY DISCOVERED IT WHEN I SAW SOME SCRATCH MARKS ON MY FRONT BUMPER THE FOLLOWING DAY. I WISHED TO STATE THAT I'M LODGING THIS REPORT TO ESTABLISH THE DRIVER FOR REPAIR CLAIMS PURPOSES & FOOTAGE SIZE IS TO HUGE TO ATTACH IN THIS REPORT. THAT'S ALL.

Police Report





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

3 of 3 Report No. T/20190508/7001

CONTINUATION OF REPORT

| Sketch Plan | | | | | | |
|--------------|-----|------|----|---------|--------|------|
| Informant is | not | able | to | provide | sketch | plan |

NP168

| Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required. |
|--|
| Date/Time: 08/05/2019 01:24 |
| Classification Of Case: |
| |









