

Your Ref: 8840223163SG-003

Date: 01<sup>st</sup> Nov 2019

Our Ref: CS1/AIG19018856/Eyd3e2

**M/s AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way #08-16

Chartis Building

Singapore 079120

Attn : Lee Ming Yao

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SKX 5684L****INSURED VEHICLE: SKQ 9734L****ACCIDENT DATE: 01/08/2017**

We thank you for your instruction on 23/10/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SKX 5684L from M/s PAR Automotive Consultancy.
- b) Singapore Accident Statement of Vehicle SKX 5684L and SKQ 9734L.
- c) Colour damaged vehicle photographs of SKX 5684L.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

## 1. Information Recorded: -

Registration Number	: SKX 5684L
Make & Model	: BMW 320I
Year of Registration	: 2011
Chassis Number	: WBAPG56010NM91080

2. We recommend that the repairs of the entire damage require about 7 (Seven) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.