

22/03/2002

ASS. REC. BY:

REF: CS1 P1 19018860 (Eg f3⁵)

Special Instruction:

Survivor:

Steve

ASSIGNMENT (Office)

From (Person):

Meiwa Chia San San

of

FC1

Date/Time: 24.10.19 11.09.19

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKD 5062L

Insured:

SHA 9397X

at Workshop m/s

Falcon- Air Auto

Tel:

67795665

of NO 8 Pandan Loop

Policy No:

Claim No:

D19006758MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A 22.10.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

emp 1

H.O.D. Endorsement:

Date/Time: 24.10.19 11.22 a.m

Person Contacted:

Andy

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKD 5062L - X

SHA 9397X - X

04/11/19 @ 1.04pm revised to Meiwa Chia by email.

06/11/19 @ 11.49am Andy informed that the vehicle has not repair yet as awaiting for availability.

06/11/19 Submit Prelim. report. - The vehicle has not send in for repair.

ACC. REC. BY:

Steve

REF:

PC1

ASSIGNMENT

From:

Date:

1.11.2019

Estimated Cost:

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

To Inspect Vehicle No:

SKD 5062 L

at Workshop m/s

Falcon - Air

of

Blk B Pandan Lerp

Insured:

Policy No.:

Claims No.:

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

12.00 pm - 1.00 pm On-site survey

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKD 5062

Yr Regn:

14/11/11

Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

BMW 116i

C.C.

1995 F98

Colour

Silk

A/C: Insured / Std / NI / NA

Sp. Reading

43448

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBA1A12040E946297

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/52R17

R:

4

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

5

mm

Rear

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

22/10/19

D.O.I.

1/11/19

Survey held at

Falcon

Des. of Damages

Frt

Rear

O/S

N/S

U/C

Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV - 39K

RECEIVED 06 NOV 2019

Date/Time, File Pass to?



: Preli. Report

11/06/11 train



: Final Report

Date/Time, File Return to?

2)

Rep. Form:

Temp. Sum / M.D. J. C.

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Invs (\$)



: Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

130

50

22

202

MOTOR SURVEY ASSIGNMENT

Date	23-10-2019	Our Ref No. D19006758MFSH
Accident Date	22-10-2019	Claim Type. Third Party
Insured Vehicle	SHA9397X	Third Party Vehicle. SKD5062L
Survey Location	NO.8 PANDAN LOOP (BLK 1 / BLK K)	
Contact Person.	ANDY	
Contact No.	67795665/ 0	Fax No. 67791110
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	FALCON-AIR AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MERINA CHIA SAN SAN	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: ANDY <andy@falconair.com.sg>
Sent: Wednesday, 6 November 2019 11:49 AM
To: Shiau Chan (LKKAUTO)
Subject: RE: KINDLY ADVISE THE STATUS OF VEHICLE SKD 5062L (DOA: 22/10/2019)

Still waiting for liability
Haven't repair yet

From: Shiau Chan (LKKAUTO) [mailto:siewsc@lkkauto.com]
Sent: Wednesday, November 06, 2019 11:21 AM
To: ANDY <andy@falconair.com.sg>
Subject: KINDLY ADVISE THE STATUS OF VEHICLE SKD 5062L (DOA: 22/10/2019)

Dear Andy,

Kindy advise the status of above vehicle.

If done of repair, kindly send us the final bill for finalise.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 4 November 2019 1:04 PM
To: 'CWS Motor Claims'; assignments; SUR
Cc: 'Merina Chia'
Subject: RE: SURVEY ASSESSMENT - D19006758MFSH/1
Attachments: CSFCI19018860Eqf3.pdf

Dear Merina,

Enclosed herewith preliminary advice of SKD 5062L.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Thursday, 24 October 2019 11:25 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Merina Chia' <MerinaChia@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19006758MFSH/1

Dear Sir/Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Sent: Thursday, 24 October, 2019 11:19 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Merina Chia <MerinaChia@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19006758MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19006758MFSH

Date: 04 November 2019

Our Ref: CS/FCI19018860/Eqf3

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKD 5062L .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 01/11/2019 at the premises of M/s FALCON-AIR AUTO, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>3,377.55</u> .
Revised Estimate Amount	: S\$ <u>3,177.56</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the front portion.



Yours faithfully

Steve
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/10/2019 13:52
Date Of Accident	22/10/2019 12:00
Exact Location Of Accident	SAGO LANE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKD5062L
Insured/Policyholder	
Name Of Registered Owner	MUNIESPARAN S/O MUTHIAH
NRIC No.	S2699037H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91354137
Alternative Phone No	OFFICE-91354137

Vehicle Particulars

Manufacturer	BMW
Model	116I
Exact Purpose for which vehicle was being used at time of accident	PRIVATE HIRE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5113315017
Cover Note Number	DRIVO CLASSIC

Driver

Name of Driver	MUNIESPARAN S/O MUTHIAH
NRIC No	S2699037H
Date Of Birth	13/10/1966
Occupation	INDOOR
Date Of Driving Pass	19/09/2002
Driving Experience	17 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91354137
Fax Number	
Contact Number	OFFICE-91354137
Email Address	NOEMAIL

Sketch Plan Pg. 1

INCOME MOTOR SERVICE CENTRE

Report Date & Start Time: 22/10/2019 / 13:45

Report No: MIT

D.O.A: 22/10/2019

Time: 12:00 hrs

Vehicle No: SKD5062L Reporting Type:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


22/10/19 / 13:45
Policyholder's Signature / Date & Time

22/10/19 / 13:45
Driver's Signature (If driver is not the policyholder) / Date & Time

Alan Tang (S098825)
Customer Care Executive
Motor Service Centre

Witnessed by Reporting Centre Personnel

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 037H

Vehicle Details

Vehicle No.: 5KD5062L
Vehicle to be Exported: Yes
Intended Deregistration Date: 23 Oct 2019
Vehicle Make: B.M.W.
Vehicle Model: 116i AT ABS D/AIRBAG 2WD HID 5DR
Primary Colour: Silver
Manufacturing Year: 2011
Engine No.: B084J068N13B16A
Chassis No.: WBA1A12040E946297
Maximum Power Output: 100.0 kW (134 bhp)
Open Market Value: \$29,093.00
Original Registration Date: 14 Nov 2011
First Registration Date: 14 Nov 2011
Transfer Count: 2
Actual ARF Paid: \$29,093.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 13 Nov 2021
PARF Rebate Amount: \$17,455.00

Intended COE Rebate Details

COE Expiry Date: 13 Nov 2021
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$56,112.00
COE Rebate Amount: \$11,545.00
Total Rebate Amount: \$29,000.00

The information contained herein is correct as at 23 Oct 2019

OK



FALCON-AIR

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

MUNIESPARAN S/O MUTHIAH
BLK252 #04-183 JURONG EAST STREET 24
SINGAPORE 600252

Attention: Motor Claim Department

Contact: 91354137

Estimate: ES003554

Date: 23/10/2019
Vehicle Num.: SKD5062L
Make/Model: BMW116I
Chassis/Eng#: WBA1A12040E946297
Accident Date: 22/10/2019
Claim No.:
Reference: TP NTUC VS MSFCI
Policy No.:

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	LIST ITEMS:		
2.	1	HEADLAMP / CUT		1,801.75
3.	1	FRONT BUMPER / CR4		871.10
4.	1	FRONT BUMPER LOGO / RPL		75.10
5.	1	TOW COVER / CUT		38.95

List Total S\$:	2,786.90
5.00% Discount S\$:	139.35
	2,647.55

LABOUR:	
TO FOCUS HEADLAMP / CHECK LIGHT SYSTEM	30.00
SPRAY PAINTING ON ACCIDENT DAMAGED AREAS INNER/OUTER	400.00 250
TO REPAIR INNER PANEL INCLUDES KNOCKING & REPLACEMENT OF PARTS	300.00 250
Labour Total S\$:	730.00

SingDollars: Three Thousand Three Hundred Seventy-Seven & Cents Fifty-Five Only

E. & O. E.

Total S\$: 3,377.55

for FALCON-AIR AUTO SERVICES PTE LTD



Steve (LKK)
8322 8813

[Handwritten signature]
4/11/19
L/L Phil 1/11/19, 1.00pm
3 day
L/S
By AL Sy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI19018860/Eqf3s2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 13-11-2019



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 9397X	Veh. Inspected	SKD 5062L
Policy No.		Coverage (\$)	0.00
Claim No.	D19006758MFSH	Excess (\$)	0.00
Assign From	MERINE CHIA SAN SAN	Assign Date	24/10/2019

2. Vehicle Particulars & Condition

Make & Model	B.M.W. 116I	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	WBA1A12040E946297	Colour	SILVER
Odometer	43448	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/50 R17	BRIDGESTONE	5 mm
L/H Front Tyre	205/50 R17	BRIDGESTONE	5 mm
R/H Rear Tyre	205/50 R17	BRIDGESTONE	5 mm
L/H Rear Tyre	205/50 R17	BRIDGESTONE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/10/2019	Inspection Date	01/11/2019
Survey held at	FALCON-AIR AUTO SERVICES PTE LTD BLK 8 PANDAN LOOP SINGAPORE 128226		

5a. Remarks

A)THE VEHICLE HAS NOT SEND IN FOR REPAIR. B)DAMAGES CONSISTENT TO ACCIDENT REPORT. C)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. D)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKD 5062L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	HEADLAMP	CUT	1,801.75	1,801.75
1	FRONT BUMPER	CRUSHED	871.10	871.10
1	FRONT BUMPER LOGO	NECESSARY	75.10	75.10
1	TOW COVER	CUT	38.95	38.95
	LESS 5% DISCOUNT		-139.35	-139.35
			2,647.55	2,647.55
LABOUR				
	TO FOCUS HEADLAMP / CHECK LIGHT SYSTEM.		30.00	30.00
	SPRAY PAINTING ON ACCIDENT DAMAGED AREAS INNER / OUTER.		400.00	250.00
	TO REPAIR INNER PANEL INCLUDES KNOCKING & REPLACEMENT OF PARTS.		300.00	250.00
			730.00	530.00
GRAND TOTAL			3,377.55	3,177.55
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)				3,177.55

Report Ref No. CS/FCI19018860/Eqf3s2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.