

ASS. REC. BY:

REF:

CS/III/19018872/USD312

Special Instruction:

Supervisor: Marcus

ASSIGNMENT (Office)

From (Person): Immen Gabriel wee

of

III

Date/Time: 21/10/2019 9:41am

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKX4593Y

Insured:

SHC8672Y

at Workshop in/s

Impenium Automotive

Tel:

9748 9940

of

25 Kelbi Bukit Road 4 # 01-41 Synergy

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 22/10/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 11:05 AM 21/10/19

Person Contacted:

Shawn

Vehicle ☒ IN / OUT

Date/Time	Action/Instruction	
	SKX4593Y - NA/INC/19018872/19/14	DOA: 22/10/2019
	SHC8672Y - NA/INC/19018872/19/14	DOA: 22/10/2019

ASS. REC. BY:

MARCUS

(12)

ASSIGNMENT

Front

Date

Estimated Cost:

OD / TR / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SKX 45934

at Workshop mis

competition

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKX 45934

Yr Regn:

12 / 15

Type:

M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Toyota corolla Altis 1598

Colour:

silver

A/C:

Insured / Std / NI / NA

Sp. Reading

71946

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MR 053REH/104537599

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55-216

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Triangle

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

22/10/19

D.O.I.

24/10/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

29/10/19 4/5 4000 contact with Shown.
(\$ 4,355.55 Red - 65%)

RECEIVED 30 OCT 2019

Date/Time, File Pass to?

30/10/19

Type

Type 4

Date/Time, File Return to?

2)

☐

: Prel. Report

☒

: Final Report

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Wash and (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Other

TOTAL

350

11

361

Payment Form:

Lump Sum / REP: \$4,000/- 4/5

PHILIPS

Fastest results



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Toyota Harrier 2.0A G-Grade Turbo super low mileage.



In House Finance Or Bank Loan
Available, Borneo Motor 5 Years
Warranty.
Speedo Monitoring Starlid



Browse by Category

Back (1 2) Next >







Sort by Date Posted

20 results/page

26 vehicles

altis

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	altis		Any	Any	2015	Any	Any	Any	Available
	Toyota	Corolla Altis 1.6A Classic	\$61,800	\$9,880 /yr	02-Jun-2015	1,598 cc	35,375 km	Sedan	Available
1 Owner Only! Well Maintained, Unit In Excellent Condition! Low Mileage Done Only 35,000Km. Don't Miss This Unit! Bank Or In House...									
Posted: 24-Oct-2019 Tags: 2015 Toyota Corolla, 2015 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota									
	Toyota	Corolla Altis 1.6A Classic	\$54,800	\$9,060 /yr	05-Mar-2015	1,598 cc	52,000 km	Sedan	Available
Nice Old No.1119, Cheapest In The Market! Selling Close To Export Price, Low Mileage Done, Fully Agent Maintained Since Day 1, 5Y Bo...									
Posted: 23-Oct-2019 Tags: 2015 Toyota Corolla, 2015 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota									
	Toyota	Corolla Altis 1.6A Classic	\$58,800	\$9,310 /yr	10-Jun-2015	1,598 cc	85,000 km	Sedan	Available
1 Owner! Fully Serviced By Borneo. 5 Years Warranty Package. Records Available. Comes With Front And Back Cameras, New Tyres! (Yo...									
360 VR Cars									
Posted: 23-Oct-2019 Tags: 2015 Toyota Corolla, 2015 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota									
	Toyota	Corolla Altis 1.6A Elegance	\$63,800	\$9,160 /yr	15-Sep-2015	1,598 cc	80,668 km	Sedan	Available
Like New Very Well Maintained By 1 Previous Owner. High ARF! Unit Maintained In Good Condition! Clean Paintwork Paired With Grey L...									
Tai Hui Automobile									
Posted: 23-Oct-2019 Tags: 2015 Toyota Corolla, 2015 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota									
	Toyota launches the new Corolla Sport								
The Corolla marks its 52nd anniversary this year, with the launch of the new Corolla Sport boasting new connectivity features.									
Read this article									
	Toyota	Corolla Altis 1.6A Elegance	\$62,800	\$8,820 /yr	27-Oct-2015	1,598 cc	59,900 km	Sedan	Available
1 Owner. In Showroom Condition, View To Believe! Hua Yang Group Since 1984! Iso 9001:2000 Certified, Bank Loan, In House Loan, Ba...									
Hua Yang Credit Pte Ltd									
Posted: 21-Oct-2019 Tags: 2015 Toyota Corolla, 2015 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota									
	Toyota	Corolla Altis 1.6A Classic	\$65,800	\$9,550 /yr	07-Oct-2015	1,598 cc	63,000 km	Sedan	Available
Fully Agent Maintained. Non Phv Unit! In Showroom Condition, View To Believe! Hua Yang Group Since 1984! Iso 9001:2000 Certified, B...									
Hua Yang Credit Pte Ltd									
Posted: 21-Oct-2019 Tags: 2015 Toyota Corolla, 2015 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota									

Compare

Compare

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 311F

Vehicle Details

Vehicle No.: SKX4593Y

Vehicle to be Exported: No

Intended Deregistration Date: 24 Oct 2019

Vehicle Make: TOYOTA

Vehicle Model: COROLLA ALTIS CLASSIC 1.6 CVT

Primary Colour: Silver

Manufacturing Year: 2015

Engine No.: 1ZRX527397

Chassis No.: MR053REH104537599

Maximum Power Output: 90.0 kW (120 bhp)

Open Market Value: \$17,452.00

Original Registration Date: 15 Dec 2015

First Registration Date: 15 Dec 2015

Transfer Count: 2

Actual ARF Paid: \$17,452.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 14 Dec 2025

PARF Rebate Amount: \$13,089.00

Intended COE Rebate Details

COE Expiry Date: 14 Dec 2025

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$56,001.00

COE Rebate Amount: \$34,371.00

Total Rebate Amount: \$47,460.00

The information contained herein is correct as at 24 Oct 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	23/10/2019 13:20
Date Of Accident	22/10/2019 17:45
Exact Location Of Accident	AYE B4 ALEXANDRA EXIT 6
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKX4593Y
Insured/Policyholder	
Name Of Registered Owner	MEGHALAA D/O KUPPAN
NRIC No	S7122311F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97482739
Alternative Phone No	OFFICE-97482739
Vehicle Particulars	
Manufacturer	TOYOTA
Model	COROLLA ALTIS
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5100927414-01
Cover Note Number	
Driver	
Name of Driver	MEGHALAA D/O KUPPAN
NRIC No	S7122311F
Date Of Birth	26/06/1971
Occupation	INDOOR
Date Of Driving Pass	21/04/2003
Driving Experience	16 YEARS AND 6 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97482739
Fax Number	
Contact Number	OFFICE-97482739
Email Address	NOEMAIL

Address	BLK 477 PASIR RIS DR 6 #04-516
Postcode	510477
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	PASIR RIS NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 1 PASIR RIS DRIVE 4 , POSTCODE: 519457 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-5852999 - FAX NO: 65855261
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC8672Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	TEO CHIN WAN HOWARD
NRIC/Passport Number	S8101107I
Contact Number	92335551

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or Agents (including their lawyers, law firm) which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be used, disclosed:
- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulations, law enforcement and government or regulatory requirements or requirements of any other statutory or regulatory body;
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 23/10/19

Driver's Signature


Date & Time:

Records Centre Personnel's Signature

Name: NHC/SH/NAZ

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report

DECLARATION

I/We declare the foregoing particulars are true to my/our respect.

Policyholder's Signature
Date & Time: 23/10/19

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Accident Scene Personnel's Signature
Name:
NR:

POLICE REPORT

CONFIDENTIAL

ANNEX E

NOTICE OF REPORTING

This is to confirm that MEGHALAA D/O KUPPAN, NRIC / FIN S7122311F reported to the Police a non-injury traffic accident which occurred at AYE before Alexandra Exit 6 on the 1st lane from the right on 22/10/2019 at 05:45pm involving the following vehicles;

V1) SKX4593Y – Toyota, Corolla Altis, Silver in colour

V2) SHC8672Y – Hyundai, i40, Blue in colour

Complainant informed that she was driving in V1. Complainant was travelling on the first lane from the right on AYE before Alexandra Exit 6 and it was a heavy jam on the expressway. The vehicle in front of complainant stopped and suddenly V2 hit the rear of V1.

Complainant stepped out of V1 and enquired if the V2 driver requires any medical attention however the V2 driver informed it was not necessary. Both parties exchanged particulars and left the scene. Complainant have in-vehicle camera installed front and rear.

Complainant vehicle (V1) was dented and scratched at the rear bumper and rear sensor dropped out. V2 front bumper was scratched.

No one was injured at the point of accident. Complainant is lodging this report to claim insurance against the other party.

The other party Teo Chin Wan Howard, 971011971, his contact number: 92335551.

2 If this accident was reported to the Police within 24 hours of its occurrence then he/she has complied with Sec 84 (2) of the Road Traffic Act, Cap 276

POLICE REPORT

Rank / Name of Issuing Officer: Sgt(2) T180128 Johnny Tan

Date: 22/10/2019 Time: 2218hrs

S/D Ref No: 85

Police Post / Unit: Pasir Ris NPC



Pasir Ris NPC
No. 1 Pasir Ris Drive 4
01-01 Singapore 519457
Tel: 1800-5852999

Original to be issued to complainant
Duplicate to be submitted to Traffic Police

CONFIDENTIAL

IMPERIUM AUTOMOTIVE

25 Kaki Bukit Road 4 #01-49 Synergy@KB, Singapore 417800

HP : 9748 9940 Shawn Tan Fax : 6346 7213

Email: shawn7530@hotmail.com

Not Authorized
LKK

4/S\$ 4000/

5 day
Thephe After 1 day

23 Oct 2019

Vehicle No.: SKX 4593 Y

Model: Toyota Corolla Altis

QTY

DESCRIPTION

AMT S\$

List Items

1	Rear boot lid	
2	Rear boot hinges	
2	Rear boot lamps	
1	Rear boot lock	
1	Rear boot rubber	
1	Rear boot "COROLLA" emblem	62.00
1	Rear boot "ALTIS" emblem	60.80
2	Rear taillamps	
1	Rear end panel	699.20
1	Rear end panel inner garnish	
1	Rear keyless sensor	
1	Rear bumper	
2	Rear bumper top brackets	
2	Rear bumper side brackets	38
2	Rear bumper reflectors	
1	Rear bumper reinforcement	
2	Rear bumper reinforcement stays	
2	Rear bumper side retainers	
2	Rear bumper PDC sensors	195
1	Rear spare tyre board	
1	Rear spare tyre panel	
1	Rear exhaust silencer	
2	Rear exhaust mountings	
2	Rear fender inner trims	

3ent/buc	\$	985.70	✓
11	\$	171.40	X
11	\$	577.40	X
twi	\$	100.80	✓
twi	\$	145.70	✓
rec	\$	80.30	✓
rec	\$	75.70	✓
crs	\$	760.20	✓
so	\$	777.40	✓
twi	\$	200.30	✓
scu	\$	185.20	X
ro/pe	\$	488.70	✓
u7	\$	181.80	X
ol/scr	\$	97.00	12c
un	\$	120.20	X
so	\$	344.70	✓
scu	\$	161.00	X
3ent	\$	130.00	✓
Shuhl	\$	390.00	12c
u7	\$	363.50	X
A	\$	1,100.70	X
11	\$	881.70	X
11	\$	97.20	X
11	\$	670.80	X
	\$	9,087.40	
Less 25%	\$	2,271.85	
	\$	6,815.55	

2-4208.10

257

9-3156.07

5-N-40.00

L-1830.00

5206.07

202

4020.81

Special Nett Items

- | | |
|---|-------------------------------|
| 1 | Rear bumper clip (1 set) |
| 1 | Rear number plate with holder |
| 1 | Rear reverse camera |

\$ Mr	50.00	40
\$ A1	50.00	X
\$ A1	480.00	X
\$	580.00	

S/N. Labour Charges

- | | |
|---|--|
| 1 | To remove, replaced damaged lamps and check up rear wiring. |
| 2 | To remove and refit inner garnishes. |
| 3 | To remove and refit rear reverse sensor. |
| 4 | To transfer boot lid mechanism and wiring assembly. |
| 5 | To remove, refit and replace exhaust silencer and mountings. |
| 6 | To apply undercoating. |
| 7 | Panel beating. |
| 8 | To respray painting on the affected areas. |

\$	80.00	30
\$	180.00	80
\$	150.00	50
\$	120.00	60
\$ A1	150.00	X
\$	180.00	60
\$	1,600.00	600
\$	1,500.00	950
\$	3,960.00	

1930

Grand Total : \$ 11,355.55

LKK Auto Consultants hence notify the Repaire of the following:

- To resurvey before/after spray painting
- To display damaged car(s) during resurvey
- Plans / costs are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III19018872/USD3N2

Date: 31/10/2019

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	
Claimant Vehicle No :	SKX4593Y	Insured Vehicle No :	SHC8672Y
Date of Loss:	22/10/2019	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKX4593Y	Engine No:	12RX527397
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A)	Chassis No:	MR053REH104537599
Reg. Date:	15/12/2015 (Man. Year: 2015)	Odometer:	71946 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Triangle 6 mm	Rear Left Side:	Triangle 6 mm
Front Right Side:	Triangle 6 mm	Rear Right Side:	Triangle 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	7,395.55	3,196.07	4,199.48	56.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,960.00	1,830.00	2,130.00	53.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,355.55	5,026.07	6,329.48	55.74
Approved Total (Overridden) (\$\$)		4,000.00		
Nett Amount (\$\$)	11,355.55	4,000.00	7,355.55	64.77

INSPECTION

Date of Assignment:	24/10/2019	
Date Inspected:	24/10/2019	Inspected At:
		Imperium Automotive - Kaki Bukit (HQ)
		25 Kaki Bukit Road 4, #01-49
		Synergy@KB
		Singapore 417800
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 Oct 2019)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKX4593Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Bent/Buckled	985.70 FL	*985.70 FL
2	2		*REAR BOOT HINGES	Not Necessary	171.40 FL	*- FL
3	2		*REAR BOOT LAMPS	Not Necessary	577.40 FL	*- FL
4	1		*REAR BOOT LOCK	Twisted	100.80 FL	*100.80 FL
5	1		*REAR BOOT RUBBER	Twisted	145.70 FL	*145.70 FL
6	1		*REAR BOOT COROLLA EMBLEM	Necessary	80.30 FL	*62.00 FL
7	1		*REAR BOOT ALTIS EMBLEM	Necessary	75.70 FL	*60.80 FL
8	2		*REAR TAILLAMPS	Cracked	760.20 FL	*760.20 FL
9	1		*REAR END PANEL	Dented	777.40 FL	*699.20 FL
10	1		*REAR END PANEL INNER GARNISH	Twisted	200.30 FL	*200.30 FL
11	1		*REAR KEYLESS SENSOR	Serviceable	185.20 FL	*- FL
12	1		*REAR BUMPER	Dented/Deformed	488.70 FL	*488.70 FL
13	2		*REAR BUMPER TOP BRACKETS	Not Necessary	181.80 FL	*- FL
14	1		*REAR BUMPER SIDE BRACKETS	O/s Cracked	97.00 FL	*35.00 FL
15	2		*REAR BUMPER REFLECTORS	Not Necessary	120.20 FL	*- FL
16	1		*REAR BUMPER REINFORCEMENT	Dented	344.70 FL	*344.70 FL
17	2		*REAR BUMPER REINFORCEMENT STAYS	Serviceable	161.00 FL	*- FL
18	2		*REAR BUMPER SIDE RETAINERS	Bent	130.00 FL	*130.00 FL
19	1		*REAR BUMPER PDC SENSORS (2 Pcs)	Shorted (1 Pc only)	390.00 FL	*195.00 FL
20	1		*REAR SPARE TYRE BOARD	Not Necessary	363.50 FL	*- FL
21	1		*REAR SPARE TYRE PANEL	Repair	1,100.70 FL	*- FL
22	1		*REAR EXHAUST SILENCER	Not Necessary	881.70 FL	*- FL
23	2		*REAR EXHAUST MOUNTINGS	Not Necessary	97.20 FL	*- FL
24	2		*REAR FENDER INNER TRIMS	Not Necessary	670.80 FL	*- FL
25	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*40.00 FS
26	1		*REAR NUMBER PLATE WITH HOLDER	Not Necessary	50.00 FS	*- FS
27	1		*REAR REVERSE CAMERA	Not Necessary	480.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	9,667.40	4,248.10
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,271.85	1,052.03
Total Parts (\$\$)	7,395.55	3,196.07

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	30.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	180.00	80.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	150.00	50.00
4	TO TRANSFER BOOT LID MECHANISM AND WIRING ASSEMBLY	New	120.00	60.00
5	TO REMOVE,REFIT AND REPLACE EXHAUST SILENCER AND MOUNTINGS	New	150.00	0.00
6	TO APPLY UNDERCOATING	New	180.00	60.00
7	PANEL BEATING	New	1,600.00	600.00
8	TO RESPRAY PAINTING ON THE AFFECTED AREAS	New	1,500.00	950.00
Gross Labour Cost (S\$)			3,960.00	1,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >